

22/03/2012

ASS. REC. BY:

REF: CS3 A1G 19006354/ EC d301 Special Instruction:Survivor: Store ASSIGNMENT (Office)

minim

From (Person): Hor xinnu 1 of A1G Date/Time: 10.4.19 8.389.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJW 3445R Insured: SLC 599Gat Workshop m/s One Plexi Tel: 86862266of NO 8 Kaki Bukit Ave 4 # 06-33Policy No: 2100463071 Claim No: 147544090480

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 8.4.19
(Client's Record) (15.4.19 12.00-3.00)CA / REV / REP. / REV 24 HRS "wp" H.O.D. Endorsement: _____Date/Time: 10.4.19 12.04pm Person Contacted: Adrian Vehicle: IN OUT

Date/Time	Action/Instruction (☒) Estimate
	<u>SJW 3445R - X</u>
	<u>SLC 599G - X</u>
	<u>Dismanthl: 15/4/2019</u>

Steve

REF:

ASSIGNMENT

From

Date:

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured

Policy No.

Claims No

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time : Action / Instruction

20/4 Spoken to Adrian, confirmed will not provide estimate for this case. No. 83E.

Steve

Pls see me

John

20/6

RECEIVED 09 JUL 2019

Date/Time, File Pass to?

☐

: Prel. Report

4)

☐

: Final Report

Date/Time, File Return to?

2)

Report Format :

DAR

Lump Sum / I.B.I. (\$) :

Days Of Repair:

Resurvey No. of Trip:

1

Survey Fee:

Transportation

) \$ + R. 5

) Photos

) Copies

)

1013

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

180

11

1011

Veh No SJW 3445 R

Yr Regn. Mar 10

Type M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 3

C.C. 1598

Colour White

A/C Insured / Std / NI / NA

Sp.Reading 228285

T/Radio: Insured / Std / NI / NA

Eng/No:

CiNo: JM 6BL 102 / A. 0138496

Gen. Cond: Good (Fair) Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil (S/Rim) / STD A/Rim or

Tyre Size: F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

D.O.A.

15/4/19

Survey held at

One flexi

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Front LH

The U/C / Chassis frame / Body Structure affected due to collision.

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Apr 2019 Edit Reg		10 Apr 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Chundamannil Chandy Abraham, ID: S2201477C		
Main Claimant:	FLEXI DRIVE ENTERPRISE, Co. Reg. No.: 52929875M		
Vehicle Reg. No.:	SJW3445R	Date of Loss:	08/04/2019 09:00 - :59
Claim Type:	TP / 1475440904SG	Policy/Cover Note No.:	2100463071 (Comprehensive)
Vehicle Reg. No. (Insured):	SLC599G	Policy No. (Claimant):	
		Excess:	
Repairer:	One Flexi Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #06-33 Premier @ Kaki Bukit, 415875 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 22/04/2019]		
Claimant's Solicitor:	VISION LAW LLC - Tel: 65342811		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (11/04/2019): No OI GIA Report
- AIG_SG (11/04/2019): Request to upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

PRE-REPAIR INSPECTION REQUEST – SJW3445R vs SLC599G (OI) on D.O.A.: 08/04/2019

From: Hor, Yinrul
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur
Sent: 10/4/2019 8:38:32 AM

Hi,

Please refer to the enclosed request from **Vision Law LLC**.
Kindly carry out Policy coverage verification **first** before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.
*Kindly assist to assign **MOHAMAD TAUFIKH** as Single Joint Expert as requested.*

Thanks & Regards,

Yin Rul, Hor (Viviane)
AIG
Claim Adjuster II, Singapore FNDL Claims Operations – Auto
Yinrul.Hor@aig.com | www.aig.sg

From: Sally Chong [mailto:sallychong@visionlawllc.com]
Sent: Tuesday, April 09, 2019 4:25 PM
To: Hor, Yinrul; Azlan, Syazairdina; Chin, Lee-Ying; AIG SGP, Claims-Survey; Lim, Sheng Yang
Cc: regina@wellscope.com.sg; 'Ong Adrian'; Leong, Kah Yin Hidden on 03-09-2017, 03:47:55; 'Hassim, Mohd Fitri'; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; 'Judy Soh'
Subject: [EXTERNAL] OUR REF.: O30-MISC.19 (SJW 3445R @ 08.04.2019) // AIG REF.: SLC 599G
Importance: High

Caution: External Email

URGENT

Dear Rajeswary,

NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES
CLAIMANT: TAN GEOK CHOO T/A FLEXI DRIVE ENTERPRISE
ACCIDENT INVOLVING SJW 3445R & SLC 599G ON 8 APRIL 2019 ALONG 188 PANDAN LOOP AT ABOUT 09:30 HRS

Thank you for your email of even date below with your list of surveyors.

Our client confirms the appointment of MOHAMAD TAUFIKH - LKK AUTO CONSULTANTS PTE LTD as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at :

Venue : ONE FLEXI PTE LTD
No. 8, Kaki Bukit Ave 4, #06-33,
Premier @ Kaki Bukit,
Singapore 415875
Contact : Mr. Adrian Ong (H/P: 8686-2266 / Tel.: 6292-5455)

If you fail to conduct the pre-repair survey within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Thank you.

Sally Chong

(Secretary)
VISION LAW LLC
133 NEW BRIDGE ROAD,
#18-01/02, CHINATOWN POINT,
SINGAPORE 059413
TEL.: 6534-2811 (ext 115)
FAX : 6535-6802

From: Hor, Yinrul
Sent: Tue, 9 Apr 2019 07:20:40 +0000
To: Sally Chong
Cc: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLC599G AND SJW3445R ON 08/04/2019

Without Prejudice

Your Reference : O30-MISC.19 (SJW 3445R @ 08.04.2019)

Our Reference : SLC599G

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services

Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Yin Rul, Hor (Viviane)

AIG

Claim Adjuster II, Singapore FNOCL Claims Operations – Auto

Yinrul.Hor@aig.com | www.aig.sg

From: Sally Chong [mailto:sallychong@visionlawllc.com]

Sent: Tuesday, April 09, 2019 2:57 PM

To: Hor, Yinrul; Azlan, Syazairdina; Chin, Lee-Ying; AIG SGP, Claims-Survey; Lim, Sheng Yang

Cc: regina@wellscope.com.sg; 'Ong Adrian'; 'Judy Soh'

Subject: [EXTERNAL] OUR REF.: O30-MISC.19 (SJW 3445R @ 08.04.2019) // AIG REF.: SLC 599G

Caution: External Email

VERY URGENT

Dear Sir,

From: Sally Chong [mailto:sallychong@visionlawllc.com]

Sent: Tuesday, 9 April, 2019 2:57 PM

To: 'Yinrul.Hor@aig.com'; 'Azlan, Syazairdina'; 'Lee-Ying.Chin@aig.com'; 'AIGSGP_ClaimsSurvey@aig.com'; 'Lim, Sheng Yang'

Cc: 'regina@wellscope.com.sg'; 'Ong Adrian'; 'Judy Soh'

Subject: OUR REF.: O30-MISC.19 (SJW 3445R @ 08.04.2019) // AIG REF.: SLC 599G

VERY URGENT

Dear Sir,

NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

CLAIMANT: TAN GEOK CHOO T/A FLEXI DRIVE ENTERPRISE

ACCIDENT INVOLVING SJW 3445R & SLC 599G ON 8 APRIL 2019 ALONG 188 PANDAN LOOP AT ABOUT 09:30 HRS

We are instructed by TAN GEOK CHOO T/A FLEXI DRIVE ENTERPRISE to notify you of a road traffic accident ON 8 APRIL 2019 ALONG 188 PANDAN LOOP AT ABOUT 09:30 HRS

involving our client's vehicle registration number **SJW 3445R** and vehicle registration number **SLC 599G** driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Thank you.

Sally Chong

(Secretary)

VISION LAW LLC

133 NEW BRIDGE ROAD,

#18-01/02, CHINATOWN POINT,

SINGAPORE 059413

TEL.: 6534-2811 (ext 115)

FAX: 6535-6802

C.c.: VEHICLE OWNER OF SLC 599G

CHUNDAMANNILK CHANDY ABRHAM

125, Sunset Way,

#03-01,

Singapore 597155

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this

email

by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

--
Adrian Ong

Mobile: +65 9749 1001

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	9875M
Vehicle Details	
Vehicle No.:	SJW3445R
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Jun 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 1.6L SDN
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	Z6845818
Chassis No.:	JM6BL10Z1A0138496
Maximum Power Output:	77.0 kW (103 bhp)
Open Market Value:	\$20,031.00
Original Registration Date:	18 Mar 2010
First Registration Date:	18 Mar 2010
Transfer Count:	0
Actual ARF Paid:	\$20,031.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Mar 2020
PARF Rebate Amount:	\$10,015.00
Intended COE Rebate Details	
COE Expiry Date:	17 Mar 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$20,802.00
COE Rebate Amount:	\$1,541.00
Total Rebate Amount:	\$11,556.00

The information contained herein is correct as at 19 Jun 2019

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Apr 2019 Edit Reg		10 Apr 2019 00:00 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	Chundamannil Chandy Abraham , ID: S2201477C			
Main Claimant:	FLEXI DRIVE ENTERPRISE , Co. Reg. No.: 52929875M			
Vehicle Reg. No.:	SJW3445R	Date of Loss:	08/04/2019 09:00 - :59 [108 Months and 21 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 1475440904SG	Policy/Cover Note No.:	2100463071 (Comprehensive)	
Vehicle Reg. No. (Insured):	SLC599G	Policy No. (Claimant):		
		Excess:		
Repairer:	One Flexi Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #06-33 Premier @ Kaki Bukit, 415875 Kaki Bukit - Tel:			
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 22/04/2019]			
Claimant's Solicitor:	VISION LAW LLC - Tel: 65342811			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (11/04/2019): No OI GIA Report
- AIG_SG (11/04/2019): Request to upload TP GIA Report

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJW3445R (1475440904SG)
[SLC599G]
TP
FLEXI DRIVE ENTERPRISE
Apr 8 2019 9:30AM
[Chundamannil Chandy Abraham]
One Flexi Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Photos/Images											3 per page			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print	
1	15/04/19 17:31	General View										Load JPG		
2	15/04/19 17:31	General View										Load JPG		
3	15/04/19 17:31	General View										Load JPG		
4	15/04/19 17:31	General View										Load JPG		
5	15/04/19 17:31	General View										Load JPG		
6	15/04/19 17:31	Odometer Reading										Load JPG		
7	15/04/19 17:31	Chassis Number										Load JPG		
8	15/04/19 17:31	General View										Load JPG		
9	15/04/19 17:31	General View										Load JPG		
10	15/04/19 17:31	General View										Load JPG		
11	15/04/19 17:31	General View										Load JPG		
12	15/04/19 17:31	General View										Load JPG		
13	15/04/19 17:31	General View										Load JPG		
14	15/04/19 17:31	General View										Load JPG		
15	15/04/19 17:31	General View										Load JPG		
16	15/04/19 17:31	General View										Load JPG		
17	15/04/19 17:31	General View										Load JPG		
18	15/04/19 17:31	General View										Load JPG		
19	15/04/19 17:31	General View										Load JPG		
20	15/04/19 17:31	General View										Load JPG		
21	15/04/19 17:31	General View										Load JPG		
22	15/04/19 17:31	General View										Load JPG		
23	15/04/19 17:31	General View										Load JPG		
24	15/04/19 17:31	General View										Load JPG		
25	15/04/19 17:31	General View										Load JPG		
26	15/04/19 17:32	Photographs of Damaged Parts										Load JPG		
27	15/04/19 17:32	Photographs of Damaged Parts										Load JPG		
28	15/04/19 17:32	Photographs of Damaged Parts										Load JPG		
29	15/04/19 17:32	Photographs of Damaged Parts										Load JPG		
30	15/04/19 17:32	Photographs of Damaged Parts										Load JPG		
31	15/04/19 17:32	Photographs of Damaged Parts										Load JPG		
32	15/04/19 17:32	Photographs of Damaged Parts										Load JPG		
33	15/04/19 17:32	Photographs of Damaged Parts										Load JPG		
34	15/04/19 17:32	Photographs of Damaged Parts										Load JPG		
35	15/04/19 17:32	Photographs of Damaged Parts										Load JPG		
36	15/04/19 17:32	Photographs of Damaged Parts										Load JPG		
37	15/04/19 17:32	Photographs of Damaged Parts										Load JPG		

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	15/04/19 17:32	Photographs of Damaged Parts	 Load JPG	☒
39	15/04/19 17:32	Photographs of Damaged Parts	 Load JPG	☒
40	15/04/19 17:32	Photographs of Damaged Parts	 Load JPG	☒
41	15/04/19 17:32	Photographs of Damaged Parts	 Load JPG	☒
42	15/04/19 17:32	Photographs of Damaged Parts	 Load JPG	☒
43	15/04/19 17:32	Photographs of Damaged Parts	 Load JPG	☒
44	15/04/19 17:32	Photographs of Damaged Parts	 Load JPG	☒
45	15/04/19 17:32	Photographs of Damaged Parts	 Load JPG	☒
46	15/04/19 17:32	Photographs of Damaged Parts	 Load JPG	☒
47	15/04/19 17:32	Photographs of Damaged Parts	 Load JPG	☒
48	15/04/19 17:32	Photographs of Damaged Parts	 Load JPG	☒
49	15/04/19 17:32	Photographs of Damaged Parts	 Load JPG	☒
50	15/04/19 17:32	Photographs of Damaged Parts	 Load JPG	☒
51	15/04/19 17:32	Photographs of Damaged Parts	 Load JPG	☒
52	15/04/19 17:32	Photographs of Damaged Parts	 Load JPG	☒
53	15/04/19 17:32	Photographs of Damaged Parts	 Load JPG	☒
54	15/04/19 17:32	Photographs of Damaged Parts	 Load JPG	☒
55	15/04/19 17:32	Photographs of Damaged Parts	 Load JPG	☒
56	15/04/19 17:32	Photographs of Damaged Parts	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19006354/ECD3E2

Date: 15/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 2100463071

Claimant Vehicle No : SJW3445R

Insured Vehicle No : SLC599G

Date of Loss: 08/04/2019

Nature of Claim: TP

Claim No: 1475440904SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJW3445R

Make & Model: MAZDA 3, 1.6 L (A)

Reg. Date: 18/03/2010 (Man. Year: 2009)

Colour: White

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: Z6845818

Chassis No: JM6BL10Z1A0138496

Odometer: 228285 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Yokohama 7 mm

Rear Left Side: Yokohama 7 mm

Front Right Side: Yokohama 7 mm

Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 10/04/2019

Date Inspected: 15/04/2019 Inspected At:

One Flexi Pte Ltd (HQ)

8 Kaki Bukit Ave 4, #06-33 Premier @ Kaki

Bukit

Singapore 415875

Estimated Period of Repair: 2.0 days

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Repair	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT BUMPER SIDE RETAINER	Broken	0.00 F	*- F
4	1		*FRT BRACE PANEL	Cut	0.00 F	*- F
F=Franchise part.				Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >