

Joy.

08/15/14

Surveyor

02

REF: ASM(AXA)

G 0228m

ASSIGNMENT

From:

Date:

11/04/2016

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLF 9701C

at Workshop m/s

volkswagen

of

1 kampung Ampet Macpherson

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

3pm (waiting)
Steven

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLF 9701C

Yr Regn:

16 sep 2016

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volkswagen Passat c.c 1798

Colour

silver

A/C: Insured / Std / NI / NA

Sp. Reading

26304

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WV W877 3C8 HE 031607

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / A/Rim or

Tyre Size:

F:

215/55R17

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

11-04-19

Survey held at

w/s

3pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

30/5 Final ind of \$5327.84 with shirshi

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) \$ + RS. \$

) Photos

) Others

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

VOLKSWAGEN CENTRE SINGAPORE

Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation Non binding - Preview

Page 1/1
Document no.
Document date 08-04-2019
Customer no. 5211000859
Customer GST-ID 196900406D
Dealer 39999
Job order number 2019000138/ 1
Job order date 08-04-2019
Service Advisor TIOW CHUAN CHEE

Company
AXA Insurance Pte Ltd
8 SHENTON WAY
Singapore 068811

Customer data:
Mr
CHEONG
CHEE KHEONG CHARLES
1 TAI HWAN WALK
555221 Singapore

License plate	Model code	First registration	VIN	Model	Mileage
SLF9701C	3G24JZ	16-09-2016	WWWZZ3CZHE031607	Passat Comfortline 1.8 TSI 132kW DSG	26,231

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	TRANSFER DOOR MECHANISM	1	pcs.	840.00	#1	840.00	898.80
	B&P MACP LABOUR	3	pcs.	840.00	#1	2,520.00	2,696.40
	B&P DIAG	1	pcs.	480.00	#1	480.00	513.60
	For Diagnostic and Programming						
	B&P MACP SPRAY PAINT	3	pcs.	800.00	#1	2,400.00	2,568.00
3G0831056AF	Door	1	pcs.	2,262.62	#1	2,262.62	2,421.00
D 378500A2	DOOR RH	1	pcs.	38.79	#1	38.79	41.51
3G0837702C 5AP	Sound Absorber Laminated	1	pcs.	155.87	#1	155.87	166.78
3G0837651C	Door Seal Outer Black	1	pcs.	157.83	#1	157.83	168.88
3G0853268 GRU	DOOR SEAL RH	1	pcs.	60.94	#1	60.94	65.21
3G085332A 3Q7	Door Seal	1	pcs.	107.51	#1	107.51	115.04
3C0853585	DOOR SEAL LOWER	1	pcs.	1.07	#1	4.28	4.58
	Cover For Door Primed	1	pcs.				
	DOOR MOLDING RH	1	pcs.				
	Decorative Moulding Chrom	1	pcs.				
	DOOR MOLDING CHROME RH	1	pcs.				
	Clip	4	pcs.				

Quotation valid till 15-04-2019

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1		9,027.84	7%	631.95	9,027.84	9,659.79
Total		9,027.84		631.95	9,027.84	9,659.79

4 Days.

Before / After repair photos.

Guo Qiang - 82880282

Customer

Service Advisor

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and Volkswagen Centre Singapore for additional services, products and promotions.—

11/4/19.

UKK Auto Consultants hereby certify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

VOLKSWAGEN CENTRE SINGAPORE

9 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052

Tax invoice
Preview

Page 1/2

Company
AXA Insurance Pte Ltd
8 SHENTON WAY
#27-01 AXA TOWER
Singapore 068811

Customer Details:
Mr
CHEONG
CHEE KHEONG CHARLES
1 TAI HWAN WALK
Singapore 555221

Document no.
Document date 29-04-2019
Customer no. 5211000859
Customer GST-ID 196900406D
Dealer 39999
Job order number 2019000240/ 1
Job order date 17-04-2019
Service Advisor TIOW CHUAN CHEE

License plate	Model code	First registration	VIN	Model	Mileage
SLF9701C	3G24JZ	16-09-2016	WWWZZZ3CZHE031607	Passat Comfortline 1.8 TSI 132kW DSG	26,231

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	B&P MACP LABOUR	1	pcs.	840.00	#1	840.00	898.80
	B&P DIAG	1	pcs.	480.00	#1	480.00	513.60
	B&P MACP SPRAY PAINT	1	pcs.	800.00	#1	800.00	856.00
	TRANSFER DOOR MECHANISM	1	pcs.	420.00	#1	420.00	449.40
3G0853268 GRU	Cover For Door Primed	1	pcs.	60.94	#1	60.94	65.21
	DOOR MOLDING RH//AH08L01						
3G0853332A 3Q7	Decorative Moulding Chrom	1	pcs.	107.51	#1	107.51	115.04
	DOOR MOLDING CHROME RH//AH09J01						
3C0853585	Clip	4	pcs.	1.07	#1	4.28	4.58
	AD04H03						
3G0831056AF	Door	1	pcs.	2,262.62	#1	2,262.62	2,421.00
3G0837702C 5AP	Door Seal Outer Black	1	pcs.	155.87	#1	155.87	166.78
3G0837651C	Door Seal	1	pcs.	157.83	#1	157.83	168.88
D 378500A2	Sound Absorber Laminated	1	pcs.	38.79	#1	38.79	41.51

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1		5,327.84	7%	372.95	5,327.84	5,700.79
Total		5,327.84		372.95	5,327.84	5,700.79

Customer

Service Advisor

Please inspect your vehicle prior to leaving our premises; we seek your understanding that we are not able to honour claims on scratches, dents etc. after your car has left our premises.

-----VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).-----

All fund transfer payments should be made payable to Volkswagen Group Singapore Pte Ltd; Bank Name: Deutsche Bank AG (Singapore Branch), Bank Account: 2528214002, Swift Code: DEUTSGSG. Please indicate Customer Number (eg. 521XXXXXX), Customer Name and Invoice Number in the payments.