

ASS. REC. BY:

REF: CS/ICS 190063761 Dvd 3 ²⁴

ial Instruction:

Surveyor: Bryan

ASSIGNMENT (Office)

Merimen

From (Person): Desmond Lee

of ECICS

Date/Time: 9.4.19 17.42 p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLD 5378P

Insured:

at Workshop m/s BH Auto Service

Tel: 6559 8944

of BIK 1 Sn ming Industrial Estate Sector C, # 01/111/113/115/117

Policy No: MPC18800031501

Claim No: DMPCL9000964

Sum Insured:

Excess: \$ 150.00

Make of Veh:

D.O.A. 6.4.2019

(Client's Record)

CA / REV REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10.4.19

Person Contacted:

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

Investigation fire

SLD 5378P - x

10/4/19

Revert vehicle TLH, pending investigation via merimen

18/4/19

Submit Ext TLH - MV: \$ 65K (EST) LTA: \$47,398 NV: \$17,602

000000

REF:

ASSIGNMENT

CDE June 2026

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 1 days Res.: Yes or No

Lum Sum: 1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLD 53787 Yr Regn: 2016 June
Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel c.c. 1496

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: - T/Radio: Insured / Std / NI / NA

Eng/No: L15B4034763

C/No: Ru11114753

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60 R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Dunlop

Front

Rear

R/Bal. - mm R/Bal. S mm

L/Bal. - mm L/Bal. S mm

D.O.A. 06/04/2019 D.O.I. 10/04/2019

Survey held at BH Ando Sin Ming

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The vehicle caught fire. Cause of

The U/C / Chassis frame / Body Structure affected due to collision.

fire due to electrical nature.

Date / Time

Action / Instruction

ECICS OD

T/A Loss

MV 65K

LTA 47.3K

NL 17.7K

RECEIVED 22 APR 2019

Date/Time, File Pass to?

☐

: Prefi. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

18/4 - typist

Report Format :

Lump Sum / L.B.I: (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

TOTAL

380

10

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Apr 2019 17:10 Sendback Est	09 Apr 2019 17:14 S\$280.00	09 Apr 2019 17:42 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	JUMAT BIN KASSIM, ID: S1370835E, Email: JUMATKASSIM@GMAIL.COM		
Vehicle Reg. No.:	SLD5378P	Date of Loss:	06/04/2019 12:00 - :59 [33 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / DMPC1900096H	Policy/Cover Note No.:	MPC18B00031501 (Comprehensive)
		Excess:	S\$750.00
Repairer:	BH Auto Services Pte Ltd (Sin Ming) Blk 1 Sin Ming Industrial Estate Sector C, #01/111/113/115/117, 575636 Sin Ming - Tel: 6559 8944		
Handling Insurer:	ECICS Limited (HQ) - Tel: 63374779 /6303 0178 ... [Handled by Desmond Lee - 6303 0167]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 18/04/2019]		
Adj Asg. Remarks:	Mr Bryan Ang of LKK to conduct a detailed survey whether this vehicle was reasonably maintain. When was the last maintenance carried out and where. What was the cause of the fire.		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:	ECICS Limited 10 Eunos Road 8 #09-04A Singapore Post Centre Singapore 408600	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Desmond Lee	Date:	10 Apr 2019

Preliminary Advice

Vehicle No	: SLD5378P	Accident Date	: 06/04/2019
Make	: HONDA VEZEL	Policy No.	: MPC18B00031501
Assignment Date	: 09/04/2019	Excess	: S\$750.00
Date of Inspection	: 10/04/2019	Est. Duration of Repair	: 0.00
Inspection At	: BH AUTO SERVICES PTE LTD (SIN MING) BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C, #01/111/113/115/117 SINGAPORE 575636		

Point of Impact / General Description of Damages

The vehicle caught fire. The cause of fire due to electrical nature.

Repairer's Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	65,000.00
COE / PARF Rebate	:S\$	47,398.00
Salvage Value	:S\$	
Margin for Repair	:S\$	17,602.00

Remarks

☐	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
☒	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
☒	Other comments : Pending investigation

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 08/04/2019 11:26
Date Of Accident 06/04/2019 12:30
Exact Location Of Accident BANGUNAN SULTAN ISKANDAR JOHOR BAHRU
Country/State of Loss MALAYSIA/JOHOR DARUL TAKZIM

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLD5378P 11/04/19 @ 1030am
Insured/Policyholder
Name Of Registered Owner JUMAT BIN KASSIM Spoke to OJ. Said was on way
NRIC No S1370835E back to SG. Went in M51a ckt
Email Address JUMATKASSIM@GMAIL.COM 7am to buy groceries and make
Mobile Phone No (LOCAL) +65-93882498
Alternative Phone No OFFICE-93882498 ~~Wife~~ stopped at various
Vehicle Particulars locations. Not continuous driving.
Manufacturer HONDA
Model VEZEL-1.5 X (A) left for SG abt 1200hrs. on the way
Exact Purpose for which vehicle was being used at time of accident PRIVATE USE Small buying small. At custom booth,
Are you claiming under your own insurance policy for repair to your vehicle? YES stopped to head over passport and saw
If No, Please state action to be taken Smaller coming out from dashboard openings
Vehicle Category PRIVATE CAR at front window side. Told officer
Insurance Company and was advised to drive forward
Name of Insurance Company ECICS LIMITED and go to office to seek assistance.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number MPC18B00031501 Flowers started to appear at glove
Cover Note Number compartment under the dashboard
Driver To Custom officers use hose to
Name of Driver JUMAT BIN KASSIM put out fire. Made HSA Police
NRIC No S1370835E report and vehicle towed back to
Date Of Birth 19/04/1959 Singapore.
Occupation INDOOR
Date Of Driving Pass 21/08/1991 Bought brand new from PI.
Driving Experience 27 YEARS AND 7 MONTHS best serving in Jan. 2019.
Gender MALE
Mobile Number (LOCAL) +65-93882498 Never received any letter from
Fax Number
Contact Number OFFICE-93882498
Email Address JUMATKASSIM@GMAIL.COM recall.

26/04/2019

SKETCH PLAN


Please Refer To Video Footage!

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 6/4/19 at about 1230hrs at Johor Baru CIQ after immigration checking, suddenly I saw smoke coming out from the dash board and glove compartment. I was asked by the immigration officer to move at the side lane and asked for help at the office. When I went out to see the car, the ^{more} smoke was already formed at the windscreen and fire has spread. With the help of immigration officers I tried to put off the fire but in vain until the firemen came and put out the fire.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature

Date & Time: 8/4/19 1055hrs.

Driver's Signature

(If driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature

Name: Moo Wen zheng

NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0835E
Vehicle Details	
Vehicle No.:	SLD5378P
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Apr 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X A
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	L15B4034763
Chassis No.:	RU11114753
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$21,209.00
Original Registration Date:	21 Jun 2016
First Registration Date:	21 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$11,693.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Jun 2026
PARF Rebate Amount:	\$8,769.00
Intended COE Rebate Details	
COE Expiry Date:	20 Jun 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,694.00
COE Rebate Amount:	\$38,629.00
Total Rebate Amount:	\$47,398.00

The information contained herein is correct as at 10 Apr 2019

OK



POLIS DIRAJA MALAYSIA

REPOT POLIS

Balai : BANGUNAN SULTAN ISKANDAR
Daerah : J/BAHRU SELATAN
Kontinjen : JOHOR
No Repot : BGN. SULTAN
ISKANDAR/001255/19
Tarikh : 06/04/2019
Waktu : 1412 PM
Bahasa : B. Malaysia
Diterima

Butir-butir Penerima Repot

Nama : MOHAMAD AZMAN BIN ABDUL AZIZ No Personel : R207839 Pangkat : KONST/P

Butir-butir Jurubahasa (Jika Ada)

Nama : --- No K/P (Baru) : --- No Polis/Tentera : ---
No Pasport : --- Bahasa Asal : ---
Alamat : ---

Butir-butir Pengadu

Nama : JUMAT BIN KASSIM

No K/P (Baru) : --- No Polis/Tentera : --- No Pasport : K0454906K

No Sijil Beranak : ---

Jantina : Lelaki Tarikh Lahir : 19/04/1959 Umur : 59 tahun 11 bulan

Keturunan : Melayu Warganegara : Singapore

Pekerjaan : SISTEM ADMINISTRATOR

Alamat Tempat Tinggal : APT BLK 14B LORONG 7 TOA PAYOH #24-245 SINGAPORE
312014

Alamat Ibu/Bapa : ---

Alamat Pejabat : ---

No Tel (Rumah) : - No Tel (Pejabat) : --- No Tel (HP) : 93882498

Emel : ---

Pengadu Menyatakan:-

PADA 06/04/2019 JAM L/KURANG 1230HRS SEMASA SAYA MEMANDU M/KAR JENIS HONDA VEZEL 1.5X NO PENDAFTARAN (SLD 5378 P) BERWARNA BIRU SEMASA BERADA DI LALUAN KERETA KELUAR MALAYSIA BANGUNAN SULTAN ISKANDAR JOHOR BAHRU. SEMASA MELEPASI PEMERIKSAAN IMIGRESEN TIBA-TIBA SAYA TERNAMPAK ASAP KELUAR DARI DASHBOARD DAN GLOVE COMPARTMET M/KAR. PEGAWAI IMIGRESEN TELAH NASIHATKAN SAYA SUPAYA BERHENTI DI TEPI DAN MEMBAWA SAYA KE PEJABATNYA UNTUK BANTUAN. APABILA SAYA KELUAR DARI PEJABAT IMIGRESEN DAPATI ASAP DARIPADA DALAM KERETA TELAH BANYAK DAN API TELAH MARAK DI BAHAGIAN DALAM KERETA SEBELAH KIRI. DENGAN BANTUAN PEGAWAI IMIGRESEN SAYA CUBA MEMADAM KEBAKARAN MENGGUNAKAN ALAT PEMADAM API TAPI TIDAK BERJAYA SEHINGGALAH PIHAK BOMBA SAMPAI DAN BERJAYA PADAM KEBAKARAN TERSEBUT. SAYA TELAH BUAT PEMERIKSAAN MENYELURUH DAPATI KESELURUHAN M/KAR TERBAKAR. PUNCA KEBAKARAN TIDAK DAPAT DIPASTIKAN. TUJUAN SAYA BUAT LAPORAN UNTUK RUJUKAN PIHAK INSURAN DAN PIHAK YANG BERKENAAN. SEKIAN LAPORAN SAYA.

Tandatangan Pengadu:

Tandatangan Jurubahasa (Jika ada):

Tandatangan Penerima Repot:

KETUA POLIS BALAI
BANGUNAN SULTAN ISKANDAR
JELUTAN BAHRU SELATAN
JOHOR BAHRU
JOHOR

(JM0846207-D)

H/P: 016-704 7552 / 012-220 8076

SINGAPORE $\rightleftharpoons$ MALAYSIA $\rightleftharpoons$ THAILAND

s to

No. 0071

Date : 6/4/19

请将车内贵重或重要的物品收起。
任何损失或遗失，本公司一概不负责。
We are not responsible for any loss or damage
valuable items left inside the car.

E. & O. E.

总额 **861**
 Total RM
 定银
 Deposit **RM**
 尚欠
 Balance **RM**

經手人 Issued by

S1370835E

19/04/1959

INDOOR

21/08/1991

27 YEARS AND 7 MONTHS

MALE

(LOCAL) +65-93882498

ax Number



明輝汽車服務私人有限公司

BH AUTO SERVICES PTE LTD

INSURER: ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC18B00031501	Date of Loss:	06/04/2019
Vehicle Reg. No.:	SLD5378P	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	JUMAT BIN KASSIM		

Make/Model:	HONDA VEZEL, 1.5 X (A)	Vehicle Reg. Date:	21/06/2016
Vehicle Colour:	BLUE		
Engine No:	L15B4034763	Chassis No:	RU11114753
Odometer:	0 KM		

Paint Type:	
Total Loss?	YES
Est. Duration of Repair (day)	31

Present Location: BH AUTO SERVICES PTE LTD (SIN MING)

COST OF CLAIMS

	Amount
Parts	0.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	280.00
Gross Total (S\$)	280.00
+ GST 7.00% (S\$)	19.60
Nett Amount (S\$)	299.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This claim is handled by: MOO WEN ZHENG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

10/04/2019 @ 1130am

Net Amount

Total loss OD Excess 750/-

[Signature]
LKK Auto

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

BH Auto Services Pte Ltd/SLD5378P/09/04/2019 17:14. Not valid without Reference section.

Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Apr 2019 17:10 Sendback Est	09 Apr 2019 17:14 S\$280.00	09 Apr 2019 17:42 Edit Adj Rpt	S\$280.00 Edit Estimates	S\$280.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	JUMAT BIN KASSIM , ID: S1370835E, Email: JUMATKASSIM@GMAIL.COM		
Vehicle Reg. No.:	SLD5378P	Date of Loss:	06/04/2019 12:00 - :59 [33 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / DMPC1900096H	Policy/Cover Note No.:	MPC18B00031501 (Comprehensive)
		Excess:	S\$750.00
Repairer:	BH Auto Services Pte Ltd (Sin Ming) Blk 1 Sin Ming Industrial Estate Sector C, #01/111/113/115/117, 575636 Sin Ming - Tel: 6559 8944		
Handling Insurer:	ECICS Limited (HQ) - Tel: 63374779 /6303 0178 ... [Handled by Desmond Lee - 6303 0167]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 18/04/2019]		
Adj Asg. Remarks:	Mr Bryan Ang of LKK to conduct a detailed survey whether this vehicle was reasonably maintain. When was the last maintenance carried out and where. What was the cause of the fire.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- ECICS (18/04/2019): **Alert - Adj Mandate Maintained - SLD5378P - Claim Handler: Desmond Lee**

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLD5378P (DMPC1900096H)

OD

Apr 6 2019 12:00PM

[JUMAT BIN KASSIM]

BH Auto Services Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser ▼

Assessment Reports

No	Finalized On	BH Auto Services Pte Ltd (Sin Ming)	Thumbnail	Print
1	09/04/19 17:14	Repairer Estimates	 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/04/19 17:17	Adjuster Immediate Advice	 Load HTM	

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/04/19 16:27	Front View Right	 Load JPG	☒
2	18/04/19 16:27	Front View Left	 Load JPG	☒
3	18/04/19 16:27	General View	 Load JPG	☒
4	18/04/19 16:27	General View	 Load JPG	☒
5	18/04/19 16:27	General View	 Load JPG	☒
6	18/04/19 16:27	General View	 Load JPG	☒
7	18/04/19 16:27	General View	 Load JPG	☒
8	18/04/19 16:27	General View	 Load JPG	☒
9	18/04/19 16:27	General View	 Load JPG	☒
10	18/04/19 16:27	General View	 Load JPG	☒
11	18/04/19 16:27	Rear View Right	 Load JPG	☒
12	18/04/19 16:27	Rear View Left	 Load JPG	☒

Documentation

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/04/19 17:06	INVESTIGATION REPORT	 Load PDF	
2	23/04/19 13:47	LTA REBATE	 Load PDF	
3	23/04/19 13:57	TOWING FEE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS19006376/DVD3S2

Date: 23/04/2019

REFERENCE

Insured/Claimant: JUMAT BIN KASSIM Policy No: MPC18B00031501
Date of Loss: 06/04/2019 Nature of Claim: OD Claim No: DMPC1900096H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLD5378P**
Make & Model: HONDA VEZEL, 1.5 X (A) Engine No: L15B4034763
Reg. Date: 21/06/2016 (Man. Year: 2016) Chassis No: RU11114753
Colour: Blue Odometer: 0 km
Engine Capacity: 1496 cc
Market Value/New Car Price: S\$65,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16
Front Left Side: Dunlop 0 mm Rear Left Side: Dunlop 5 mm
Front Right Side: Dunlop 0 mm Rear Right Side: Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	280.00	280.00	0.00	0.00
Calculated Gross Total (S\$)	280.00	280.00	0.00	0.00
- Excess (S\$)	0.00	750.00	-750.00	
(S\$)	280.00	-470.00	750.00	267.86
+ GST 7.00/7.00% (S\$)	19.60	-32.90	52.50	267.86
Nett Amount (S\$)	299.60	-502.90	802.50	267.86

INSPECTION

Date of Assignment: 09/04/2019 Present Location: BH Auto Services Pte Ltd (Sin Ming)
BH Auto Services Pte Ltd (Sin Ming)
Date Inspected: 10/04/2019 Inspected At: Blk 1 Sin Ming Industrial Estate Sector C,
#01/111/113/115/117
Singapore 575636
Estimated Period of Repair: 0.0 days

Adjuster: BRYAN TANI

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$65,000.00
OMV :	\$21,209.00
PARF Rebate (1) :	\$8,769.00
Quota Premium Paid :	\$53,694.00
COE Rebate (2) :	\$38,629.00
Total Rebate (1) + (2) = :	\$47,398.00

The total amount incurred will be Market Value \$65,000.00 minus Total Rebate \$47,398.00 = \$17,602.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Apr 2019)
Parts:	M1-SUV	HONDA VEZEL 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLD5378P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >