

Page 1 of 1

ASSIGNMENT

Surveyor

From (Person)

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No.

at Workshop n/a

of

Policy No.

Sum Insured

Make of Veh.

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time

REF CS3/III 19006386/TICd302

ASSIGNMENT (Office)

of III

Date/Time 10/4/19 @ 2:11pm

Bill to

Insured

Tel:

Claim No.

Excess

D.O.A.

H.O.D. Endorsement

Person Contacted

Vehicle IN / OUT

Date/Time

Action/Instruction (X) Estimate

SFH 6018Y-X

SH 8082Y-X

Dismantle: 11/4/2019 0439pm

Tan Kah
Gabriel Wee

SFH 6018Y
V-teeh Auto
1 Soon Lee street #06-04/07

SH 8082Y
6264 6211

MS-Chong

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Wednesday, 10 April 2019 2:11 PM
To: Sim Teo Koon; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: 'V-TECH AUTO SERVICE'; Sherini Pillai
Subject: RE: ACCIDENT INVOLVING SFH6018Y & SH8082T ON 8-4-2019
Attachments: 10042019131838.pdf

Dear Sir / Mdm

This Pre-Repair Survey is on Without Prejudice Basis.

THIRD PARTY VEHICLE NO. : SFH6018Y
III INSURED VEHICLE NO. : SH8082T
DATE OF LOSS : 08.04.19

We acknowledge receipt of your email.

In compliance to Pre-Action Protocol for NIMA cases, we note that

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANTS to conduct the pre-repair survey.

This claim is handled by **Sherini**.

Please let us have your client's accident report and repair estimate for our appointed surveyor to conclude his report.

****We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

****Surveyor kindly upload this assignment to Merimen.**

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Sim Teo Koon [mailto:tk_sim@juseq.com.sg]
Sent: 10 April, 2019 12:44 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: 'V-TECH AUTO SERVICE' <vtech.autoservice@gmail.com>
Subject: RE: ACCIDENT INVOLVING SFH6018Y & SH8082T ON 8-4-2019

Dear Sir,

We refer to your letter / email.

We are instructed that our client is not agreeable to all the surveyors proposed by you.

Pursuant to Appendix C, pre-action protocol for NIMA cases, we are also instructed to furnish you our client's list of motor surveyors for your selection:-

1. PAL'S APPRAISER PTE LTD
2. LCW APPRAISER PTE LTD
3. MC-COY APPRAISER PTE LTD
4. TREASURE APPRAISAL SERVICES
5. UNITED Appraisal And Management Pte Ltd
6. PROMINENT APPRAISER SERVICES
7. ST APPRAISAL SERVICES
8. AEON AUTO CONSULTANTS LLP
9. CL APPRAISER PTE LTD
10. CONSTANT APPRAISER SERVICES

Please be informed that if the above is not agreeable by you, our client's motor vehicle is available for pre-repair inspection at the under-stated workshop:-

V-Tech Auto Service

No. 1 Soon Lee Street #06-04 to 07

Singapore 627605

Tel : 6264-6211 Fax : 6264-6233

*** Further, please remind your appointed surveyor to request for post repair inspection if you wish to do so under NIMA Protocol Appendix C paragraph 2.11.**

Regards,

Sim Teo Koon (On behalf of Mr Michael Yap)

JusEquity Law Corporation.

Tel: 6506 6065, Fax: 6536 9339

E-mail: tk_sim@juseq.com.sg

From: Motor Claim - III [<mailto:motorclaim@iii.com.sg>]

Sent: 10 April 2019 12:28

To: Sim Teo Koon <tk_sim@juseq.com.sg>

Subject: RE: ACCIDENT INVOLVING SFH6018Y & SH8082T ON 8-4-2019

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext – 248

From: Sim Teo Koon [mailto:tk_sim@juseq.com.sg]
Sent: 10 April, 2019 12:25 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: ACCIDENT INVOLVING SFH6018Y & SH8082T ON 8-4-2019

Dear Sirs,

Please refer to our notice of accident.

Regards,

Sim Teo Koon (On behalf of Mr Michael Yap)
JusEquity Law Corporation
171 Chin Swee Road #02-06, CES Centre
Singapore 169877
Tel: 6506 6065 / 6536 9339
Fax: 6536 5368
E-mail: tk_sim@juseq.com.sg

This message (and all its attachments) is intended only for the use of the individual or entity to whom it is addressed and is privileged and confidential. If you are not the intended recipient, please notify us immediately by return electronic mail, delete this message and you should not disseminate, distribute or copy any information contained herein.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K



JusEquity Law Corporation

ADVOCATES & SOLICITORS • COMMISSIONER FOR OATHS

171 Chin Swee Road #02-06, CES Centre, Singapore 169877
Telephone: (65) 6536 9339, Fax: (65) 6536 5368 (Litigation)
Email: claims@juseq.com.sg website: www.juseq.com.sg

Our Ref: JEQ/190279/0419/ VT

Your Ref: **SH8082T**

10 April 2019

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
GAS BUILDING
SINGAPORE 575717

By Post Only

India International Insurance Pte Ltd
Singapore

By Email:
motorclaim@iii.com.sg

Dear Sir

ACCIDENT INVOLVING SFH6018Y & SH8082T ON 8-4-2019

We act for the owner of vehicle no. SFH6018Y.

We hereby notify you of a road traffic accident on **8 April 2019** at about **1830 hrs**, at Marina Boulevard involving our client's vehicle and vehicle registration no. **SH8082T** driven by you / your insured at the material time. A copy of our client's accident report is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully

Encl.

CONFIDENTIALITY CAUTION

This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by telephone and return the original message to us at the above address at our expense. Thank you.

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	3907A
Vehicle Details	
Vehicle No.:	SFH6018Y
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Apr 2019
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3G A
Primary Colour:	Pink
Manufacturing Year:	2008
Engine No.:	L13A4144912
Chassis No.:	GE61131301
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$14,770.00
Original Registration Date:	20 Jan 2009
First Registration Date:	20 Jan 2009
Transfer Count:	3
Actual ARF Paid:	\$14,770.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	19 Jan 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$13,024.00
COE Rebate Amount:	\$12,344.00
Total Rebate Amount:	\$12,344.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 23 Apr 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	09/04/2019 17:12
Date Of Accident	08/04/2019 18:30
Exact Location Of Accident	MARINA BOULEVARD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SFH6018Y
Insured/Policyholder	
Name Of Registered Owner	TOY CAR
Co Reg No	52883907A
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-91823146
Vehicle Particulars	
Manufacturer	HONDA
Model	FIT
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5103395423
Cover Note Number	
Driver	
Name of Driver	MOHAMED SHAHRIM BIN ABDUL KARIM
NRIC No	S8313502F
Date Of Birth	24/04/1983
Occupation	INDOOR
Date Of Driving Pass	27/09/2006
Driving Experience	12 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91823146
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 168 WOODLANDS STREET 11 #02-111
Postcode	730168
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SH8082T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SHA2607L
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's
Date & Time



Driver's Signature
(If driver is not the policyholder)
Date & Time




Reporting Centre Personnel's Signature
Name
NRIC/FIN No.



Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I (SFH6018Y) WAS TRAVELLING ALONG MARINA BLVD APPROACHING STRAITS VIEW WHEN SHA 2607L SLOWED DOWN AND HALTED I FOLLOW SUIT AS I HALTED MY VEHICLE SH 8082T CRASHED ON TO MY REAR BUMPER, DUE TO THE IMPACT MY VEHICLE CRASHED INTO SHA 2607L REAR BUMPER. NOBODY IS INJURED.

DECLARATION

(I/We declare the following particulars are true in every respect.)

Police Officer's Signature
Date & Time

Driver's Signature
(If driver is not the police officer)
Date & Time

Reporting Officer's Signature
Name
NOC/IR No.

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Apr 2019 17:56 Edit Reg		10 Apr 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:

Co. Reg. No.: -

Main Claimant:

TOY CAR, Co. Reg. No.: 52883907A

Vehicle Reg. No.:

SFH6018Y

Claim Type:

TP

Vehicle Reg. No. (Insured):

SH8082T

Repairer:

V-Tech Auto Service (HQ) No.1 Soon Lee Street, #06-04 Pioneer Center, 627605 Pioneer - Tel: 62646211

Handling Insurer:

India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 22/04/2019]

Date of Loss:

08/04/2019 18:00 - :59
[122 Months and 19 Days From LTA Reg Date (Man Yr)]

Policy/Cover Note No.:

Policy No. (Claimant):

Excess:

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS



















































[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SFH6018Y
[SH8082T]
TP
TOY CAR
Apr 8 2019 6:00PM
[-]
V-Tech Auto Service

Upload Documents Upload Photos Compose New Letter			View View in Browser		
Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	23/04/19 13:33	General View		Load JPG	<input checked="" type="checkbox"/>
2	23/04/19 13:33	General View		Load JPG	<input checked="" type="checkbox"/>
3	23/04/19 13:33	General View		Load JPG	<input checked="" type="checkbox"/>
4	23/04/19 13:33	General View		Load JPG	<input checked="" type="checkbox"/>
5	23/04/19 13:33	General View		Load JPG	<input checked="" type="checkbox"/>
6	23/04/19 13:33	General View		Load JPG	<input checked="" type="checkbox"/>
7	23/04/19 13:33	General View		Load JPG	<input checked="" type="checkbox"/>
8	23/04/19 13:33	General View		Load JPG	<input checked="" type="checkbox"/>
9	23/04/19 13:33	General View		Load JPG	<input checked="" type="checkbox"/>
10	23/04/19 13:33	General View		Load JPG	<input checked="" type="checkbox"/>
11	23/04/19 13:33	General View		Load JPG	<input checked="" type="checkbox"/>
12	23/04/19 13:33	General View		Load JPG	<input checked="" type="checkbox"/>
13	23/04/19 13:33	General View		Load JPG	<input checked="" type="checkbox"/>
14	23/04/19 13:33	General View		Load JPG	<input checked="" type="checkbox"/>
15	23/04/19 13:33	General View		Load JPG	<input checked="" type="checkbox"/>
16	23/04/19 13:33	General View		Load JPG	<input checked="" type="checkbox"/>
17	23/04/19 13:33	General View		Load JPG	<input checked="" type="checkbox"/>
18	23/04/19 13:33	General View		Load JPG	<input checked="" type="checkbox"/>
19	23/04/19 13:33	General View		Load JPG	<input checked="" type="checkbox"/>
20	23/04/19 13:33	General View		Load JPG	<input checked="" type="checkbox"/>
21	23/04/19 13:33	General View		Load JPG	<input checked="" type="checkbox"/>
22	23/04/19 13:33	General View		Load JPG	<input checked="" type="checkbox"/>
23	23/04/19 13:33	General View		Load JPG	<input checked="" type="checkbox"/>
24	23/04/19 13:33	General View		Load JPG	<input checked="" type="checkbox"/>
25	23/04/19 13:33	General View		Load JPG	<input checked="" type="checkbox"/>
26	23/04/19 13:33	General View		Load JPG	<input checked="" type="checkbox"/>
27	23/04/19 13:33	General View		Load JPG	<input checked="" type="checkbox"/>
28	23/04/19 13:33	General View		Load JPG	<input checked="" type="checkbox"/>
29	23/04/19 13:33	General View		Load JPG	<input checked="" type="checkbox"/>
30	23/04/19 13:33	General View		Load JPG	<input checked="" type="checkbox"/>
31	23/04/19 13:33	General View		Load JPG	<input checked="" type="checkbox"/>
32	23/04/19 13:33	General View		Load JPG	<input checked="" type="checkbox"/>
33	23/04/19 13:33	General View		Load JPG	<input checked="" type="checkbox"/>
34	23/04/19 13:33	General View		Load JPG	<input checked="" type="checkbox"/>
35	23/04/19 13:33	General View		Load JPG	<input checked="" type="checkbox"/>
36	23/04/19 13:33	General View		Load JPG	<input checked="" type="checkbox"/>
37	23/04/19 13:33	General View		Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	23/04/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
39	23/04/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
40	23/04/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
41	23/04/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
42	23/04/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
43	23/04/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
44	23/04/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
45	23/04/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
46	23/04/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
47	23/04/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
48	23/04/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
49	23/04/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
50	23/04/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
51	23/04/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
52	23/04/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
53	23/04/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
54	23/04/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
55	23/04/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
56	23/04/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
57	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	23/04/19 13:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	11/04/19 08:43	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III19006386/T1CD3E2

Date: 24/04/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle
No : SFH6018Y

Insured Vehicle No : SH8082T

Date of Loss: 08/04/2019

Nature of Claim:

TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFH6018Y

Make & Model: HONDA FIT, 1.3 (A)

Reg. Date: 20/01/2009 (Man. Year: 2008)

Colour: Pink

Engine Capacity: 1339 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: L13A4144912

Chassis No: GE61131301

Odometer: 102697 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15

Rear Tyre Size:

195/55 R15

Front Left Side: Maxxis 6 mm

Rear Left Side:

Maxxis 6 mm

Front Right Side: Maxxis 6 mm

Rear Right Side:

Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 10/04/2019

Date Inspected: 10/04/2019 Inspected At:

V-Tech Auto Service (HQ)

No.1 Soon Lee Street, #06-04 Pioneer
Center

Singapore 627605

Estimated Period of Repair: 0.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 23 Apr 2019)

Parts: 144 HONDA FIT 1.3 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SFH6018Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >