

FORM 1000

ASSIGNMENT

REV 03/III 023122/ Jqd 3<sup>07</sup>

Initial Instruction

Surveyor  
Merimen  
From Person  
three fee  
Stanley Jeli

ASSIGNMENT (Office)

III

Date/Time 9/4/2019

Estimated Cost

Bill to

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To: Inspect Vehicle No:

817 2564D

Insured: SHD 48322

at Workshop no:

Hendon Automotive

Tel: 9459 2885

of

280 Woodlands Ind. Park E5 # 01-19

Policy No:

Mcgm0015

Claim No:

M 07 18120671

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A 20/12/18

CA / REV / REP. / REV 24 HRS

Wp

27/12/18

Date/Time: 5:38pm @ 26/12/18

Person Contacted

Lynn

H.O.D. Endorsement

Vehicle OUT

| Date/Time | Action/Instruction                            |
|-----------|-----------------------------------------------|
|           | (✓) Estimate                                  |
|           | 817 2564D - X                                 |
|           | SHD 48322 - X                                 |
| 10/4/19   | Dismantle: 28/12/2018 @ 2.35pm                |
|           | Submit LS \$ 3900, 6 days? (Red to 7100, 36%) |
|           | MV: \$ 12.5k (est); LTA: 8640; NV: \$ 3860    |

*[Signature]*

11/4/2019

RECEIVED 15 APR 2019

REF:

III

Anita Jia

P.R.S (Merimen)

## ASSIGNMENT

Form

Date 27/12/18

Estimated Cost

OD ☒ WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No

SLT 2564D

at Workshop no

Hendon Automotive

at 280 Woodlands Ind. park ES# 01-19

Insured

Policy No

Claims No

Sum Insured

Excess


(Client's Record)

Make of Vehicle

Lynn 9459 2885

(Policy Condition)

Remark The veh had commenced its repair at the time of inspection.



Bal. or Market Value

IDAC Accident Report

Consistent? Yes or No

GIA / PR Seen

Consistent? Yes or No

Est. Repairs:

days Res: Yes or No

Lump Sum

% 3 Val Yes or No

CA / REV / REP. / 24 HRS <sup>cup</sup>

Vehicle IN / OUT

Date:

Person Contacted

Vehicle

SLT 2564 D

Ex Regs 19 Feb 2009

Type: ☒ M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Suzuki Swift

CS 1586

Colour

Yellow

A/C: Insured / Std / NI / NA

Sp Reading

125359

T/Radio: Insured / Std / NI / NA

Eng/No:

Chassis

JSAEZC31S00203409

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Order / Jammed / Leaked / Burnt orBrake: ☒ Order / Jammed / Leaked / Burnt orMod: ☒ Nil / ☒ STD Air / Rim or

Tyre Size

F: 205/45 R17

R: -

BS / ☒ EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal

6

mm

R/Bal

6

mm

L/Bal

6

mm

L/Bal

6

mm

D.O.A 22/12/18

D.O.I 27/12/18 @ 2:27pm

Survey held at

Hendon Automotive

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MV - \$12,500

PV - \$8640

NV - \$3860

DeadTime: File Pass to:

☐

: Prel. Report

1)

☐

: Final Report

DeadTime: File Return to:

2)

Days Of Repair:

Resurvey No. of Trip:

1

Survey Fee

120

Transportation

1. 2. 3. 4. 5.

1. 2. 3.

1. 2. 3.

1. 2.

TOTAL

10

130

Report Format:

PRG

Lump Sum / I.B.I.:

Add Fee:

☐

Site Insp \$

☐

Interview \$

☐

Tech Insp \$

☐

Week end \$

## Nivitha (LKK Auto)

---

**From:** Stanley Lai <stanley.lai@iii.com.sg>  
**Sent:** Tuesday, 9 April 2019 2:34 PM  
**To:** Admin-D (LKKAuto); 'sur@lkkauto.com'  
**Cc:** Sherini Pillai; Mekavathanan Sarangapani; Hsiao Tong (chewht@lkkauto.com); Olivia Lau (olivialau@lkkauto.com)  
**Subject:** RE: MCT18120671

Dear Sir/Mdm,

Rights granted in Merimen for the above LOD. Kindly proceed with the paper survey.

TP Veh No. : **SLT2564D**

Warmest regards,

Stanley Lai

**Motor Claims Department**

**India International Insurance Pte Ltd**

64 Cecil Street #04-02 IOB Building

Singapore 049711

Tel: 6347 6100 Ext 206 Fax: 6224 4174

**S&P 'A-' rated Company**



**From:** Mekavathanan Sarangapani

**Sent:** Monday, 8 April, 2019 8:20 AM

**To:** Hsiao Tong (chewht@lkkauto.com) <chewht@lkkauto.com>; Olivia Lau (olivialau@lkkauto.com) <olivialau@lkkauto.com>

**Cc:** Stanley Lai <stanley.lai@iii.com.sg>; Sherini Pillai <sherini@iii.com.sg>

**Subject:** MCT18120671

LOD from TP lwyer Advance Law

Paper survey please TP asking fo S\$ 5K odd ?? 2008 vehicle

Meka

Met 18/20671

|                   |          |       |  |
|-------------------|----------|-------|--|
| RESERVES          |          |       |  |
| TPPD              | PRESERVE | 411   |  |
| TPPI              | PRESERVE |       |  |
| UNINSURED LOSS    | PRESERVE |       |  |
| SUBRO             | PRESERVE |       |  |
| LPPN              |          | P Sny |  |
| INVESTIGATION FEE |          |       |  |
| SURVEY FEES       |          |       |  |
| LEGAL FEES        |          |       |  |
| OTHERS            |          |       |  |
| FRAUD CHECK       |          |       |  |
| UPLOAD TO MERIMEN |          |       |  |
| GRANT RIGHTS      |          |       |  |

\*\*\*\*\*  
 \*\*\* TX REPORT \*\*\*  
 \*\*\*\*\*

TRANSMISSION OK

TX/RX NO 0357  
 RECIPIENT ADDRESS 62585521  
 DESTINATION ID  
 ST. TIME 27/03 14:40  
 TIME USE 00'22  
 PAGES SENT 1  
 RESULT OK

FAXED  
 27 MAR 2019  
 MOTCLM DEPT.

**ADVANCE**  
 ADVANCE LAW FIRM

Advocates & Solicitors  
 Commissioner for Oaths  
 Notary Public  
 UEN/GST Reg no.: 100390208H

430 Lorong 6 Toa Payoh  
 #11-01 Orangetree Building  
 Singapore 319402  
 Tel: (65) 6323 5488 (5 lines)  
 Fax: (65) 6258 5521  
 (65) 6325 7738

Business Hours: Mon to Fri  
 9.00am to 6.00pm

Directors:  
 DANNY TEO KIM SOON (MD)  
 DAVID HK FONES

Senior Associates:  
 SIM HUI SHIEN, ADELINE

Associates:  
 TAN SHU HUA VANESSA

Consultant:  
 WONG CHEE MUN



Your insured : SHD 4832ZZ

Our ref : DT/mlc/100709/PD(st)(Hendor)

19 March 2019

India International Insurance Singapore  
 64 Cecil Street  
 #04/05 & 06/02 IOB Building  
 Singapore 049711

Attn : Motor Claims Department

Dear Sir

**ACCIDENT INVOLVING SLT 2564D & SHD 4832ZZ ALONG CTE ON 22.12.18**

We act for **BAN KOK POH**, the owner of **SLT 2564D** at the material time of the said accident.

We are instructed that the accident was caused by your/your insured's driver's negligent driving and/or management of your vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

|                                 |   |                   |
|---------------------------------|---|-------------------|
| 1. Costs of repairs (LUMP SUM)  | : | \$5,900.00        |
| 2. Loss of use (PRI - \$60 x 2) | : | \$ 120.00         |
| 3. Loss of use (\$60 x 15)      | : | \$ 900.00         |
| 4. LTA search fee               | : | \$ 7.49           |
| 5. Survey fee                   | : | \$ 698.00         |
| 6. Costs                        | : | \$ 700.00         |
| 7. Incidentals                  | : | \$ 80.00          |
|                                 |   | <u>\$8,405.49</u> |

We enclose the following documents:-

1. LTA search fee;
2. Repair bill;
3. Survey report together with invoice;

BY HAND

MLC/18120671.  
 Aick  
 - 12/12/18

# ADVANCE

ADVANCE LAW LLC

Advocates & Solicitors  
Commissioner for Oaths  
Notary Public  
UEN/GST Reg no.: 201330208H

Email: admin@advlawllc.com

430 Lorong 6 Toa Payoh  
#11-01 Orangetree Building  
Singapore 319402  
Tel: (65) 6323 5488 (5 lines)  
Fax: (65) 6258 5521  
(65) 6225 7738

Business Hours: Mon to Fri  
9.00am to 6.00pm

Directors:  
DANNY TEO KIM SOON (MD)  
DAVID HK FONES

Senior Associates:  
SIM HUI SHIEN, ADELINE

Associates:  
TAN SHU HUA VANESSA

Consultant:  
WONG CHEE MUN



Your insured : **SHD 4832ZZ**

Our ref : DT/mlc/100709/PD(st)(Hendon)

19 March 2019

India International Insurance Singapore  
64 Cecil Street  
#04/05 & 06/02 IOB Building  
Singapore 049711

BY HAND

Attn : Motor Claims Department

Dear Sir

**ACCIDENT INVOLVING SLT 2564D & SHD 4832ZZ ALONG CTE ON 22.12.18**

We act for **BAN KOK POH**, the owner of **SLT 2564D** at the material time of the said accident.

We are instructed that the accident was caused by your/your insured's driver's negligent driving and/or management of your vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

|                                 |                          |
|---------------------------------|--------------------------|
| 1. Costs of repairs (LUMP SUM)  | \$5,900.00               |
| 2. Loss of use (PRI - \$60 x 2) | \$ 120.00                |
| 3. Loss of use (\$60 x 15)      | \$ 900.00                |
| 4. LTA search fee               | \$ 7.49                  |
| 5. Survey fee                   | \$ 698.00                |
| 6. Costs                        | \$ 700.00                |
| 7. Incidentals                  | \$ 80.00                 |
|                                 | <b><u>\$8,405.49</u></b> |

We enclose the following documents:-

1. LTA search fee;
2. Repair bill;
3. Survey report together with invoice;
4. Colour-scan photos of the damaged motorcar;
5. GIA and traffic report

MLC/18120671.  
Ade Sherini  
27/3/2019

Please note that you or your insured driver should send us an acknowledgement of receipt within 14 days of your receipt of your letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer.

Please also note that if you have a counterclaim against our client arising out of the accident, you are also required to send us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully,

  
ADVANCE LAW LLC

## Enquire Vehicle & Owner Information ( Vehicle No. SHD4832Z As At 22 Dec 2018 / 10:45:00 )

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: 100709

City / Suburb / Postcode:

Owner ID Type: Company

Owner ID: 199303821R

Owner Name: COMFORT TRANSPORTATION PTE LTD

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 383

Registered Street Name: SIN MING DRIVE

Registered Unit No.: -

Registered Building Name: GAS BUILDING

Registered Postal Code: 575717

City / Suburb / Postcode:

Vehicle No.: SHD4832Z

Make Description/Model: HYUNDAI / I40 1.7L CRDI AT ABS AIRBAG 4DR

Insurance Company Name: INDIA INT'L INS PTE LTD

# HENDON AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-19 Harvest @ Woodlands (S) 757322

Tel : 9459 2885

Fax: 6334 5178

Email: hendon.automotive@gmail.com

Date : 02/03/2019

OUR REF : TP/SLT 2564D/19

M/S :BAN KOK POH  
BLK 181 PASIR RIS STREET 11  
#06-16  
SINGAPORE 510818

Statement Of Claim On Veh No : SLT 2564D

MODEL : SUZUKI SWIFT

LUMP SUM OF REPAIR

INCLUDING SUPPLY OF PARTS & LABOUR

PANEL BEATING & SPRAY PAINTING

\$5,900.00





> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 0598B

### Vehicle Details

Vehicle No.: SLT2564D  
Vehicle to be Exported: No  
Intended Deregistration Date: 28 Dec 2018  
Vehicle Make: SUZUKI  
Vehicle Model: SWIFT 1.6 AT  
Primary Colour: Yellow  
Manufacturing Year: 2008  
Engine No.: M16A1434871  
Chassis No.: JSAEZC31S00203409  
Maximum Power Output: 92.0 kW (123 bhp)  
Open Market Value: \$17,252.00  
Original Registration Date: 19 Feb 2009  
First Registration Date: 19 Feb 2009  
Transfer Count: 1  
Actual ARF Paid: \$17,252.00 8626

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 18 Feb 2019  
PARF Rebate Amount: \$8,626.00

### Intended COE Rebate Details

COE Expiry Date: 18 Feb 2019  
COE Category: A - Car (1600cc & below)  
COE Period(Years): 10  
QP Paid: \$1,020.00  
COE Rebate Amount: \$14.00  
Total Rebate Amount: \$8,640.00

The information contained herein is correct as at 28 Dec 2018

$$\begin{aligned} & \$28800 \text{ (5 yrs COE)} - \$8626 = \$20174 \\ & 20174 \div 60 = 336 \\ & 336 + 8626 = 9298 \\ & 9298 - 8640 = \$658 \text{ (NU)} \end{aligned}$$

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                    |
|----------------------------|--------------------|
| Date Of Report             | 24/12/2018 16:25   |
| Date Of Accident           | 22/12/2018 10:45   |
| Exact Location Of Accident | CENTRAL EXPRESSWAY |
| Country/State of Loss      | SINGAPORE          |

### DETAILS OF OWN VEHICLE

|                             |                      |
|-----------------------------|----------------------|
| Vehicle Registration Number | SLT2564D             |
| <b>Insured/Policyholder</b> |                      |
| Name Of Registered Owner    | BAN KOK POH          |
| NRIC No                     | S7210598B            |
| Email Address               | NOEMAIL              |
| Mobile Phone No             | (LOCAL) +65-91904224 |
| Alternative Phone No        | OFFICE-NOPHONE       |

### Vehicle Particulars

|              |              |
|--------------|--------------|
| Manufacturer | SUZUKI       |
| Model        | SWIFT 1.6 AT |

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

|                           |                                      |
|---------------------------|--------------------------------------|
| Name of Insurance Company | AIG ASIA PACIFIC INSURANCE PTE. LTD. |
| Type Of Coverage          | COMPREHENSIVE                        |
| Fleet Policy              | NO                                   |
| Policy Number             | 170086648                            |
| Cover Note Number         |                                      |

### Driver

|                      |                         |
|----------------------|-------------------------|
| Name of Driver       | GERMAINE BAN FANGYU     |
| NRIC No              | S9608699G               |
| Date Of Birth        | 17/02/1996              |
| Occupation           | INDOOR                  |
| Date Of Driving Pass | 30/11/2017              |
| Driving Experience   | 1 YEAR AND 0 MONTHS     |
| Gender               | FEMALE                  |
| Mobile Number        | (LOCAL) +65-96548422    |
| Fax Number           |                         |
| Contact Number       |                         |
| Email Address        | GERMAINEBAN@HOTMAIL.COM |

|                                                     |                                           |
|-----------------------------------------------------|-------------------------------------------|
| Address                                             | APT BLK 181 PASIR RIS STREET 11<br>#06-16 |
| Postcode                                            | 510818                                    |
| Was driver an employee of the Insured's Company     | NO                                        |
| If No, Relationship of the Driver with the Insured  | CHILDREN                                  |
| Vehicle Registration Number of Driver's Own Vehicle | -                                         |
|                                                     | -                                         |
|                                                     | -                                         |
| Insurance Company of Driver's Own Vehicle           | -                                         |
|                                                     | -                                         |
|                                                     | -                                         |

#### General Information of the Accident

|                    |                          |
|--------------------|--------------------------|
| Type Of Accident   | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR                    |
| Road Surface       | DRY                      |

#### Other Information

|                                                                                             |     |
|---------------------------------------------------------------------------------------------|-----|
| Was any foreign vehicle involved in this accident?                                          | NO  |
| Number of vehicles (including own vehicle) involved in the accident                         | 2   |
| Was any body injured in the Accident?                                                       | YES |
| Was any injured conveyed to hospital by ambulance?                                          | NO  |
| Was any other material or property damaged?                                                 | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO  |
| Number of Passengers (Including Driver)                                                     | 1   |

#### Details of Police Action

|                                           |                                                                                          |
|-------------------------------------------|------------------------------------------------------------------------------------------|
| Was the accident reported to the police?  | YES                                                                                      |
| If Yes, Please state which Police Station |                                                                                          |
| Police Station Name                       | ROCHOR N.P.C. 11 KAMPONG KAPOR ROAD, SINGAPORE 208678                                    |
| Police Station Address                    | <b>ROAD:</b> 11 KAMPONG KAPOR ROAD , <b>POSTCODE:</b> 208678 , <b>COUNTRY:</b> SINGAPORE |
| Police Station Contact                    | <b>TEL NO:</b> - <b>FAX NO:</b>                                                          |
| Was notice of intended Prosecution given? | NO                                                                                       |
| If Yes, against whom?                     |                                                                                          |

#### Circumstances of Accident

PLEASE REFER TO THE SKETCH PLAN

#### Attachment(s)

|                                               |     |
|-----------------------------------------------|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera?   | NO  |
| Was there any audio recorded?                 | NO  |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                             |          |
|-----------------------------|----------|
| Vehicle Registration Number | SHD4832Z |
| Vehicle Make/Model/Colour   |          |
| Details Of Properties       |          |
| Vehicle Category            | TAXI     |
| Name of Driver              |          |
| NRIC/Passport Number        |          |
| Contact Number              |          |
| Address                     |          |
| Postcode                    |          |
| Insurance Company Name      |          |

Nature Of Damage

No. Of Passenger (Including Driver)

)

)

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)

Date & Time: 24/12/2018  
4.30PM.

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No :

SCENE OF THE ACCIDENT

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

|                                                                                                                                                                             |                                            |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------|
| LICENSE PLATE:                                                                                                                                                              | SLT 25640                                  |
| CONTACT NUMBER:                                                                                                                                                             | 96548422                                   |
| E-MAIL ADDRESS:                                                                                                                                                             | germainewan@hotmail.com                    |
| LOCATION:                                                                                                                                                                   | ( Please refer to police report )          |
| NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION. |                                            |
| Please state:                                                                                                                                                               |                                            |
| <input type="checkbox"/> Claim Own Policy                                                                                                                                   | <input type="checkbox"/> Claim Third Party |
| <input checked="" type="checkbox"/> Claim SWTP at other workshop                                                                                                            | <input type="checkbox"/> Reporting Only    |

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature \_\_\_\_\_  
(If driver is not the policyholder)  
Date & Time: 3/1/20

Date & Time: 04/12/2018  
4:30 PM

Reporting Centre Personnel's Signature  
Name: \_\_\_\_\_  
NRIC/FIN No.: \_\_\_\_\_



**SINGAPORE  
POLICE FORCE**



T/20181224/2080

Police Station Of Origin:  
Rochor N.P.C  
11 Kampong Kapur Road SINGAPORE  
208678  
Tel No: 1800-2949999

1 of 3

Report No. T/20181224/2080

**REPORT OF A TRAFFIC ACCIDENT**

|                                            |                  |                           |
|--------------------------------------------|------------------|---------------------------|
| Date/Time Report Made:<br>24/12/2018 15:33 | Vide Report No.: | Station Diary No.:<br>118 |
|--------------------------------------------|------------------|---------------------------|

**Informant's Particulars**

|                                           |            |                              |                                                                        |                            |
|-------------------------------------------|------------|------------------------------|------------------------------------------------------------------------|----------------------------|
| Name of Informant:<br>GERMAINE BAN FANGYU |            |                              | Address:<br>APT BLK 181 PASIR RIS STREET 11 #06-16 SINGAPORE<br>510181 |                            |
| ID Type / ID No.:<br>NRIC NO / S9608699G  |            |                              | Contact No.:<br>Home/Office: Mobile: 96548422                          |                            |
| Nationality:<br>SINGAPORE CITIZEN         |            |                              | Email:                                                                 |                            |
| Sex:<br>Female                            | Age:<br>22 | Date of Birth:<br>17/02/1996 | Type of Informant:<br>Driver                                           |                            |
| Race:<br>Chinese                          |            |                              | Language:                                                              | Institution / School Name: |
| Occupation:<br>SELF EMPLOYED              |            |                              | Driving Licence Information:<br>Class: 3 Date of Expiry:               |                            |

**General Information of the Accident**

|                                                                         |            |                                    |                                            |                                     |
|-------------------------------------------------------------------------|------------|------------------------------------|--------------------------------------------|-------------------------------------|
| Type of Accident:                                                       | Non-Injury | Drink Drive:<br>No                 | Date/Time of Accident:<br>22/12/2018 10:45 | Type of Location:<br>Straight Road  |
| Location:<br>Along Road 1 Traveling Toward Road 2<br>CENTRAL EXPRESSWAY |            |                                    |                                            |                                     |
| Weather:<br>Cloudy                                                      |            | Road Surface:<br>Dry               |                                            | Road Speed Limit:                   |
| Traffic Flow:<br>One Way                                                |            | Traffic Control:<br>Not Controlled |                                            | Traffic Volume:<br>Light            |
| Type of Collision:<br>Between Moving Vehicles - Head To Rear            |            |                                    |                                            | Anyone conveyed by ambulance:<br>No |

**Details of Vehicle Involved**

| Vehicle No. | Type | Make    | Model     | Color  | Condition         | No of Passenger |
|-------------|------|---------|-----------|--------|-------------------|-----------------|
| SHD4832Z    | Car  | HYUNDAI |           | Blue   | Slightly Damaged  | 0               |
| SLT2564D    | Car  | SUZUKI  | Swift 1.6 | Yellow | Seriously Damaged | 0               |

**Details of Person Involved**

|                                 |                                |  |
|---------------------------------|--------------------------------|--|
| Any Pedestrian Involved: No     |                                |  |
| No. of Pedestrians Injured: NIL | Use of Pedestrian Crossing: NA |  |



**SINGAPORE  
POLICE FORCE**



T/20181224/2080

Police Station Of Origin:  
Rochor N.P.C  
11 Kampong Kapur Road SINGAPORE  
208678  
Tel No: 1800-2949999

2 of 3

Report No T/20181224/2080

**CONTINUATION OF REPORT**

|                                   |                               |                                        |                                 |
|-----------------------------------|-------------------------------|----------------------------------------|---------------------------------|
| <b>Driver</b>                     |                               |                                        |                                 |
| Name                              | GERMAINE BAN FANGYU           | ID No.                                 | S9608699G                       |
| Related Vehicle                   | SLT2564D (Car)                | Contact No.                            | 96548422                        |
| Hospital/Clinic                   | NG TENG FONG GENERAL HOSPITAL | Class of Driving Licence & Expiry Date | Class: 3<br>Date of Expiry: NIL |
| Date Treatment                    | 23/12/2018                    | Date Discharge                         | 23/12/2018                      |
| No. of Days granted Medical Leave | 05                            | Degree of Injury                       | NIL                             |

**Brief Details.**

On 22/12/2018 I was travelling from my residential address to Park Infinitia since 1015hrs. I was travelling about 20km/h along CTE (City) and was joining the merging lane towards Exit 7C from Seletar (TPE/SLE) Towards AYE Near Moulmein on the second lane. The vehicle in front of me was slowing down and as such, I had follow suit. Thereafter I felt an impact from the rear of my vehicle and my vehicle had inch forward about 1.5-2 meters away. However, my vehicle did not hit onto the rear of any vehicle in front of me.

I then step out of my vehicle and made a check on my vehicle damaged. My vehicle exhaust pipe was shifted, the rear bumper clip was lose and my vehicle registration plate number was dented. In addition, the plate number holder was lose and the grill to rear had fallen apart.

The taxi driver (HP No: 98528285) had initially wanted to compensate S\$50 but I refused to. We had then exchanged numbers. On the day of the incident, no one was injured and no one was conveyed via ambulance. I had felt sharp pain on my back and as such went to the Ng Teng Fong General Hospital on 23/12/2018 and was issued with a outpatient sick leave from 23/12/2018 to 27/12/2018.

The taxi vehicle front plate registration were slightly cracked. I would like to state that I have installed in-car camera but I am not sure if it was recording.





**SINGAPORE  
POLICE FORCE**



T/20181224/2080

Police Station Of Origin:  
Rochor N.P.C  
11 Kampong Kapur Road SINGAPORE  
208678  
Tel No: 1800-2949999

3 of 3


Report No. T/20181224/2080

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

|                                                                                              |                                                                                                                |
|----------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|
| Signature Of Officer Recording The Report:<br>A /<br>Sgt 3 NURUL ASHIQIN BINTI MOHD SHUKOR   | Signature Of Informant:<br> |
| Signature Of Interpreter:<br>Not applicable                                                  | Date/Time:<br>24/12/2018 15:33                                                                                 |
| Officer In Charge Of Case:<br>TP / GIA /<br>Staff Sgt WONG SIEU LUI<br>Contact No.: 65476151 | Classification Of Case:                                                                                        |
| Authentication Stamp<br>NP158                                                                |                                                                                                                |

# Treasure Appraisal Services

9 Joo Chiat Place Singapore 427743

HP: (65) 9833 1618 Fax: (65) 6747 1017

Email: treasureappraisal@gmail.com

Reg No: 53218791A



## TAX INVOICE

Bill to : Ban Kok Poh

C/O : Hendon Automotive Pte Ltd

280 Woodlands Industrial Park E5 #01-19

Harvest @ Woodlands

Singapore 757322

Tel: 9459 2885

Contact: Lynn Sim

Fax: 6334 5178

HP:

Invoice No : TAS-1812-1173

Date : 31-Dec-18

Report No : T-HD-181224/2564D

Terms : COD

| S/N   | Descriptions                                                                                                                                                                                                                                                                                                                                                                                                                                                                          | Amount (S\$) |
|-------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------|
| 1     | <p>Service Rendered In Respect of:</p> <p>Vehicle Number : SLT 2564 D<br/>Vehicle Make/Model : Suzuki Swift<br/>Date of Inspection : 26-Dec-18<br/>Date of Accident : 22-Dec-18</p> <p>Appraisal fees include transportation and follow-up inspection.</p> <p>Submission of appraisal report by hand.</p> <p>Photography services including storage of media and submission of color photograph copies by hand.</p> <p><b>SINGAPORE DOLLARS SIX HUNDRED AND NINETY-EIGHT ONLY</b></p> | \$ 698.00    |
| Total |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       | \$ 698.00    |

E. & O.E

All cheques should be crossed and made payable to "Treasure Appraisal Services".

All cheques should indicate our "Invoice No" on the reverse side of the cheque.

for Treasure Appraisal Services



# Treasure Appraisal Services

9 Joo Chiat Place Singapore 427743  
HP: (65) 9833 1618 Fax: (65) 6747 1017  
Email: treasureappraisal@gmail.com  
Reg No: 53218791A



## VEHICLE ASSESSMENT REPORT

Report No : T-HD-181224/2564D  
Date : 31-Dec-18

### REFERENCE

Assigned By : Ban Kok Poh  
Name of Workshop : Hendon Automotive Pte Ltd  
Place of Inspection : 280 Woodlands Industrial Park E5 #01-19 Harvest @ Woodlands Singapore 757322  
Date of Assignment : 24-Dec-18  
Date of Accident : 22-Dec-18  
Date of Inspection : 26-Dec-18

### PARTICULARS OF DAMAGED VEHICLE

|                |                |                   |                     |
|----------------|----------------|-------------------|---------------------|
| Vehicle Reg No | : SLT 2564 D   | Chassis No        | : JSAEJC31S00203409 |
| Year of Reg    | : Feb-09       | Odometer/km       | : 125359            |
| Make/Model     | : Suzuki Swift | Engine No         | : M16A1434871       |
| Vehicle Colour | : Yellow       | Engine Capacity   | : 1586 cc           |
| Vehicle Type   | : Hatchback    | Transmission Type | : Auto              |

### PRE-ACCIDENT CONDITION OF VEHICLE (STATIC TESTS ONLY)

|                     |               |                    |               |
|---------------------|---------------|--------------------|---------------|
| General Condition   | : Good        |                    |               |
| Body Paint Work     | : Good        | Footbrake          | : Serviceable |
| Steering            | : Serviceable | Handbrake          | : Serviceable |
| Front Undercarriage | : Serviceable | Rear Undercarriage | : Serviceable |

| TIRES CONDITION  | Tire Brand  | Size         | Tread Balance |
|------------------|-------------|--------------|---------------|
| Front RH         | : Yokohama  | : 205/45 R17 | : 80%         |
| Rear RH          | : Yokohama  | : 205/45 R17 | : 80%         |
| Front LH         | : Yokohama  | : 205/45 R17 | : 80%         |
| Rear LH          | : Yokohama  | : 205/45 R17 | : 80%         |
| Road Wheels Type | : Sport Rim |              |               |

Note: The above percentages represent the estimated remaining balance of the tire treads in mm.  
\* Denotes damaged components.

### SYNOPSIS OF DAMAGES

At the time of survey, we noted that the vehicle has sustained an impact damages on the rear portions.

For further detail of the damages, please refer to our schedule and 178 pcs of surveyed photograph attached.

# Treasure Appraisal Services

9 Joo Chiat Place Singapore 427743  
HP: (65) 9833 1618 Fax: (65) 6747 1017  
Email: treasureappraisal@gmail.com  
Reg No: 53218791A



## RECOMMENDATIONS

We referred to your instruction to appraise the above vehicle SLT 2564 D on 26-Dec-18 and in the accordance, we have carried out a physical assessment at your appointed workshop.

A static inspection was carried out and report is enclosed for your reference. The estimated repair cost submitted by the repairer for SGD 9,370.52 as per attached schedule has been scrutinised and revised by us against the actual damages found on the vehicle and we recommended the replacements and rectifications accordingly.

The repair cost has been revised to SGD 7,403.53 and therefore in the consideration of the repairer giving a further 20% even discount, it was agreed that the repairs to be carried out at a contractual lump sum of SGD 5,900.00 nett.

In such event, the repairer shall has the prerogative to either use new, OEM, re-conditioned parts and/or repair any damaged body parts that the repairer is confident and capable of repairing as long as the vehicle is put on the road in its pre-accident and road worthy condition and to the entire satisfaction of the owner.

Under normal circumstances, the estimated period of repairs is **Eight (8)** working days.

Pursuant to your instructions, we have NOT AUTHORISED to carry out the repairs on your behalf and we are submitting this report for your consideration.

This survey and/or appraisalment was carried out to the best of our knowledge, ability and on a "STRICTLY WITHOUT PREJUDICE" basis to any party concern.

We are reverting the matter to you for your discretion.

Yours Truly,  
Treasure Appraisal Services

Dixon Yeo T W  
Automobile Appraiser

The revised estimate was made from a visual inspection. Any discrepancies or unseen damage/s should be notified to the company within **Fourteen (14) days** from the date thereof. Otherwise, the revised amount should deem to be valid.

This report is strictly confidential and is given for the use of client and their authorised assigned agent and any disclosure or publication of it or part or whole shall be the responsibility of such person and no liability shall be attached to TREASURE APPRAISAL SERVICES thereof.

# Treasure Appraisal Services

9 Joo Chiat Place Singapore 427743  
HP: (65) 9833 1618 Fax: (65) 6747 1017  
Email: treasureappraisal@gmail.com  
Reg No: 53218791A



## APPRAISEMENT SCHEDULE

Vehicle Registration No: SLT 2564 D

Report No: T-HD-181224/2564D

| S/N                    | Descriptions                                    | Condition | Qty   | Repairer's Estimate | Our Assessment |
|------------------------|-------------------------------------------------|-----------|-------|---------------------|----------------|
| <b>LIST ITEMS</b>      |                                                 |           |       |                     |                |
| 1                      | Tailgate panel <i>DD</i>                        | Damaged   | 1 pc  | \$ 528.75           | \$ 528.75      |
| 2                      | Tailgate "S" emblem                             | Necessary | 1 pc  | \$ 14.00            | \$ 14.00       |
| 3                      | Tailgate "SWIFT" emblem                         | Necessary | 1 pc  | \$ 18.60            | \$ 18.60       |
| 4                      | Tailgate "Sports" emblem                        | Necessary | 1 pc  | \$ 17.35            | \$ 17.35       |
| 5                      | Tailgate outer handle <i>unx</i>                | Reusable  | 1 pc  | \$ 57.60            | \$ -           |
| 6                      | Tailgate outer handle opening switch <i>unx</i> | Reusable  | 1 pc  | \$ 65.30            | \$ -           |
| 7                      | Tailgate RH hinge <i>unx</i>                    | Repaired  | 1 pc  | \$ 30.00            | \$ -           |
| 8                      | Tailgate LH hinge <i>unx</i>                    | Repaired  | 1 pc  | \$ 30.00            | \$ -           |
| 9                      | Tailgate RH damper <i>unx</i>                   | Damaged   | 1 pc  | \$ 89.50            | \$ 89.50       |
| 10                     | Tailgate LH damper <i>unx</i>                   | Damaged   | 1 pc  | \$ 89.50            | \$ 89.50       |
| 11                     | Tailgate lock assy <i>Jam ✓ Δ</i>               | Damaged   | 1 pc  | \$ 130.99           | \$ 130.99      |
| 12                     | Tailgate trim board <i>unx</i>                  | Reusable  | 1 pc  | \$ 102.35           | \$ -           |
| 13                     | Tailgate weather strip <i>DEF</i>               | Damaged   | 1 pc  | \$ 66.65            | \$ 66.65       |
| 14                     | RH tail lamp assy <i>CRA</i>                    | Damaged   | 1 pc  | \$ 227.05           | \$ 227.05      |
| 15                     | LH tail lamp assy <i>CRA ✓ Δ</i>                | Damaged   | 1 pc  | \$ 227.05           | \$ 227.05      |
| 16                     | RH tail lamp panel <i>3R</i>                    | Repaired  | 1 pc  | \$ 206.05           | \$ -           |
| 17                     | LH tail lamp panel <i>3R</i>                    | Repaired  | 1 pc  | \$ 206.05           | \$ -           |
| 18                     | Rear bumper cover <i>DEF</i>                    | Damaged   | 1 pc  | \$ 518.75           | \$ 518.75      |
| 19                     | Number plate lamp assy <i>CRA ✓ Δ</i>           | Damaged   | 1 set | \$ 34.50            | \$ 34.50       |
| 20                     | Rear RH bumper impact bracket <i>BT</i>         | Damaged   | 1 pc  | \$ 23.50            | \$ 23.50       |
| 21                     | Rear LH bumper impact bracket <i>BT</i>         | Damaged   | 1 pc  | \$ 23.50            | \$ 23.50       |
| 22                     | Rear bumper top holder <i>unx</i>               | Necessary | 1 pc  | \$ 18.20            | \$ 18.20       |
| 23                     | Rear bumper clip <i>unx</i>                     | Necessary | 1 set | \$ 28.00            | \$ 28.00       |
| 24                     | Rear RH bumper side retainer <i>CRA</i>         | Damaged   | 1 pc  | \$ 28.00            | \$ 28.00       |
| 25                     | Rear LH bumper side retainer <i>CRA</i>         | Damaged   | 1 pc  | \$ 28.00            | \$ 28.00       |
| 26                     | Rear end panel <i>DD</i>                        | Damaged   | 1 pc  | \$ 199.90           | \$ 199.90      |
| 27                     | Rear end panel air vent <i>CRA</i>              | Damaged   | 1 pc  | \$ 26.65            | \$ 26.65       |
| 28                     | Rear end panel garnish <i>CRA</i>               | Damaged   | 1 pc  | \$ 62.00            | \$ 62.00       |
| 29                     | Keyless antenna assy <i>unx</i>                 | Damaged   | 1 pc  | \$ 55.70            | \$ 55.70       |
| 30                     | Spare tire board <i>BT</i>                      | Damaged   | 1 pc  | \$ 98.90            | \$ 98.90       |
| 31                     | Spare tire panel <i>BUC</i>                     | Damaged   | 1 pc  | \$ 270.25           | \$ 270.25      |
| 32                     | Spare tire tool sponge tray <i>unx</i>          | Reusable  | 1 pc  | \$ 169.70           | \$ -           |
| 33                     | Rear exhaust silencer <i>unx</i>                | Damaged   | 1 pc  | \$ 411.95           | \$ 411.95      |
| 34                     | Rear exhaust mounting <i>unx</i>                | Damaged   | 3 pcs | \$ 37.50            | \$ 37.50       |
|                        |                                                 |           |       | \$ 4,141.79         | \$ 3,274.74    |
| Less Discount : 15%    |                                                 |           |       | \$ 621.27           | \$ 491.21      |
| List Parts Sub-Total : |                                                 |           |       | \$ 3,520.52         | \$ 2,783.53    |

### SPECIAL NETT ITEMS

|   |                                          |         |       |           |                      |
|---|------------------------------------------|---------|-------|-----------|----------------------|
| 1 | Rear number plate with holder <i>BUC</i> | Damaged | 1 set | \$ 50.00  | \$ 50.00 <i>40</i>   |
| 2 | Reverse sensor assy <i>Startled</i>      | Damaged | 1 set | \$ 350.00 | \$ 280.00 <i>200</i> |

# Treasure Appraisal Services

9 Joo Chiat Place Singapore 427743  
 HP: (65) 9833 1818 Fax: (65) 6747 1017  
 Email: treasureappraisal@gmail.com  
 Reg No: 53218791A



| S/N                        | Descriptions             | Condition | Qty   | Repairer's Estimate | Our Assessment |
|----------------------------|--------------------------|-----------|-------|---------------------|----------------|
| <b>SPECIAL NETT ITEMS</b>  |                          |           |       |                     |                |
| 3                          | Reverse camera assy      | Damaged   | 1 set | \$ 450.00           | \$ 350.00      |
| 4                          | Tailgate glass sealant   | Necessary | 1 pc  | \$ 150.00           | \$ 120.00 40   |
| 5                          | Tailgate glass seal form | Necessary | 1 pc  | \$ 120.00           | \$ 100.00 40   |
| Special Nett Parts Total : |                          |           |       | \$ 1,120.00         | \$ 900.00      |
| Parts Total :              |                          |           |       | \$ 4,640.52         | \$ 3,683.53    |

| S/N | Labour Descriptions                                                                                                                                                                                                                 | Repairer's Estimate | Our Assessment   |
|-----|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------|------------------|
| 1   | To furnish towing service to workshop.                                                                                                                                                                                              | \$ 150.00           | \$ 60.00 X       |
| 2   | Diagnose, replace and/or repair to rectify rear electrical system for proper functioning.                                                                                                                                           | \$ 60.00            | \$ 40.00 30      |
| 3   | Transfer boot lid / tailgate mechanism and wiring assy to facilitate body repairs.                                                                                                                                                  | \$ 150.00           | \$ 80.00 50      |
| 4   | Dismantle, replace and/or re-install reverse sensor assy and rectify for proper functioning.                                                                                                                                        | \$ 150.00           | \$ 80.00 30      |
| 5   | Dismantle, replace and/or re-install reverse camera assy and rectify for proper functioning.                                                                                                                                        | \$ 150.00           | \$ 120.00 X      |
| 6   | Dismantle replace and/or re-install rear windscreen / tailgate glass assy to facilitate body repairs.                                                                                                                               | \$ 150.00           | \$ 120.00 ✓      |
| 7   | Dismantle and re-install rear interior upholstery; trimming and garnish/es to facilitate body repairs.                                                                                                                              | \$ 200.00           | \$ 180.00 40     |
| 8   | To carry out accident body repairs; dismantle vehicle body part/s, dismember affected damaged body panel/s, replace and/or repair, re-construction, weld to re-join and re-align vehicle body structures to pre-accident condition. | \$ 1,500.00         | \$ 1,300.00 1000 |
| 9   | Dismantle, replace, repair and/or re-install rear exhaust pipe muffler assy.                                                                                                                                                        | \$ 150.00           | \$ 120.00 X      |
| 10  | Dismantle, replace, repair and/or re-install boot lid or tailgate spoiler assy.                                                                                                                                                     | \$ 150.00           | \$ 120.00 X      |
| 11  | To furnish, putty, sanding, masking, prepare paint mixture & toning, complete cleaning, spray paint, polishing and waxing on affected areas.                                                                                        | \$ 1,500.00         | \$ 1,200.00 800  |
| 12  | To furnish and apply under-sealing & rust proofing coats on accident affected area.                                                                                                                                                 | \$ 300.00           | \$ 240.00 90     |

# Treasure Appraisal Services

9 Joo Chiat Place Singapore 427743

HP: (65) 9833 1618 Fax: (65) 6747 1017

Email: treasureappraisal@gmail.com

Reg No: 53218791A



| S/N                    | Labour Descriptions                                                 | Repairer's Estimate | Our Assessment |
|------------------------|---------------------------------------------------------------------|---------------------|----------------|
| 13                     | Conduct water leakage tests to ensure proper air and water sealing. | \$ 120.00           | \$ 60.00 30    |
| Labour Total :         |                                                                     | \$ 4,730.00         | \$ 3,720.00    |
| Parts & Labour Total : |                                                                     | \$ 9,370.52         | \$ 7,403.53    |

Note: The repairer has agreed to undertake the repairs at our adjusted amount of SGD 5,900.00 on a \*Contractual Lump Sum Basis corresponding to supply of all parts, labour and spray painting charges.

N.B: \*Under Contractual Lump Sum Basis, the repairer shall have the prerogative to either use new, OEM, re-conditioned parts and/or repair any damaged body parts that the repairer is confident and capable of repairing as long as the vehicle is put on the road in its pre-accident and road worthy condition and to the entire satisfaction of the owner.

Under normal circumstances, the estimated period of repairs is **Eight (8)** working days. Pursuant to your instruction, we have NOT AUTHORISED the repairs on your behalf.

Treasure Appraisal Services

Dixon Yeo P W  
Automobile Appraiser

L/S \$3800/- 6days

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                         |
|----------------------------|-------------------------|
| Date Of Report             | 24/12/2018 13:53        |
| Date Of Accident           | 22/12/2018 11:30        |
| Exact Location Of Accident | SLIP RD FROM PIE TO CTE |
| Country/State of Loss      | SINGAPORE               |

### DETAILS OF OWN VEHICLE

|                             |                                |
|-----------------------------|--------------------------------|
| Vehicle Registration Number | SHD4832Z                       |
| <b>Insured/Policyholder</b> |                                |
| Name Of Registered Owner    | COMFORT TRANSPORTATION PTE LTD |
| Co Reg No                   | 199303821R                     |
| Email Address               | FLEETSAFETY@CDGTAXI.COM.SG     |
| Mobile Phone No             |                                |
| Alternative Phone No        | OFFICE-65508768                |

### Vehicle Particulars

|                                                                              |                |
|------------------------------------------------------------------------------|----------------|
| Manufacturer                                                                 | HYUNDAI        |
| Model                                                                        | I40            |
| Exact Purpose for which vehicle was being used at time of accident           |                |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO             |
| If No, Please state action to be taken                                       | REPORTING ONLY |
| Vehicle Category                                                             | TAXI           |

### Insurance Company

|                           |                                       |
|---------------------------|---------------------------------------|
| Name of Insurance Company | INDIA INTERNATIONAL INSURANCE PTE LTD |
| Type Of Coverage          | THIRD PARTY FIRE AND/OR THEFT         |
| Fleet Policy              | YES                                   |
| Policy Number             | MCOM0015                              |
| Cover Note Number         |                                       |

### Driver

|                      |                       |
|----------------------|-----------------------|
| Name of Driver       | CHUA TECK LAI         |
| NRIC No              | S1590189F             |
| Date Of Birth        | 21/01/1963            |
| Occupation           | OUTDOOR               |
| Date Of Driving Pass | 12/12/1983            |
| Driving Experience   | 35 YEARS AND 0 MONTHS |
| Gender               | MALE                  |
| Mobile Number        | (LOCAL) +65-98528285  |
| Fax Number           |                       |
| Contact Number       |                       |
| Email Address        | CTECKLAI@YAHOO.COM    |



|                                                     |                         |
|-----------------------------------------------------|-------------------------|
| Address                                             | 82 07-947 WHAMPOA DRIVE |
| Postcode                                            | 320082                  |
| Was driver an employee of the Insured's Company     | NO                      |
| If No, Relationship of the Driver with the Insured  | OTHER - TAXI DRIVER     |
| Vehicle Registration Number of Driver's Own Vehicle | -                       |
|                                                     | -                       |
|                                                     | -                       |
| Insurance Company of Driver's Own Vehicle           | -                       |
|                                                     | -                       |
|                                                     | -                       |

#### General Information of the Accident

|                    |                          |
|--------------------|--------------------------|
| Type Of Accident   | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR                    |
| Road Surface       | DRY                      |

#### Other Information

|                                                                                             |                               |
|---------------------------------------------------------------------------------------------|-------------------------------|
| Was any foreign vehicle involved in this accident?                                          | NO                            |
| Number of vehicles (including own vehicle) involved in the accident                         | 2                             |
| Was any body injured in the Accident?                                                       | YES                           |
| Was any injured conveyed to hospital by ambulance?                                          | NO                            |
| Was any other material or property damaged?                                                 | YES                           |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO                            |
| Number of Passengers (Including Driver)                                                     | 4                             |
| Passenger 1                                                                                 | NAME: : -<br>GENDER: : MALE   |
| Passenger 2                                                                                 | NAME: : -<br>GENDER: : FEMALE |
| Passenger 3                                                                                 | NAME: : -<br>GENDER: : MALE   |

#### Details of Police Action

|                                           |    |
|-------------------------------------------|----|
| Was the accident reported to the police?  | NO |
| If Yes, Please state which Police Station |    |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom?                     |    |

#### Circumstances of Accident

SEE ATTACH.

#### Attachment(s)

|                                               |     |
|-----------------------------------------------|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera?   | YES |
| Remarks/ Reasons:                             | -   |
| Was there any audio recorded?                 | NO  |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                             |             |
|-----------------------------|-------------|
| Vehicle Registration Number | SLT2564D    |
| Vehicle Make/Model/Colour   |             |
| Details Of Properties       |             |
| Vehicle Category            | PRIVATE CAR |
| Name of Driver              |             |
| NRIC/Passport Number        |             |

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage REAR

No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name PASSENGER

Approximate Age

Injuries Sustain NECK

Injured person in which vehicle? SHD4832Z


Were seat belts worn?

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 22/12/18 at about 11:30 hrs, I was driving at above said location. Suddenly Veh B in front braked to stopped, I immediately applied brake upon seeing this. However it was too late, my taxi front portion collided onto the rear portion of Veh B.

03 passengers on board my taxi. No injury reported at the scene. After that, the male passenger claim that his children was injured.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE.  
CO. REG. NO. 189307821R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: Lo Wei Yeng  
NRIC/FIN No.: 24/12/18

CRP/ACC Sketch Plan Form V2

# **IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

LOMFORT TRANSPORTATION PTE LTD

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Accident Photo



Accident Photo



Accident Photo



Accident Photo





Accident Photo



Accident Photo





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS3/III18023122/Jqd3e2-1

64 CECIL STREET  
#05-02 IOB BUILDING SINGAPORE 049711

Date : 16-04-2019



Code : III2

## 1. Policy Particulars :- THIRD PARTY CLAIM

|              |             |                |            |
|--------------|-------------|----------------|------------|
| Insured Veh. | SHD 4832Z   | Veh. Inspected | SLT 2564D  |
| Policy No.   | MCOM0015    | Coverage (\$)  | 0.00       |
| Claim No.    | MCT18120671 | Excess (\$)    | 0.00       |
| Assign From  | STANLEY LAI | Assign Date    | 09/04/2019 |

## 2. Vehicle Particulars & Condition

|              |                   |              |            |
|--------------|-------------------|--------------|------------|
| Make & Model | SUZUKI SWIFT      | c.c          | 1586       |
| Engine No.   | HIDDEN            | Year of Reg. | 2009       |
| Chassis No.  | JSAEZC31S00203409 | Colour       | YELLOW     |
| Odometer     | 125359            | Steering     | IN ORDER   |
| Brakes       | IN ORDER          | Modification | SPORTS RIM |
| General      | GOOD              |              |            |

## 3. Conditions of Tyres

|                | Size       | Make   | Balance |
|----------------|------------|--------|---------|
| R/H Front Tyre | 205/45 R17 | DUNLOP | 6 mm    |
| L/H Front Tyre | 205/45 R17 | DUNLOP | 6 mm    |
| R/H Rear Tyre  | 205/45 R17 | DUNLOP | 6 mm    |
| L/H Rear Tyre  | 205/45 R17 | DUNLOP | 6 mm    |

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

## 5. General Information

|                |                                                                           |                 |            |
|----------------|---------------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 22/12/2018                                                                | Inspection Date | 27/12/2018 |
| Survey held at | HENDON AUTOMOTIVE<br>280 WOODLANDS IND PARK E5<br>#01-11 SINGAPORE 757322 |                 |            |

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

|                                     |                |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 6 Working Days |
|-------------------------------------|----------------|



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 2564D

| Qty | Description of Parts                 | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--------------------------------------|----------------------|---------------------------|-------------------|
|     | <b>REPLACEMENT OF PARTS</b>          |                      |                           |                   |
| 1   | TAILGATE PANEL                       | DENTED               | 528.75                    | 528.75            |
| 1   | TAILGATE "S" EMBLEM                  | NECESSARY            | 14.00                     | 14.00             |
| 1   | TAILGATE "SWIFT" EMBLEM              | NECESSARY            | 18.60                     | 18.60             |
| 1   | TAILGATE "SPORTS" EMBLEM             | NECESSARY            | 17.35                     | 17.35             |
| 1   | TAILGATE OUTER HANDLE                | NOT NECESSARY        | 57.60                     | -                 |
| 1   | TAILGATE OUTER HANDLE OPENING SWITCH | NOT NECESSARY        | 65.30                     | -                 |
| 1   | TAILGATE RH HINGE                    | NOT NECESSARY        | 30.00                     | -                 |
| 1   | TAILGATE LH HINGE                    | NOT NECESSARY        | 30.00                     | -                 |
| 1   | TAILGATE RH DAMPER                   | NOT NECESSARY        | 89.50                     | -                 |
| 1   | TAILGATE LH DAMPER                   | NOT NECESSARY        | 89.50                     | -                 |
| 1   | TAILGATE LOCK ASSY                   | JAMMED               | 130.99                    | 130.99            |
| 1   | TAILGATE TRIM BOARD                  | NOT NECESSARY        | 102.35                    | -                 |
| 1   | TAILGATE WEATHER STRIP               | DEFORMED             | 66.65                     | 66.65             |
| 1   | RH TAIL LAMP ASSY                    | CRACKED              | 227.05                    | 227.05            |
| 1   | LH TAIL LAMP ASSY                    | CRACKED              | 227.05                    | 227.05            |
| 1   | RH TAIL LAMP PANEL                   | TO REPAIR SEE LABOUR | 206.05                    | -                 |
| 1   | LH TAIL LAMP PANEL                   | TO REPAIR SEE LABOUR | 206.05                    | -                 |
| 1   | REAR BUMPER COVER                    | DEFORMED             | 518.75                    | 518.75            |
| 1   | SET NUMBER PLATE LAMP ASSY           | CRACKED              | 34.50                     | 34.50             |
| 1   | REAR RH BUMPER IMPACT BRACKET        | BENT                 | 23.50                     | 23.50             |
| 1   | REAR LH BUMPER IMPACT BRACKET        | BENT                 | 23.50                     | 23.50             |
| 1   | REAR BUMPER TOP HOLDER               | NECESSARY            | 18.20                     | 18.20             |
| 1   | SET REAR BUMPER CLIP                 | NECESSARY            | 28.00                     | 28.00             |
| 1   | REAR RH BUMPER SIDE RETAINER         | CRACKED              | 28.00                     | 28.00             |
| 1   | REAR LH BUMPER SIDE RETAINER         | CRACKED              | 28.00                     | 28.00             |
| 1   | REAR END PANEL                       | DENTED               | 199.90                    | 199.90            |
| 1   | REAR END PANEL AIR VENT              | CRACKED              | 26.65                     | 26.65             |
| 1   | REAR END PANEL GARNISH               | CRACKED              | 62.00                     | 62.00             |
| 1   | KEYLESS ANTENNA ASSY                 | NOT NECESSARY        | 55.70                     | -                 |

Report Ref No. CS3/III18023122/Jqd3e2-1



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 3

| Qty | Description of Parts                                                                                     | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|----------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
| 1   | SPARE TIRE BOARD                                                                                         | BENT          | 98.90                     | 98.90             |
| 1   | SPARE TIRE PANEL                                                                                         | BUCKLED       | 270.25                    | 270.25            |
| 1   | SPARE TIRE TOOL SPONGE TRAY                                                                              | NOT NECESSARY | 169.70                    | -                 |
| 1   | REAR EXHAUST SILENCER                                                                                    | NOT NECESSARY | 411.95                    | -                 |
| 3   | REAR EXHAUST MOUNTING                                                                                    | NOT NECESSARY | 37.50                     | -                 |
|     | LESS 15% DISCOUNT                                                                                        |               | -621.27                   | -388.59           |
|     |                                                                                                          |               | 3,520.52                  | 2,202.00          |
|     | <b>SPECIAL NETT ITEMS</b>                                                                                |               |                           |                   |
| 1   | SET REAR NUMBER PLATE WITH HOLDER (SN)                                                                   | BUCKLED       | 50.00                     | 40.00             |
| 1   | SET REVERSE SENSOR ASSY (SN)                                                                             | SHORTED       | 350.00                    | 200.00            |
| 1   | SET REVERSE CAMERA ASSY (SN)                                                                             | NOT NECESSARY | 450.00                    | -                 |
| 1   | TAILGATE GLASS SEALANT (SN)                                                                              | NECESSARY     | 150.00                    | 60.00             |
| 1   | TAILGATE GLASS SEAL FORM (SN)                                                                            | NECESSARY     | 120.00                    | 40.00             |
|     |                                                                                                          |               | 1,120.00                  | 340.00            |
|     | <b>LABOUR</b>                                                                                            |               |                           |                   |
|     | TO FURNISH TOWING SERVICE TO WORKSHOP.                                                                   | NOT NECESSARY | 150.00                    | -                 |
|     | DIAGNOSE, REPLACE AND / OR REPAIR TO RECTIFY REAR ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.              |               | 60.00                     | 30.00             |
|     | TRANSFER BOOT LID / TAILGATE MECHANISM AND WIRING ASSY TO FACILITATE BODY REPAIRS.                       |               | 150.00                    | 50.00             |
|     | DISMANTLE, REPLACE AND / OR RE-INSTALL REVERSE SENSOR ASSY AND RECTIFY FOR PROPER FUNCTIONING.           |               | 150.00                    | 30.00             |
|     | DISMANTLE, REPLACE AND / OR RE-INSTALL REVERSE CAMERA ASSY AND RECTIFY FOR PROPER FUNCTIONING.           | NOT NECESSARY | 150.00                    | -                 |
|     | DISMANTLE REPLACE AND / OR RE-INSTALL REAR WINDSCREEN / TAILGATE GLASS ASSY TO FACILITATE BODY REPAIRS.  |               | 150.00                    | 120.00            |
|     | DISMANTLE AND RE-INSTALL REAR INTERIOR UPHOLSTERY; TRIMMING AND GARNISH / ES TO FACILITATE BODY REPAIRS. |               | 200.00                    | 40.00             |

Report Ref No. CS3/III18023122/Jqd3e2-1

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 3 of 3

| Qty                                                                         | Description of Parts                                                                                                                                                                                                                                                                                        | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
|                                                                             | TO CARRY OUT ACCIDENT BODY REPAIRS; DISMANTLE VEHICLE BODY PART/S, DISMEMBER AFFECTED DAMAGED BODY PANEL/S, REPLACE AND / OR REPAIR, RE-CONSTRUCTION, WELD TO RE-JOIN AND RE-ALIGN VEHICLE BODY STRUCTURES TO PRE-ACCIDENT CONDITION. INCLUSIVE OF THE REPAIR OF RH TAIL LAMP PANEL AND LH TAIL LAMP PANEL. |               | 1,500.00                  | 1,000.00          |
|                                                                             | DISMANTLE, REPLACE, REPAIR AND / OR RE-INSTALL REAR EXHAUST PIPE MUFFLER ASSY.                                                                                                                                                                                                                              | NOT NECESSARY | 150.00                    | -                 |
|                                                                             | DISMANTLE, REPLACE, REPAIR AND / OR RE-INSTALL BOOT LID OR TAILGATE SPOILER ASSY.                                                                                                                                                                                                                           | NOT NECESSARY | 150.00                    | -                 |
|                                                                             | TO FURNISH, PUTTY, SANDING, MASKING, PREPARE PAINT MIXTURE & TONING, COMPLETE CLEANING, SPRAY PAINT, POLISHING AND WAXING ON AFFECTED AREAS.                                                                                                                                                                |               | 1,500.00                  | 800.00            |
|                                                                             | TO FURNISH AND APPLY UNDER-SEALING & RUST PROOFING COATS ON ACCIDENT AFFECTED AREA.                                                                                                                                                                                                                         |               | 300.00                    | 90.00             |
|                                                                             | CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND WATER SEALING.                                                                                                                                                                                                                                         |               | 120.00                    | 30.00             |
|                                                                             |                                                                                                                                                                                                                                                                                                             |               | 4,730.00                  | 2,190.00          |
| <b>GRAND TOTAL</b>                                                          |                                                                                                                                                                                                                                                                                                             |               | <b>9,370.52</b>           | <b>4,732.00</b>   |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |                                                                                                                                                                                                                                                                                                             |               |                           | <b>3,800.00</b>   |

Report Ref No. CS3/III18023122/Jqd3e2-1

MARKET VALUE: \$12,500.00(EST)-LTA REIMBURSEMENT VALUE: \$8,640.00=NETT VALUE: \$3,860.00

ONG HWEE JIE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.