

Volkswagen Centre Singapore



Biz Reg. No. 53103069E
GST No. M20098505-2

~~DRUG-CHAMBER~~ : 2/3/19

NO VIDEO

Letter of Claims Request for direct settlement.

We are submitting a claim on behalf of our customer KELVINDER SINGH
NRIC S8331577 F insured of vehicle SLR T752E against
your insured vehicle number SAC 5149 L (AKA)
On the accident dated on 6-4-19 (ddmmyyyy) along PARKED AT YISHUN
ST-22 PARKING LOT.

Dated this 10 APR 2019 (day) of _____ (month) 2019 .

Charmaine Kong
Volkswagen Group Singapore
Accident Claims Dept.
charmaine.kong@vw.com.sg
DID : 63057176/ 63057299
HP: 92361399

VOLKSWAGEN CENTRE SINGAPORE

Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 1/1

Mr
KELVINDER
SINGH
457 YISHUN STREET 41
Singapore 760457

Document no.
Document date 06-04-2019
Customer no. 5211038487
Customer GST-ID
Dealer 39999
Job order number 2019000137/ 1
Job order date 06-04-2019
Service Advisor YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SLR7752E	5G1	28-08-2017	WWWZZZAUZHWO78992	Golf 7	15,762

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	LABOUR	2	pcs.	840.00	#1	1,680.00	1,797.60
	FRONT BUMPER						
	Spray Painting	2	pcs.	800.00	#1	1,600.00	1,712.00
	FRONT BUMPER						
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
	Harness Repair and Short Circuit Check						

Quotation valid till 13-04-2019

Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1		4,040.00	7%	282.80	4,040.00	4,322.80
Total		4,040.00		282.80	4,040.00	4,322.80

Customer

Service Advisor

---VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).---