

* 22/09/2019

ASS. REC. BY:

REF: CS/MSG 19006444/ECd 302

Special Instruction:

Surveyor: SteveASSIGNMENT (Office)

minn

From (Person): Kenny Ong Thiam Beng of MSGDate/Time: 11.4.19 10.30pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SCP 8890AInsured: SLZ 87202at Workshop m/s T & S motoTel: 64845518of Block 5035 Ang Mo Kio Industrial Park 2 # 01-357Policy No: 29114756mkf

Claim No: _____

Sum Insured: _____

Excess: _____

Make of Veh: _____

D.O.A 9.4.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

"wp"

H.O.D. Endorsement: _____

Date/Time: 11.4.19 10.30amPerson Contacted: mr ohVehicle IN / OUT

Date/Time	Action/Instruction Estimate (X)
	SCP 8890A - X
	SLZ 87202 - X
	Dismantle: 12/4/2019
	After repair: 15/4/2019

Curran

Steve

REF: MS19

ASSIGNMENT

From: Date: 11.4.2019

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SCP 8890A

at Workshop m/s T & S motor

of Block 5035 Amk Industrial Park 2# 01-357

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
XXX	

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

"wp"

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SCP 8890A

Yr Regn: 7/12/15

Type: (M) Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda CRV

C.C. 2354

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

79399

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MRA RM 3850 GP000117

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/60R18

R:

BS (DUN) / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

9/4/19

D.O.I.

11/4/19

Survey held at

T & S motor

Des. of Damages: Frt / (Rear) / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair range 4k - 5k, 6 days

12/4/2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

120

Transportation:

) S + RS, SI

) Photos

) Others

10

TOTAL

130

Report Format: PRS

Lump Sum / I.B.I. (\$

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Apr 2019		11 Apr 2019 10:24 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G		
Main Claimant:	SENG KOK CHENG, ID: S0096250C		
Vehicle Reg. No.:	SCP8890A	Date of Loss:	09/04/2019 17:00 - :59 [40 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	29114756MKF (Comprehensive) Coverage: 01/02/2019 - 31/01/2020
Vehicle Reg. No. (Insured):	SLZ8720Z	Policy No. (Claimant):	
		Excess:	
Repairer:	T & S Motor Service - Amk (HQ) Block 5035 Ang Mo Kio Industrial Park 2 #01-357, 569538 Ang Mo Kio - Tel: 64845518		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Keny Ong Thiam Beng - 6643 1309]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/04/2019]		
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY:DISPUTE (OI NON-REPORTING) CONTACT: MEI HUA 9756 7923. Car In.		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6250C
Vehicle Details	
Vehicle No.:	SCP8890A
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Apr 2019
Vehicle Make:	HONDA
Vehicle Model:	CRV 2.4 5AT 2WD S/R
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	K24Z98502571
Chassis No.:	MRHRM3850GP000117
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$28,587.00
Original Registration Date:	07 Dec 2015
First Registration Date:	07 Dec 2015
Transfer Count:	0
Actual ARF Paid:	\$32,022.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Dec 2025
PARF Rebate Amount:	\$24,016.00
Intended COE Rebate Details	
COE Expiry Date:	06 Dec 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$61,103.00
COE Rebate Amount:	\$40,647.00
Total Rebate Amount:	\$64,663.00

The information contained herein is correct as at 11 Apr 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	10/04/2019 11:04
Date Of Accident	09/04/2019 17:00
Exact Location Of Accident	CTE TOWARDS PIE (UPPER SERANGOON EXIT)
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SCP8890A
Insured/Policyholder	SINGAPORE ACCIDENT STATEMENT
Name Of Registered Owner	SENG KOK CHENG
NRIC No	S0096250C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96350812
Alternative Phone No	OTHERS-86996315
Vehicle Particulars	
Manufacturer	HONDA
Model	CR-V-2.4 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01018584
Cover Note Number	07/12/2018 - 06/12/2019
Driver	
Name of Driver	TIA KA HWA
NRIC No	S7662493C
Date Of Birth	11/10/1976
Occupation	INDOOR
Date Of Driving Pass	20/09/2010
Driving Experience	8 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-86996315
Fax Number	
Contact Number	OTHERS-96350812
Email Address	CECILIA TKH@GMAIL.COM

Address	2D DA SILVA LANE
Postcode	545005
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - DAUGHTER-IN-LAW
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : JERALDINE CECILIA SENG GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE SKETCH PLAN BY DRIVER

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	PASS TO OWN WORKSHOP
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLZ8720Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE HIRE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Operator's Signature
Name:
NRIC/FIN No.:



Sketch Plan Pg. 2

Date of accident: 9/4/2019 Time: 5.08pm Location: Along CTE towards PIE /
 My Vehicle A: SCP8890A Vehicle B: SLZ8720Z Vehicle C: UPP Serangoon
 SKETCH PLAN Exit



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 9 April 2019 5pm I was driving along CTE towards Upper Serangoon/PIE exit. It was raining heavily. Visibility was poor. Traffic was slow and congested. Suddenly the car in front of me braked to stop. I braked as well to avoid running into the car in front. But the car behind me SLZ8720Z crashed into my car with a loud bang. We moved to the side of the road to avoid blocking traffic on the highway.

☐ Claim OD/TP at Ah Lim Motor ☒ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:
 My workshop: T & S Motor Service
 Email address: tsmotor@service@hotmail.com
 & myself:
 Email address: Cecilia@tkh@gmail.com

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Person's Signature
 Name:
 NRIC/FIN No.:



AH LIM MOTOR COMPANY

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Apr 2019		11 Apr 2019 10:24 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G		
Main Claimant:	SENG KOK CHENG, ID: S0096250C		
Vehicle Reg. No.:	SCP8890A	Date of Loss:	09/04/2019 17:00 - :59 [40 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	29114756MKF (Comprehensive) Coverage: 01/02/2019 - 31/01/2020
Vehicle Reg. No. (Insured):	SLZ8720Z	Policy No. (Claimant):	
		Excess:	
Repairer:	T & S Motor Service - Amk (HQ) Block 5035 Ang Mo Kio Industrial Park 2 #01-357, 569538 Ang Mo Kio - Tel: 64845518		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Keny Ong Thiam Beng - 6643 1309]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Imm.Advice due 12/04/2019]		
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY:DISPUTE (OI NON-REPORTING) CONTACT: MEI HUA 9756 7923. Car in.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

















































ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SCP8890A
[SLZ8720Z]
TP
SENG KOK CHENG
Apr 9 2019 5:00PM
[GRAB RENTALS PTE LTD]
T & S Motor Service - Amk

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images								3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print
1	11/04/19 19:07	General View							Load JPG	<input checked="" type="checkbox"/>
2	11/04/19 19:07	General View							Load JPG	<input checked="" type="checkbox"/>
3	11/04/19 19:07	General View							Load JPG	<input checked="" type="checkbox"/>
4	11/04/19 19:07	General View							Load JPG	<input checked="" type="checkbox"/>
5	11/04/19 19:07	General View							Load JPG	<input checked="" type="checkbox"/>
6	11/04/19 19:07	General View							Load JPG	<input checked="" type="checkbox"/>
7	11/04/19 19:07	General View							Load JPG	<input checked="" type="checkbox"/>
8	11/04/19 19:07	General View							Load JPG	<input checked="" type="checkbox"/>
9	11/04/19 19:07	General View							Load JPG	<input checked="" type="checkbox"/>
10	11/04/19 19:07	General View							Load JPG	<input checked="" type="checkbox"/>
11	11/04/19 19:07	General View							Load JPG	<input checked="" type="checkbox"/>
12	11/04/19 19:07	General View							Load JPG	<input checked="" type="checkbox"/>
13	11/04/19 19:07	General View							Load JPG	<input checked="" type="checkbox"/>
14	11/04/19 19:07	General View							Load JPG	<input checked="" type="checkbox"/>
15	11/04/19 19:07	General View							Load JPG	<input checked="" type="checkbox"/>
16	11/04/19 19:07	General View							Load JPG	<input checked="" type="checkbox"/>
17	11/04/19 19:07	General View							Load JPG	<input checked="" type="checkbox"/>
18	11/04/19 19:07	General View							Load JPG	<input checked="" type="checkbox"/>
19	11/04/19 19:07	General View							Load JPG	<input checked="" type="checkbox"/>
20	11/04/19 19:07	General View							Load JPG	<input checked="" type="checkbox"/>
21	11/04/19 19:07	General View							Load JPG	<input checked="" type="checkbox"/>
22	11/04/19 19:07	General View							Load JPG	<input checked="" type="checkbox"/>
23	11/04/19 19:07	General View							Load JPG	<input checked="" type="checkbox"/>
24	11/04/19 19:07	General View							Load JPG	<input checked="" type="checkbox"/>
25	11/04/19 19:07	General View							Load JPG	<input checked="" type="checkbox"/>
26	11/04/19 19:07	General View							Load JPG	<input checked="" type="checkbox"/>
27	11/04/19 19:07	General View							Load JPG	<input checked="" type="checkbox"/>
28	11/04/19 19:07	Odometer Reading							Load JPG	<input checked="" type="checkbox"/>
29	11/04/19 19:07	General View							Load JPG	<input checked="" type="checkbox"/>
30	11/04/19 19:07	General View							Load JPG	<input checked="" type="checkbox"/>
31	11/04/19 19:07	Chassis Number							Load JPG	<input checked="" type="checkbox"/>
32	15/04/19 13:29	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>
33	15/04/19 13:29	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>
34	15/04/19 13:29	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>
35	15/04/19 13:29	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>
36	15/04/19 13:29	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>
37	15/04/19 13:29	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	15/04/19 13:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
88	15/04/19 13:29	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
89	15/04/19 13:29	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
90	15/04/19 13:29	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
91	15/04/19 13:29	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
92	15/04/19 13:29	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
93	15/04/19 13:30	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
94	15/04/19 13:30	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
95	15/04/19 13:30	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	10/04/19 15:38	PRI & TP DETAILS		Load PDF	
2	10/04/19 15:52	SURVEY DISAGREE ON SJE - ASSIGN LKK		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19006444/ECD3E2

Date: 15/04/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29114756MKF

Claimant Vehicle No : SCP8890A

Insured Vehicle No : SLZ8720Z

Date of Loss: 09/04/2019

Nature of Claim: TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SCP8890A

Make & Model: HONDA CR-V, 2.4 L (A)

Engine No: K24Z98502571

Reg. Date: 07/12/2015 (Man. Year: 2015)

Chassis No: MRHRM3850GP000117

Colour: Silver

Odometer: 79399 km

Engine Capacity: 2354 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R18

Rear Tyre Size: 225/60 R18

Front Left Side: Dunlop 7 mm

Rear Left Side: Dunlop 7 mm

Front Right Side: Dunlop 7 mm

Rear Right Side: Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 11/04/2019

Date Inspected: 11/04/2019 Inspected At:

T & S Motor Service - Amk (HQ)
Block 5035 Ang Mo Kio Industrial Park 2
#01-357
Singapore 569538

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Apr 2019)
Parts:	M1-SUV	HONDA CR-V 2.4 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCP8890A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >