

Surveyor:

Moham

ASSIGNMENT (Office)

From (Person):

Chung Sun Sen

of

ETI

Date/Time:

11/4/19 @ 10:58am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJM 8132X

Insured:

SJV 3016B

at Workshop no:

Npt Auto

Tel:

6784 0663

of

Blk 9005 Tampines St 93 #01-246 / 254

Policy No:

OMP CSN 309 134 1901

Claim No:

SNM 1AD20161602

Sum Insured:

Rate:

Make of Veh:

(Client's Record)

D.O.A.

09/04/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:55am @ 11/4/19

Person Contacted:

Peggy

Vehicle:

IN OUT

Date/Time:

Action/Instruction (✓) Estimate

SJM 8132X - X

SJV 3016B - X ...

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Thursday, 11 April 2019 10:58 AM
To: peggy
Cc: 'assignments'
Subject: RE: ACCD INLVG SJU8132X AND SJV3016B ON 09/04/2019 / OUR REF: SNM19D201616

Without Prejudice

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: peggy [mailto:nphauto@pacific.net.sg]
Sent: Thursday, 11 April, 2019 10:39 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: RE: ACCD INLVG SJU8132X AND SJV3016B ON 09/04/2019 / OUR REF: SNM19D201616

Dear Sirs

We appoint Marcus Chua to pre survey the car.

Please arrange him to survey the car.

REGARDS

PEGGY FOO
NPH AUTO SERVICE
Email : peggy@nphauto.com
TEL: 67840663
FAX: 67840692

From: Chong Boon Sen [<mailto:boonsen.chong@sg.cntaiping.com>]

Sent: Thursday, 11 April 2019 10:35 AM

To: nphauto@pacific.net.sg

Subject: RE: ACCD INLVG SJU8132X AND SJV3016B ON 09/04/2019 / OUR REF: SNM19D201616

Without Prejudice

We refer to the above matter.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson

Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: peggy [<mailto:nphauto@pacific.net.sg>]

Sent: Thursday, 11 April 2019 10:16 AM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: ACCD INLVG SJU8132X AND SJV3016B ON 09/04/2019

Dear Sirs

We refer to the above matter and was negligence by your insured driver SJV3016B.

Attach documents and please arrange your surveyor to survey the car.

REGARDS

PEGGY FOO
NPH AUTO SERVICE
Email : peggy@nphauto.com
TEL; 67840663
FAX: 67840692

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

		Qty	Unit	Price	Amount	Amount	Amount	
15	rear bumper	10		890.00	890.00	890.00	✓	
16	rear bumper reflector lamp L&R	20		72.50	72.50	145.00	✓	
17	rear bumper towing hook cover	10		35.20	35.20	35.20	✓	
18	rear bumper sponge	10		120.00	120.00	120.00	✓	
19	rear bumper clips	40		5.00	5.00	20.00	✓	
20	rear bumper side retainer L&R	20		100.00	100.00	200.00	✓	
21	rear lamp bumper retainer L&R	20		40.00	40.00	80.00	✓	
22	rear boot rubber	10		325.00	325.00	325.00	✓	
23	rear lamp center rocker panel rear end panel	10		1625.00	1625.00	1,625.00	✓	1,625.00
24	rear lamp center rocker panel inner garnish	10		315.00	315.00	315.00	✓	
25	rear bumper bracket L&R	20		100.00	100.00	200.00	✓	
26	rear spare tyre tool box	10		655.00	655.00	655.00	✓	
27	rear spare tyre tool box top cover	10		885.50	885.50	885.50	✓	



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg



Your Ref : Page : 2/3
Our Ref : TP0029/04/19 Date : 11/04/2019

THIRD PARTY CLAIM

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total	
		\$	\$	\$	
28 rear bumper center lower inner cowling	12.5	18	318.40	318.40	✓
29 rear bumper lower cowling LH	11	18	279.90	279.90	X
30 rear exhaust pipe	2	18	500.00	500.00	X
31 rear center garnish clip	11	88	5.00	40.00	X
32 rear center exhaust box	2	18	4387.60	4,387.60	X

16,082.85

-4,020.71

Less 25%

Total Material

\$12,062.14

Special Nett Items

33 rear windscreen sealant	250	18	40.00	40.00	✓
34 rear bumper parking camera	Shut	18	650.00	650.00	380
35 rear bumper parking sensor	Shut	18	200.00	200.00	✓
36 rear number plate w/casing	one	18	45.00	45.00	40

935.00

0.00

Total S/Nett

\$935.00

Labour & Misc

1 Remove & install rear windscreen.	150.00	120
2 Remove & install rear seat carpet.	180.00	100
3 Remove & install rear exhaust box.	100.00	60
4 Remove & install parking sensor.	100.00	50
5 Remove & install r/boot, r/lamp, r/bumper, cut out & renew r/lamp center panel, knock spare tyre panel, r/fender L&R and restraigten body & chassis.	1,800.00	1400
6 Spray painting.	1,300.00	1150
7 Car-o-liner.	350.00	X
8 Check wiring system and re-wiring.	40.00	30
9 Repair rear seat.	800.00	300
	4,820.00	

Total Labour

\$4,820.00

Nett Total Before Gst

\$17,817.14

S.N-660

1. The above estimate is valid for 30 days from the date of issue.
2. The estimate is subject to the availability of materials and labour.
3. The estimate is subject to the approval of the insurance company.
4. The estimate is subject to the approval of the customer.
5. The estimate is subject to the approval of the NPH Auto Service.
6. The estimate is subject to the approval of the relevant authorities.
7. The estimate is subject to the approval of the relevant insurance company.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/04/2019 09:07
Date Of Accident	09/04/2019 17:10
Exact Location Of Accident	PIE LORRINE ROAD TOWARDS CHANGI AIRPORT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJU8132X
Insured/Policyholder	
Name Of Registered Owner	LUI NAI YU
NRIC No	S8233135B
Email Address	GARYLUINAIYU@GMAIL.COM
Mobile Phone No	(LOCAL) +65-92201525
Alternative Phone No	OFFICE-92201525

Vehicle Particulars

Manufacturer	TOYOTA
Model	MARK X-2.4 ZIO (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	29/12/2018
Cover Note Number	28/12/2019

Driver

Name of Driver	LUI NAI YU
NRIC No	S8233135B
Date Of Birth	09/10/1982
Occupation	INDOOR
Date Of Driving Pass	15/04/2005
Driving Experience	13 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92201525
Fax Number	
Contact Number	OFFICE-92201525
Email Address	GARYLUINAIYU@GMAIL.COM

Address	BLK 520B PASIR RIS STREET 51 #02-847
Postcode	512528
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG LORRINE ROAD TOWARDS CHANGI AIRPORT TRAFFIC WAS BAD I BRAKED MY CAR ACCORDINGLY TO THE TRAFFIC CONDITIONS. SUDDENLY A CAR SJV3016B HIT ON TO MY REAR ENDED. AT THAT TIME MY CAR WAS STATIONARY.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJV3016B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

9TH APRIL 2019 . AROUND 1710 HRS ALONG PIE (20KM)
LORRINE ROAD TOWARDS CHANGI AIRPORT TRAFFIC WAS BAD.
I BRAKED MY CAR (SVI 8132X) ACCORDINGLY TO
THE TRAFFIC CONDITIONS . SUDDENLY THE CAR (SVI 3014B)
REAR ENDED INTO MY CAR

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature:
Date & Time:

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

Invest with Fast Direct Execution

Multi-awarded, multi-regulated broker

Our services involve a significant risk
loss of your invested

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Only \$15k/Year Best Car For Renew For COE 10 Years!

Well Maintained By Owner! Popular
Service By Owner!
Cars Inn Credit Starling

Post an Ad

Advertiser Login

Ways of Selling

Browse by Category

Sort by Date Posted

4 vehicles

toyota mark zio

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
------	-------	-------	--------------	----------	---------	---------	---

Search Selection

toyota mark zio

Any

Any

Any

Any

Any

**Toyota Mark X Zio 2.4A (New 5-yr COE)****\$43,800****\$8,750 /yr****14-Aug-2009****2,362 cc****138,000 km****S**

100% Loan Available! Most Affordable 7 Seater Station Wagon Vehicle To Own In Town! 6 Months Warranty Engine Gearbox! Not To Be Us Now!

Posted: 06-Apr-2019 Tags: 2009 Toyota Mark, 2009 toyota mark, Toyota Mark, toyota mark, Toyota, Mark, mark, Used Toyota

**Toyota Mark X Zio 2.4A (New 5-yr COE)****\$40,800****\$8,150 /yr****11-May-2009****2,362 cc****-****S**

Trade In Welcome, Bank And In House Loan All Available, Interested Please Call For Viewing, Viewing By Appointment Only.

Boeki Auto Pte Ltd

Posted: 02-Apr-2019 Tags: 2009 Toyota Mark, 2009 toyota mark, Toyota Mark, toyota mark, Toyota, Mark, mark, Used Toyota

**Toyota Mark X Zio 2.4A G****\$26,800****N.A****27-Jul-2009****2,362 cc****-****S**

Best Deal. Superb Condition. Up To 100% Flexible Loan. Optional New 5 Year COE \$42,800 Or New 10 Year COE \$58,800. We Provide L Rate. Flexible Loan And High Trade In Are Available. Packa...

Classic Credit Pte Ltd

Posted: 21-Mar-2019 Tags: 2009 Toyota Mark, 2009 toyota mark, Toyota Mark, toyota mark, Toyota, Mark, mark, Used Toyota

**Toyota Mark X Zio 2.4A (COE till 08/2028)****\$52,800****\$5,640 /yr****18-Aug-2008****2,362 cc****-****S**

High Flexible Loan. We Provide Lowest Interest Rate. Flexible Loan And High Trade In Are Available. Package With Unrivaed Warranty Certificate And Test Report. Check Out Our New Offer N...

Classic Credit Pte Ltd

Posted: 11-Mar-2019 Tags: 2008 Toyota Mark, 2008 toyota mark, Toyota Mark, toyota mark, Toyota, Mark, mark, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
------	-------	-------	--------------	----------	---------	---------	---

For old advertisements, view **Expired ads**

Compare

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?

Price Range

Depreciation

Year Reg

Vehicle Type

Home » Used Cars » Classic Credit Pte Ltd » Toyota Mark X Zio 2.4A G

Toyota Mark X Zio 2.4A G

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

CLASSIC CREDIT



SGCARMART'S PREMIUM DEALER
2013 / 2014 / 2015 / 2016 / 2017

Price \$26,800

Depreciation N.A.

Reg Date 27-Jul-2009
(3mths 15days COE left)

Mileage N.A.

Manufactured 2008

Road Tax \$1,638 /yr

Transmission Auto

Dereg Value \$16,573 as of today (change)

OMV \$32,071

COE \$18,501

ARF \$32,071

Engine Cap 2,362 cc

Power 120.0 kW (160 bhp)

Curb Weight 1,570 kg

No. of Owners 1

Type of Vehicle Stationwagon

Features

Smooth And Responsive 2.4L 4 Cylinders Inline 16 Valves DOHC Engine, Fuel Efficiency, Front Wheel Drive, Airbags, ABS, View specs of the Toyota Mark X Zio (2007-2014)

Accessories

Sports Rims, Leather Seats, Audio System, Reverse Sensors, Fog Lamps, Auto Headlights, Retractable Side Mirrors.

Description

Best Deal. Superb Condition. Up To 100% Flexible Loan. Optional New 5 Year COE \$42,800 Or New 10 Year COE \$58,800. We Provide Lowest Interest Rate. Flexible Loan And High Trade In Are Available. Package With Unrivalled Warranty Complete With Certificate And Test Report. Meet Our Friendly Consultant For An Non Obligation Advise.

Cal Compare



Location Map

Shortlist

Com

Report Error

M

Seller Information

Company	Classic
	» dealer
	» 30 vet
Address	61 Ubi P #08-07 Search
Location	Automot
Office No	684120
Contact Person(s)	Mr Chei Roland

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3135B
Vehicle Details	
Vehicle No.:	SJU8132X
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	MARK X ZIO 2.4 A
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	2AZC365667
Chassis No.:	ANA100016732
Maximum Power Output:	120.0 kW (160 bhp)
Open Market Value:	\$26,089.00
Original Registration Date:	29 Dec 2009
First Registration Date:	29 Dec 2009
Transfer Count:	2
Actual ARF Paid:	\$26,089.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Dec 2019
PARF Rebate Amount:	\$13,044.00
Intended COE Rebate Details	
COE Expiry Date:	28 Dec 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$20,200.00
COE Rebate Amount:	\$1,405.00
Total Rebate Amount:	\$14,449.00

The information contained herein is correct as at 11 Apr 2019

OK






...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Apr 2019		24 Apr 2019 09:27 Edit Adj Rpt	S\$8,800.00 Edit Estimates	S\$8,800.00 View Rpt		Pending for Survey Report Cancel Case



















































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ID: -								
Main Claimant:	LUI NAI YU, ID: S82331358								
Vehicle Reg. No.:	SJU8132X	Date of Loss:	09/04/2019 17:00 - :59 [111 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D201616C02	Policy/Cover Note No.:	DMPCSN30923419011						
Vehicle Reg. No. (Insured):	SJV3016B	Policy No. (Claimant):	29/12/2018						
		Excess:	S\$0.00						
Repairer:	NPH Auto Service (HQ) Blk 9005 Tampines Steet 93, #01-246/254, 528839 Tampines - Tel: 6784 0663								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 06/05/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJU8132X (SNM19D201616C02)
 [SJV3016B]
 TP
 LUI NAI YU
 Apr 9 2019 5:00PM
 [-]
 NPH Auto Service

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser					
Assessment Reports									1 per page		<input type="checkbox"/>		<input checked="" type="checkbox"/>				
No	Finalized On	NPH Auto Service (HQ)							Thumbnail		Print						
1	10/04/19 09:17	Accident Statement							 Load HTML								
Photos/Images														3 per page		<input type="checkbox"/>	
No	Finalized On	NPH Auto Service (HQ)							Thumbnail		Print						
1	10/04/19 09:16	Accident Photo <small>[Linked Accident Report Documents]</small>							 Load JPG		<input checked="" type="checkbox"/>						
2	10/04/19 09:16	Accident Photo <small>[Linked Accident Report Documents]</small>							 Load JPG		<input checked="" type="checkbox"/>						
3	10/04/19 09:16	Driving License <small>[Linked Accident Report Documents]</small>							 Load JPG		<input checked="" type="checkbox"/>						
4	10/04/19 09:16	Accident Photo <small>[Linked Accident Report Documents]</small>							 Load JPG		<input checked="" type="checkbox"/>						
5	10/04/19 09:16	Accident Photo <small>[Linked Accident Report Documents]</small>							 Load JPG		<input checked="" type="checkbox"/>						
6	10/04/19 09:16	Accident Photo <small>[Linked Accident Report Documents]</small>							 Load JPG		<input checked="" type="checkbox"/>						
7	10/04/19 09:16	Accident Photo <small>[Linked Accident Report Documents]</small>							 Load JPG		<input checked="" type="checkbox"/>						
8	10/04/19 09:16	Accident Photo <small>[Linked Accident Report Documents]</small>							 Load JPG		<input checked="" type="checkbox"/>						
9	10/04/19 09:16	Accident Photo <small>[Linked Accident Report Documents]</small>							 Load JPG		<input checked="" type="checkbox"/>						
10	10/04/19 09:16	Accident Photo <small>[Linked Accident Report Documents]</small>							 Load JPG		<input checked="" type="checkbox"/>						
11	10/04/19 09:16	Accident Photo <small>[Linked Accident Report Documents]</small>							 Load JPG		<input checked="" type="checkbox"/>						
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print						
1	24/04/19 11:19	Odometer Reading							 Load JPG		<input checked="" type="checkbox"/>						
2	24/04/19 11:19	General View							 Load JPG		<input checked="" type="checkbox"/>						
3	24/04/19 11:19	Chassis Number							 Load JPG		<input checked="" type="checkbox"/>						
4	24/04/19 11:19	General View							 Load JPG		<input checked="" type="checkbox"/>						
5	24/04/19 11:19	General View							 Load JPG		<input checked="" type="checkbox"/>						
6	24/04/19 11:19	General View							 Load JPG		<input checked="" type="checkbox"/>						
7	24/04/19 11:19	General View							 Load JPG		<input checked="" type="checkbox"/>						
8	24/04/19 11:19	General View							 Load JPG		<input checked="" type="checkbox"/>						
9	24/04/19 11:19	General View							 Load JPG		<input checked="" type="checkbox"/>						
10	24/04/19 11:19	General View							 Load JPG		<input checked="" type="checkbox"/>						
11	24/04/19 11:19	General View							 Load JPG		<input checked="" type="checkbox"/>						
12	24/04/19 11:19	General View							 Load JPG		<input checked="" type="checkbox"/>						
13	24/04/19 11:19	General View							 Load JPG		<input checked="" type="checkbox"/>						
14	24/04/19 11:19	General View							 Load JPG		<input checked="" type="checkbox"/>						
15	24/04/19 11:19	General View							Load JPG		<input checked="" type="checkbox"/>						
16	24/04/19 11:19	General View							Load JPG		<input checked="" type="checkbox"/>						
17	24/04/19 11:19	General View							Load JPG		<input checked="" type="checkbox"/>						
18	24/04/19 11:19	General View							Load JPG		<input checked="" type="checkbox"/>						

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	NPH Auto Service (HQ)	Thumbnail	Print
19	24/04/19 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
20	24/04/19 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
21	24/04/19 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
22	24/04/19 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
23	24/04/19 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
24	24/04/19 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
25	24/04/19 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
26	24/04/19 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
27	24/04/19 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
28	24/04/19 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
29	24/04/19 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
30	24/04/19 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
31	24/04/19 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
32	24/04/19 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
33	24/04/19 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
34	24/04/19 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
35	24/04/19 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
36	24/04/19 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
37	24/04/19 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
38	24/04/19 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
39	24/04/19 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
40	24/04/19 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
41	24/04/19 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
42	24/04/19 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
43	24/04/19 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
44	24/04/19 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
45	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
46	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
47	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
48	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
49	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
50	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
51	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
52	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
53	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
54	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
55	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
56	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
57	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
58	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
59	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
60	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
61	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
62	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
63	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
64	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
65	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
66	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
67	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
68	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	NPH Auto Service (HQ)	Thumbnail	Print
69	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
70	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
71	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
72	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
73	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
74	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
75	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
76	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
77	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
78	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
79	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
80	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
81	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
82	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
83	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
84	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
85	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
86	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
87	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
88	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
89	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
90	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
91	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
92	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
93	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
94	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
95	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
96	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
97	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
98	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
99	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
100	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
101	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
102	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
103	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
104	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
105	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
106	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
107	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
108	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
109	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
110	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
111	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
112	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
113	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
114	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
115	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
116	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
117	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
118	24/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	NPH Auto Service (HQ)	Thumbnail	Print
119	24/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
120	24/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
121	24/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
122	24/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
123	24/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
124	24/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
125	24/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
126	24/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
127	24/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
128	24/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
129	24/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
130	24/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
131	24/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	24/04/19 09:28	repair estimate	Load PDF	
No	Finalized On	NPH Auto Service (HQ)	Thumbnail	Print
1	10/04/19 09:15	Sketch Plan <small>[Linked Accident Report Documents]</small>	Load TIF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	NPH Auto Service (HQ)	Thumbnail	Print
1	10/04/19 09:17	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	NPH Auto Service (HQ)	Thumbnail	Print
1	10/04/19 09:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	10/04/19 09:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	10/04/19 09:16	Driving License	Load JPG	<input checked="" type="checkbox"/>
4	10/04/19 09:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	10/04/19 09:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	10/04/19 09:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	10/04/19 09:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	10/04/19 09:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	10/04/19 09:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	10/04/19 09:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	10/04/19 09:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	NPH Auto Service (HQ)	Thumbnail	Print
1	10/04/19 09:15	Sketch Plan	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

--

Show Remarks To: ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT19006479/UQD3Q2

Date: 06/05/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN30923419011

Claimant Vehicle
No: SJU8132XInsured Vehicle
No: SJV3016B

Date of Loss: 09/04/2019

Nature of Claim: TP

Claim
No: SNM19D201616C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJU8132X**

Make & Model: TOYOTA MARK X, 2.4 ZIO (A)

Reg. Date: 29/12/2009 (Man. Year: 2008)

Colour: White

Engine Capacity: 2362 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 2AZC365667

Chassis No: ANA100016732

Odometer: 143488 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45Z R18

Rear Tyre Size: 225/45Z R18

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,997.14	7,840.72	5,156.42	39.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,820.00	3,210.00	1,610.00	33.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,817.14	11,050.72	6,766.42	37.98
Approved Total (Overridden) (S\$)		8,800.00		
(S\$)	17,817.14	8,800.00	9,017.14	50.61
+ GST 7.00/7.00% (S\$)	1,247.20	616.00	631.20	50.61
Nett Amount (S\$)	19,064.34	9,416.00	9,648.34	50.61

INSPECTION

Date of Assignment: 24/04/2019

Date Inspected: 11/04/2019 Inspected At:

NPH Auto Service (HQ)
Blk 9005 Tampines Steet 93, #01-246/254
Singapore 528839

Estimated Period of Repair: 8.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 06 May 2019)
Parts: 143	TOYOTA MARK X 2.4 ZIO (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJU8132X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR WINDSCREEN RUBBER MOULDING	Necessary	115.00 FL	*115.00 FL
2	1	*REAR BOOT	Badly Dented	1,250.00 FL	*1,250.00 FL
3	1	*REAR BOOT MARK X EMBLEM	Necessary	80.00 FL	*80.00 FL
4	1	*REAR BOOT ZIO EMBLEM	Necessary	75.00 FL	*75.00 FL
5	1	*REAR BOOT CENTER LOGO	Necessary	72.20 FL	*72.20 FL
6	1	*REAR NUMBER PLATE LAMP GARNISH W/CGROME	Cracked	585.00 FL	*585.00 FL
7	2	*REAR LICENCE PLATE LAMP	Not Necessary	169.20 FL	*- FL
8	1	*REAR BOOT LOCK SENSOR	Cracked	120.00 FL	*120.00 FL
9	1	*REAR BOOT LOCK TOP	Dented / Shorted	425.00 FL	*425.00 FL
10	1	*REAR BOOT LOWER CATCH	Not Necessary	43.50 FL	*- FL
11	1	*REAR BOOT LOCK INNER HANDLE COVER	Not Necessary	48.35 FL	*- FL
12	2	*REAR BOOT DAMPER L&R	Not Necessary	520.00 FL	*- FL
13	1	*REAR BOOT INNER FINISHER	Deformed /Torn	708.00 FL	*708.00 FL
14	2	*REAR LAMP ASSY L&R	Cracked	850.00 FL	*850.00 FL
15	1	*REAR BUMPER	Distorted	890.00 FL	*890.00 FL
16	2	*REAR BUMPER REFLECTOR LAMP L&R	Not Necessary	145.00 FL	*- FL
17	1	*REAR BUMPER TOWING HOOK COVER	Torn	35.20 FL	*35.20 FL
18	1	*REAR BUMPER SPONGE	Torn	120.00 FL	*120.00 FL
19	4	*REAR BUMPER CLIPS	Necessary	20.00 FL	*20.00 FL
20	2	*REAR BUMPER SIDE RETAINER L&R	Bent	200.00 FL	*200.00 FL
21	2	*REAR LAMP BUMPER RETAINER L&R	Bent	80.00 FL	*80.00 FL
22	1	*REAR BOOT RUBBER	Twisted	325.00 FL	*325.00 FL
23	1	*REAR END PANEL	Badly Dented	1,625.00 FL	*1,250.00 FL
24	1	*REAR END PANEL INNER GARNISH	Distorted	315.00 FL	*315.00 FL
25	2	*REAR BUMPER BRACKET L&R	Bent	200.00 FL	*200.00 FL
26	1	*REAR SPARE TYRE TOOL BOX	Distorted	655.00 FL	*655.00 FL
27	1	*REAR SPARE TYRE TOOL BOX TOP COVER	Warped /Dented	885.50 FL	*885.50 FL
28	1	*REAR BUMPER CENTER LOWER INNER COWLING	Distorted	318.40 FL	*318.40 FL
29	1	*REAR BUMPER LOWER COWLING LH	Not Necessary	279.90 FL	*- FL
30	1	*REAR EXHAUST PIPE	Repair	500.00 FL	*- FL
31	8	*REAR CENTER GARNISH CLIP	Not Necessary	40.00 FL	*- FL
32	1	*REAR CENTER EXHAUST BOX	Repair	4,387.60 FL	*- FL
33	1	*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
34	1	*REAR BUMPER PARKING CAMERA	Shorted	650.00 FS	*380.00 FS
35	1	*REAR BUMPER PARKING SENSOR	Shorted	200.00 FS	*200.00 FS
36	1	*REAR NUMBER PLATE W/CASING	Cracked	45.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 17,017.85 10,234.30
 - List Item Discount on L Items 25.00/25.00% (S\$) 4,020.71 2,393.58

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					12,997.14	7,840.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & INSTALL REAR WINDSCREEN	New	150.00	120.00
2	REMOVE & INSTALL REAR SEAT CARPET	New	180.00	100.00
3	REMOVE & INSTALL REAR EXHAUST BOX	New	100.00	60.00
4	REMOVE & INSTALL PARKING SENSOR	New	100.00	50.00
5	REMOVE & INSTALL R/BOOT ,R/LAMP ,R/BUMPER ,CUT OUT & RENEW R/LAMP CENTER PANEL,KNOCK SPARE TYRE PANEL ,R/FENDER L&R AND RESTRAIGHTEN BODY & CHASSIS	New	1,800.00	1,400.00
6	SPRAY PAINTING	New	1,300.00	1,150.00
7	CAR-O-LINER	New	350.00	0.00
8	CHECK WIRING SYSTEM AND RE-WIRING	New	40.00	30.00
9	REPAIR REAR SEAT	New	800.00	300.00
Gross Labour Cost (\$\$)			4,820.00	3,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >