

Surveyor: Taufik

ASSIGNMENT (Office)

From (Person): Jas tan of ASM (AXA) Date/Time: 11/4/2019

Estimated Cost: _____ Bill to: _____

☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SGQ 34685 Insured: _____at Workshop m/s: performance Tel: 91165600of 303 Alexandra RoadPolicy No: _____ Claim No: SGM01558Sum Insured: _____ Excess: NILMake of Veh: _____ D.O.A. 02/04/2019
(Client's Record)CA / ☒ REV / REP. / REV 24 HRS H.O.D. Endorsement: _____Date/Time: 9:50am 11/4/19 Person Contacted: Kalvin Vehicle ☒ IN / OUT

Date/Time Action/Instruction (✓) Estimate

SGQ 34685 - X12/4/19 Revert vehicle CTL via SMART claim16/4/19 Submit uneconomical T/L - mv: \$110K (Est) LTA: \$69,332 MV: \$40,668

Taufik

REF:

AXA

INSURANCE

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop no: _____

of _____

Insured: _____

Policy No: _____

Claim No: _____

Sum Insured: _____

Excess: _____

NIL

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: _____

\$110K

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lump Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Kevin

Veh No: SGQ3468S Reg: 202 Jan

Type: Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 740L

cc 2979.

Colour: white

A/C Insured / Std / Nil / NA

Sp. Reading: 95093

T/Radio: Insured / Std / Nil / NA

Eng/Ho: _____

ChNo: WSAK3420300984079

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275/40 R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6

mm

R/Bal: C

mm

L/Bal: 6

mm

L/Bal: C

mm

D.O.A.:

D.O.I. 11/4/19

Survey held at: pm

Des. of Damages: Frt / Rear / O/S / N/S / U/R / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Battery work
 * Total loss, not economical to repair.

RECEIVED 16 APR 2019

Date/Time, File Pass to?



: Prelim. Report

01



: Final Report

Date/Time, File Return to?

16/4 - typst

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

5 x PS 50

Holding

Other

TOTAL

300

Report Format:

SMART claim

Lump Sum / LB.L: (3)

Add Fee:



Site Insp. (\$)



Interview (\$)



Tech. Insp. (\$)



Weekend (\$)

MV RANGE \$96K TO \$105K

Type

🔔 Question

Message

Please take note of the market value range and advise whether the vehicle is economical to repair.

Reply *

Dear Jas,

Based on MV range vehicle recommended "CTL". We will submit our report accordingly. Thanks Veron Chen

Cancel Reply

Reply Now

New Message

Type *

☒ Message

Subject *

Message *

Dear Jas,
Please be informed that IA submitted. We have Not Authorize repair. Vehicle not economical to repair,Vehicle recommended 'CTL'.Thanks Veron Chen



Auto
Consultants
Pte Ltd

81 UBI AVE 1, #01-25 FAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 12/4/2019

Survey details

Date of loss	2/4/2019
Date of appointment	11/4/2019
Date of survey	11/4/2019
Location of survey	PERFORMANCE MOTORS LTD

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SGQ 3468S
Make and Model	BMW 740LI
Date of registration	25/1/2012
Excess	NIL
Market Value	\$110,000.00
Parf Rebate	\$69,332.00
Nett Loss	\$40,668.00

Repair details

Initial Estimate	\$107,615.54
------------------	--------------

Proposed/Revised repair cost:

Parts	\$58,764.20
"Check items (Estimated)	\$5,596.25
Labour	\$37,526.51
Total	\$101,886.96
Lump Sum (Estimated)	

Number of days of repair	30 days (est)
--------------------------	---------------

Remarks:

The vehicle sustained damages at the n/s body, o/s body and undercarriage. The undercarriage affected due to collision.

Damages Consistent
Repair Cost Not Economical
Vehicle recommended "CTL"



Service Request Details

Claim

S9M01J58

Reference

None 

Loss Date

April 2, 2019

Report Date

Apr 4, 2019 8:46:00 AM

Request Date

April 10, 2019

Due Date

April 17, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated workshop survey

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SGQ34685



PRODUCT

740 LI

Service Address

303 Alexandra Road, , , 159941

Primary Contact/Insured

DONG YU

87 JURONG WEST CENTRAL 3, #08-48 CENTRIS THE, 648343, Singapore

98323468

JUSHISIN@YAHOO.COM

Claim Handler

TAN Jas

6568804844

jas.tan@axa.com.sg

Additional Instructions

PML OD XS NIL survey WP-pend investigation

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

[+ Upload Documents](#)

NAME

OD PML-EMAIL.pdf

TYPE

Letters and Correspondence

SUB-TYPE

Workshop

AUTHOR

RATAN BHOSALE Pragati

DATE UPLOADED

April 10, 2019

NAME

OD PML-ESTIMATE.pdf

TYPE

Forms / Claim Documents



AUTHOR	RATAN BHOSALE Pragati
--------	-----------------------

DATE UPLOADED	April 10, 2019
---------------	----------------

NAME	 SGQ34685 INSD GIA.PDF
------	---

TYPE	Reports & Statement
------	---------------------

SUB-TYPE	GIA Report
----------	------------

AUTHOR	RATAN BHOSALE Pragati
--------	-----------------------

DATE UPLOADED	April 10, 2019
---------------	----------------

RATAN BHOSALE Pragati

From: Kevin Leong Wai Kit <kevin.leong.waikit@simedarby.com.sg>
Sent: Wednesday, April 10, 2019 2:10 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: OD Claim - SGQ3468S - D.O.A : 02/04/19
Attachments: SKM_558e19041014060.pdf

Categories: Pragati

Dear All,

Kindly refer to above attach OD Claim for : SGQ3468S
Please arrange for survey on this car.
Car already in workshop.

Thank you

Regards,

Kevin Leong

Customer Service Advisor | Body and Paint
Performance Motors Limited

303 Alexandra Road

Sime Darby Performance Centre

Singapore 159941

Hp (+65) 9116 5600 | Fax (+65) 6479 4601

Kevin.leong.waikit@simedarby.com.sg



"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/04/2019 08:46
Date Of Accident	02/04/2019 17:20
Exact Location Of Accident	HIGHWAY TO YONGPENG RNR
Country/State of Loss	MALAYSIA/WILAYAH PERSEKUTUAN

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGQ3468S
Insured/Policyholder	
Name Of Registered Owner	DONG YU
NRIC No	S7261418F
Email Address	JUSHISIN@YAHOO.COM
Mobile Phone No	(LOCAL) +65-98323468
Alternative Phone No	OTHERS-98323468

Vehicle Particulars

Manufacturer	BMW
Model	740LI
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA084831
Cover Note Number	

Driver

Name of Driver	DONG YU
NRIC No	S7261418F
Date Of Birth	11/12/1972
Occupation	INDOOR
Date Of Driving Pass	16/01/2007
Driving Experience	12 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98323468
Fax Number	
Contact Number	OTHERS-98323468
Email Address	JUSHISIN@YAHOO.COM

Address	87 JURONG WEST CENTRAL 3 #08-48 THE CENTRIS
Postcode	648343
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	NO COLLISION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : ENG LEE LING GENDER: : FEMALE
Passenger 2	NAME: : LIU WEN YAO GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	JOHOR BATU BAHAT
Police Station Address	ROAD: -, POSTCODE: -, COUNTRY: MALAYSIA
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (POPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time:

3/4/2018

5pm

Driver's Signature

(If driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ATTACHED MALAYSIAN POLICE REPORT

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

3/4/2016
5 PM

Driver's Signature _____

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



POLIS DIRAJA MALAYSIA

REPOT POLIS

Balai : Jabatan KDN/KA
Daerah : Jabatan KDN/KA
Kontinjen : BUKIT AMAN
No Repot : TRAFIK BATU PAHAT/004412/19
Tarikh : 02/04/2019
Waktu : 1932 PM
Bahasa Diterima : B. Malaysia

Pegawai Penyiasat : R112949

Butir-butir Penerima Repot

Nama : ZULKEFLI BIN MD YASIN

No Personel : R112949

Pangkat : SJN

Butir-butir Jurubahasa (Jika Ada)

Nama : ---

No K/P (Baru) : ---

No Polis/Tentera : ---

No Paspot : ---

Bahasa Asal : ---

Alamat : ---

Butir-butir Pengadu

Nama : JONG YU

No K/P (Baru) : ---

No Polis/Tentera : ---

No Paspot : S7261418F

No Sijil Beranak : ---

Jantina : Lelaki

Tarikh Lahir : 11/12/1972

Umur : 46 tahun 3 bulan

Keturunan : Cina

Warganegara : Singapore

Pekerjaan : SENDIRI

Alamat Tempat Tinggal : 87 JURONG WEST CENTRAL 3 #08-48 SINGAPORE, 648343

Alamat Ibu/Bapa : ---

Alamat Pejabat : ---

No Tel (Rumah) : ---

No Tel (Pejabat) : ---

No Tel (HP) : 98323468

Emel : ---

Pengadu Menyatakan:-

PADAHAL 02/04/2019 JAM LEBIH KURANG 1730HRS SEMASA SAYA MEMANDU M/KAR NO PENDAFTARAN : SGO 3463 S. JENIS BMW DARIDAPA KUALA LUMPUR MENGHALA KE SINGAPURA. APABILA TIBA DILEBUHRAYA KM 107. JEADAAN KETIKA ITU HUJAN LEBAT MENYEBABKAN JALAN LICIN SAYA HENDAK MASUK KE R&R SUSUR KIRI LALU M/KAR SAYA HILANG KAWALAN DAN TERBABAS LALU TERLANGGAR PENGHADANG JALAN SEBELAH KIRI. M/KAR SAYA MENGALAMI KEROSAKAN TAYAR HADAPAN SEBELAH KIRI TERCAJUT, BUMPER HADAPAN PECAH, LAMPU SEBELAH KIRI PECAH, CERMIN HADAPAN RETAK, BAHAGIAN BAWAH M/KAR ROSAK DAN LAIN-LAIN KEROSAKAN BELUM PASTI LAGI. SEKIAN LAPORAN SAYA.

Tandatangan Pengadu:

Tandatangan Jurubahasa (Jika ada):

Tandatangan Penerima Repot:

ID Penerima | Tarikh @ Masa Cetak

: R112949 | 02/04/2019 07:40:42 PM

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

1418F

Vehicle Details

Vehicle No.:

SGQ34685

Vehicle to be Exported:

No

Intended Deregistration Date:

10 Apr 2019

Vehicle Make:

B.M.W.

Vehicle Model:

740Li AT 5R HID DSC NAV HUD INT A/STR

Primary Colour:

White

Manufacturing Year:

2011

Engine No.:

11028015N54B30A

Chassis No.:

WBAKB42030CY84079

Maximum Power Output:

240.0 kW (321 bhp)

Open Market Value:

\$84,379.00

Original Registration Date:

25 Jan 2012

First Registration Date:

25 Jan 2012

Transfer Count:

0

Actual ARF Paid:

\$84,379.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

24 Jan 2022

PARF Rebate Amount:

\$50,627.00

Intended COE Rebate Details

COE Expiry Date:

24 Jan 2022

COE Category:

E - Open Category

COE Period(Years):

10

QP Paid:

\$67,101.00

COE Rebate Amount:

\$18,705.00

Total Rebate Amount:**\$69,332.00**

The information contained herein is correct as at 10 Apr 2019

OK

BMW 740 Used Vehicle List (3 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
BMW 7 Series 740Li Sunroof	\$123,800	\$21,870 /yr	03-Dec-2012	2,979 cc	32,000 km	SBB Autoworld Pte Ltd	Available

Lowest Possible Authentic Mileage! Full PML Agent Service Records. Like New Inside And Out. View To Be Impressed. STA / Workshop Inspection Extremely Welcomed. Please Sms / Whatsapp For Appointment To ...

Office No. - -

Desmond - 81183439 | KC - 93977671

BMW 7 Series 740i Luxury Sunroof	\$96,500	\$15,720 /yr	19-Nov-2012	2,979 cc	112,000 km	Bavarian Marques Pte Ltd	Available
----------------------------------	----------	--------------	-------------	----------	------------	--------------------------	-----------

Facelift Luxury Model With Updated I-Drive, Adaptive LED Headlamps, Digital Speedometer, Soft Close And Many More! PML Unit With Full Agent Service History. Zero Wear And Tear Issues Or Repairs Requir...

Office No. - 68162642

Aran - 87517624 | Shawn - 88188544 | Koen - 92233437 | Darren - 82007582

BMW 7 Series 740Li Sunroof	\$110,800	\$24,550 /yr	25-Jan-2012	2,979 cc	91,000 km	Quantum Automobile	Available
----------------------------	-----------	--------------	-------------	----------	-----------	--------------------	-----------

The BMW 7 Series Embodies Luxury That Inspires Driving Dynamics That Enthuse And A Visual Presence That Earns Universal Admiration. It Is A Product Of A Self Assured Design Philosophy And Consistent Y...

Office No. - 62223873

Leo - 96917313

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2019 sgCarMart. All rights reserved.

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 50718
Date Estimated : 03/04/2019
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 8

- ESTIMATE REPAIR FOR -

Dong Yu
87 Jurong West Central 3
#08-48

Singapore 648343

- ACCOUNT - 238

AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGQ3468S	CY84079	25/01/2012	740LiA	0

DESCRIPTION

VALUE

To Replace Frt & rear bumper, frt LH wheel housing, RH side frame, frt LH fender, frt LH door, LH side sill & all attachments cause by accident. To repair on frt bonnet

15300. 17,000.00

Painting on frt & rear bumper, frt LH wheel housing, frt LH fender, Frt LH door, LH side sill, LH rocker panel, LH rear fender, LH A-pillar, B-pillar, C-pillar, bonnet & roof frame

9449. 10,499.00

To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs.

742. 873.00

To remove and install front suspension for inspection and replace damaged parts.

2256. 2,655.00

To check steering geometry and conduct wheel alignment according to BMW specification (1x)

451 531.00

To remove and install power steering pump, power steering rack and pinion to facilitate repairs.

451 531.00

To replace tyre and wheel rim including balancing. (3x).

240 282.00

To replace front windscreen glass.

487 574.00

To conduct water leak tests.

63 75.00

To supply and install front windscreen solar film.

451 531.00

To supply and install IU unit bracket.

✓ 31.00

To replace front dashboard panel and conduct checks for proper function.

677 797.00

To check electrical wiring systems for proper function.

150 177.00

To replace left headlight.

408 481.00

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 50718
Date Estimated : 03/04/2019
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 8

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGQ3468S	CY84079	25/01/2012	740LiA	0

DESCRIPTION

VALUE

To replace both front seat belts and tensioners including reset and checks for proper function.

451 531.00

To replace both rear seat belts and tensioners including reset and checks for proper functions.

451 531.00

To replace roof top headlining and ITS head air bag including reset and checks for proper function.

581 684.00

To replace front dashboard passenger air bag including reset and checks for proper function.

451 531.00

To replace front seat crash-active head restraint air bags including reset and conduct check for function.

451 531.00

To carry out body cavity preservation.
(Per panel) frt LH fender

100 118.00

To carry out body cavity preservation.
(Per panel) frt LH door

100 118.00

To carry out body cavity preservation.
(For cut panel) LH side frame

451 531.00

To tow accident vehicle to PML workshop using winch out.

✓ 350.00

Being charge for custom levy fees.

✓ 350.00

To tow accident vehicle from Malaysia to Singapore custom.

✓ 500.00

Tyre Michelin 275/40/R19 x3

80% 1984-51 2,480.64

Sundries.

✓ 150.00

Total Labour 1: 42,442.64

DESCRIPTION

QTY

PRIC

VALUE

HEXAGON SCREW WITH FLANGE

1 7.65

✓ 7.65

BULB WHITE (H8 12V 35W)

1 31.90

✓ 31.90

Hexagon scre

4 15.65

✓ 62.60

AUXILIARY RADIATOR

1 655.65

✓ 655.65

OIL PAN

1 352.75

✓ 352.75

HEX NUT WITH FLANGE M16X1.5-10 ZNN1

1 9.75

✓ 9.75

FRONT AXLE SUPPORT

1 1,929.90

✓ 1,929.90

LH TENSION STRUT WITH HYDR MOUNT

1 505.20

✓ 505.20

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 50718
Date Estimated : 03/04/2019
Prepared By : Kevin Leong Wai Kit

Page No. : 3 of 8

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGQ3468S	CY84079	25/01/2012	740LiA	0

DESCRIPTION	QTY	PRIC	VALUE
CONTROL ARM CAMBER CORRECTION-30MIN	1	722.45	bt 722.45
LH WISHBONE BOTTOM RUBBER MOUNT	1	606.25	bt 606.25
WHEEL HUB WITH BEARING FRT	1	503.00	bt 503.00
FRT LH KING PIN	1	659.40	de 659.40
FRT GUIDE SUPPORT	1	151.45	de 151.45
SPRING PAD LOWER	1	15.15	de 15.15
SPRING PAD UPPER	1	17.80	bt 17.80
FRONT SWING SUPPORT	1	113.35	bt 113.35
LH TIE ROD	1	361.75	bt 361.75
EXCH. HYDRO STEERING GEAR ACTIVE	1	6,777.65	bt 6,777.65
SET PIPE ZF	1	246.40	bt 246.40
(DG) AIRBAG MODULE DRIVER'S SIDE	1	1,672.00	el 1,672.00
SELF LOCKING COLLAR NUT	2	4.55	el 9.10
HEX BOLT WITH WASHER	1	19.10	el 19.10
DUST CAP	1	6.75	el 6.75
(S/L) REPAIR SET BRAKE CALIPER	1	43.05	mi 43.05
VENTILATION VALVE	1	10.55	mi 10.55
PROTECTION PLATE LH	1	77.50	mi 77.50
FRT LH BRAKE DISC VENTILATED 348X36	1	499.80	mi 499.80
(S/L) CALIPER HOUSING LH	1	754.90	mi 754.90
CLIP	1	38.25	de 38.25
Calliper carrier	1	439.55	mi 439.55
FRT BRAKE PAD	1	465.90	mi 465.90
FRT BRAKE PAD SENSOR	1	56.00	de 56.00
Holder	1	22.10	el 22.10
DSC PULSE GENERATOR FRT	1	208.70	el 208.70
ALLOY RIM 81/2Jx19 MULTISPOKE 235	1	1,219.40	el 1,219.40
ALLOY RIM 91/2Jx19 MULTISPOKE 235	2	1,341.30	el 2,682.60
HEX NUT WITH FLANGE	2	3.10	el 6.20
ACTIVE STABILIZER BAR	1	3,366.85	bt 3,366.85
FRT LH SPRING STRUT	1	1,385.65	bt 1,385.65
FRT LH DOOR	1	2,218.10	bt 2,218.10
FRT LH FENDER	1	1,231.15	bt 1,231.15
ENGINE SUPPORT LH	1	1,186.20	bt 1,186.20
FRT LH WHEELHOUSE	1	2,061.70	bt 2,061.70
Positionieru T-bolt	1	5.65	el 5.65
LH BODY SIDE FRAME	1	3,731.15	bt 3,731.15
LEFT DOOR SILL	1	642.10	bt 642.10
T WELD BOLT L=5.4MM	20	0.85	el 17.00
FRT RH SIDE PANEL BRACKET 1	1	34.25	el 34.25
FRT LH 2 SIDE PANEL BRACKET	1	34.25	el 34.25
SIDE PANEL BRACKET FRT LH 3	1	34.25	el 34.25
LH SIDE PANEL HEADLIGHT HOLDER	1	34.25	el 34.25
SET MOUNTS PDC SENSOR FRT	1	64.85	el 64.85
FRT BUMPER LOWER MOUNT	1	179.40	el 179.40
FRT BUMPER TOP CARRIER	1	830.95	el 830.95
FRT BUMPER GRILLE AIR INLET MIDDLE	1	68.25	el 68.25
FRT BUMPER RH GRILLE AIR INLET OPEN	1	74.85	X 74.85
FRT BUMPER LH MOULDING (CHROME)	1	48.70	el 48.70

Performance Motors Limited

A Sime Darby Motors Company

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 50718
Date Estimated : 03/04/2019
Prepared By : Kevin Leong Wai Kit

Page No. : 4 of 8

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGQ3468S	CY84079	25/01/2012	740LiA	0

DESCRIPTION

QTY

PRIC

VALUE

FRT BUMPER RH MOULDING (CHROME)	1	36.80	36.80
FRT BUMPER TOW HOOK COVER (PRIMED)	1	51.95	51.95
FRT BUMPER LH FLAP COVER (PRIMED)	1	40.80	40.80
FRT BUMPER RH FLAP COVER (PRIMED)	1	51.95	51.95
FRT BUMPER W/SIDE VIEW CAMERA (PDC)	1	1,540.90	1,540.90
DEFORMATION ELEMENT FRT LOWER LH CLAMP	1	123.45	123.45
CLAMP	6	5.50	33.00
CLAMP	10	2.65	26.50
FRT W/SCREEN CLAMP	12	2.40	28.80
CLAMP	8	2.50	20.00
EMBLEM GROMMET	2	0.80	1.60
BMW EMBLEM	1	71.25	71.25
BUMP STOP	12	4.10	49.20
FRT W/SCREEN (HUD)	1	1,784.80	1,784.80
FRT W/SCREEN MOULDING	1	62.55	62.55
FRT LH DOOR WINDOW FRAME CHROME	1	355.40	355.40
COVER COLUMN B DOOR FRONT LH (S/L) FRT DOOR WEATHERSTRIP	1	275.70	275.70
FRT LH DOOR CHANNEL COVER EXTERIOR	1	225.10	225.10
INNER LH WINDOW CHANNEL COVER	1	173.95	173.95
SEAL DOOR GAP FRT BOTTOM	1	118.30	118.30
FRT LH DOOR ROOF SEAM SEAL	1	55.15	55.15
MOULD HEADLINING SLIDING ROOF	1	151.60	151.60
Trim Panel dashboard	1	1,794.65	1,794.65
(S/L) SOUND INSULATION WINDSHIELD	1	1,889.55	1,889.55
FRT LH COVER FOR RR WHEELHOUSE	1	130.50	130.50
FRT LH COVER WHEEL ARCH FRT SECTION	1	139.85	139.85
EXPANDING RIVET	1	139.85	139.85
FRT BUMPER TOP IMPACT ABSORBER	3	0.70	2.10
AIR DUCT BRAKE LH	1	70.45	70.45
AIR DUCT	1	55.95	55.95
COVER BOTTOM LH	1	335.45	335.45
LATERAL UNDERBODY SHIELD LEFT	1	55.95	55.95
RH LATERAL UNDERBODY SHIELD	1	194.70	194.70
ENGINE COMP. SHIELD UNDERRIDE PROT.	1	194.70	194.70
COVERING TANK LEFT	1	202.15	202.15
COVERING TANK RIGHT	1	83.50	83.50
LH AIR CHANNEL	1	83.50	83.50
CENTER UNDERFLOOR COATING	1	55.95	55.95
UNDEFLOOR COATING COVER	1	180.45	180.45
SUPPORT LH	1	34.90	34.90
(S/L) FRT LH DOOR A JOINT GASKET	1	105.60	105.60
SUPPORT LH	1	93.75	93.75
MOUNT STRIP ROCKER PANEL FRT LH	1	8.10	8.10
MOUNT STRIP ROCKER PANEL RR LH	1	17.60	17.60
DOOR SILL COVER PRIMED LH	1	15.50	15.50
LH PROTECTION FOIL	1	528.50	528.50
(D/G) REPAIR KIT HEAD RESTRAINT CRA	1	11.15	11.15
FRT PDC WIRING SET	2	179.20	358.40
	1	132.60	132.60

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 50718
Date Estimated : 03/04/2019
Prepared By : Kevin Leong Wai Kit

Page No. : 5 of 8

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGQ3468S	CY84079	25/01/2012	740LiA	0

DESCRIPTION	QTY	PRIC	VALUE
CABLE SET FRT END	1	265.60	265.60
RAIN LIGHT SOLAR & FOGGING SENSOR	1	372.55	372.55
HEADLIGHT VERTICAL AIM CONTROL	1	169.55	169.55
INSERT DIRECTION INDICATOR LH	1	653.85	653.85
Cover	1	37.35	37.35
SET OF COVER PLATE HEADLIGHT LH	1	39.75	39.75
LH AHL-XENON HEADLIGHT	1	3,376.70	3,376.70
HEADLIGHT BALLAST MODULE XENON LIGH	1	763.70	763.70
CONTROL UNIT XENON LIGHT	1	867.85	867.85
FRT LH SIGNAL LAMP TRIM COVER	1	72.95	72.95
FRT LH FENDER SIGNAL LAMP	1	132.40	132.40
FOG LIGHT LH	1	276.25	276.25
BULB (12V 55W H3)	1	14.95	14.95
BULB XENON LIGHT W/IGNITION ELEMENT	1	381.50	381.50
DECOUPLING RING PDC TORQUE CONVERTE	9	5.05	45.45
BUMPER PDC SENSOR (300 ALPINWEISS)	2	368.80	737.60
SET ADHESIVE PADS FOR ACE 2.0	1	41.15	41.15
rear centre upper belt	1	377.20	377.20
Upper belt	2	290.20	580.40
FRT RH UPPER BELT (SCHWARZ)	1	403.05	403.05
FRT LH UPPER BELT (SCHWARZ)	1	403.05	403.05
(DG) LH HEAD AIRBAG	1	666.60	666.60
(DG) RH HEAD AIRBAG	1	666.60	666.60
(DG) AIRBAG MODULE FOR PASSANGER SIDE	1	1,333.20	1,333.20
(DG) CLEANER R1 (100ML)	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	263.10
(DG/SL) GLASS PRIMER 30ML (VP206)	1	27.85	27.85
(S/L) SEAM SEAL 300ML	1	33.80	33.80

Total Parts : 65,172.90

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
Date&Time 11/4/19 2 1230 Excess S\$ NIL.
Surveyor's Name Tanyin Sign [Signature]
Surveyor's Tel 97495744 Authorised Yes / No

Authorised Date _____ Time Not authorised

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail tanyin@pml.com

No. of Working Days Recommend 30 days

Labour 1	:	42,442.64
Parts	:	65,172.90
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	7,533.09
Grand Total	:	115,148.63

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **