

ASSOCIATION

REF

CS/AIG/9006488/Gcd3^{sr}

Special Instructions

Surveyor
MUNN
From (Per)

ASSIGNMENT (Office)

From (Person)

Chin Lee Ying

40

AIG

Date/Time: 1/4/19 @ 10.35am

Estimated Cost:

1511-02

OD (T) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No. _____

GBF 9818 T

Insured: SJ 28624

at Workshop m/a

1969 S.B. Auto

Tel: 81890680

of

21caki Bukit Ave 2 #01-32

Policy No:

1800001263

Chain No:

087032112286

Sum Insured:

Index

D.O.A 06/04/2019

Make of Veh.

(Client's Record)

CA / REV / REP. / REV 24 HRS

11.3.10. Endorsement

Date/Time:

11:32am @ 11/4/17

Person Contacted:

Ann

Vehicle IN/OUT

Date/Time

[illegible]

4BT-98187-X

94B-98181-X
S9128624-CC3/At618007610/Sub392

DOA: 23/04/2018

Dismantle: 15/4/2019

After repair: 21/6/2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRJ

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Apr 2019 Edit Reg		11 Apr 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main		Reference		Claim Details		Documents		Show All	
CLAIM SUBFOLDER DETAILS								[Created by adjuster]	
Insured:	LEE FARMING JEROME, ID: S6946308H								
Main Claimant:	TONG CHEONG (SOON KEE) TRADING, Co. Reg. No.: 35408800M								
Vehicle Reg. No.:	GBF9818T			Date of Loss:	06/04/2019 11:00 - :59				
Claim Type:	TP / 0870321122SG			Policy/Cover Note No.:					
Vehicle Reg. No. (Insured):	SJJ2862U			Policy No. (Claimant):					
				Excess:					
Repairer:	1969 S B Auto Mac Pte Ltd () 2 Kaki Bukit Ave 2, Autohub #01-32, 417921 Kaki Bukit - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian Meng] kianmeng.chan@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 23/04/2019]								
Claimant's Solicitor:	MATHEW CHEW & CHELLIAH - Tel: 65331123								
ASSOCIATED MAIL RECEIVED								View All Compose Case Mail	
<ul style="list-style-type: none"> AIG_SG (12/04/2019): Request To Upload TP GIA Report AIG_SG (12/04/2019): No OI GIA REPORT 									
ALL ASSOCIATED TASKS								View All Search Tasks Create New Task Complete	
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJJ2862U A...

From: Chin, Lee-Ying
To: assignments, admin-a@lkkauto.com
Cc: Fong, Andy-SY, Fan, Winnie-LW
Sent: 11/4/2019 10:35:43 AM
Attachments:  SAS-Client.pdf

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

From: Lalita-MCC [mailto:lalita@mccllegalfirm.com]
Sent: Tuesday, April 09, 2019 3:39 PM
To: Tan, Bennie-WZ
Cc: Sung Beng-Anne
Subject: [EXTERNAL] Our Ref LC/5331/19/TCT1(S2)N. //// Your Ref SJJ 2862U

Caution: External Email

Our Ref LC/5331/19/TCT1(S2)N
Your Ref SJJ 2862U

9 April 2019

AIG ASIA PACIFIC INSURANCE PTE LTD
(INSURER OF SJJ 2862U)

BY EMAIL & FAX (64153727)

Dear Sirs

NOTICE FOR PRE-REPAIR INSPECTION
CLAIMANT: TONG CHEONG (SOON KEE) TRADING
ACCIDENT INVOLVING GBF 9818T AND SJJ 2862U ALONG THE CAR PARK
AT BLK 18 JOO SENG ROAD, SINGAPORE ON 6/4/19 AT 1115 HOURS

We act for TONG CHEONG (SOON KEE) TRADING.

We are instructed by our client to notify you of a road traffic accident on the above date and time and place involving our client's motor-vehicle **GBF 9818T** and your insured motor-vehicle **SJJ 2862U**. A copy of our client's Singapore Accident Statement is enclosed.

As a result of the accident, our client's motor-vehicle has been damaged. Before our client proceeds to repair the damaged motor-vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey to our client's vehicle. Inspection may be carried out at the following address:-

Venue: 1969 S B Auto Mac Pte Ltd
2 Kaki Bukit Ave 2,
Autohub #01-32
Singapore 417921

Kindly confirm the date and time as well as the name of the surveyor who will be carrying out the inspection. You may contact the workshop at:

Contact Person: Frankie
Telephone no: 81890680

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the motor-vehicle without further reference to you.

Yours faithfully

Cc 1969 S B Auto Mac Pte Ltd - by email

Acknowledgment by surveyor

Signature
Name

Date

Yours faithfully

Ms Lalita Chelliah

Partner

MATHEW CHEW & CHELLIAH

133 New Bridge Road

#13-10 Chinatown Point

Singapore 059413

UEN No: 53131184L

Tel: +65 6533 1123 Fax: +65 6533 1121 Email: lawyers@mcclegalfirm.com

CONFIDENTIALITY: This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by return email and delete the original message.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/04/2019 12:54
Date Of Accident	06/04/2019 11:15
Exact Location Of Accident	BLK 18 JOO SENG ROAD OPEN CP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF9818T
Insured/Policyholder	
Name Of Registered Owner	TONG CHEONG (SOON KEE) TRADING
Co Reg No	35408800M
Email Address	VICTORTCLEOW@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97541183
Alternative Phone No	OFFICE-63381711

Vehicle Particulars

Manufacturer	TOYOTA
Model	PROACE
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5090986927-01
Cover Note Number	

Driver

Name of Driver	LEOW TET CHEE
NRIC No	S0094192A
Date Of Birth	25/12/1950
Occupation	OUTDOOR
Date Of Driving Pass	16/06/1969
Driving Experience	49 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97541183
Fax Number	
Contact Number	
EMail Address	VICTORTCLEOW@GMAIL.COM

Address	APT BLK 18 JOO SENG ROAD #10-155 S360018
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE SIZE IS TOO LARGE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJJ2862U
Vehicle Make/Model/Colour	RED
Details Of Properties	NIL
Vehicle Category	PRIVATE CAR
Name of Driver	LEE FARMING JEROME
NRIC/Passport Number	S6946308H
Contact Number	
Address	NIL
	NIL
Postcode	NIL
Insurance Company Name	
Nature Of Damage	NIL
No. Of Passenger (Including Driver)	1

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

06 Apr 2019
@ 1300 hr

SKETCH PLAN

Refer to the Attached

INSURER:	HTUL
VEHICLE:	GBF9818T
DOA:	6/4/2019
CLAIM TYPE:	Third Party
WORKSHOP:	Sung Beng Motor

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____

Date & Times:

Driver's Signature
(If driver is not the policyholder)

Date & Time: 06 Apr 2019
@ 1300hr

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Accident Sketch Plan Pg. 1

Accident Date: 6 April 2019 Time about 11am to 11:15am

Vehicle B driver Mr Lee steer his steering wheel to the left while reversing and hit my left rear while I stop my vehicle knowing that it is very cramp to move.

I lodge this report to claim Third Party.


Video Attached

STAMP (車 牌) : ...
SUNG (SOON KEE) TRADING
No 100 Bencoolen St
Singapore 169048
Tel: 6733 1830

[Signature]

6/4/2019
@ 1300hr.

Carpark
Blk 18
Zoo Lang Road



S0094192A
A - GBF 9818T MR Lee
B - SJJ 28624 MR Lee (Jerome)
S6946308H

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	8800M
Vehicle Details	
Vehicle No.:	GBF9818T
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PROACE 1.6 MANUAL
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	BH020006959
Chassis No.:	YARVBBHVBGZ058628
Maximum Power Output:	-
Open Market Value:	\$31,537.00
Original Registration Date:	19 May 2017
First Registration Date:	19 May 2017
Transfer Count:	0
Actual ARF Paid:	\$1,577.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	18 May 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$26,029.00
COE Rebate Amount:	\$21,082.00
Total Rebate Amount:	\$21,082.00

The information contained herein is correct as at 12 Apr 2019

OK

GBF 9818T

Rear Bumper / Cut.

" " Side Retainer LH / ee.

" " clips / me

Rear Body Panel x Repair.

Sliding Door LH / Buc

" " " Protector / SCR

Rocker Panel LH x Repair.

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Apr 2019 Edit Reg		11 Apr 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	LEE FARMING JEROME, ID: S6946308H		
Main Claimant:	TONG CHEONG (SOON KEE) TRADING, Co. Reg. No.: 35408800M		
Vehicle Reg. No.:	GBF9818T	Date of Loss:	06/04/2019 08:00 - :59 [22 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 0870321122SG	Policy/Cover Note No.:	1800001263 (Comprehensive)
Vehicle Reg. No. (Insured):	SJJ2862U	Policy No. (Claimant):	
		Excess:	
Repairer:	1969 S B Auto Mac Pte Ltd () 2 Kaki Bukit Ave 2, Autohub #01-32, 417921 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian Meng] kianmeng.chan@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 23/04/2019]		
Claimant's Solicitor:	MATHEW CHEW & CHELLIAH - Tel: 65331123		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (12/04/2019): Request To Upload TP GIA Report
- AIG_SG (12/04/2019): No OI GIA REPORT

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBF9818T (0870321122SG)
[SJJ2862U]**

TP



























TONG CHEONG (SOON KEE) TRADING

Apr 6 2019 8:25AM

[LEE FARMING JEROME]

1969 S B Auto Mac Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser ▼	
Photos/Images															3 per page ▼		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print	
1	12/04/19 10:36	Odometer Reading														Load JPG	<input checked="" type="checkbox"/>	
2	12/04/19 10:36	Chassis Number														Load JPG	<input checked="" type="checkbox"/>	
3	12/04/19 10:37	General View														Load JPG	<input checked="" type="checkbox"/>	
4	12/04/19 10:37	General View														Load JPG	<input checked="" type="checkbox"/>	
5	12/04/19 10:37	General View														Load JPG	<input checked="" type="checkbox"/>	
6	12/04/19 10:37	General View														Load JPG	<input checked="" type="checkbox"/>	
7	12/04/19 10:37	General View														Load JPG	<input checked="" type="checkbox"/>	
8	12/04/19 10:37	General View														Load JPG	<input checked="" type="checkbox"/>	
9	12/04/19 10:37	General View														Load JPG	<input checked="" type="checkbox"/>	
10	12/04/19 10:37	General View														Load JPG	<input checked="" type="checkbox"/>	
11	12/04/19 10:37	General View														Load JPG	<input checked="" type="checkbox"/>	
12	12/04/19 10:37	General View														Load JPG	<input checked="" type="checkbox"/>	
13	12/04/19 10:37	General View														Load JPG	<input checked="" type="checkbox"/>	
14	12/04/19 10:37	General View														Load JPG	<input checked="" type="checkbox"/>	
15	12/04/19 10:37	General View														Load JPG	<input checked="" type="checkbox"/>	
16	12/04/19 10:37	General View														Load JPG	<input checked="" type="checkbox"/>	
17	12/04/19 10:37	General View														Load JPG	<input checked="" type="checkbox"/>	
18	12/04/19 10:37	General View														Load JPG	<input checked="" type="checkbox"/>	
19	12/04/19 10:37	General View														Load JPG	<input checked="" type="checkbox"/>	
20	12/04/19 10:37	General View														Load JPG	<input checked="" type="checkbox"/>	
21	12/04/19 10:37	General View														Load JPG	<input checked="" type="checkbox"/>	
22	19/06/19 12:09	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
23	19/06/19 12:09	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
24	19/06/19 12:09	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
25	19/06/19 12:09	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
26	19/06/19 12:09	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
27	19/06/19 12:09	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
28	19/06/19 12:09	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
29	19/06/19 12:09	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
30	19/06/19 12:09	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
31	19/06/19 12:09	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
32	19/06/19 12:09	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
33	19/06/19 12:09	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
34	19/06/19 12:09	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
35	19/06/19 12:09	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	19/06/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	19/06/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	19/06/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	19/06/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	19/06/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	19/06/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	19/06/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	19/06/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	19/06/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	19/06/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	19/06/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	19/06/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	19/06/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	19/06/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	19/06/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	19/06/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	19/06/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	19/06/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	19/06/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	19/06/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	03/09/19 09:08	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
57	03/09/19 09:08	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
58	03/09/19 09:08	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
59	03/09/19 09:08	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
60	03/09/19 09:08	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
61	03/09/19 09:08	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	03/09/19 09:08	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19006488/GCD3S2

Date: 03/09/2019

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800001263
Claimant Vehicle No :	GBF9818T	Insured Vehicle No :	SJJ2862U
Date of Loss:	06/04/2019	Nature of Claim:	TP
		Claim No:	0870321122SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF9818T		
Make & Model:	TOYOTA PROACE, 1.6 (A)	Engine No:	BH020006959
Reg. Date:	19/05/2017 (Man. Year: 2016)	Chassis No:	YARVBBHVBGZ058628
Colour:	Silver	Odometer:	74143 km
Engine Capacity:	1560 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/65 R16	Rear Tyre Size:	215/65 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	11/04/2019	
Date Inspected:	11/04/2019	Inspected At: 1969 S B Auto Mac Pte Ltd 2 Kaki Bukit Ave 2, Autohub #01-32 Singapore 417921
Estimated Period of Repair:	4.0 days	

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	0.00 F	*- F
2	1		*REAR BUMPER SIDE RETAINER LH	Deformed	0.00 F	*- F
3	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	1		*REAR BODY PANEL	Repair	0.00 F	*- F
5	1		*SLIDING DOOR LH	Buckled	0.00 F	*- F
6	1		*SLIDING DOOR LH PROTECTOR	Scratched	0.00 F	*- F
7	1		*ROCKER PANEL LH	Repair	0.00 F	*- F
				Total Parts (S\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >