



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19006513/Kga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 10-12-2020



ATTN: CYNTHIA LOH

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKH 9145J	Veh. Inspected	SLG 7460E
Policy No.	P1580292	Coverage (\$)	0.00
Claim No.	S9M01JUM	Excess (\$)	0.00
Assign From		Assign Date	11/04/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA WISH (A)	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	ZGE206030605	Colour	METALLIC GREY
Odometer	113432	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/50Z R17	KUMHO	8 mm
L/H Front Tyre	215/50Z R17	KUMHO	8 mm
R/H Rear Tyre	215/50Z R17	KUMHO	8 mm
L/H Rear Tyre	215/50Z R17	KUMHO	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	09/04/2019	Inspection Date	11/04/2019
Survey held at	K KIM HIN AUTO PTE LTD BLK 34 SIN MING DRIVE, #01-114, SINGAPORE 575708		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------