

ASS. REC. BY: CWS REP: CS/FCI18013647/G-103 Special Services

Surveyor: Steve ASSIGNMENT (Office): FCI

From (Person): Lerrone Jew Date/Time: 26/7/18 @ 11:26am

Estimated Cost: _____ Bill to: _____

OD ☒ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGW 3221E Insured: SHA 9930G

at Workshop in/ of: Cycle & Camiaeye Kia Tel: 9181 9978

209 Ponden Gardens

Policy No: _____ Claim No: D1800 5648 MF8H

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A: 21/07/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS Cup H.O.D. Endorsement: _____

Date/Time: 11:26am @ 26/7/18 Person Contacted: Edwin Vehicle IN ☒ OUT

Date/Time	Action/Instruction (✓)	Estimate	11/10/18 - Vehicle not in	20/12/18 - VNI temporary Ula
	SGW 3221E - x	2/11/18 - vni		case - Reverted through on
	SHA 9930G - x	8/11/18 - vehicle still not in		Celise 24/12/18
27/7/18 -	called Edwin vehicle not in	13/12/18 - still vehicle not in yet	} Mr. Jay	
30/7/18 -	called Edwin still not in	15/12/18 - still vehicle not in yet		
2/8/18 -	vehicle not in yet	17/12/18 - called Mr. Jay around VNI.		
6/8/18 -	vehicle not in	7/1/18 - VNI (Edwin)		
19/11/18 -	VNI yet check liability (edwin)	11/1/18 - vehicle still not in (edwin)		

12/4/19 @ 4:38pm - revised preli advise. via email

confirm.

3/5. Part by Part \$2434 (Red. 3267; 57%)

4 days

RECEIVED 03 MAY 2019

140
90
73
213

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s: _____

of _____

Insured _____

Policy No _____

Claims No _____

Sum Insured _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No

SW 3221 E

Yr Regn.

24/03/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

KIA Forte K3

CC

1591

Colour

Blue

A/C

Insured / Std / NI / NA

Sp. Reading

55218

T/Ratio: Insured / Std / NI / NA

Eng/No:

C/No:

KNAF 2411 MHS676531

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

215/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

21/7/18

D.O.A.

11/4/19

Survey held at

C d C

Des. of Damages: Frl / Rear / O/S / N/S / UIC / Rooftop or

Front RH

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time / Action / Instruction

Date/Time. File Pass to?

☐

: Procl. Report

4)

☐

: Final Report

Date/Time. File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) S + R: 0

) Photos

) Collect

Report Format :

Lump Sum / I.B.I. (\$) :

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

10/1/17

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Friday, 12 April 2019 4:38 PM
To: Admin-D (LKKAUTO); 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005648MFSH/1
Attachments: PRELI ADVISED SGW 3221E.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SGW 3221E**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 20 December 2018 2:35 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005648MFSH/1

Dear Sir/Mdm,

Please be informed that we are unable to conduct the inspection after some attempts to inform the workshop to present the vehicle.

This case has been pending for a long time due to the unavailability of the owner, therefore we decided to temporarily close this case.

Kindly advise us if there is any arrangement made and will be glad to re-open the case accordingly.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)





Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005648MFSH

Date: 12/4/2019

Our Ref: CS/FCI18013647/Etd3-1

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SGW 3221E

Please be informed that we had conducted the inspection of the abovementioned vehicle 11/4/2019 at the premises of M/s Cycle & Carriage have the following to report: -

Workshop Estimate Amount	: S\$	<u>5,701.00</u>
Revised Estimate Amount	: S\$	<u>2,402.00</u>
"Check" Items Amount	: S\$	<u>312.00</u>
Market Value	: S\$	<u> </u>
LTA Reimbursement Value	: S\$	<u> </u>
Nett Value	: S\$	<u> </u>

Description of Damage:
The vehicle sustained damages at the
Front RH portion.



Comments/ Present Status:
Damages Consistent.

Yours faithfully
Steve
Automotive Assessor

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5980D
Vehicle Details	
Vehicle No.:	SGW3221E
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Apr 2019
Vehicle Make:	KIA
Vehicle Model:	FORTE K3 1.6A
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	G4FGGH653887
Chassis No.:	KNAFZ411MH5676531
Maximum Power Output:	95.3 kW (127 bhp)
Open Market Value:	\$17,666.00
Original Registration Date:	24 Mar 2017
First Registration Date:	24 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$17,666.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Mar 2027
PARF Rebate Amount:	\$13,249.00
Intended COE Rebate Details	
COE Expiry Date:	23 Mar 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,789.00
COE Rebate Amount:	\$40,371.00
Total Rebate Amount:	\$53,620.00

The information contained herein is correct as at 11 Apr 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/07/2018 16:52
Date Of Accident	21/07/2018 20:35
Exact Location Of Accident	BLK 339 BUKIT BATOK ST 34 S(650339) CAR PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGW3221E
Insured/Policyholder	
Name Of Registered Owner:	LIM JIN YANG
NRIC No	S8705980D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98441384
Alternative Phone No	OTHERS-98441384

Vehicle Particulars

Manufacturer	KIA
Model	FORTE K3-1.6 SX (A)
Exact Purpose for which vehicle was being used at time of accident	PARKED
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100505217-01
Cover Note Number	

Driver

Name of Driver	LIM JIN YANG
NRIC No	S8705980D
Date Of Birth	28/02/1987
Occupation	INDOOR
Date Of Driving Pass	16/09/2005
Driving Experience	12 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98441384
Fax Number	
Contact Number	OTHERS-98441384
Email Address	NOEMAIL

Address	318B YISHUN AVENUE 9 #12-138 SINGAPORE
Postcode	762318
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	YISHUN NORTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 31 YISHUN CENTRAL, POSTCODE: 768827, COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8529999 - FAX NO: 68522299
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT AIG ONLINE REPORT: WSV18001094

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA9930G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to facilitate delivery of the same as well as on the external cover of envelopes/mail packages); and
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by or to all Insurers and/or their third party service providers or agents (including their lawyers/law firms), which may be disclosed for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be used / disclosed:
 - (i) to all insurers and/or any other third parties that assist in investigating, handling, settling, controlling or managing fraud, regulators, law enforcement and government agencies;
 - (ii) for complying with requirements under any regulatory requirements.

Policyholder's Signature

Date & Time:

24/7 1640

Driver's Signature


(If driver is not the policyholder)

Date & Time:

Police/Insurance Personnel's Signature

Date & Time:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 24/7 1640

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Date & Time:



SINGAPORE POLICE FORCE



T/20180723/2179

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

1 of 3

Report No. T/20180723/2179

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 23/07/2018 22:11		Vide Report No.:		Station Diary No.: 142	
Informant's Particulars					
Name of Informant: LIM JIN YANG			Address: APT BLK 318B YISHUN AVENUE 9 #12-138 SINGAPORE 762318		
ID Type / ID No.: NRIC NO / S8705980D			Contact No.: Home/Office: Mobile: 98441384		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 31	Date of Birth: 28/02/1987	Type of Informant: Vehicle Owner		
Race: Chinese			Language:		Institution / School Name:
Occupation: Technician			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident					
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 22/07/2018 20:30	Type of Location: Car Park	
Location: Along Road 1 BUKIT BATOK STREET 34			21/07/2018		
Blk 339 Bukit Batok Street 34 open space carpark					
Weather: Clear	Road Surface: Dry		Road Speed Limit: 60/2 200		
Traffic Flow: Two Way	Traffic Control: Not Controlled		Traffic Volume: Light		
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SGW3221E	Car	KIA		Blue		0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20180723/2179

2 of 3

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

Report No. T/20180723/2179

CONTINUATION OF REPORT

Vehicle Owner			
Name	LIM JIN YANG	ID No.	S8705980D
Related Vehicle	SGW3221E (Car)	Contact No.	98441384
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 21/07/2018 at around 2015hrs , I parked my vehicle at Blk 339 Bukit Batok open space carpark unknown carpark lot no and everything was normal and intact before I left my car. at around 2040hrs , I went back to my car but I did not check if there was any damage on my car. On the 22/07/2018 at night , I checked my car and realized that there was damage on the front right bumper of my car. I suspect it was hit by another car and as such I retrieve the footage from my car in built camera and it was revealed on the 21/07/2018 at around 2033hrs , one Taxi bearing vehicle no 9930G had collided into the front right bumper of my car while reversing and moved off without leaving behind any note with his particulars. From the footage , I could not make out the first 3 alphabets of the vehicle numbers as it was quite dark but I could see 9930G in the footage and I believe the car is a Taxi.



**SINGAPORE
POLICE FORCE**



T/20180723/2179

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

3 of 3

Report No. T/20180723/2179

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:
F /
Staff Sgt ZENG ZHIMIN, KEVIN

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / HRT /
Sr Staff Sgt TAN JEOK LENG
Contact No.: 65476144

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
23/07/2018 22:11

Classification Of Case:



CERTIFICATE OF INSURANCE

KIA AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Lim Jin Yang
 Period of Insurance : 24 Mar 2018 To 23 Mar 2019
 Engine No. : G4FGGH653887
 Chassis No. : KNAFZ411MH5676531

Vehicle No. : SGW3221E
 Policy No. : 2100505217-01
 Endorsement No. :
 Issued Date : 23 Feb 2018

ABOUT THE COVER

Make/Model : KIA FORTE K3 1.6 A SX
 Engine Capacity/Tonnage : 1,591.00 CC
 Driver Restriction : NA
 Sum Insured : Market Value
 Off Peak Car : No
 First Year of Registration : 2017
 Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.
 You have to pay an additional sum of \$3,000 as 'Young and/or Inexperienced Driver Excess' ('YIDR') if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1600cc - 1600cc

* Limitations rendered inoperative by Section 5 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 163) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Lim Jin Yang - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65884501
2. Cycle & Carriage Customer Service Centre (For Windscreen claim only) Add: 241 Alexandra Road Singapore 199931 64276900
3. Cycle & Carriage Customer Service Centre (For windscreen claim only) Add: 330 Ulu Rd 3 Singapore 408950 67484000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 163), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1958 (Malaysia).

0500709295

CYCLE & CARRIAGE - MIMILE(QA)

239 ALEXANDRA ROAD

SINGAPORE 159930 ANSP - MOTOR

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Mimile

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

642642

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: **S8705980D**

Name
LIM JIN YANG

Birth Date: **28 Feb 1987**
Issue Date: **16 Sep 2005**

1001368980D

FOR C&C USE ONLY

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S8705980D**



Name

LIM JIN YANG

林 锦 杨

Race

CHINESE

Date of birth

28-02-1987

Country/Place of birth

SINGAPORE

Sex

M

5708243

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor cars < 3000 kg with < 7 passengers, exclusive of the driver, and motor tractors / vehicle's < 2500 kg

PASS DATE
16 Sep 2005



Serial No. **S8705980D**




Date of issue

01-03-2017

Address

**APT BLK 318B YISHUN AVENUE 9
#12-13B
SINGAPORE 762318**

NP 428A



License No: **S8705980D**

FOR C&C USE ONLY



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Lim Jin Yang	Cust No/Name /Lim Jin Yang
Blk 318B Yishun Avenue 9	Reg No/Reg Date SGW3221E / 24/03/201
#12-138	Date In/Mileage / 0
Singapore 762318	Chassis No KNAFZ411MH5676531
Contact No Mobile: 98441384	Engine No G4FGGH653887
	Make/Model KIA/FORTE K3 1.6 A SX HADQ
	Colour/Trim D7U PLANET BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	28/03/2019/ 11:39	QUE	261 / Edwin Caina	47286			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								550 1650.00
RENEW & RE-ALIGN FRT DAMAGED PORTION:								
-RENEW FRT BUMPER								
-REPAIR FRT FENDER RH								
E PNT98000								840 1000.00
RESPRAY FRT BUMPER & FRT FENDER RH								
A 54900099								50.00
CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM								
A 10028901								200.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
M SUNDRY								X? 300.00
APPLY PAINT PROTECTION ON AFFECTED AREAS								
E PNT88000								80 100.00
REMOVE & REFIT FRT PARKING SENSOR								
M SUNDRY								20.00
Sundries								
P	COVER-FR BUMPER	/ CUT			1.00	633.00	00.00	633.00
M	STRIP ASSY-FR BUMPER UPR	/ ALC			1.00	29.00	00.00	29.00
M	BRACKET-FR BUMPER SIDE MTG,RH				1.00	12.00	00.00	12.00
M	LAMP ASSY-HEAD,RH	X	NN		1.00	1707.00	00.00	1707.00

Estimate

12/4/19.

Steve (LKK)

4 days

11/4/19 3:15pm

P/P, Resurvey before spray with primer

SURVEYOR NAME: Steve (LKK)

SURVEYOR SIGNATURE: 4 days

DATE: 11/4/19 3:15pm

REMARKS: P/P, Resurvey before spray with pre-judge

Confirm & accepted by: hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

7% GST on 5701.00 399.07

Nett 5,701.00

Total Payable 6,100.07

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



LKK
Steve

VEHICLE NO : SGW3221E

MODEL : KIA/FORTE K3 1.6 A SX

WIP : 47286

Material	:	\$	<u>694.00</u>
Labour	:	\$	<u>1,740.00</u>
Sub-Total	:	\$	<u>2,434.00</u>
Less 2% Disc	:	\$	<u>-</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>2,434.00</u>
GST 7%	:	\$	<u>170.38</u>
Grand Total	:	\$	<u>2,604.38</u>
Finalise By/Date : <u>Unny ON 27/04/19</u>			


☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 4 WORKING DAYS + 2 days (week end)

* TP vehicle no: SHA9930G

* claim loss of RENTAL.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-6500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Lim Jin Yang	Cust No/Name /Lim Jin Yang
Blk 318B Yishun Avenue 9	Reg No/Reg Date SGW3221E / 24/03/2017
#12-138	Date In/Mileage 11/04/2019/ 55218
Singapore 762318	Chassis/Package KNAFZ411MH5676531 /KC17
Contact No Mobile: 98441384	Engine No G4FGGH653887
11/04/	Make/Model KIA/FORTE K3 1.6 A SX HADQ
	Colour/Trim D7U PLANET BLUE / WK SATURN BLACK


Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	27/04/2019/ 14:55	TLE	884 / Lauro Songcuan	47286

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW & REALIGN FRONT DAMAGED PORTION: RENEW FRONT BUMPER, REPAIR FRONT FENDER RH				550.00 ✓
E PNT98000 RESpray FRT BUMPER & FRT FENDER RH				840.00 ✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				50.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				200.00 ✓
E PNT88000 REMOVE & REFIT FRONT PARKING SENSOR				80.00 ✓
M SUNDRY SUNDRIES				20.00 ✓
X COVER-FR BUMPER ✓	1.00	633.00	00.00	633.00 ✓
X STRIP ASSY-FR BUMPER UPR ✓	1.00	29.00	00.00	29.00 ✓
X ORNAMENT-KIA NO.115 → <i>supp.</i>	1.00	32.00	00.00	32.00 ✓
Z TEXT TP CLAIM - FIRST CAPITAL SURVEYOR: STEVE (LKK) 11.04.2019 DOA: 21.07.2018 04 DAYS				

Cycle & Carriage celebrates 120 years.
Visit www.cyclecarriage.com/120 for more info!

Parts	694.00	Nett	2,434.00
Labour	1,720.00	7% GST on	170.38
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00	Total Payable	2,604.38
Sundry/Others	20.00		
Total (w/o GST)	2,434.00		

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO.: FIRST CAPITAL

Supplementary For Registration No.: SGW 3221 E

Materials

1 (3) Ornament- KIA No. 115

/ MEC

Cost (\$)

32.00

2.24

7% GST

Total

34.24

Thank You.

Yours faithfully
CYCLE & CARRIAGE KIA PTE LTD

LARRY SONGCUAN
CUSTOMER SERVICE
TEL: 6568 4658
FAX : 6567 5258

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18013647/Etd3e2-1

36 ROBINSON ROAD

#16-01 CITY HOUSESINGAPORE 068877

Date : 06-05-2019



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 9930G	Veh. Inspected	SGW 3221E
Policy No.		Coverage (\$)	0.00
Claim No.	D18005648MFSH	Excess (\$)	0.00
Assign From	LURENE JAW	Assign Date	26/07/2018

2. Vehicle Particulars & Condition

Make & Model	KIA FORTE K3	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KNAFZ411MH5676531	Colour	BLUE
Odometer	55218	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/45 R17	DUNLOP	7 mm
L/H Front Tyre	215/45 R17	DUNLOP	7 mm
R/H Rear Tyre	215/45 R17	DUNLOP	7 mm
L/H Rear Tyre	215/45 R17	DUNLOP	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/07/2018	Inspection Date	11/04/2019
Survey held at	CYCLE & CARRIAGE KIA PTE LTD 209 PANDAN GARDENS SINGAPORE 609339		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGW 3221E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRIES (SN)	NECESSARY	20.00	20.00
1	COVER-FR BUMPER (SN)	CUT	633.00	633.00
1	STRIP ASSY-FR BUMPER UPR (SN)	NECESSARY	29.00	29.00
1	BRACKET-FR BUMPER SIDE MTG, RH (SN)	NOT NECESSARY	12.00	-
1	LAMP ASSY-HEAD, RH (SN)	NOT NECESSARY	1,707.00	-
1	ORNAMENT-KIA NO.115 (SN) (ADDITIONAL)	NECESSARY	32.00	32.00
LABOUR			2,433.00	714.00
RENEW & RE-ALIGN FRT DAMAGED PORTION :				
-RENEW FRT BUMPER.			1,650.00	550.00
-REPAIR FRT FENDER RH.				
RESPRAY FRT BUMPER & FRT FENDER RH.				
CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM.			1,000.00	840.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.			50.00	50.00
APPLY PAINT PROTECTION ON AFFECTED AREAS.			200.00	200.00
REMOVE & REFIT FRT PARKING SENSOR.		NOT NECESSARY	300.00	-
			100.00	80.00
GRAND TOTAL			3,300.00	1,720.00
			5,733.00	2,434.00
RECOMMENDED COST OF REPAIRS				2,434.00

Report Ref No. CS/FCI18013647/Etd3e2-1

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.