

INS. CASE OWNER:

CC 5, EOL 1900 6842, KIPK

LKK:
IDAC:

Surveyor:

Amc

DOI:

ASSIGNMENT

11-4-19

Date / Time:

11-4-19

Registered in Merimen:

Pre-assign / CCU / FTE

SLJ 8402B



Insured Vehicle No. :

Name of Insured :

Insured Tel No. :

HP:

Excess Sec II :SS

D.O.A : 10/4/19

Is driver the owner? (YES / NO)

Nature of Accident :

If NO, Driver Name / Age :


Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SAC 1994P



INSRS:

WSP: C065107ay

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time

SAC 1994P - C065107ay 29/10/19
SLJ 8402B. x

STAGE DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No. :

If NO or B 28, Ass. Lia :

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

OMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701

Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508969

383 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 609286

320 Ubi Road 3 Singapore 406608

24 Senoko Loop Singapore 758158

7 Sungei Kadut Way Singapore 728791

501 Yishun Industrial Park A Singapore 768732

Date/Time: 11.04.2019 10:58

Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD

Sales Order: 3913777

JC NO.: 305286402

OMER

S COMFORT TRANSPORTATION PTE LTD
OMER NO. 7010045
ESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)


JUNT CARD NO.

REGN NO.: SHC1994P	MILEAGE
MAKE : HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G2)	DATE/TIME IN 11.04.2019 09:10
YR OF MANU 08.10.2018	TARGET DATE
CHASSIS CODE KMHC851CVKU114798	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 10.04.2019
NATURE: 3P 10.04.19

S/NO	LABOR CODE	DESCRIPTION
000060	PB	PANEL BEATING
000070	SP	SPRAYPAINT CHARGE
000080	L	R/I REVERSE SENSOR



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

No.: SHC1994P LIMITS

Vehicle No.: SHC1994P

Service Advisor

Signature/Date

Name of Service Advisor

Date

COMFORTDELGRO ENGINEERING PTE LTD

Date: 11.04.2019

Time: 10:58:07

REPAIR ESTIMATE

Page: 1

EQ Ins (P/P)

12 TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305286402
 REGN NO : SHC1994P
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 08.10.2018
 DATE/TIME IN : 11.04.2019 09:10
 ACCIDENT DATE : 10.04.2019

LKK - Kalvin

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	REAR BUMPER	1	459.40	20.00	367.52	✓
0002	04-01-0104-2533-G	REAR BUMPER CENTRE-BLACK	1	322.30	20.00	257.84	✓
0003	04-01-0104-0851-G	REAR BUMPER REFLECTOR LH	1	30.50	20.00	24.40	X
0004	09-01-9999-0068-A	REVERSE SENSOR	1	135.70		135.70	✓
0005	04-01-0104-1150-A	REAR BUMPER MAT	1	50.00		50.00	✓

Towing Cover

SUB-TOTAL : 835.46

JOB NATURE

Per Mmbr plate \$25
 Rear Bumper Reinforcement

0000	PB	PANEL BEATING				280.00 200
0001	SP	SPRAYPAINT CHARGE				250.00 200
0002	L	R/I REVERSE SENSOR				120.00 30

SUB-TOTAL : 650.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

EQ Ins (P/P)
LKK - kalvin

Date: 11.04.2019

Time: 10:58:07

Page: 2

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305286402
REGN NO : SHC1994P
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 08.10.2018
DATE/TIME IN : 11.04.2019 09:10
ACCIDENT DATE : 10.04.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

Lmkf

TOTAL : 1,485.46

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Kalvin 11/4/19

11/4/19 11/10/19

2 Drgs

P/P

Before Part photo

LKK Auto Co. warrants that the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Our Job Ref No : 305286402

Date : 15/04/19

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN ANG


Vehicle Reg No. : SHC1994P

Date of Accident : 10-Apr-19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: EQ INSURANCE --- SLJ8402B
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$1,219.10
 - (b) Labour Charges \$430.00
 - Total for Part-By-Part Repair Cost** \$1,649.10
 - (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% _____
Final Lumpsum Repair cost _____
3. Estimated normal period for repairs: 2 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : LIM T S

Tel : 62148398

Fax : 65468156

Signature : 

Name : KALVIN

Date : 15/4/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees	-----			
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

Date: 12.04.2019

REPAIR ESTIMATE

Time: 17:46:52

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305286402
REGN NO : SHC1994P
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 08.10.2018
DATE/TIME IN : 11.04.2019 09:10
ACCIDENT DATE : 10.04.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	REAR BUMPER	1	459.40	20.00	367.52
0002	04-01-0104-2533-G	REAR BUMPER CENTRE-BLACK	1	322.30	20.00	257.84
0003	04-01-0104-2544-G	REAR BUMPER TOW COVER*	1	5.40	20.00	4.32
0004	09-01-9999-0068-A	REVERSE SENSOR	1	135.70		135.70
0005	04-01-0104-1150-A	REAR BUMPER MAT	1	50.00		50.00
0006	FNPS	NO PLATE(S)*	1 N	25.00		25.00
0007	04-01-0104-2288-G	REAR BUMPER REINFORCEMENT*	1	294.80	20.00	235.84
0008	04-01-0104-3819-G	REAR BUMPER REIN-BRKT LH*	1	138.10	20.00	110.48
0009	09-01-0104-2133-G	ANTENNA ASSY-SMARTKEY*	1	40.50	20.00	32.40

SUB-TOTAL : 1,219.10

JOB NATURE

0000	PB	PANEL BEATING	200.00
0001	SP	SPRAYPAINT CHARGE	200.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305286402
REGN NO : SHC1994P
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 08.10.2018
DATE/TIME IN : 11.04.2019 09:10
ACCIDENT DATE : 10.04.2019

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0002 L R/I REVERSE SENSOR	30.00				

SUB-TOTAL : 430.00

TOTAL : 1,649.10


MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :