

<<

Service Request Details

Claim

S8M011OF

Reference

CS3/ASM18020119/Gga3s2-1



Loss Date

November 2, 2018

Report Date

Nov 7, 2018 10:07:00 AM

Request Date

November 20, 2018

Due Date

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Wait for: Approve invoice

Add Invoice

Vehicle Information

Incident Vehicle

SLA8883T

Registration #

Make

TPVD MERCEDES-BENZ

Model

GLA

Service Address

Primary Contact/Insured

TAN HWEE LIN DAPHNE
BLK 99A LORONG 2 TOA PAYOH, #14-39,
310099, Singapore
90094818

Claim Handler

CHEN Xinyou

chen.xinyou@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

+

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKKInvoice1[1] AC1811864 (PRS).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	March 26, 2020
 LKKInvoice1[2].pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	March 26, 2020
 LKKAdjustment1a[1].pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	March 26, 2020
 LKKInspection[1].pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	March 26, 2020
 LKKPhoto(3).pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	March 26, 2020
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	March 26, 2020

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 EMAIL.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	March 26, 2020
 LKKPreRepairInspection-SLA 8883T - Est COR S\$7,000.00 / 05 days repair.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	November 19, 2018
 LKKInvoice-SLA 8883T.pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	November 19, 2018
 LKK photo2.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	November 19, 2018
 LKK photo.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	November 19, 2018
 Photo of damaged parts.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	November 13, 2018
 Inspection Photographs.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	November 8, 2018
 SKK1003Y INSD GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	November 7, 2018
 TP PRI FROM WORKSHOP WITH GIA REPORT.msg	Letters and Correspondence	Workshop	DHAKAL Raghav	November 7, 2018