

ASS. RES. 100

SALE VEHICLE

Miniman

From Owner

Quo Qiang

Gabriel wee

REP

CS3/III19006547/Ged3er

Ref of Instruction

ASSIGNMENT (Office)

III

Date/Time

12/4/19 @ 11:50am

Estimated Cost

Bill by

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No

SLV 344A

Insured

SHC 88617

at Workshop / m/s

Apex Motoring

Tel

6842 4992

of

25 kaki Bukit Rd 4 # 01-55 syrengr

Policy No

Claim No

Sum Insured

Excess

Make of Veh

D.O.A

10/04/2019

(Client's Record)

CA / REV / REP / REV 24 HRS

H.O.D. Endorsement

Date/Time

12:03pm @ 12/4/19

Person Contacted

Me-him

Vehicle

IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SLV 344A - NS / INC 19 003229 / T/sd3
	SHC 88617 - CS3 / A19 11 001708 / H/n 19 27
	Dismantle: 15/4/2019 0443pm

Don: 15/2/19

Don: 26/01/2011

10/11/19

Surveyor:

PRS

REF:

III

PRS

ASSIGNMENT

From: Date: 12/4/19

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLV 344A

at Workshop m/s

of 28 kaki Bukit Rd 4 #01-55 Synergy

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{cup}

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLV 344A Yr Regn: Dec / 17

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota C-HR C.C. 1797

Colour: silver A/C: Insured / Std / NI / NA

Sp. Reading: 10352 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: 8YX 10 20 88 901

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R17

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 12-04-19

Survey held at

Des. of Damages: Frt / Rear / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$3000 - \$4000

16/4/2019

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Preli. Report☐ : Final Report

Days Of Repair:

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp. (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: PRS

Lump Sum / I.B.I: (\$)

120

10

130

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Friday, 12 April 2019 11:50 AM
To: peijie@expresscar.com.sg; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: Zuhaidah Samsuri
Subject: RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. SLV344A (Accident involving SLV344A and SHC8861T on 10.04.2019)
Attachments: shc8861t_20190412100107.pdf

Dear Sir / Mdm

This Pre-Repair Survey is on Without Prejudice Basis.

THIRD PARTY VEHICLE NO.: SLV344A

III INSURED VEHICLE NO.: SHC8861T

DATE OF LOSS: 10.04.19

We acknowledge receipt of your email.

In compliance to Pre-Action Protocol for NIMA cases, we note that We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANTS to conduct the pre-repair survey.

This claim is handled by Aida.

Please let us have your client's accident report and repair estimate for our appointed surveyor to conclude his report.

**We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.

**Surveyor kindly upload this assignment to Merimen.

Thank You.

Best Regards,
Gabriel Wee

64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext – 248

-----Original Message-----

From: peijie@expresscar.com.sg [mailto:peijie@expresscar.com.sg]

Sent: 12 April, 2019 11:11 AM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: Re: PRE-REPAIR INSPECTION FOR VEHICLE NO. SLV344A (Accident involving SLV344A and SHC8861T on 10.04.2019)

Dear Sir/ Madam,

We do not agree to your list of surveyor.

Kindly refer below for our list of surveyor :

- 1)Teo Hoon Tong – Kelvin Automotive Appraising Services
- 2)Chang Fuh Keong, Dave – Sincere Appraisal Services
- 3)Ho Joo Loong, Danny – HJL Auto Appraiser Services
- 4)Lee Kok Weng – Lee Automobile Appraisers Services
- 5)Hong Shiyuan – Kelvin Automotive Appraising Services
- 6)Ong Ah Keng, Kent – KTO Automobile Assessors
- 7)Ong Poh Meng

– Aeon Auto Consultants LLP 8)Philip Foo – Presicion Appraisal Services 9)Thor Teck Soon, David – JAS Appraisal Services

Thanks.

Best Regards,
Peijie
82 Lorong 23 Geylang
#03-06 ATRIX
S(388409)
DID: 91690825

On 2019-04-12 10:09, Motor Claim - III wrote:

- > Dear Sir / Mdm,
- >
- > We acknowledge receipt of your letter.
- >
- > We propose using one of the following motor surveyors:
- >
- > * LKK Auto Consultants Pte Ltd
- > * Vicom Assessment Centre Pte Ltd
- >
- > Please notify us within 02 days of receipt of this letter for surveyor
- > agreed on or if you have any objections to the above list.
- >
- > _Best Regards,_
- >
- > GABRIEL WEE
- >
- > 64 Cecil Street; #05 - IOB Building
- >
- > Singapore 049711
- >
- > Tel: 6347 6100, Ext - 248
- >
- > Kindly note that by submitting this claim to us, you are deemed to
- > have agreed to us collecting, using, disclosing and processing your
- > personal data, sharing your personal data with our service providers
- > (located both inside and outside Singapore) and/or with other insurers
- > in the general insurance industry, including the General Insurance
- > Association of Singapore. This enables us to ensure proper processing,
- > handling and/or dealing with your claim, which includes investigating
- > the said claim, and complying with applicable laws. If you do not
- > agree to the same, kindly let us know immediately.
- >
- > DISCLAIMER:
- > This email is intended solely for the person to whom it has been
- > addressed.
- > It may contain confidential and/or legally privileged information.
- > If you are not the person for whom this e-mail was intended, or if
- > this e-mail has reached you by mistake, please delete it immediately
- > and inform us of the error and also be hereby notified that any use,
- > distribution, transmission, printing, copying or dissemination of this
- > information in any way or in any manner is strictly prohibited and may
- > be unlawful.

- > Internet communications may not be entirely secure or accurate as
- > information could be intercepted, corrupted, lost, delayed or contain
- > viruses.
- > Therefore, we do not accept liability for any errors or omissions in
- > the content of this message or any delay in delivery which may arise
- > as a result of Internet transmission or any modification.
- > Print this email only if it is absolutely necessary and help in
- > preservation of environment.
- > India International Insurance Pte Ltd.
- > Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful.

Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K



11/04/2019

INDIA INTERNATIONAL INSURANCE PTE LTD

64 Cecil Street
#04 / #05 IOB Building
Singapore 049711
Fax : 6224 4174

Dear Sirs

**ACCIDENT BETWEEN VEHICLE NO. SLV 344 A AND VEHICLE NO. SHC 8861 T
ON 10/04/2019 @ 1815 HRS**

We are the appointed repair workshop of vehicle no. **SLV 344 A**.

We understand that you are the insurer of vehicle no. **SHC 8861 T**.

The owner of vehicle number **SLV 344 A** has authorised us to carry out the repairs to his vehicle which was damaged by your insured's vehicle. The owner intends to make a claim against your insured and/or insured's authorised driver for the accident which is caused wholly and/or contributed by your insured and/or your insured's authorised driver's negligence.

We hereby give you notice of the accident and an opportunity to inspect the damaged to the vehicle prior to the commencement of the repairs.

The vehicle is now at our workshop awaiting for your inspection at the following address: 25 Kaki Bukit Road 4 #01-55 Synergy @ KB Singapore 417800. Kindly email 10 surveyors list to me @ Email: peijie@expresscar.com.sg.
Miss Lim Mobile No. 6842 4992 / 9169 0825.

Yours faithfully



> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SLV344A		
Vehicle Type :	Z10 - Private Hire (Chauffeur) Motor Car		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	TOYOTA		
Vehicle Model :	C-HR HYBRID 1.8S CVT		
Chassis No. :	ZYX102088901		
Propellant :	Petrol-Electric		
Engine No. :	2ZR8260935		
Motor No. :	07WA17J05687		
Engine Capacity :	1797 cc		
Power Rating :	53.0 kW		
Maximum Power Output :	90.0 kW (120 bhp)		
Maximum Laden Weight :	1715 kg		
Unladen Weight :	1440 kg		
Year Of Manufacture :	2017		
Original Registration Date :	20 Dec 2017		
Lifespan Expiry Date :	-		
COE Category :	B - Car above 1600cc or 97kW (130bhp)		
Quota Premium :	\$57,414.00		
COE Expiry Date :	19 Dec 2027		
Road Tax Expiry Date :	19 Jun 2019		
PARF Eligibility Expiry Date :	19 Dec 2027		
Inspection Due Date :	19 Dec 2020		
Intended Transfer Date :	23 Apr 2019		
CO2 Emission :	87.00 (g/km)		
CEV/VES Rebate Utilised Amount :	\$25,471.00		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
The current road tax expiry is 19 Jun 2019. You may renew the road tax from 20 Mar 2019 with all pre-requisite(s) fulfilled. If the road tax is renewed after 19 Jun 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 20 Jun 2019 to 19 Dec 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	487.00	-	487.00
Total Amount Payable :			512.00
Amount Payable (From 20 Jun 2019 to 19 Jun 2020)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	974.00	-	974.00
Total Amount Payable :			999.00

You may print this page for reference.

OK

Print

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	6882D
Vehicle Details	
Vehicle No.:	SLV344A
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	C-HR HYBRID 1.8S CVT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	2ZR8260935
Chassis No.:	ZYX102088901
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$27,479.00
Original Registration Date:	20 Dec 2017
First Registration Date:	20 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Dec 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	19 Dec 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,414.00
COE Rebate Amount:	\$49,685.00
Total Rebate Amount:	\$53,435.00

The information contained herein is correct as at 23 Apr 2019

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Apr 2019 17:11 Edit Reg		12 Apr 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: -, Co. Reg. No.: -									
Main Claimant: -									
Vehicle Reg. No.: SLV344A		Date of Loss: 10/04/2019 00:00 - :59 [15 Months and 21 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): SHC8861T		Policy No. (Claimant):							
		Excess:							
Repairer: Apex Motoring () 25 Kaki Bukit Road 4, #01-55 Synergy @ KB, 417800 Kaki Bukit - Tel:									
Handling Insurer: India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 24/04/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLV344A
[SHC8861T]
TP

-
Apr 10 2019 12:00AM
[-]
Apex Motoring

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	15/04/19 10:04	General View						Load JPG	<input checked="" type="checkbox"/>	
2	15/04/19 10:04	General View						Load JPG	<input checked="" type="checkbox"/>	
3	15/04/19 10:04	General View						Load JPG	<input checked="" type="checkbox"/>	
4	15/04/19 10:04	General View						Load JPG	<input checked="" type="checkbox"/>	
5	15/04/19 10:04	General View						Load JPG	<input checked="" type="checkbox"/>	
6	15/04/19 10:04	General View						Load JPG	<input checked="" type="checkbox"/>	
7	15/04/19 10:04	General View						Load JPG	<input checked="" type="checkbox"/>	
8	15/04/19 10:04	General View						Load JPG	<input checked="" type="checkbox"/>	
9	15/04/19 10:04	General View						Load JPG	<input checked="" type="checkbox"/>	
10	15/04/19 10:04	General View						Load JPG	<input checked="" type="checkbox"/>	
11	15/04/19 10:04	General View						Load JPG	<input checked="" type="checkbox"/>	
12	15/04/19 10:04	General View						Load JPG	<input checked="" type="checkbox"/>	
13	15/04/19 10:05	Odometer Reading						Load JPG	<input checked="" type="checkbox"/>	
14	15/04/19 10:05	Chassis Number						Load JPG	<input checked="" type="checkbox"/>	
15	16/04/19 11:53	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
16	16/04/19 11:53	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
17	16/04/19 11:53	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
18	16/04/19 11:53	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
19	16/04/19 11:53	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
20	16/04/19 11:53	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
21	16/04/19 11:53	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
22	16/04/19 11:53	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
23	16/04/19 11:53	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
24	16/04/19 11:53	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
25	16/04/19 11:53	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
Documentation							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	India International Insurance Pte Ltd (HQ)						Thumbnail	Print	
1	15/04/19 08:34	Singapore Accident Statement						Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST				Reset	Save	Print
There are no document checklists configured.						

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III19006547/GCD3E2

Date: 23/04/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SLV344A

Insured Vehicle No : SHC8861T

Date of Loss: 10/04/2019

Nature of Claim: TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLV344A

Make & Model: TOYOTA C-HR, 1.8 HYBRID S/G (A)

Engine No: 2ZR8260935

Reg. Date: 20/12/2017 (Man. Year: 2017)

Chassis No: ZYX102088901

Colour: Silver

Odometer: 101352 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17

Rear Tyre Size: 215/60 R17

Front Left Side: KAPSEN 6 mm

Rear Left Side: KAPSEN 6 mm

Front Right Side: KAPSEN 6 mm

Rear Right Side: KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 12/04/2019

Date Inspected: 12/04/2019 Inspected At:

Apex Motoring
25 Kaki Bukit Road 4, #01-55 Synergy @
KB
Singapore 417800

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Apr 2019)
Parts:	M1-SUV	TOYOTA C-HR 1.8 HYBRID S/G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV344A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >