

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
AXA INSURANCE PTE LTD			Ref: CC4/ASM19006566/R1ps3s2		
0.011		04			
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811			Date: 21-04-2020		
ATTN: RICHARD ANG		Code: ASM			
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SFS 8822X	Veh. Inspected	SKX 2785Z	
	Policy No.	GA307907/1	Coverage (\$)	0.00	
	Claim No.	S9M01JUV	Excess (\$)	0.00	
	Assign From	RICHARD ANG	Assign Date	12/04/2019	
2. Vehicle Particulars & Condition					
	Make & Model	MERCEDES BENZ B180 STYLE	c.c	1595	
	Engine No.	HIDDEN	Year of Reg.	2015	
	Chassis No.	WDD2462422J365887	Colour	BROWN	
	Odometer	42619	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm	
	L/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm	
	R/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm	
	L/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm	
4.					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	09/04/2019	Inspection Date	15/04/2019	
	Survey held at	CYCLE & CARRIAGE INDUSTRI	IES (1986) PL		
		188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days			