

ASS. POLICY

REF: CS3/CTI190066A1/Bcd327

Mr. Jim
Meinen

Mr. Jim
Elaine Cheong

ASSIGNMENT (Office)

of CTI

Date/Time: 15/4/19 @ 10.40am

Estimated Cost

Bill to:

OD / TP RES / OF RES / EVA / INV / MY / CS

To Inspect Vehicle No.

SFK 308J

Insured

SKW 629K

at Workshop in/:

Revol Carz

Tel:

9322 2338

of 10 Amk Ind. Park 2A #02-18

Policy No.

DMPCSN 3039391801

Claim No.

SNM19D201619C02-d

Sum Insured

Excess:

Make of Veh

(Client's Record)

D.O.A

10/4/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time:

11:08am @ 15/4/19

Person Contacted:

June

Vehicle

IN OUT

Date/Time	Action/Instruction (X) Estimate	
	SFK 308J - CVI / VAL 16010239 / Uv	DOA: 31/5/2016
	SKW 629K - CS/CTI19006623 / Uvd3	DOA: 10/4/2019
	Dismantle: 22/4/2019	

REF: CTI

ASSIGNMENT

PRS

From: Date: 15/4/2019

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SFK 308J

at Workshop m/s: Revol Carz

of Blk 10 Amk Ind Park 2A #02-18

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SFK 308J Yr Regn: 1/6/2005

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Mark X 2.5A c.c 2499

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 248977 T/Radio: Insured / Std / NI / NA

Eng/No: 4GR0071838

C/No: GRX1200025782

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/35/19

R: 245/35/19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 10 D.O.I. 15/4/19

Survey held at: Revol Carz

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range 2500/2 - 3500/2
	MV 15,000/2
	PV 8,105/2
	NV 6,895/2
	Signature: [Handwritten Signature]
	17/4/2019
	RECEIVED 26 APR 2019

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 1

Report Format: PRE

Lump Sum / I.B.I.: (\$)

- Add Fee:
- : Site Insp (\$)
 - : Interview (\$)
 - : Tech. Invs (\$)
 - : Weekend (\$)

Survey Fee:	190
Transportation:	
S + RS, SI	
Photos	
Others	
TOTAL	190

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Apr 2019		15 Apr 2019 13:38 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:									
Main Claimant:	TAN SU HIN, ID: S8067927J								
Vehicle Reg. No.:	SFK308J	Date of Loss: 10/04/2019 12:00 - :59							
Claim Type:	TP / SNM19D201619C02	Policy/Cover Note No.: DMPCSN3039391801							
Vehicle Reg. No. (Insured):	SKW629K	Policy No. (Claimant): DMPCSN3039391801							
		Excess: S\$1,000.00							
Repairer:	Revol Carz Garage Pte Ltd (HQ) Block 10, Ang Mo Kio Ind Park 2A, #02-18, AMK Auto Point, 568047 Ang Mo Kio - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/04/2019]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Sent: Monday, 15 April 2019 10:40 AM
To: Hui Ting; 'assignments'
Cc: Corene
Subject: RE: Our client's vehicle no. SFK308J (REVOL); Your insured's vehicle no. SKW629K - PRI (CLAIM REF: SNM19D201619C02-9)
Attachments: FW: Our client's vehicle no. SFK308J (REVOL); Your insured's vehicle no.... (2.42 MB)

WITHOUT PREJUDICE

Dear Hui Ting,

We refer to your email of 15.04.19.

We are not agreeable to proposed list of surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below with attachment and liaise with third party workshop accordingly.

Thank you.

Regards,

Elaine Cheong
Executive (Motor Claims)
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6530
Fax: 6224 7478 / 6224 7175
Email: elaine.cheong@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: Hui Ting [mailto:huiting@crossbordersllc.com]
Sent: Monday, 15 April, 2019 9:54 AM
To: Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Cc: Corene <corene@crossbordersllc.com>
Subject: RE: Our client's vehicle no. SFK308J (REVOL); Your insured's vehicle no. SKW629K - PRI (CLAIM REF: SNM19D201619C02-9)

Your attention is drawn to the CONFIDENTIALITY NOTICE below.

WITHOUT PREJUDICE

Dear Elaine

1. We refer to your email dated 15 April 2019.
2. Our client objects appointing your surveyors as a single joint expert.
3. We propose one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:-
 - a) Dennis Yap PAL'S Appraiser Pte Ltd
 - b) Yap Teck Lee LCW Appraiser Pte Ltd
 - c) Yap Teck Chye MC-Coy Appraiser Pte Ltd
 - d) Dixon Yeo Treasure Appraiser Pte Ltd
4. Please let us know within two (2) working days whether you are agreeable to the appointment of any of the above motor surveyors as a single joint expert.

Thank You.

Regards
Huiting
TEL: 6438 1323 ext 2006

CrossBorders LLC
133 New Bridge Road
#23-03/04/05 Chinatown Point
Singapore 059413
Tel: (65) 6438 1323
Fax: (65) 6438 2313

CONFIDENTIALITY NOTICE

This e-mail from CrossBorders LLC (including any attachment(s) to it) is confidential and may also be privileged and exempt from disclosure under applicable law. Accordingly, if you are not the intended recipient please notify us immediately, delete this e-mail (including any attachment to it) from your computer system and do not disclose or distribute it to any other person or continue to read this e-mail. Thank you.

CrossBorders LLC DOES NOT ACCEPT SERVICE OF COURT DOCUMENTS OR NOTICE OF ANY PROCEEDINGS BY FACSIMILE OR EMAIL

From: Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Sent: Monday, 15 April 2019 9:45 AM
To: Hui Ting <huiting@crossbordersllc.com>
Subject: RE: Our client's vehicle no. SFK308J (REVOL); Your insured's vehicle no. SKW629K - PRI (CLAIM REF: SNM19D201619C02-9)

WITHOUT PREJUDICE

Dear Huiting,

We refer to your fax dated 11.04.19.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING

Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards,

Elaine Cheong

Executive (Motor Claims)

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 6389 6530

Fax: 6224 7478 / 6224 7175

Email: elaine.cheong@sg.cntaiping.com

Website: www.sg.cntaiping.com

From: Claims Dept of CTI

Sent: Thursday, 11 April, 2019 5:26 PM

To: Elaine Cheong <elaine.cheong@sg.cntaiping.com>

Subject: FW: Our client's vehicle no. SFK308J (REVOL); Your insured's vehicle no. SKW629K - PRI

Dear Elaine,

FYI. Document has been added to the file on your desk. Claim no. SNM19D201619

From: Hui Ting [<mailto:huiting@crossbordersllc.com>]

Sent: Thursday, 11 April 2019 4:59 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: Corene <corene@crossbordersllc.com>

Subject: Our client's vehicle no. SFK308J (REVOL); Your insured's vehicle no. SKW629K - PRI

Your attention is drawn to the CONFIDENTIALITY NOTICE below.

WITHOUT PREJUDICE

Dear Sirs

1. Please find attached our PRI notice dated 11 April 2019 for your kind attention.
2. Please reply email to corene@crossborderllc.com & huiting@crossborderllc.com

Thank You.

Regards

Huiting

TEL: 6438 1323 ext 2006

CrossBorders LLC
133 New Bridge Road
#23-03/04/05 Chinatown Point
Singapore 059413
Tel: (65) 6438 1323
Fax: (65) 6438 2313

CONFIDENTIALITY NOTICE

This e-mail from CrossBorders LLC (including any attachment(s) to it) is confidential and may also be privileged and exempt from disclosure under applicable law. Accordingly, if you are not the intended recipient please notify us immediately, delete this e-mail (including any attachment to it) from your computer system and do not disclose or distribute it to any other person or continue to read this e-mail. Thank you.

CrossBorders LLC DOES NOT ACCEPT SERVICE OF COURT DOCUMENTS OR NOTICE OF ANY PROCEEDINGS BY FACSIMILE OR EMAIL

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

CROSSBORDERS LLC

Advocates & Solicitors | Commissioner for Oaths | Notary Public

Our Ref: AJ.tk.Revol (SFK308J)
Your Ref: SKW629K

11 April 2019

China Taiping Insurance (Singapore) Pte. Ltd. BY FAX: 6224 7478 & EMAIL
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909
Attn: Motor Claims Department

URGENT

Dear Sirs

NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY
CLAIMANT: TAN SU HIN.
TRAFFIC ACCIDENT ON 10 APRIL 2019 AT 12:10 HRS ALONG ANG MO KIO INDUSTRIAL
PARK 2A INVOLVING VEHICLES NO. SFK308J & SKW629K

We are instructed by Tan Su Hin to notify you of a road accident on 10 April 2019 at about 12:10 hrs along Ang Mo Kio Industrial Park 2A involving our client's vehicle registration number SFK308J and vehicle registration number SKW629K driven by your insured at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.


As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days (excluding any intervening Saturday, Sunday and Public Holiday) of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Venue: Revol Carz Garage Pte Ltd ✓
Address: 10, Ang Mo Kio Industrial Park 2A
#02-18 AMK Autopoint
Singapore (568047)
Contact: June (9322 2338) / Gavin (9740 6855)

Please liaise with the above workshop directly.

Yours faithfully


Crossborders LLC

Email: corene@crossbordersllc.com /
huiting@crossbordersllc.com
encs

**PLEASE LET US KNOW THE DATE
OF THE PRE-REPAIR INSPECTION**

.....

CONFIDENTIALITY CAUTION
THIS DOCUMENT IS FOR THE ADDRESSEE(S) ONLY AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE
SUBJECT TO LEGAL PRIVILEGE. IF YOU HAVE RECEIVED THIS IN ERROR, PLEASE CONTACT US IMMEDIATELY.

CROSSBORDERS LLC

A LIMITED LIABILITY CORPORATION. REGISTRATION NUMBER 201305284K
GST REGISTRATION NUMBER 201305284K

MAIN OFFICE
133 NEW BRIDGE ROAD
#23-03/04/05
CHINATOWN POINT
SINGAPORE 059413
TEL: 6438 1323
FAX: 6438 2313

BRANCH OFFICE
1 JALAN BERSEH
#03-12 NEW WORLD CENTRE
SINGAPORE 209037

PLEASE SEND ALL
CORRESPONDENCES TO
THE MAIN OFFICE

WE DO NOT ACCEPT
SERVICE BY FAX

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7927J
Vehicle Details	
Vehicle No.:	SFK308J
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	MARK X 2.5 A
Primary Colour:	White
Manufacturing Year:	2005
Engine No.:	4GR0071838
Chassis No.:	GRX1200025782
Maximum Power Output:	158.0 kW (211 bhp)
Open Market Value:	\$34,808.00
Original Registration Date:	01 Jun 2005
First Registration Date:	01 Jun 2005
Transfer Count:	2
Actual ARF Paid:	\$38,289.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 May 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$36,068.00
COE Rebate Amount:	\$8,105.00
Total Rebate Amount:	\$8,105.00
Message	

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 16 Apr 2019

OK

COE left 11 months
 1 yr 1.7 months
 ↑

MV 15,000/-
 PV 8,105/-
 NV 6,895/-

Termin Bill
 16/4/19

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/04/2019 16:28
Date Of Accident	10/04/2019 12:10
Exact Location Of Accident	ANG MO KIO IND'L PARK 2A
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFK308J
Insured/Policyholder	
Name Of Registered Owner	TAN SU HIN
NRIC No	S8067927J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91723427
Alternative Phone No	Others-91723427

Vehicle Particulars

Manufacturer	TOYOTA
Model	MARK X-2.5 (A)
Exact Purpose for which vehicle was being used at time of accident	PTE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3039391801
Cover Note Number	01/06/2018 - 31/05/2019

Driver

Name of Driver	TAN SU HIN
NRIC No	S8067927J
Date Of Birth	09/11/1980
Occupation	INDOOR
Date Of Driving Pass	25/06/2009
Driving Experience	9 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91723427

Fax Number
 Contact Number OTHERS-91723427
 EMail Address NOEMAIL
 Address BLK 119 BISHAN ST 12 #02-53
 Postcode 570119
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name ANG MO KIO SOUTH NEIGHBOURHOOD POLICE CENTRE
 Police Station Address ROAD: 81 ANG MO KIO AVE 3 , POSTCODE: 569929 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-4519999 - FAX NO: 65535679
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT NO.: T/20190410/2125.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: WITH OWN WORKSHOP
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKW629K
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

VEHICLE NO.: SFK 308J
INSURER : China Taiping
DATE & TIME: 10/4/19 @ 12:10


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: (mk)
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report No = T/20190410/2125

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Claim Own Policy Claim Third Party Reporting Only
 Claim OD/TP at other workshop (by own workshop)

Sketch Plan #3


**SINGAPORE
POLICE FORCE**


T/20190410/2125

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999

1 of 3

Report No. T/20190410/2125

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 10/04/2019 14:40		Vide Report No.:		Station Diary No.: 66	
Informant's Particulars					
Name of Informant: TAN SU HIN			Address: APT BLK 119 BISHAN STREET 12 #02-53 SINGAPORE 570119		
ID Type / ID No.: NRIC NO / S8067927J			Contact No.: Home/Office: Mobile: 91723427		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 38	Date of Birth: 09/11/1980	Type of Informant: Vehicle Owner		
Race: Chinese			Language:		Institution / School Name:
Occupation: Workshop Manager			Driving Licence Information: Class: 2B,3		Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 10/04/2019 12:10	Type of Location: Car Park
Location: Along Road 1 ANG MO KIO INDUSTRIAL PARK 2A Blk 10 "Autopoint" shop				
Weather:		Road Surface:		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collision:				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SFK308J	Car	TOYOTA	Mark X	White	Slightly Damaged	0
SKW629K	Car	HONDA	Odyssey	White	Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Sketch Plan #4



**SINGAPORE
POLICE FORCE**



T/20190410/2125

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999

2 of 3

Report No. T/20190410/2125

CONTINUATION OF REPORT

Vehicle Owner			
Name	TAN SU HIN	ID No.	S8067927J
Related Vehicle	SFK308J (Car)	Contact No.	91723427
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 10/4/19 at about 0630hrs, I parked my car outside "Autopoint" and went inside to start work. At around 1220hrs, I was informed by my colleague that someone had hit my car and drove off. I checked the CCTV and saw that a white car had hit my parked car when it was driving through. The CCTV captured said driver's face and vehicle registration number.

Sketch Plan #5



**SINGAPORE
POLICE FORCE**



T/20190410/2125

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999

3 of 3

Report No. T/20190410/2125

CONTINUATION OF REPORT

Sketch Plan


Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Sgt 3 ONG KOK CHUAN
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / HRT / Sr Staff Sgt IRMAN BIN MOHAMAD SAID Contact No.: 65476145

Signature Of Informant:
Date/Time: 10/04/2019 14:40
Classification Of Case: SN 085

Authentication Stamp
NP168



IC & DL

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8067927J



Name
TAN SU HIN
姓 名
Tan
CHINESE
Date of Birth 09-11-1980 Sex M
Country of Birth MALAYSIA



REPUBLIC OF SINGAPORE DRIVING LICENCE


Identity Card No. S8067927J



Name
TAN SU HIN
Date of Birth 09 Nov 1980
Issue Date 17 Apr 2013




Identity Card No. S8067927J



Signature
WALAN SU HIN
Date of Issue
12-22-2013

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

Class 2C Motorcycles (C&A) up to 25 Jan 2024
Class 2 Motor Cycles 3000kg with up to 7 passengers, excluding all the driver, and other motor vehicles (C, D, E, F, G, H, I, J, K, L, M, N, O, P, Q, R, S, T, U, V, W, X, Y, Z)



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Apr 2019		15 Apr 2019 13:38	S\$0.00	S\$0.00 View Rpt		Pending for Survey Report

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: TAN SU HIN , ID: S8067927J									
Vehicle Reg. No.:	SFK308J	Date of Loss:	10/04/2019 12:00 - :59 [166 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D201619C02	Policy/Cover Note No.:	DMPCSN3039391801						
Vehicle Reg. No. (Insured):	SKW629K	Policy No. (Claimant):	DMPCSN3039391801						
		Excess:	S\$1,000.00						
Repairer:	Revol Carz Garage Pte Ltd (HQ) Block 10, Ang Mo Kio Ind Park 2A, #02-18, AMK Auto Point, 568047 Ang Mo Kio - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 25/04/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/> View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SFK308J (SNM19D201619C02)**
[SKW629K]
TP
TAN SU HIN
Apr 10 2019 12:00PM
[-]
Revol Carz Garage Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page <input type="checkbox"/>	
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	11/04/19 16:15	Accident Statement	Load HTM	<input type="checkbox"/>
Photos/Images			3 per page <input type="checkbox"/>	
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	11/04/19 16:15	IC & DL [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	11/04/19 16:15	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	11/04/19 16:15	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	11/04/19 16:15	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	11/04/19 16:15	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	11/04/19 16:15	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	11/04/19 16:15	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/04/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
2	26/04/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
3	26/04/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
4	26/04/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
5	26/04/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
6	26/04/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
7	26/04/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
8	26/04/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
9	26/04/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
10	26/04/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
11	26/04/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
12	26/04/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
13	26/04/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
14	26/04/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
15	26/04/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
16	26/04/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
17	26/04/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
18	26/04/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
19	26/04/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
20	26/04/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
21	26/04/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
22	26/04/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
23	26/04/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
24	26/04/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
25	26/04/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
26	26/04/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
27	26/04/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
28	26/04/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
29	26/04/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
30	26/04/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
31	26/04/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
32	26/04/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
33	26/04/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
34	26/04/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
35	26/04/19 11:31	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
36	26/04/19 11:31	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
37	26/04/19 11:31	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
38	26/04/19 11:31	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
39	26/04/19 11:31	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
40	26/04/19 11:31	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
41	26/04/19 11:31	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
42	26/04/19 11:31	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
43	26/04/19 11:31	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
44	26/04/19 11:31	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	15/04/19 13:41	PRS - SFK308J (REVOL CARZ GARAGE)	Load PDF	

No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	11/04/19 16:14	Sketch Plan [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	11/04/19 16:14	Sketch Plan #2 [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	11/04/19 16:14	Sketch Plan #3 [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	11/04/19 16:14	Sketch Plan #4 [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	11/04/19 16:14	Sketch Plan #5 [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	11/04/19 16:15	Accident Statement	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	11/04/19 16:15	IC & DL	Load JPG	<input checked="" type="checkbox"/>
2	11/04/19 16:15	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	11/04/19 16:15	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	11/04/19 16:15	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	11/04/19 16:15	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	11/04/19 16:15	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	11/04/19 16:15	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
---------------	--	--	------------	-------------------------------------

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail Print
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail Print
1	11/04/19 16:14	Sketch Plan		Load JPG <input checked="" type="checkbox"/>
2	11/04/19 16:14	Sketch Plan #2		Load JPG <input checked="" type="checkbox"/>
3	11/04/19 16:14	Sketch Plan #3		Load JPG <input checked="" type="checkbox"/>
4	11/04/19 16:14	Sketch Plan #4		Load JPG <input checked="" type="checkbox"/>
5	11/04/19 16:14	Sketch Plan #5		Load JPG <input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19006641/BCD3E2

Date: 10/05/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMPCSN3039391801	
Claimant Vehicle No: SFK308J	Insured Vehicle No: SKW629K	
Date of Loss: 10/04/2019	Nature of Claim: TP	Claim No: SNM19D201619C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFK308J	Engine No:	4GR0071838
Make & Model:	TOYOTA MARK X, 2.5 (A)	Chassis No:	GRX1200025782
Reg. Date:	01/06/2005 (Man. Year: 2005)	Odometer:	248977 km
Colour:	White		
Engine Capacity:	2499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/35 R19	Rear Tyre Size:	245/35 R19
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	15/04/2019	
Date Inspected:	15/04/2019 Inspected At:	Revol Carz Garage Pte Ltd (HQ) Block 10, Ang Mo Kio Ind Park 2A, #02-18, AMK Auto Point Singapore 568047
Estimated Period of Repair:	5.0 days	

Adjuster: Lim Teow Guan

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500.00 -\$3,500.00

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 10 May 2019)
Parts: 143	TOYOTA MARK X 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFK308J)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >