



Your Ref: BK.BK.18212.17

Date: 18th April 2019

Our Ref: CS1/LAW19006681/K1vd3s2

M/s Bonnie Kwok LLC
101A Upper Cross Street
#08-12 People's Park Centre
Singapore 058358

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
FBE 6658M INSURED VEHICLE: CB 7281M ACCIDENT DATE: 30/09/2017**

We thank you for your instruction on 12/04/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FBE 6658M from M/s AJAX Inspection Services Pte Ltd.
- b) Survey report by Automax Survey with colour photographs.
- c) Singapore Accident Statement of Vehicles FBE 6658M and CB 7281M.
- d) Colour damaged vehicle photographs of FBE 6658M.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: FBE 6658M
Make & Model	: Yamaha T135
Year of Registration	: 2010
Chassis Number	: 5YP302747
Engine Capacity	: 135 cc

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.