

ASS. REC. BY:

REF: CS/MSG19006726 / Ks d3d

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

Minimum

From (Person): Monica Chung Pei zhen of MSI.G Date/Time: 15.4.19 12:43 p.m

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD ~~(TP)~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMJ 7213A Insured: FBM 8948 X

at Workshop m/s MBM Wheel Power Tel: 9328 8668

of 160 sin ming drive # 06-02

Policy No: M50/VMS/18-991946-WTT Claim No: MSC/V/19-000470

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 10.4.2019  
(Client's Record)

CA / REV / REP. / REV 24 HRS "wp" H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 16.4.19 9.30 a.m. Person Contacted: Danny Vehicle IN / OUT

Date/Time	Action/Instruction	Estimate (✓)
	SMJ 7213A - X	
	FBM 8948X - X	
17/04/19	@ 13:59 p.m. revised IA to	
915	11 Bpm @ 32nd encl & confirmed	
	( \$ 4,905.50 Red - 61% )	

ASS. REC. BY:

REF: 17561

Kenneth

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s NBM

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SMJ 7213A Yr Regn: 11, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Mer G6C43 c.c. 2996

Colour: M.D. Blue A/C: Insured / Std / NI / NA

Sp. Reading: 15046 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WDC 25336421 = 235086

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NI / S/R/Im / STD / A/R/Im or

Tyre Size: F: 235/55R19

R: 255/50R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 9 mm R/Bal. 9 mm

L/Bal. 9 mm L/Bal. 9 mm

D.O.A. 10/4/19 D.O.I. 16/4/19

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>File pass to</u>

RECEIVED 11 JUN 2019

M. Monto  
11/6/2019

Date/Time, File Pass to? 11/06/19  
 : Prell. Report  
 : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee:	<u>150</u>
Transportation:	_____
_____ S - RS. _____ SI	_____
_____ Fines	_____
_____ Others	<u>11</u>
TOTAL	<u>161</u>

Add Fee:  : Site Insp (\$ \_\_\_\_\_ )  
 : Interview (\$ \_\_\_\_\_ )  
 : Tech Invs (\$ \_\_\_\_\_ )  
 : Weekend (\$ \_\_\_\_\_ )

Report Format : \_\_\_\_\_  
Lump Sum / I.B.I: (\$) 3,200/- HS

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Apr 2019		15 Apr 2019 16:43 Assign				<a href="#">New Assignment</a> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	JAAFAR BIN ABU BAKAR, ID: S8335107A, Tel: +6587490595								
Main Claimant:	SG CAR CHOICE PRE-OWNED, Co. Reg. No.: 53376613C								
Vehicle Reg. No.:	SMJ7213A	Date of Loss: 10/04/2019 20:00 - :59 [17 Months and 7 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / MSC/V/19-000420	Policy/Cover Note No.: MSD/VMS/18-991946-WTT (TP, Fire & Theft) Coverage: 08/05/2018 - 07/05/2019							
Vehicle Reg. No. (Insured):	FBM8948X	Policy No. (Claimant): Excess:							
Repairer:	MBM Wheelpower Pte Ltd (HQ) 160 Sin Ming Drive #06-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6262 8888								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 16/04/2019]								
Driver/Custodian (Insured):	JAAFAR BIN ABU BAKAR (35 / Male), NRIC: S8335107A, Tel: +6587490595 Email:								
Adj Asg. Remarks:	LIAB: DISPUTE (OI NON REPORTING) . CONTACT: DANNY @ 93288668. on WP.								
<b>ASSOCIATED MAIL RECEIVED</b>									
		<a href="#">View All</a> <a href="#">Compose Case Mail</a>							
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>									
		<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 17 Apr 2019

**Preliminary Advice**

Insured Vehicle No : FBM8948X  
TP Vehicle No : SMJ7213A  
Make : MERCEDES-BENZ GLA45 AMG  
Date of Inspection : 16/04/2019  
Inspection At : MBM Wheelpower Pte Ltd (HQ)  
160 Sin Ming Drive #06-02, Sin Ming AutoCity  
Singapore 575722  
Accident Date : 10/04/2019  
Assignment Date : 15/04/2019  
Est. Duration of Repair : 4 days

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages n/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,105.50
Revised Amount	:S\$	4,900.20
Check Items (Estimated)	:S\$	1,529.60
Total	:S\$	6,429.80
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	11/04/2019 15:44
Date Of Accident	10/04/2019 20:20
Exact Location Of Accident	CTE TOWARDS AMK AVE 1
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMJ7213A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SG CAR CHOICE PRE-OWNED
Co Reg No	53376613C
Email Address	JOSPEH88@LIVE.COM.SG
Mobile Phone No	(LOCAL) +65-96899696
Alternative Phone No	OFFICE-96899696

### Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	GLC43 AMG-3.0 4MATIC (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	QBE INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	8-V0017892-MVA
Cover Note Number	

### Driver

Name of Driver	LIAUW WEI LOONG, JOSEPH
NRIC No	S8818400I
Date Of Birth	27/05/1988
Occupation	INDOOR
Date Of Driving Pass	20/08/2008
Driving Experience	10 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96899696
Fax Number	
Contact Number	
EMail Address	JOSPEH88@LIVE.COM.SG

Address	160 LENTOR LOOP #03-01
Postcode	789094
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	COMMONWEALTH NEIGHBOURHOOD POLICE POST
Police Station Address	<b>ROAD:</b> BLK 111 COMMONWEALTH CRESCENT (ANNEX) , <b>POSTCODE:</b> 140111 , <b>COUNTRY:</b> SINGAPORE
Police Station Contact	<b>TEL NO:</b> 1800-4749999 - <b>FAX NO:</b> 64715297
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT NO.: T/20190411/2103

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE SIZE TOO BIG
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBM8948X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name	UNKNOWN
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	FBM8948X
Were seat belts worn?	NO
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by Interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) Investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

*Refer to police report no.: T/20190411/2103*

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---


---


---

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



**SINGAPORE  
POLICE FORCE**



T/20190411/2103

Police Station Of Origin:  
Commonwealth NPP  
111 Commonwealth Crescent (Annex) #01-  
288A SINGAPORE 140111  
Tel No: 1800-4749999

1 of 3

Report No. T/20190411/2103

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 11/04/2019 15:05	Vide Report No.: F/20190410/0142	Station Diary No.: 27
--	-------------------------------------	--------------------------

Informant's Particulars			
Name of Informant: LIAUW WEI LOONG, JOSEPH		Address: 160 LENTOR LOOP #03-01 SINGAPORE 789094	
ID Type / ID No.: NRIC NO / S88184001		Contact No.: Home/Office: Mobile: 96899696	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 30	Date of Birth: 27/05/1988	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: SELF EMPLOYED		Driving Licence Information: Class: 2B,2A,3 Date of Expiry:	

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 10/04/2019 20:20	Type of Location: Straight Road
Location: Along Road 1 CENTRAL EXPRESSWAY CTE Towards SLE near AMK AVE 1 exit first lane				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved						
Vehicle No	Type	Make	Model	Color	Condition	No. of Passenger
FBM8948X	Motorcycle	YAMAHA		Blue	Slightly Damaged	1
SMJ7213A	Car	MERCEDES BENZ	GLC43	Blue	Slightly Damaged	0

Details of Vehicle Insurance				
Vehicle No	Insurance Company	Insurance No	Effective	Expiry Date
SMJ7213A	QBE Insurance (Singapore) Pte Ltd			



**SINGAPORE  
POLICE FORCE**



T/20190411/2103

2 of 3

Report No. T/20190411/2103

Police Station Of Origin:  
Commonwealth NPP  
111 Commonwealth Crescent (Annex) #01-  
288A SINGAPORE 140111  
Tel No: 1800-4749999

## CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Name	Unknown	ID No.	NIL
Related Vehicle	FBM8948X (Motorcycle)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	LIAUW WEI LOONG, JOSEPH	ID No.	S88184001
Related Vehicle	SMJ7213A (Car)	Contact No.	96899696
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 10/04/2019, at about 2020hrs, I was driving my Blue Mercedes Benz, GLC43, vehicle registration number: SMJ7213A, along the Central Expressway going towards SLE and I was just before the Ang Mo Kio Avenue 1 exit. At that time, I was driving on the first lane.

Suddenly, the vehicle in front of me conducted emergency brakes and I also applied my brakes and I came to a full stop. I then felt an impact from the rear of my vehicle and I came out and saw that a Blue Yamaha motorcycle, bearing vehicle registration number: FBM8948X, had collided into the left rear of my vehicle. I noticed that the rider had a female pillion with him.

I then rendered assistance to him and also called for ambulance. Subsequently, ambulance came and examined him and his pillion and conveyed both of them to hospital. Traffic Police also attended to my scene, reference report number: F/20190410/0142, Traffic Police Investigation Officer: Afiq, contact number: 65476171 and I wish to state that my vehicle has in-car camera and I have the video footage. I wish to state that I am not injured and the damage to my vehicle was to the left rear bumper.



**SINGAPORE  
POLICE FORCE**



T/20190411/2103

Police Station Of Origin:  
Commonwealth NPP  
111 Commonwealth Crescent (Annex) #01-  
288A SINGAPORE 140111  
Tel No: 1800-4749999

3 of 3




Report No. T/20190411/2103

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: D/ Sgt 3 YIP XUANYU 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 11/04/2019 15:05
Officer In Charge Of Case: TP / GIT / Sgt 3 RASHIDAH BINTE AZMAN Contact No.: 65476216	Classification Of Case:  
Authentication Stamp NP168  SINGAPORE POLICE FORCE	EN 50

> [Back to OneMotoring](#)

## Enquire Transfer Fee

### Vehicle Details

Vehicle No.:	SMJ7213A
Vehicle Type:	N18 - Passenger (Co) Company Car (Single Rate)
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	GLC43 AMG COUPE 4MATIC AUTO
Chassis No.:	WDC2533642F235086
Propellant:	Petrol
Engine No.:	27682330584254
Engine Capacity:	2996 cc
Maximum Power Output:	270.0 kW ( 362 bhp)
Maximum Laden Weight:	2460 kg
Unladen Weight:	1855 kg
Year Of Manufacture:	2017
Original Registration Date:	03 Nov 2017
Lifespan Expiry Date:	-
COE Category:	E - Open - all except motorcycle
Quota Premium:	\$49,012.00
COE Expiry Date:	02 Nov 2027
Road Tax Expiry Date:	02 May 2019
PARF Eligibility Expiry Date:	02 Nov 2027
Inspection Due Date:	02 Nov 2020
Intended Transfer Date:	11 Apr 2019
CO2 Emission:	192.00 (g/km)
CEV/VES Rebate Utilised Amount:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

The current road tax expiry is 02 May 2019. You may renew the road tax from 03 Feb 2019 with all pre-requisite(s) fulfilled. If the road tax is renewed after 02 May 2019, late renewal fee(s) will be imposed. Please use [Enquire Road Tax Payable](#) to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

### Amount Payable (From 03 May 2019 to 02 Nov 2019)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
<b>Sub Total:</b>			<b>25.00</b>
Nett Road Tax Amount (After Offsetting Over Payment):	1,191.00	-	1,191.00
<b>Total Amount Payable:</b>			<b>1,216.00</b>

### Amount Payable (From 03 May 2019 to 02 May 2020)


	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
<b>Sub Total:</b>			<b>25.00</b>
Nett Road Tax Amount (After Offsetting Over Payment):	2,382.00	-	2,382.00
<b>Total Amount Payable:</b>			<b>2,407.00</b>

You may print this page for reference.

OK

Print

# MBM WHEELPOWER PTE LTD



Your Ref: FBM8948X  
Our Ref: SMJ7213A

To: MSIG INSURANCE SINGAPORE

Date: 13/4/2019  
From: Danny  
Fax: 64525333  
Contact: 93288668  
Make / Model: MERC-BENZ GLC43 AMG-3.0  
Chassis No.: WDC2533642F235086  
Engine No.: 27682330584254  
Year of Make: 2017  
Accident Date: 10 April 2019

CC

*Not Authorised*  
*Recovery B4 paint*  
*4 days*

Fax

ESTIMATE FOR VEHICLE NO. : SMJ7213A

DESCRIPTION	Part Number	QTY	List Price
REAR BUMPER	A 253 885 07 01 9999	1	\$ 1,628.00 <i>RM</i>
REAR BUMPER COVER	A 253 885 09 00	1	\$ 662.00 <i>RM/Dig</i>
REAR BUMPER LOWER LIP	A 000 990 54 92 9051	1	\$ 876.00 <i>RM</i>
REAR LH REFLECTOR	A 217 820 01 74	1	\$ 86.00 <i>?</i>
REAR LH BUMPER BRACKET		1	\$ 120.00 <i>?</i>
REAR BUMPER LH RETAINER		1	\$ 118.00 <i>RM</i>
TAIL PIPE LH BRACKET	A 253 885 25 01	1	\$ 162.00 <i>RM</i>
TAIL PIPE TRIM LH	A 000 490 08 27	1	\$ 617.00 <i>RM</i>
REAR BUMPER LH MOUNTING	A 253 880 09 12	1	\$ 205.00 <i>?</i>
TAIL LAMP LH		1	\$ 888.00 <i>RM</i>
REAR LH ABSORBER	A 253 885 14 00	1	\$ 203.00 <i>?</i>
DISTANCE SENSOR @\$250 EACH		2	\$ 500.00 <i>?</i>
DECOUPLING RING		2	\$ 30.00 <i>?</i>
Total:			\$ 6,095.00
LESS 10%:			\$ (609.50)
<b>Parts Total:</b>			<b>\$ 5,485.50</b>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

**SPECIAL NETT**


BODY SEALANT	1	\$	<i>na</i> 80.00 <del>X</del>
G-GUARD COATING	1	\$	<i>?</i> 500.00

**LABOUR**

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT,WELD & STRAIGHTEN ON THE AFFECTED PARTS.		\$	<i>4501</i> 1,000.00
TO REMOVE & REPLACE BUMPER SENSORS		\$	<i>601</i> 80.00
TO CHECK & RECONNECT ALL NECESSARY WIRING		\$	<i>201</i> 60.00
TO SPRAY PAINT ON THE AFFECTED AREAS		\$	<i>8001</i> 900.00
Total:		\$	8,105.50
7% GST:		\$	567.39
<b>Grand Total:</b>		<b>\$</b>	<b>8,672.89</b>

Mbm wheelpower pte ltd  
160 SIN MING DRIVE  
#06-02  
SIN MING AUTOCITY  
t 62828888 f 64525333  
Company Registration Number : 200204110W

Ks



# MBM WHEELPOWER PTE LTD

Your Ref: FBM8948X  
Our Ref: SMJ7213A

To: MSIG INSURANCE SINGAPORE

*Not Authorized*

Date: 13/4/2019

CC

*Resurvey B4 paint*

From: Danny

Fax: 64525333

Contact: 93288668

Make / Model: MERC-BENZ GLC43 AMG-3.0

Chassis No.: WDC2533642F235086

Engine No.: 27682330584254

Year of Make: 2017

Accident Date: 10 April 2019

Fax

*4 days  
11pm @ 3200h*

ESTIMATE FOR VEHICLE NO. : SMJ7213A

DESCRIPTION	Part Number	QTY	List Price
REAR BUMPER → 1300	A 253 885 07 01 9999	1	\$ 1,628.00 ✓
REAR BUMPER COVER → 435	A 253 885 09 00	1	\$ 662.00 ✓
REAR BUMPER LOWER LIP	A 000 990 54 92 9051	1	\$ 876.00 X
*REAR LH REFLECTOR	A 217 820 01 74	1	\$ 86.00 X
*REAR LH BUMPER BRACKET		1	\$ 120.00 X
REAR BUMPER LH RETAINER		1	\$ 118.00 X
TAIL PIPE LH BRACKET	A 253 885 25 01	1	\$ 162.00 X
TAIL PIPE TRIM LH	A 000 490 08 27	1	\$ 617.00 X
REAR BUMPER LH MOUNTING	A 253 880 09 12	1	\$ 205.00 X
TAIL LAMP LH → 705		1	\$ 888.00 ✓
*REAR LH ABSORBER	A 253 885 14 00	1	\$ 203.00 X
*DISTANCE SENSOR @\$250 EACH → 7205		2	\$ 500.00 ✓
*DECOUPLING RING NBL		2	\$ 30.00 ✓
Total: \$			6,095.00
LESS 10% \$			(609.50)
Parts Total: \$			5,485.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer  
Signature:  
Date:



SPECIAL NETT

BODY SEALANT  
G-GUARD COATING

1 \$  
1 \$

*400/-* *nn* 80.00  
*?* 500.00  
*25d.*

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO  
KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.  
TO REMOVE & REPLACE BUMPER SENSORS  
TO CHECK & RECONNECT ALL NECESSARY WIRING  
TO SPRAY PAINT ON THE AFFECTED AREAS

\$ *450/-* 1,000.00  
\$ *60/-* 80.00  
\$ *20/-* 60.00  
\$ *600/-* 900.00

Total: \$ 8,105.50  
7% GST: \$ 567.39  
Grand Total: \$ 8,672.89

*Parts: \$3521.70*  
*3/10: \$400*  
*L: \$1130*  

---

*T: \$6051.70*

*1/10: \$4050/-*

Mbm wheelpower pte ltd  
160 SIN MING DRIVE  
#06-02  
SIN MING AUTOCITY  
t 62628888 f 64525333  
Company Registration Number : 200204110W

NAME: SG Car Choice Pre-Owned
1 Commonwealth Lane
#01-01 One Commonwealth
S(149544)
Vehicle No.: SMJ7213A



**INVOICE**

GST REG NO: 200504627K  
 Tax Invoice: INV8222056-1  
 Invoice Date: 03/11/2018

S/N	Qty	Particular	Unit Price	Amount
01.		Being charge polish and apply ceramic coating on whole car	\$ 1,388.00	\$ 1,388.00
		G-GUARD 'RADIANT' 3-LAYER COAT		

SUB TOTAL:	\$	1,388.00
7% GST:	\$	97.16
E. & O.E Total S\$ (SGD)	\$	<u>1,485.16</u>

The above items are received in good order and condition by

Customer's Signature/Co. Stamp

for KBS Motorsport Pte Ltd

Terms & Conditions:

kbs motorsports pte ltd  
 160 Sin Ming Drive, #06-03 Sin Ming Autocity, S575722  
 t 64515 333 f 64525 333

Attn: Mr Danny  
 NAME: MBM WHEELPOWER PTE LTD  
 No. 160 Sin Ming Drive  
 #06-02, Sin Ming Autocity  
 S(575722)



Vehicle No.: SMJ7213A

**INVOICE**

GST REG NO: 200504627K  
 Tax Invoice: INV8222056-2  
 Invoice Date: 17/04/2019

S/N	Qty	Particular	Unit Price	Amount
01.		Being charge polish and apply ceramic coating on rear bumper & LH rear fender	\$ 400.00	\$ 400.00
		G-GUARD 'RADIANT' 3-LAYER COAT		

SUB TOTAL:	\$	400.00
7% GST:	\$	28.00
E. & O.E Total S\$ (SGD)	\$	<u>428.00</u>

The above items are received in good order and condition by

Customer's Signature/Co.Stamp



*[Handwritten Signature]*

for KBS Motorsport Pte Ltd

Terms & Conditions:

kbs motorsports pte ltd  
 160 Sin Ming Drive, #06-03 Sin Ming Autocity, S575722  
 t 64515 333 f 64525 333

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Apr 2019		15 Apr 2019 16:43 <a href="#">Edit Adj Rpt</a>	<b>S\$3,200.00</b> <a href="#">Edit Estimates</a>	<b>S\$3,200.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]
Insured:	JAAFAR BIN ABU BAKAR, ID: S8335107A, Tel: +6587490595			
Main Claimant:	SG CAR CHOICE PRE-OWNED, Co. Reg. No.: 53376613C			
Vehicle Reg. No.:	SMJ7213A	Date of Loss:	10/04/2019 20:00 - :59 [17 Months and 7 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / MSC/V/19-000420	Policy/Cover Note No.:	MSD/VMS/18-991946-WTT (TP, Fire & Theft) Coverage: 08/05/2018 - 07/05/2019	
Vehicle Reg. No. (Insured):	FBM8948X	Policy No. (Claimant):		
		Excess:		
Repairer:	MBM Wheelpower Pte Ltd (HQ) 160 Sin Ming Drive #06-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6262 8888			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 15/05/2019]			
Driver/Custodian (Insured):	JAAFAR BIN ABU BAKAR (35 / Male), NRIC: S8335107A, Tel: +6587490595 Email:			
Adj Asg. Remarks:	LIAB: DISPUTE (OI NON REPORTING) . CONTACT: DANNY @ 93288668. on WP.			

ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.		

ALL ASSOCIATED TASKS <input type="checkbox"/>										<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

[https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=dsp\\_...](https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=dsp_...) 21/6/2019

## Claim Documents

\*SMJ7213A (MSC/V/19-000420)  
[FBM8948X]  
TP  
SG CAR CHOICE PRE-OWNED  
Apr 10 2019 8:00PM  
[JAAFAR BIN ABU BAKAR]  
MBM Wheelpower Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View <span style="border: 1px solid black; padding: 2px;">View in Browser</span> <input type="button" value="v"/>		
<b>Assessment Reports</b>							1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print		
1	17/04/19 13:59	Adjuster Immediate Advice			Load HTM	<input type="checkbox"/>		
<b>Photos/Images</b>							3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print		
1	11/06/19 12:18	General View			Load JPG	<input checked="" type="checkbox"/>		
2	11/06/19 12:18	General View			Load JPG	<input checked="" type="checkbox"/>		
3	11/06/19 12:18	General View			Load JPG	<input checked="" type="checkbox"/>		
4	11/06/19 12:18	General View			Load JPG	<input checked="" type="checkbox"/>		
5	11/06/19 12:18	General View			Load JPG	<input checked="" type="checkbox"/>		
6	11/06/19 12:18	General View			Load JPG	<input checked="" type="checkbox"/>		
7	11/06/19 12:18	General View			Load JPG	<input checked="" type="checkbox"/>		
8	11/06/19 12:18	General View			Load JPG	<input checked="" type="checkbox"/>		
9	11/06/19 12:18	General View			Load JPG	<input checked="" type="checkbox"/>		
10	11/06/19 12:18	General View			Load JPG	<input checked="" type="checkbox"/>		
11	11/06/19 12:18	General View			Load JPG	<input checked="" type="checkbox"/>		
12	11/06/19 12:18	General View			Load JPG	<input checked="" type="checkbox"/>		
13	11/06/19 12:18	General View			Load JPG	<input checked="" type="checkbox"/>		
14	11/06/19 12:18	General View			Load JPG	<input checked="" type="checkbox"/>		
15	11/06/19 12:18	General View			Load JPG	<input checked="" type="checkbox"/>		
16	11/06/19 12:18	General View			Load JPG	<input checked="" type="checkbox"/>		
17	11/06/19 12:18	General View			Load JPG	<input checked="" type="checkbox"/>		
18	11/06/19 12:20	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>		
19	11/06/19 12:20	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>		
20	11/06/19 12:20	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>		
21	11/06/19 12:20	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>		
22	11/06/19 12:20	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>		
<b>Documentation</b>							1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)			Thumbnail	Print		
1	15/04/19 14:00	TPD SMJ7213A - ESTIMATE & GIA REPORT			Load PDF	<input type="checkbox"/>		
2	15/04/19 14:00	TPD SMJ7213A - PRI			Load PDF	<input type="checkbox"/>		

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>			Reset	Save	Print
There are no document checklists configured.					

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Handling Insurer  
Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

Our File No: CS/MSG19006726/KSD3E2

Date: 21/06/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMS/18-991946-WTT
Claimant Vehicle No :	SMJ7213A	Insured Vehicle No :	FBM8948X
Date of Loss:	10/04/2019	Nature of Claim:	TP
		Claim No:	MSCN/19-000420

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMJ7213A</b>		
Make & Model:	MERCEDES-BENZ GLA45 AMG, 2.0 4MATIC (A)	Engine No:	27682330584254
Reg. Date:	03/11/2017 (Man. Year: 2017)	Chassis No:	WDC2533642F235086
Colour:	Metallic Dark Blue	Odometer:	15046 km
Engine Capacity:	2996 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	255/50 R19
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

The above values represent the remaining tyre treads depth

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>	
Parts	5,565.50	2,592.00	2,973.50	53.43	
Miscellaneous Items	0.00	0.00	0.00		
Labour	2,540.00	1,380.00	1,160.00	45.67	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
<b>Calculated Gross Total (S\$)</b>	<b>8,105.50</b>	<b>3,972.00</b>	<b>4,133.50</b>	<b>51.00</b>	
<b>Approved Total (Overridden) (S\$)</b>		<b>3,200.00</b>			
	(S\$)	8,105.50	3,200.00	4,905.50	60.52
<b>+ GST 7.00/7.00% (S\$)</b>	567.39	224.00	343.39	60.52	
<b>Nett Amount (S\$)</b>	<b>8,672.89</b>	<b>3,424.00</b>	<b>5,248.89</b>	<b>60.52</b>	

INSPECTION

Date of Assignment:	15/04/2019	
Date Inspected:	16/04/2019 Inspected At:	MBM Wheelpower Pte Ltd (HQ) 160 Sin Ming Drive #06-02, Sin Ming AutoCity Singapore 575722

Estimated Period of Repair: 4.0 days

---

**Adjuster:** KENNETH KONG

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 21 Jun 2019)	
<b>Parts:</b> M1-SUV	MERCEDES-BENZ GLA45 AMG 2.0 4MATIC (A) (Catalogue:Merimen Singapore 1.0)	
<b>Labour:</b> Repairer's	(Price-denominated Standard List)	
<b>Print Code:</b>	(Unsubmitted, no print-code for SMJ7213A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.		

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	1,628.00 FL	*1,300.00 FL
2	1		*REAR BUMPER COVER	Dented / Distorted	662.00 FL	*435.00 FL
3	1		*REAR BUMPER LOWER CLIP	Serviceable	876.00 FL	*- FL
4	1		*REAR LH REFLECTOR	Serviceable	86.00 FL	*- FL
5	1		*REAR LH BUMPER BRACKET	Repair	120.00 FL	*- FL
6	1		*REAR BUMPER LH RETAINER	Serviceable	118.00 FL	*- FL
7	1		*TAIL PIPE LH BRACKET	Repair	162.00 FL	*- FL
8	1		*TAIL PIPE TRIM LH	Serviceable	617.00 FL	*- FL
9	1		*REAR BUMPER LH MOUNTING	Serviceable	205.00 FL	*- FL
10	1		*TAIL LAMP LH	Cut	888.00 FL	*705.00 FL
11	1		*REAR LH ABSORBER	Serviceable	203.00 FL	*- FL
12	2		*DISTANCE SENSOR	Shorted	500.00 FL	*410.00 FL
13	2		*DECOUPLING RING	Necessary	30.00 FL	*30.00 FL
14	1		*BODY SEALANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>6,175.00</b>	<b>2,880.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	609.50	288.00
<b>Total Parts (S\$)</b>	<b>5,565.50</b>	<b>2,592.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	G-GUARD COATING	New	500.00	250.00
2	TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS	New	1,000.00	450.00
3	TO REMOVE & REPLACE BUMPER SENSORS	New	80.00	60.00
4	TO CHECK & RECONNECT ALL NECESSARY WIRING	New	60.00	20.00
5	TO SPRAY PAINT ON THE AFFECTED AREAS	New	900.00	600.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,540.00</b>	<b>1,380.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >