

ASS. REC. BY:

REF: CS/msg19006730/urvd 307

Special Instruction:

Supervisor: MARCUSASSIGNMENT (Office)From (Person): Fievel Foo win y90of MSIGDate/Time: 16.4.2019 9.24.9.m

Estimated Cost: _____

Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLK 2459YInsured: YK 5769Dat Workshop m/s Imperium AutomotiveTel: 97489940of 25 Raki Bukit Road 4, #01-49Policy No: A 29019356TmrClaim No: 590587

Sum Insured: _____

Excess: _____

Make of Veh: _____

(Client's Record)

D.O.A. 12.4.19

CA / REV / REP. / REV 24 HRS

"rwp"

H.O.D. Endorsement: _____

Date/Time: 16.4.2019

Person Contacted: _____

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate (✓)
	SLK 2459Y - NA / INC 19006605 / Y	D.O.A - 12/04/2019
	YK 5769D - NA / INC 19006605 / Y	D.O.A - 12/04/2019
17/4/19	Informed Fievel pending workshop est via merimen	
24/4/19	Send preli revised via merimen	

ASSIGNMENT

From: Date: 16/4/2019

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLK 2459Y
at Workshop m/s Imperium Automotive
of 25 kaki Bukit Rd 4 # 01-49

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 2 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up L7A52237

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLK 2459Y Yr Regn: 1.17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: Toyota corolla Altis c.c 1598

Colour: Gray A/C: Insured / Std / NI / NA

Sp. Reading: 53404 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MR053 REH104562670

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55 R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 12/4/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 7yrf. 9mth

227800 net 21763

23/4/19 1/5 6600 Confirmed with Shawn. (Red 9365.10, 596)

RECEIVED 24 APR 2019

24/4/2019

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 24/4 - typist

Report Format: merimen

Lump Sum / I.B.I: (\$ 6600/-)

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

☐ S + RS, ☐ SI

☐ Photos

☐ Others

TOTAL

200

0

210

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Apr 2019		16 Apr 2019 09:24 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	YONG SOON GENGRL CONTRACTOR PTE LTD, Co. Reg. No.: 0								
Main Claimant:	PHUA JOO KHING, ID: S2107267B								
Vehicle Reg. No.:	SLK2459Y	Date of Loss:	12/04/2019 16:00 - :59 [27 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 590587	Policy/Cover Note No.:	A29009356TMV (Third Party Only) Coverage: 25/08/2018 - 24/08/2019						
Vehicle Reg. No. (Insured):	YK5769D	Policy No. (Claimant):							
		Excess:							
Repairer:	Imperium Automotive - Kaki Bukit (HQ) 25 Kaki Bukit Road 4, #01-49 Synergy@KB, 417800 Kaki Bukit - Tel: 97489940								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 17/04/2019]								
Driver/Custodian (Insured):	LIM HOCK LEE (), NRIC: S11762681, Tel: +6598979166 Email:								
Adj Asg. Remarks:	on WP, MANUALLY ASSIGNED. LIAB: 100%. TP AGREE ON SJE - ASSIGN LKK AUTO. CONTACT: SHAWN TAN @ 9748 9940.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:	MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
-----	--	-------	---

Attn:	Fievel Foo Wen Yao	Date:	24 Apr 2019
-------	--------------------	-------	-------------

Preliminary Advice

Insured Vehicle No	: YK5769D		
TP Vehicle No	: SLK2459Y	Accident Date	: 12/04/2019
Make	: TOYOTA COROLLA ALTIS	Assignment Date	: 16/04/2019
Date of Inspection	: 16/04/2019	Est. Duration of Repair	: 4.00
Inspection At	: IMPERIUM AUTOMOTIVE - KAKI BUKIT (HQ) 25 KAKI BUKIT ROAD 4, #01-49 SYNERGY@KB SINGAPORE 417800		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,965.10
Revised Amount	:S\$	6,600.00 (LUMP SUM)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

Nivitha (LKK Auto)

From: Crystal Lee <crystal_lee@sg.msig-asia.com>
Sent: Monday, 15 April 2019 4:41 PM
To: assignments@lkkauto.com; admin-d@lkkauto.com
Cc: Ong Zi Hui
Subject: Survey Request - Manual Assigned
Attachments: 15042019163828-0001.pdf

PRI FOR SLK2459Y YOUR REF:JEQ/SLK2459/IMP OUR REF: YK5769D

Manual Assigned

Dear Sir/Mdm,

Please refer to the attachment.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment.

Thank you & Best regards,

Crystal Lee

Admin Officer, Claims Services (In-House Survey)

D: +65 6594 2535 | F: +65 6643 1349 | crystal_lee@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

Venessa Chan

From: Venessa Chan
Sent: Monday, 15 April, 2019 3:24 PM
To: Alfred Ng
Cc: Nabilah Rasol; Fievel Foo
Subject: RE: PRI FOR SLK2459Y YOUR REF:JEQ/SLK2459/IMP OUR REF: YK5769D

Dear Alfred,

Thank you for your selection of **LKK Auto Consultants.**

We will proceed to appoint **LKK Auto Consultants** via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol

Thank you.

Have A Great Week Ahead!

Venessa Chan

Admin Officer, Claims Services (Motor)

Direct line +65 6594 2470 | Direct fax +65 6225 7402 | venessa_chan@sg.msig-asia.com



MSIG



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Alfred Ng [mailto:alfred_ng@juseq.com.sg]
Sent: Monday, 15 April, 2019 2:32 PM
To: Venessa Chan <venessa_chan@sg.msig-asia.com>
Cc: Nabilah Rasol <nabilah_rasol@sg.msig-asia.com>; Fievel Foo <Fievel_Foo@sg.msig-asia.com>
Subject: Re: PRI FOR SLK2459Y YOUR REF:JEQ/SLK2459/IMP OUR REF: YK5769D

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Sir/Madam,

We refer to your email today.

Our client is agreeable to appoint the following surveyor as our single joint expert.

LKK Auto Consultants Pte Ltd.

Please be informed that our client's vehicle is available for inspection at the understated workshop:-

IMPERIUM AUTOMOTIVE

25 Kaki Bukit Road 4 #01-49,

Synergy@KB

Singapore 417800

Tel:9748 9940 Fax: 6346 7213

Mr. Shawn Tan

With Regards

Alfred Ng

Executive

On behalf of Mr Michael Yap

M/s JusEquity Law Corporation

No. 171 Chin Swee Road

#02-01/02/06 Singapore 169877

Tel : 6536 9339

Fax: 6536 5368

IMPORTANT NOTICE:

This message is intended only for the attention of the addressee and may contain legally privileged and/or confidential information. Its unauthorised use, disclosure, storage or copying is not permitted. If you are not the intended recipient, please permanently delete the original, destroy all copies and inform the sender.

----- Original Message -----

From: Venessa Chan

To: Sim Teo Koon ; Tan Mei Ling ; Alfred Ng

Cc: Nabilah Rasol ; Fievel Foo

Sent: Monday, April 15, 2019 1:31 PM

Subject: PRI FOR SLK2459Y YOUR REF:JEQ/SLK2459/IMP OUR REF: YK5769D

Dear Sir/Madam,

We refer to your email on 15.04.19.

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) Automobile Inspection Services Pte Ltd
- 4) STA Inspection Pte Ltd
- 5) **MSIG In-House Surveyors**

This Fast-Lane Settlement option is for clear-cut liability which MSIG will expedite offer @ 100% with express payment. Priority will be given to those opted for our in-house survey

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

- 1 Calvin Ang
- 2 Kenneth Kong
- 3 Marcus Chua
- 4 Henry Ng
- 5 Lau Kwok Kwong
- 6 Frankie Pang
- 7 Ng You Han
- 8 Gary Soon
- 9 Chow Bo Xiong
- 10 Axel Lee

NB:

- (a) *Fast-Lane Settlement is not applicable for cases that liability is in dispute*
- (b) If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Please contact us (MSIG) by clicking this link: motorsurvey@sg.msigg-asia.com

Thank you.

Have A Great Week Ahead!

Venessa Chan

Admin Officer, Claims Services (Motor)

Direct line +65 6594 2470 | Direct fax +65 6225 7402 | venessa_chan@sg.msigg-asia.com



MSIG



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msigg.com.sg



A Member of **MS&AD** INSURANCE GROUP

View Sent Message

This mail is associated with :

***SLK2459Y (590587)**

[YK5769D]

TP

PHUA JOO KHING

Apr 12 2019 4:00PM

[YONG SOON GENGRL CONTRACTOR PTE LTD]

Imperium Automotive - Kaki Bukit

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 17/04/2019 15:41 PM.

To MSIG_FFWY1

Subject TP SURVEY SLK 2459Y

Dear Fievel,

Please be informed that we have inspected the vehicle SLK 2459Y on 16/4/2019.

We are pending estimate from repairer.

Best Regards,

Veron Chen

DOCUMENTS SUMMARY

There are no documents.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	7267B

Vehicle Details

Vehicle No.:	SLK2459Y
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS CLASSIC 1.6 CVT
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	1ZRY347431
Chassis No.:	MR053REH104562670
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$17,987.00
Original Registration Date:	11 Jan 2017
First Registration Date:	11 Jan 2017
Transfer Count:	0
Actual ARF Paid:	\$17,987.00 8993

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Jan 2027
PARF Rebate Amount:	\$13,490.00

Intended COE Rebate Details

COE Expiry Date:	10 Jan 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,101.00
COE Rebate Amount:	\$38,747.00
Total Rebate Amount:	\$52,237.00

The information contained herein is correct as at 16 Apr 2019

OK

CHEAPEST CAR INSURANCE RENEWAL



Compare
10+ Insurers

GET A CHEAPER QUOTE NOW!

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Toyota Vios 1.5A



2.88%P.A Low Interest@Gv
Finance.2 Years Warranty.
\$1500 Down Monthly From \$468
GV Credit Pte Ltd StarAd

KA-HUP

VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND

HOTLINE: 6741 9997

[view our cars](#)

Browse by Category



Sort by Date Posted



20 results/page

16 vehicles

Toyota corolla altis

Advanced Search



Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota corolla altis		Any	Any	2017	Any	Any	Any	Available
	Toyota	Toyota Corolla Altis 1.6A Elegance	\$81,800	\$9,040 /yr	24-Mar-2017	1,598 cc	31,000 km	Sedan	Available
One And Only High-Specs Model With Sport Bodykit In The Market. 5 Years Manufacturer Warranty By Borneo Motors Till Mar 2022. Serviced & Maintained By Agent, Meticulously Taken Care Of By Single Owner...									
Republic Auto									
Posted: 16-Apr-2019 Tags: 2017 Toyota Corolla, 2017 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota									
	Toyota	Toyota Corolla Altis 1.6A Elegance	\$79,800	\$8,800 /yr	22-Mar-2017	1,598 cc	23,037 km	Sedan	Available
Low Interest From 1.99%, In House Loan Available, Low Mileage, Superb Well Maintained That Is As Good As Brand New And Smell Like Brand New! Fully Agent (Borneo Motor) Maintained With On-going Warrant...									
Dickson Automobile									
Posted: 14-Apr-2019 Tags: 2017 Toyota Corolla, 2017 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota									
	Toyota	Toyota Corolla Altis 1.6A Elegance	\$76,800	\$8,540 /yr	10-Feb-2017	1,598 cc	48,557 km	Sedan	Available
Elegance Model. 1 Owner, Non Private Hire/Leasing Car! Road Tax Till Feb 20! Agent Serviced With Proof/5 Years Warranty. Genuine Low Mileage Done 48557km. Like Brand New. 100% Accident Free. Call Now!									
Lake View Credit Pte Ltd									
Posted: 14-Apr-2019 Tags: 2017 Toyota Corolla, 2017 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota									
	Toyota	Toyota Corolla Altis 1.6A	\$82,800	\$8,880 /yr	09-Oct-2017	1,598 cc	31,000 km	Sedan	Available
Facelifted Toyota Altis! Equipped With A Much More Powerful Engine Powered With 128 Bhp! Still Under Warranty From Borneo Motors! Fully Serviced And Maintained By Borneo Motors! Only 1 Previous Owner!...									
Posted: 13-Apr-2019 Tags: 2017 Toyota Corolla, 2017 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota									
	Toyota	Toyota Camry							
Toyota Camry takes on Volkswagen's Passat									
The Toyota Camry offers more legroom for rear passengers, is sportier around corners and has more safety systems but the Volkswagen Passat is more affordable and feels more premium overall.									
Find out more!									
	Toyota	Toyota Corolla Altis 1.6A	\$82,800	\$8,890 /yr	03-Oct-2017	1,598 cc	17,000 km	Sedan	Available
Facelifted Toyota Altis! Equipped With A Much More Powerful Engine Powered With 128 Bhp! Still Under Warranty From Borneo Motors! Fully Serviced And Maintained By Borneo Motors! Only 1 Previous Owner!...									
AL Autocar Pte Ltd									
Posted: 13-Apr-2019 Tags: 2017 Toyota Corolla, 2017 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota									
	Toyota	Toyota Corolla Altis 1.6A Elegance	\$77,800	\$8,480 /yr	12-Apr-2017	1,598 cc	30,000 km	Sedan	Available

Compare

PREMIUM AD

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/04/2019 16:58
Date Of Accident	12/04/2019 16:00
Exact Location Of Accident	ALONG CHANGI SOUTH AVENUE 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK2459Y
Insured/Policyholder	
Name Of Registered Owner	PHUA JOO KHING
NRIC No	S2107267B
Email Address	SHAWN7530@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-94816557
Alternative Phone No	OTHERS-94816557

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5097197197-01
Cover Note Number	

Driver

Name of Driver	PHUA JOO KHING
NRIC No	S2107267B
Date Of Birth	15/04/1947
Occupation	INDOOR
Date Of Driving Pass	13/06/1968
Driving Experience	50 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94816557
Fax Number	
Contact Number	OTHERS-94816557
Email Address	SHAWN7530@HOTMAIL.COM

Address	BLK 745 YISHUN STREET 72 #05-177
Postcode	2276
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN (COLLISION TYPE IS TP REVERSE AND HIT INSURED)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YK5769D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	LIM HOCK LEE
NRIC/Passport Number	
Contact Number	98979166
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.



8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

 13/04/2019
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No: 

SKETCH PLAN

(B) YK5769D



I going straight Road I saw Vehicle B YK 57690 was Reverse in a one way direction. My car stop try to back and Vehicle B Hit me.

I Got Video Footage.

I/We declare the foregoing particulars are true in every respect.

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No: _____

Special Nett Items

1	Front bumper clip (1 set)	rec	\$	60.00	50
1	Front number plate with holder	sent	\$	50.00	40
			\$	110.00	

S/N. Labour Charges

1	To check wiring and reset headlamps focussing.	\$	80.00	30
2	To remove, replace air-con condenser and conduct leakage test.	\$	180.00	100
3	To apply tuff kote.	\$	180.00	60
4	Panel beating.	\$	1,500.00	600
5	To respray painting on the affected areas.	\$	1,400.00	800
		\$	3,340.00	

Grand Total : \$ 15,965.10

8296.69
6637

Insurance Consultants are notified
the for name of the firm is:

- To remove, replace, repair painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplemental agreement is resurveyed and
is subject to the insurance company

Acknowledged by Repainer:
Signature:
Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Apr 2019		16 Apr 2019 09:24 Edit Adj Rpt	S\$6,600.00 Edit Estimates	S\$6,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	YONG SOON GENGRL CONTRACTOR PTE LTD , Co. Reg. No.: 0								
Main Claimant:	PHUA JOO KHING , ID: S2107267B								
Vehicle Reg. No.:	SLK2459Y	Date of Loss:	12/04/2019 16:00 - :59 [27 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 590587	Policy/Cover Note No.:	A29009356TMV (Third Party Only) Coverage: 25/08/2018 - 24/08/2019						
Vehicle Reg. No. (Insured):	YK5769D	Policy No. (Claimant):							
		Excess:							
Repairer:	Imperium Automotive - Kaki Bukit (HQ) 25 Kaki Bukit Road 4, #01-49 Synergy@KB, 417800 Kaki Bukit - Tel: 97489940								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 16/05/2019]								
Driver/Custodian (Insured):	LIM HOCK LEE (), NRIC: S1176268I, Tel: +6598979166 Email:								
Adj Asg. Remarks:	on WP. MANUALLY ASSIGNED. LIAB: 100%. TP AGREE ON SJE - ASSIGN LKK AUTO. CONTACT: SHAWN TAN @ 9748 9940.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLK2459Y (590587)
[YK5769D]
TP
PHUA JOO KHING
Apr 12 2019 4:00PM
[YONG SOON GENGRL CONTRACTOR PTE LTD]
Imperium Automotive - Kaki Bukit

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports						1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)					Thumbnail	Print	
1	15/04/19 17:40	Accident Statement From: SC - Reg. No: YK5769D, Claimant: YONG SOON GENGRL CONTRACTOR PTE LTD					Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	24/04/19 09:40	Adjuster Immediate Advice					Load HTM		
Photos/Images						3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	24/04/19 09:33	General View					Load JPG	<input checked="" type="checkbox"/>	
2	24/04/19 09:33	General View					Load JPG	<input checked="" type="checkbox"/>	
3	24/04/19 09:33	General View					Load JPG	<input checked="" type="checkbox"/>	
4	24/04/19 09:33	General View					Load JPG	<input checked="" type="checkbox"/>	
5	24/04/19 09:33	General View					Load JPG	<input checked="" type="checkbox"/>	
6	24/04/19 09:33	General View					Load JPG	<input checked="" type="checkbox"/>	
7	24/04/19 09:33	General View					Load JPG	<input checked="" type="checkbox"/>	
8	24/04/19 09:33	General View					Load JPG	<input checked="" type="checkbox"/>	
9	24/04/19 09:33	General View					Load JPG	<input checked="" type="checkbox"/>	
10	24/04/19 09:33	General View					Load JPG	<input checked="" type="checkbox"/>	
11	24/04/19 09:33	General View					Load JPG	<input checked="" type="checkbox"/>	
12	24/04/19 09:33	General View					Load JPG	<input checked="" type="checkbox"/>	
13	24/04/19 09:33	General View					Load JPG	<input checked="" type="checkbox"/>	
14	24/04/19 09:33	General View					Load JPG	<input checked="" type="checkbox"/>	
15	24/04/19 09:33	General View					Load JPG	<input checked="" type="checkbox"/>	
16	24/04/19 09:33	General View					Load JPG	<input checked="" type="checkbox"/>	
17	24/04/19 09:33	General View					Load JPG	<input checked="" type="checkbox"/>	
18	24/04/19 09:33	General View					Load JPG	<input checked="" type="checkbox"/>	
19	24/04/19 09:33	General View					Load JPG	<input checked="" type="checkbox"/>	
20	24/04/19 09:33	General View					Load JPG	<input checked="" type="checkbox"/>	
21	24/04/19 09:33	General View					Load JPG	<input checked="" type="checkbox"/>	
22	24/04/19 09:33	General View					Load JPG	<input checked="" type="checkbox"/>	
23	24/04/19 09:33	General View					Load JPG	<input checked="" type="checkbox"/>	
24	24/04/19 09:33	General View					Load JPG	<input checked="" type="checkbox"/>	
25	24/04/19 09:33	General View					Load JPG	<input checked="" type="checkbox"/>	
26	24/04/19 09:33	General View					Load JPG	<input checked="" type="checkbox"/>	
27	24/04/19 09:33	General View					Load JPG	<input checked="" type="checkbox"/>	
28	24/04/19 09:33	General View					Load JPG	<input checked="" type="checkbox"/>	
29	24/04/19 09:33	General View					Load JPG	<input checked="" type="checkbox"/>	
30	24/04/19 09:33	General View					Load JPG	<input checked="" type="checkbox"/>	
31	24/04/19 09:33	General View					Load JPG	<input checked="" type="checkbox"/>	
32	24/04/19 09:33	General View					Load JPG		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
33	24/04/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
34	24/04/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
35	24/04/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
36	24/04/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
37	24/04/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
38	24/04/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
39	24/04/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
40	24/04/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
41	24/04/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
42	24/04/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
43	24/04/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
44	24/04/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
45	24/04/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
46	24/04/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
47	24/04/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
48	24/04/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
49	24/04/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
50	24/04/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
51	24/04/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
52	24/04/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
53	24/04/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
54	24/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	24/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	24/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	24/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	24/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	24/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	24/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	24/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	24/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	24/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	24/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	24/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	24/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	24/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	24/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	24/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	24/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	24/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	24/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	24/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	24/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	24/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	24/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	24/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	24/04/19 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
79	24/04/19 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
80	24/04/19 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
81	24/04/19 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
82	24/04/19 09:34	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
83	24/04/19 09:34	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
84	24/04/19 09:34	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
85	24/04/19 09:34	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
86	24/04/19 09:34	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
87	24/04/19 09:34	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
88	24/04/19 09:34	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
89	24/04/19 09:34	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
90	24/04/19 09:34	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
91	24/04/19 09:34	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
92	24/04/19 09:34	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
93	24/04/19 09:34	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
94	24/04/19 09:34	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
95	24/04/19 09:34	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
96	24/04/19 09:34	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
97	24/04/19 09:34	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
98	24/04/19 09:34	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
99	24/04/19 09:34	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
100	24/04/19 09:34	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
101	24/04/19 09:34	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
102	24/04/19 09:34	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
103	24/04/19 09:34	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
104	24/04/19 09:34	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
105	24/04/19 09:34	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
106	24/04/19 09:34	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
107	24/04/19 09:34	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
108	24/04/19 09:34	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
109	24/04/19 09:34	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
110	24/04/19 09:34	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
111	24/04/19 09:34	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
112	24/04/19 09:34	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
113	24/04/19 09:34	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
114	24/04/19 09:34	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
115	24/04/19 09:34	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
116	24/04/19 09:34	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
117	24/04/19 09:34	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
118	24/04/19 09:34	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
119	24/04/19 09:34	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	15/04/19 17:40	E-FILE REPORT (SLK2459Y) From: SC - Reg. No: YK5769D, Claimant: YONG SOON GENGRL CONTRACTOR PTE LTD		Load PDF	
2	15/04/19 17:45	TP PRI & ACCDT REPORT		Load PDF	
3	16/04/19 08:01	TP agree on SJE		Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)		Thumbnail	Print
1	16/04/19 09:20	email - manual assign		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)



Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19006730/UVD3E2

Date: 07/05/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29009356TMV

Claimant Vehicle
No : SLK2459Y

Insured Vehicle No : YK5769D

Date of Loss: 12/04/2019

Nature of Claim: TP

Claim No: 590587

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLK2459Y

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Engine No: 1ZRY347431

Reg. Date: 11/01/2017 (Man. Year: 2016)

Chassis No: MR053REH104562670

Colour: Grey

Odometer: 53404 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,625.10	6,706.69	5,918.41	46.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,340.00	1,590.00	1,750.00	52.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,965.10	8,296.69	7,668.41	48.03
Approved Total (Overridden) (S\$)		6,600.00		
Nett Amount (S\$)	15,965.10	6,600.00	9,365.10	58.66

INSPECTION

Date of Assignment: 16/04/2019

Date Inspected: 16/04/2019 Inspected At:

Imperium Automotive - Kaki Bukit (HQ)

25 Kaki Bukit Road 4, #01-49

Synergy@KB

Singapore 417800

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 May 2019)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK2459Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented / Buckled	1,240.50 FL	*1,218.15 FL
2	2		*FRONT BONNET HINGES	Not Necessary	235.00 FL	*- FL
3	1		*FRONT BONNET LOCK	Twisted	160.10 FL	*160.10 FL
4	2		*FRONT BONNET RUBBER	Necessary	90.90 FL	*70.00 FL
5	2		*FRONT HEADLAMPS	Holder Cracked	5,633.40 FL	*1,890.40 FL
6	2		*FRONT HEADLAMPS PANELS	Repair	401.80 FL	*- FL
7	1		*FRONT GRILLE ASSY	Cracked	564.00 FL	*372.80 FL
8	1		*FRONT GRILLE LOGO	Necessary	68.00 FL	*48.50 FL
9	1		*FRONT BUMPER	Dented / Deformed	700.60 FL	*561.60 FL
10	2		*FRONT BUMPER FOG LAMPS	Not Necessary	401.60 FL	*- FL
11	2		*FRONT BUMPER FOG LAMP COVERS	Not Necessary	379.80 FL	*- FL
12	1		*FRONT BUMPER INNER SPONGE	Torn	166.70 FL	*105.30 FL
13	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	300.80 FL	*- FL
14	1		*FRONT BUMPER LOWER CENTRE MOULDING	Not Necessary	155.00 FL	*- FL
15	1		*FRONT BUMPER REINFORCEMENT	Bent	480.50 FL	*374.40 FL
16	2		*FRONT BUMPER SIDE RETAINERS	Bent	161.80 FL	*133.00 FL
17	1		*FRONT SUPPORT PANEL	Bent / Twisted	1,074.50 FL	*945.11 FL
18	1		*FRONT BRACE PANEL	Twisted	225.20 FL	*145.20 FL
19	2		*HORNS	Not Necessary	178.00 FL	*- FL
20	1		*AIR CON CONDENSER	Bent / Punctured	1,287.20 FL	*1,287.20 FL
21	1		*RADIATOR	Bent / Twisted	1,510.50 FL	*1,510.50 FL
22	1		*RADIATOR FAN BLADE	Not Necessary	155.50 FL	*- FL
23	1		*RADIATOR FAN COWLING	Not Necessary	233.80 FL	*- FL
24	1		*RADIATOR FAN MOTOR	Not Necessary	699.80 FL	*- FL
25	2		*RADIATOR TOP MOUNTINGS	Not Necessary	181.80 FL	*- FL
26	1		*SET FRONT BUMPER CLIP	Necessary	60.00 FS	*50.00 FS
27	1		*FRONT NUMBER PLATE WITH HOLDER	Bent	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,796.80	8,912.26
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,171.70	2,205.57
Total Parts (\$\$)	12,625.10	6,706.69

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING	New	80.00	30.00
2	TO REMOVE, REPLACE AIR-CON CONDENSER AND CONDUCT LEAKAGE TEST	New	180.00	100.00
3	TO APPLY TUFF KOTE	New	180.00	60.00
4	PANEL BEATING	New	1,500.00	600.00
5	TO RESPRAY PAINTING ON THE AFFECTED AREAS	New	1,400.00	800.00
Gross Labour Cost (S\$)			3,340.00	1,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >