

ASS. REC. BY:

REF: CS³/MSG190067351 Gcd3^{SP}

Special Instruction:

Director: GR

Minivan

ASSIGNMENT (Office)

From (Person): Monica Chung Pui Shan of MSIG

Date/Time: 16.4.19 10.27.a.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBE 740Y

Insured: SKL 8320E

at Workshop m/s RS Automotive

Tel: 67483032 / 91826089

of 3066 ubi road | # 01-3941384

Policy No: 27633063smp

Claim No: _____

Sum Insured: _____

Excess: _____

Make of Veh:

(Client's Record)

D.O.A. 12.4.2019

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement: _____

Date/Time: 16.4.19 11.06a.m

Person Contacted: Richard

Vehicle IN / OUT

Date/Time	Action/Instruction	Estimate	X
	GBE 740Y - X		
	SKL 8320E - X		
	Dismantle: 18/4/2019		

PPS
Surveyor bul.

REF: MS19

ASSIGNMENT

From: _____ Date: 16.4.2019

Veh No: GBE 740Y Yr Regn: 26 Aug 2015

Estimated Cost: _____

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: GBE 740Y

Make: Nissan NV350 c.c. 2488

at Workshop m/s: RS AUTOMOTIVE

Colour: Silver A/C: Insured / Std / NI / NA

of 3066 ubi road 1 # 01-394/388

Sp. Reading: 124472 T/Radio: Insured / Std / NI / NA

Insured: _____

Eng/No: _____

Policy No. _____

C/No: JN1MC2E 26 20003150

Claims No. _____

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: _____ Excess: _____

Steering: In Order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In Order / Jammed / Leaked / Burnt or

Make of Veh: _____


Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 195R15

R: 11

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value: _____

Front _____ Rear _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

R/Bal. 5 mm

GIA / PR Seen: _____ Consistent? : Yes or No

L/Bal. 5 mm

Est. Repairs: 12 days Res.: Yes or No

D.O.A. _____ D.O.I. 16-04-19

Lum Sum: _____ % 3 Val.: Yes or No

Survey held at _____ w/s _____ 4pm

CA / REV / REP. / 24 HRS nwp"

Des. of Damages: Fr / Rear / O/S / N/S / UIC / Rooftop or

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>\$10k - \$12k</u>
	<u>18/4/2019</u>

Date/Time, File Pass to? : Preli. Report

Days Of Repair: 12

1) : Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee:	
Transportation:	
S + RS, SI	
Photos	
Others	
TOTAL	

2) _____

Add Fee: : Site Insp (\$)

Report Format : PRS

: Interview (\$)

Lump Sum / I.B.I. (\$) _____)

: Tech. Invs (\$)

: Weekend (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Apr 2019 14:50		16 Apr 2019 10:27 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS [\[Created by insurer\]](#)

Insured:	CHEN ZIFEI, ID: S2739016A		
Main Claimant:	SEE FWA ELECTRONICS & ELECTRICAL ENGINEERING, Co. Reg. No.: 21593200E		
Vehicle Reg. No.:	GBE740Y	Date of Loss:	12/04/2019 00:00 - :59 [43 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	27633063SMP Coverage: 27/12/2018 - 26/12/2019
Vehicle Reg. No. (Insured):	SKL8320E	Policy No. (Claimant):	
Repairer:	RS Automotive Workshop (HQ) 3066 Ubi Road 1, #01-394/384, 408700 Ubi - Tel: 67483032		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 17/04/2019]		
Driver/Custodian (Insured):	CHEN YINGLING (), NRIC: S8673572E Email:		
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY:DISPUTE. CONTACT:RICHARD 9182 6089 . on WP.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/04/2019 15:35
Date Of Accident	12/04/2019 09:50
Exact Location Of Accident	BEDOK NORTH AVE 3 BEFORE JUNC BEDOK NORTH RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBE740Y
Insured/Policyholder	
Name Of Registered Owner	SEE FWA ELECTRONICS & ELECTRICAL ENGINEERING
Co Reg No	21593200E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81253305
Alternative Phone No	OFFICE-81253305

Vehicle Particulars

Manufacturer	NISSAN
Model	NV350 PANEL VAN 2.5 5MT 5DR EURO V
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5082851040-02
Cover Note Number	

Driver

Name of Driver	KOK LEE SIONG
NRIC No	S2557478H
Date Of Birth	27/03/1962
Occupation	OUTDOOR
Date Of Driving Pass	27/10/1983
Driving Experience	35 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94571771
Fax Number	
Contact Number	OFFICE-94571771
EMail Address	NOEMAIL

Address BLK 418 BEDOK NORTH AVENUE 2
#09-97

Postcode 460418

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -
-
-

Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1
NAME: : LEE SIOW YONG
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name BEDOK NORTH NEIGHBOURHOOD POLICE CENTRE

Police Station Address ROAD: 30 BEDOK NORTH ROAD , POSTCODE: 469676 , COUNTRY: SINGAPORE

Police Station Contact TEL NO: 1800-2449999 - FAX NO: 62447258

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT - T/20190412/2077.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKL8320E

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

DETAILS OF INJURED PERSON 1

Name LEE SIOW YONG

Approximate Age

Injuries Sustain BODY

Injured person in which vehicle? GBE740Y

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Person's Signature
Name:
NRIC/FIN No.:

Police Report



**SINGAPORE
POLICE FORCE**



T/20190412/2077

Police Station Of Origin:
Bedok North N.P.C
30 Bedok North Road SINGAPORE 469676
Tel No: 1800-2449999

1 of 3

Report No. T/20190412/2077

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 12/04/2019 14:17		Vide Report No.: G/20190412/0055		Station Diary No.: 91	
Informant's Particulars					
Name of Informant: KOK LEE SIONG			Address: APT BLK 418 BEDOK NORTH AVENUE 2 #09-97 SINGAPORE 460418		
ID Type / ID No.: NRIC NO / S2557478H			Contact No.: Home/Office: Mobile: 94571771		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 57	Date of Birth: 27/03/1962	Type of Informant: Driver		
Race: Chinese		Language: English		Institution / School Name:	
Occupation: Electrician		Driving Licence Information: Class: 2B,2A,3 Date of Expiry:			

General Information of the Accident				
Type of Accident: Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 12/04/2019 09:50	Type of Location: Straight Road	
Location: Along Road 1 BEDOK NORTH AVENUE 3 ALONG BEDOK NORTH AVE 3 TOWARDS BEDOK RESERVOIR NEAR TO BETHESA BEDOK-TAMPINES CHURCH				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBE740Y	Van	NISSAN	NV350 PANEL VAN 2.5 5MT 5DR EURO V	Silver	Seriously Damaged	1
SKL8320E	Car	BMW	520I AT D/AB 2WD 4DR LED NAV	Blue		0

Police Report



**SINGAPORE
POLICE FORCE**



T/20190412/2077

Police Station Of Origin:
Bedok North N.P.C
30 Bedok North Road SINGAPORE 469676
Tel No: 1800-2449999

2 of 3

Report No. T/20190412/2077

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	KOK LEE SIONG	ID No.	S2557478H
Related Vehicle	GBE740Y (Van)	Contact No.	94571771
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 12/04/2019 at about 0950hrs, I was driving my vehicle GBE740Y along Bedok North Ave 3 towards Bedok Reservoir Rd. While approaching the carpark entrance of Blk 401 Bedok North Ave 3, one vehicle, SKL8320E, driving on the opposite direction along Bedok North Ave 3 towards New Upp Changi Rd, made a right turn towards the carpark entrance of Blk 401. However, I was traveling straight and the front of vehicle SKL8320E collided onto the right front side of my vehicle. I had one passenger at that time. Both of us got down our vehicles and no one was injured. As the collision caused my vehicle to swerved to the left, my vehicle knocked onto one lamppost. Subsequently, Traffic Police arrived and I was given a case card reference no: G/20190412/0055 and advised to lodge this police report.

Police Report



**SINGAPORE
POLICE FORCE**



T/20190412/2077

Police Station Of Origin:
Bedok North N.P.C
30 Bedok North Road SINGAPORE 469676
Tel No: 1800-2449999

3 of 3



Report No. T/20190412/2077

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sgt 2 KOH WEN RUI 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 12/04/2019 14:17
Officer In Charge Of Case: TP / GIT / Insp TAN CHIN YONG Contact No.: 65476178 	Classification Of Case:
Authentication Stamp NP168	

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Business
Owner ID:	3200E
Vehicle No.:	GBE740Y
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Apr 2019
Vehicle Make:	NISSAN
Vehicle Model:	NV350 PANEL VAN 2.5 5MT 5DR EURO V
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	YD25355465A
Chassis No.:	JN1MC2E26Z0003150
Maximum Power Output:	-
Open Market Value:	\$23,914.00
Original Registration Date:	26 Aug 2015
First Registration Date:	26 Aug 2015
Transfer Count:	0
Actual ARF Paid:	\$1,196.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	25 Aug 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$37,786.00
COE Rebate Amount:	\$24,022.00
Total Rebate Amount:	\$24,022.00

The information contained herein is correct as at 16 Apr 2019

OK

▶ NV350 Used Vehicle List (7 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
Nissan NV350 2.5M (Diesel)	\$44,800	\$7,420 /yr	28-Apr-2015	2,488 cc	106,478 km	ABWIN Bus Pte Ltd	Available

\$168 Drive-away! Flexible In House Loan. Low Mileage Van. Regular Servicing Done At Tan Chong Since Day 1. Tip Top Condition Plus Warranty Given. Original Paintwork Same As New Unit. Well Care By Ex-o...

Office No. - 69339414

Yi - 92415583 | Ah Chong - 91297320

Nissan NV350 2.5A (Diesel)	\$58,900	\$9,630 /yr	28-May-2015	2,488 cc	63,627 km	William's Auto	Available
-----------------------------------	-----------------	-------------	-------------	----------	-----------	----------------	------------------

10 Seaters Excursion Bus In Excellent Condition. Well Maintained And Regularly Serviced. Call Now For Viewing Appointment!

Office No. - 67436811

Mr Png - 97942630

Nissan NV350 2.5A (Diesel)	\$43,800	\$7,060 /yr	30-Jun-2015	2,488 cc	-	Skylink Auto Pte Ltd	Available
-----------------------------------	-----------------	-------------	-------------	----------	---	----------------------	------------------

One Of The Lowest Depreciation! Low Maintenance And Good Fuel Economy Model! High Loan And Trade-In Available!

Office No. - 62665858

Jack - 96686090 | Sky - 97300832 | Chris - 82549889 | David - 98806776

Nissan NV350 2.5M (Diesel)	\$52,800	\$8,240 /yr	10-Sep-2015	2,488 cc	80,064 km	Car (S) Pte Ltd	Available
-----------------------------------	-----------------	-------------	-------------	----------	-----------	-----------------	------------------

Get In Touch With Our Friendly Sales Consultant Right Away For An Non Obligation Viewing! Loan Available! Free Rear Passenger Seats, 1 Owner, Carpeted Floorboard, Stock Condition, Original Paintwork. ...

Office No. - 63863322

Ray - 81281193 | Joel - 96558282

Nissan NV350 2.5A (Diesel)	\$58,800	\$8,840 /yr	10-Dec-2015	2,488 cc	130,000 km	ABWIN (1994) Pte Ltd	Available
-----------------------------------	-----------------	-------------	-------------	----------	------------	----------------------	------------------

1 Owner! Affordable Monthly Cheaper Than Leasing! Best Time To Purchase Now As Price Quantum Is Lowest In Past 3 Years! Cheapest In Town! 100% Loan Available. High Trade In Welcome. ETS Welcome. Low I...

Office No. - -

Jarrett Goh - 91013261 | Alson - 93897875 | Ah Hwee - 81984020

Nissan NV350 2.5A (Diesel)	\$50,800	\$7,610 /yr	17-Dec-2015	2,488 cc	-	ABWIN Bus Pte Ltd	Available
-----------------------------------	-----------------	-------------	-------------	----------	---	-------------------	------------------

1 Owner! Affordable Monthly Cheaper Than Leasing! Best Time To Purchase Now As Price Quantum Is Lowest In Past 3 Years! Cheapest In Town! Full Loan Available. Trade In Welcome. Low Interest Rate, Bank ...

Office No. - 69339414

KK Tang - 81245503 | Nicholas - 96793310

Nissan NV350 2.5A (Diesel)	\$49,800	\$7,420 /yr	31-Dec-2015	2,488 cc	-	Car (S) Pte Ltd	Available
-----------------------------------	-----------------	-------------	-------------	----------	---	-----------------	------------------

Low Monthly Installment! Full Cash Payment Are Also Welcome! Single Owner! Modification Available To Cater For Your Industry Needs! Definitely Reliable Yet Low Maintenance With Very High Productivity!...

Office No. - 63863322

Winson - 83802211 | Leon Teo - 92329611 | Rain Lim - 81027051 | William Low - 91776311

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2019 sgCarMart. All rights reserved.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Apr 2019 14:50		16 Apr 2019 10:27 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CHEN ZIFEI , ID: S2739016A		
Main Claimant:	SEE FWA ELECTRONICS & ELECTRICAL ENGINEERING , Co. Reg. No.: 21593200E		
Vehicle Reg. No.:	GBE740Y	Date of Loss:	12/04/2019 09:00 - :59 [43 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 590654	Policy/Cover Note No.:	B27633063SMP (Comprehensive) Coverage: 27/12/2018 - 26/12/2019
Vehicle Reg. No. (Insured):	SKL8320E	Policy No. (Claimant):	
		Excess:	S\$700.00
Repairer:	RS Automotive Workshop (HQ) 3066 Ubi Road 1, #01-394/384, 408700 Ubi - Tel: 67483032		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 17/04/2019]		
Driver/Custodian (Insured):	CHEN YINGLING (), NRIC: S8673572E Email:		
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY:DISPUTE. CONTACT:RICHARD 9182 6089 . on WP.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Claim Documents

***GBE740Y (590654)**
[SKL8320E]
TP
SEE FWA ELECTRONICS & ELECTRICAL ENGINEERING
Apr 12 2019 9:00AM
[CHEN ZIFEI]
RS Automotive Workshop

Upload Documents Upload Photos Compose New Letter			View <input type="button" value="View in Browser"/>
Photos/Images			3 per page <input type="button" value="Print"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail
1	18/04/19 10:04	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
2	18/04/19 10:04	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
3	18/04/19 10:04	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
4	18/04/19 10:04	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
5	18/04/19 10:04	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
6	18/04/19 10:04	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
7	18/04/19 10:04	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
8	18/04/19 10:04	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
9	18/04/19 10:04	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
10	18/04/19 10:04	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
11	18/04/19 10:04	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
12	18/04/19 10:04	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
13	18/04/19 10:04	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
14	18/04/19 10:04	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
15	18/04/19 10:04	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
16	18/04/19 10:04	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
17	18/04/19 10:04	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
18	18/04/19 10:04	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
19	18/04/19 10:04	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
20	18/04/19 10:04	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
21	18/04/19 10:04	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
22	18/04/19 10:04	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
23	18/04/19 10:04	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
24	18/04/19 10:04	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
25	18/04/19 10:04	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
26	18/04/19 10:04	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
27	18/04/19 10:04	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
28	18/04/19 10:04	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
29	18/04/19 10:04	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
30	18/04/19 10:04	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
31	18/04/19 10:04	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
32	18/04/19 10:04	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
33	18/04/19 10:04	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
34	18/04/19 10:04	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
35	18/04/19 10:04	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
37	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
38	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
39	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
40	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
41	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
42	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
43	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
44	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
45	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
46	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
47	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
48	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
49	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
50	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
51	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
52	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
53	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
54	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
55	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
56	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
57	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
58	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
59	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
60	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
61	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
62	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
63	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
64	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
65	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
66	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
67	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
68	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
69	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
70	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
71	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
72	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
73	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
74	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
75	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
76	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
77	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
78	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
79	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
80	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
81	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
82	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
83	18/04/19 10:04	General View	Load JPG	<input checked="" type="checkbox"/>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19006735/GCD3S2
Date: 02/05/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: B27633063SMP
Claimant Vehicle No: GBE740Y Insured Vehicle No: SKL8320E
Date of Loss: 12/04/2019 Nature of Claim: TP Claim No: 590654

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBE740Y** Engine No: YD25355465A
Make & Model: NISSAN NV350, 2.5 5MT 5DR EURO V (A) Chassis No: JN1MC2E26Z0003150
Reg. Date: 26/08/2015 (Man. Year: 2014) Odometer: 124472 km
Colour: Silver
Engine Capacity: 2488 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm
Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 16/04/2019
Date Inspected: 16/04/2019 Inspected At: RS Automotive Workshop (HQ)
3066 Ubi Road 1, #01-394/384
Singapore 408700
Estimated Period of Repair: 12.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$10,000.00 - \$12,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 02 May 2019)

Parts: N/A NISSAN NV350 2.5 5MT 5DR EURO V (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBE740Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >