

ASS. REC. BY:

REF:

CS/2019006739/ KS d3024

Special Instruction:

Surveyor: Kenneth

Minim

ASSIGNMENT (Office)

From (Person): Grah Pau Loong

of

SMD

Date/Time: 16.4.2019 10.42.9.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGL 1433 L

Insured:

at Workshop m/s Lai Huat (nung ku)

Tel:

64538110

of 160 Sin ming Drive # 04-01

Policy No: D18 MTPV 01018959

Claim No: CMTD1901886

Sum Insured:

Excess:

TBA

Make of Veh:

(Client's Record)

D.O.A 12.4.2019

22.4.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 16.4.19 10.52.9.m

Person Contacted:

Jenny

Vehicle IN (OUT)

Date/Time

Action/Instruction

Estimate (✓)

SGL 1433 L - X

22/4/19

@ 14:49 p.m. revised PA to Grah Pau Loong
via minim

22/4/19

@ 14:51 p.m. mandate required authorise repair
to Grah Pau Loong via minim

Surveyor

REF: SMO CS/SMO1900 6739/ ksd3

ASSIGNMENT

From: Date: 22.4.2019

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SGK 1433 L

at Workshop m/s Lai Huat

of 160 sin ming Drive # 04-01

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


\$0-70A

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 8741

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / (REV) / REP. / 24 HRS

"WP"

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SGK 1433L

Yr Regn:

11 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Bmw 316i

C.C.

1500

Colour

N.P. white

A/C:

Insured / Std / NI / NA

Sp. Reading

86144

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBA3A16090NS38209

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

7

mm

L/Bal.

6

mm

L/Bal.

7

mm

D.O.A.

12/4/19

D.O.I.

22/4/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
22/04/19 @ 16:22 p.m.	mandate approved by Pau Wong via messenger
22/04/19 @ 17:51 p.m.	revert authorise repair to Terry (repairer) via email.
13/5 81734.20 Cashmere	(\$80/- Rd - 4%)

[Signature]

23/5/2019

Date/Time, File Pass to?

24/05/19

1) Typist

Date/Time, File Return to?

2)



: Preli. Report



: Final Report

Days Of Repair: 2

Resurvey No. of Trip: 2

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

290

Transportation:

\$ + RS, \$ SI

Photos

Others

11

TOTAL

261

Report Format :

Lump Sum / I.B.I: (\$ 1734.20 P/P)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Apr 2019 Sendback Est	16 Apr 2019 09:59 S\$1,539.20	16 Apr 2019 10:42 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	VOON SWEE SANG, ID: S18286451		
Vehicle Reg. No.:	SGK1433L	Date of Loss:	12/04/2019 19:00 - :59 [52 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / CMTD1901886	Policy/Cover Note No.:	D18MTPV01018959 (Comprehensive)
		Excess:	
Repairer:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 26/04/2019]		
Driver/Custodian:	JOEY VOON CHIN YONG (27 / Male), NRIC: S9143462H, Tel: +6592221353 Email: traveleher@gmail.com		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

MV - \$741K

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	86451
Vehicle Details	
Vehicle No.:	SGK1433L
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Apr 2019
Vehicle Make:	B.M.W.
Vehicle Model:	316i 1.6 AT D/AB 4DR ABS HID
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	A751J775N13B16A
Chassis No.:	WBA3A16090NS38209
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$28,891.00
Original Registration Date:	27 Nov 2014
First Registration Date:	27 Nov 2014
Transfer Count:	1
Actual ARF Paid:	\$22,448.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Nov 2024
PARF Rebate Amount:	\$16,836.00
Intended COE Rebate Details	
COE Expiry Date:	26 Nov 2024
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$72,890.00
COE Rebate Amount:	\$40,777.00
Total Rebate Amount:	\$57,613.00

The information contained herein is correct as at 22 Apr 2019

OK

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 24 May 2019 5:03 PM
To: 'Jenny Lim'
Cc: 'Kenneth Kong'
Subject: RE: Finalisation - SGK 1433L / BMW 316i
Attachments: SGK 1433L - SUPPLEMENTARY MARKED.pdf

Dear Jenny,

Supplementary approved by insurance.

Confirmed final fig of \$ 1,734.20 (part by part) @ 2 days of repairs before excess \$0/- & GST.

Final invoice and all supporting documents sent over to Sompo Insurance Singapore Pte. Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jenny Lim [mailto:jenny.lim@laihuat.com.sg]
Sent: Friday, 10 May 2019 4:26 PM
To: Kenneth Kong <KennethKong@lkkauto.com>
Subject: Finalisation - SGK 1433L / BMW 316i

Dear Sir

For your confirmation, please:

- Parts: \$1,122.00 (include supplementary)
- 10%: \$ 112.20
- L&P: \$ 500.00
- Total: \$1,734.20 / 2 days**

Supporting documents and photographs are enclosed for your reference.

Thank you.

Kind regards.

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596267

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 22 April 2019 5:51 PM
To: jenny.lim@laihuat.com.sg
Cc: SUR
Subject: SGK 1433L OD 12/04/2019

Dear Jenny,

As instructed by our client, please proceed to repair the insured vehicle **SGK 1433L (Excess \$ 0/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

SGK1433L (CMTD1901886)

OD

Apr 12 2019 7:00PM

[VOON SWEE SANG]

Lai Huat (Meng Kee) Motor Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From Sampo Insurance Singapore Pte. Ltd. (SOMPO_SG), sent on 23/05/2019 11:22 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$1734.20) - SGK1433L - Claim Handler: GNOH PAU LOONG

Approved:1734.20.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

SGK1433L (CMTD1901886)

OD

Apr 12 2019 7:00PM

[VOON SWEE SANG]

Lai Huat (Meng Kee) Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From Sampo Insurance Singapore Pte. Ltd. (SOMPO_SG), sent on 22/04/2019 16:22 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$1459.20) - SGK1433L - Claim Handler: GNOH PAU LOONG

Approved:1459.20.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: GNOH PAU LOONG

Date: 23 May 2019

Preliminary Advice

Vehicle No	: SGK1433L	Accident Date	: 12/04/2019
Make	: BMW 316I	Policy No.	: D18MTPV01018959
Assignment Date	: 16/04/2019	Excess	: S\$0.00
Date of Inspection	: 22/04/2019	Est. Duration of Repair	: 2 days
Inspection At	: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity Singapore 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,814.20 (INCLUSIVE SUPPLEMENTARY)
Revised Amount	:S\$	1,734.20 (INCLUSIVE SUPPLEMENTARY)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,734.20
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have received supplementary from repairer. Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair. Supplementary amount is \$ 275.00.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: GNOH PAU LOONG

Date: 22 Apr 2019

Preliminary Advice

Vehicle No	: SGK1433L	Accident Date	: 12/04/2019
Make	: BMW 316I	Policy No.	: D18MTPV01018959
Assignment Date	: 16/04/2019	Excess	: S\$0.00
Date of Inspection	: 22/04/2019	Est. Duration of Repair	: 2 days
Inspection At	: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity Singapore 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,539.20
Revised Amount	:S\$	1,322.00
Check Items (Estimated)	:S\$	137.20
Total	:S\$	1,459.20
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	74,000.00
COE / PARF Rebate	:S\$	57,613.00
Salvage Value	:S\$	
Margin for Repair	:S\$	16,387.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/04/2019 18:14
Date Of Accident	12/04/2019 19:20
Exact Location Of Accident	TERMINAL 4 CARPARK 4A
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGK1433L
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	VOON SWEE SANG
NRIC No	S1828645I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97885382
Alternative Phone No	OTHERS-97885382

Vehicle Particulars

Manufacturer	BMW
Model	316I 1.6 AT D/AB 4DR ABS HID
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle?	YES
--	-----

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01018959
Cover Note Number	NA

Driver

Name of Driver	JOEY VOON CHIN YONG
NRIC No	S9143462H
Date Of Birth	30/11/1991
Occupation	INDOOR
Date Of Driving Pass	08/06/2011
Driving Experience	7 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92221353
Fax Number	
Contact Number	
Email Address	TRAVELEHER@GMAIL.COM

Address	NA
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : PASSENGER 1 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was at Terminal 4 carpark No 4A. I was reversing my vehicle and I overlooked and slightly hit vehicle SME7268T front bumper. Slight dent on my rear bumper. No injuries were involved. We still deciding to do private settling.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SME7268T
Vehicle Make/Model/Colour	TOYOTA SIENTA HYBRID 1.5
Details Of Properties	NA
Vehicle Category	PRIVATE CAR
Name of Driver	KASINATHAM SOLAI ALAGAR
NRIC/Passport Number	S8071477G
Contact Number	90266412
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorized Driver.
- Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon request by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the Centre and to copies of the report being made available at the Centre.
- Consent under the Personal Data Protection Act (PDPA)
 - I understand, acknowledge, agree and consent that:
 - My insurer, my witness and the General Insurance Association of Singapore (GIA) may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured my vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyer/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - processing, handling and/or dealing with my claims, including the settlement of the claims and any necessary investigations relating to the claims;
 - investigating the accident and/or my claims;
 - carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/postal packages), and/or
 - complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyer/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
 - my Personal Information may be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyer/law firms), which may be sites outside of Singapore, for one or more of the above Purposes.

VERIFIED BY ALAN MARKS
REPORTING OFFICER

Muhammad Firza Bin Ideris

Witnessed by Reporting Centre
(Personnel)

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Sketch Plan

Terminal 4 Concourse 4A

A'SGR1433L
B'SME7268T

ACCIDENT STATEMENT (2000 characters)

I was at Terminal 4 carpark No 4A. I was reversing my vehicle and I overlooked and slightly hit vehicle SME7268T front bumper. Slight dent on my rear bumper. No injuries were involved. We still deciding to do private settling.

Taxi Voucher No :

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect.

VERIFIED BY AJAX MARS REPORTING OFFICER -
MUHAMMAD FIIZA BIN IDRIS

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time:

13 April 2019 at 4:59 PM

Date/Time:

13 April 2019 at 4:26 PM

Elizabeth Lee

From: Joey Voon <traveleher@gmail.com>
Sent: Monday, 15 April 2019 12:24 PM
To: Joanne
Cc: group@ajaxmars.com
Subject: ***SPAM*** Re: GIA REPORT-SGK1433L

Hi MARS,

I would like to proceed to claim under my own insurance policy. May i know how do i go about from here?

Thanks!

Regards,
Joey

On Sat, 13 Apr 2019 at 8:56 PM, Joanne <joanne@ajaxmars.com> wrote:

Dear Sir/Madam,

Please find attached file, the GIA Accident Report for your perusal.

Should you wish to reply to this email, kindly click "Reply All"

If you require any further clarification on the matter, please do not hesitate to contact us at 6333 2222.

Thank You.

Mobile Accident Response Service (MARS)
Tel: 6333 2222



Virus-free. www.avast.com



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
 6 Raffles Quay #18-00 Singapore 048580
 Tel (65) 6224 0010 Fax (65) 6224 0030
 Operating Hours : Monday to Friday, 09:00 – 17:00
 UEN: S66SS0020G / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MBHH19048305 Vehicle Registration No: SGK1433L
 Name (as shown in NRIC) : JOEY VOON CHIN YONG NRIC/FIN/Passport No : S9143462H
 (*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
 Address : _____ Singapore ()
 Contact (Tel) : _____ Mobile No. : 92221353
 Email Address : traveleher@gmail.com
 Date of Accident : 12/04/2019 Time of Accident : 19:20 HRS
 Place of Accident : TERMINAL 4 CARPARK 4A
 Insurance Company: SOMPO INSURANCE SINGAPORE PTE LTD

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

AMEND TO OD CLAIM.

 Policyholder / Driver's Signature
 Date:

 Reporting Centre Personnel's Signature
 Name: Elizabeth
 NRIC/FIN No.:
 Date: 15/04/2019

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S9143462H



Name

JOEY VOON CHIN YONG

溫 俊 榮

Race

CHINESE

Date of birth

30-11-1991

Sex

M

Country of birth

SINGAPORE

S9143462H

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S9143462H

Name:

JOEY VOON CHIN YONG

Birth Date: 30 Nov 1991

Issue Date: 08 Jun 2011




001971493D



4425487

NRIC No. S9143462H



Date of issue

15-06-2009

Address

APT BLK 521 PASIR RIS STREET 52
#10-01
SINGAPORE 510521

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars=<3000kg with =<7 passengers, exclusive of the driver; and other motor vehicles =<2500kg 08 Jun 2011



Licence No: S9143462H

NP 428A

Certificate of Insurance**MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)**

Cert No./Policy No. : D18MTPV01018959
Insured : YOON SWEE SANG
Motor Car (Registration No.) : SKQ4169B
Cover : Comprehensive - ExcelDrive GOLD
Policy Commencement Date : 17 NOVEMBER 2018 00:00
Policy Expiry Date : 16 NOVEMBER 2019 23:59
Maximum Liability (Section I) : Market value at time of loss
Excess* : \$500 - Section I
(Waived up to S\$1,000 if accident repair is done at ExcelDrive Workshops for the first claim per policy year)
Voluntary Excess* : N.A
Windscreen Excess* : S\$100.00 - Waived if Repair at ExcelDrive Workshop
Loss of Use : Per Policy Schedule

* Subject to GST wherever applicable

Persons or Classes of Persons entitled to drive*

1. The Insured.
2. Any other person who is driving on the Insured's order or with his permission.
3. In the event of the death of the insured,
 - a. any member of the insured's family, or a paid driver who has been driving the Motor Car during the life of the insured and permission to drive had not been withdrawn prior to the death of the insured; and
 - b. any other person who has been given permission to drive the Motor Car prior to the death and such permission had not been withdrawn by the Insured.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Car or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Car. And provided further that the Motor Car is registered under the Road Traffic Act (Chapter 276) and its registration under the Road Traffic Act (Chapter 276) has not been cancelled at the time of the accident, loss or damage.

Limitations As To Use

Use only for social, domestic and pleasure purpose and for the Insured's business. The Policy does not cover use for hire or reward, racing, pace-making, speed testing, reliability trial, the carriage of goods other than samples in connection with any trade or business or use for any purposes in connection with the Motor Trade.

ExcelDrive Workshops and Accident Reporting

It is a condition precedent to liability that the Insured shall call at the Company's Accident Reporting Center with the Motor Car within 24 hours of the accident or by the next working day thereof.

All accident repairs to the Motor Car must be carried out at ExcelDrive Workshops, otherwise the claim is not payable under the Policy. For ExcelDrive Prestige Plan, accident repairs to the Motor Car can be carried out at any workshop other than ExcelDrive Workshops.

For the list of Accident Reporting Centres and ExcelDrive Workshops, please visit our website at www.sompo.com.sg or call our Emergency Hotline: (65) 6226 3323.

I/We HEREBY CERTIFY that the policy to which this Certificate relates is issued in accordance with (1) the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia); and (2) the Policy terms, conditions and exceptions of the Private Car Policy ref MTP.27

Sompo Insurance Singapore Pte. Ltd.



Authorised Signatory

Date/Time of Issue : 14 NOVEMBER 2018 11:54

IMPORTANT NOTICE

- o Keep the Certificate in your Motor Car;
- o Under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189), it shall be unlawful for any person to use or cause to permit any other person to use a motor vehicle without a valid policy of insurance under the Act;
- o On the sale of the Motor Car or if for any reason the insurance is terminated during its currency, the Insured must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a statutory declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189);
- o This Policy will cease to be valid once the Motor Car has been sold to another person. The Policy is not transferable to the new owner of the Motor Car.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 8645I

Vehicle Details

Vehicle No.: SGK1433L

Vehicle to be Exported: No

Intended Deregistration Date: 15 Apr 2019

Vehicle Make: B.M.W.

Vehicle Model: 316I 1.6 AT D/AB 4DR ABS HID

Primary Colour: White

Manufacturing Year: 2014

Engine No.: A751J775N13B16A

Chassis No.: WBA3A16090NS38209

Maximum Power Output: 100.0 kW (134 bhp)

Open Market Value: \$28,891.00

Original Registration Date: 27 Nov 2014

First Registration Date: 27 Nov 2014

Transfer Count: 1

Actual ARF Paid: \$22,448.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 26 Nov 2024

PARF Rebate Amount: \$16,836.00

Intended COE Rebate Details

COE Expiry Date: 26 Nov 2024

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$72,890.00

COE Rebate Amount: \$40,919.00

Total Rebate Amount: \$57,755.00

The information contained herein is correct as at 15 Apr 2019

OK

來發(明記)摩多有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity
160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722
Tel: 64538110 Fax: 64596267 Email: info@laihuat.com.sg
UEN: 199407592C

INSURER: Sompoo Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM


Claim Type:	OD (Own Damage)	Ref. No:	70420
Policy No:	D18MTPV01018959	Date of Loss:	12/04/2019
Vehicle Reg. No.:	SGK1433L	Driveable?	
Driver Age/Info:	27 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	VOON SWEE SANG		
Driver:	JOEY VOON CHIN YONG		

Make/Model:	BMW 316I, 1.6 AT D/AB 4DR ABS HiD (A)	Vehicle Reg, Date:	27/11/2014
Vehicle Colour:	White		
Engine No:	A751J775N13B16A	Chassis No:	WBA3A16090NS38209
Odometer:	85850 KM		

Paint Type:

Total Loss? NO

Est. Duration of Repair (day) 2 day



Not Notified
Recovery 84palm
Fax: 62564315

Description of Accident/Loss: I WAS AT TERMINAL 4 CARPARK NO 4A. I WAS REVERSING MY VEHICLE AND I OVERLOOKED AND SLIGHTLY HIT VEHICLE SME7268T FRONT BUMPER. SLIGHT DENT ON MY REAR BUMPER. NO INJURIES WERE INVOLVED. WE STILL DECIDING TO DO PRIVATE SETTLING.

Remarks: VEHICLE IN: 22.04.2019

Present Location: LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING)

COST OF CLAIMS

	Amount
Parts	959.20
Miscellaneous Items	0.00
Labour	280.00
Paintwork Labour	300.00
Towing	0.00

Gross Total (S\$)	1,539.20
+ GST 7.00% (S\$)	107.74
Nett Amount (S\$)	1,646.94

This claim is handled by: JENNY LIM LAI FOONG

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Apr 2019)

Parts: 143 BMW 316I 1.6 AT D/AB 4DR ABS HID (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Lai Huat (Meng Kee) Motor Pte Ltd/SGK1433L/16/04/2019 09:59

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Rear bumper	0.00	0.00	*820.00 F
2	1		*Rear bumper PDC holders (1 set)	0.00	0.00	*22.00 F
3	1		*Rear exhaust heat shield	0.00	0.00	*30.00 F
Sub Total (S\$)						872.00
+ Margin on L,N Items 10.00% (S\$)						87.20
Total Parts (S\$)						959.20

F=Franchise part.

Lai Huat (Meng Kee) Motor Pte Ltd/SGK1433L/16/04/2019 09:59. Not valid without Reference section.
Generated using Merimen a-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	To spray paint (Pearl white)	New	300.00 ²²⁰¹
<u>Labour Items</u>			
2	To dismantle + refix rear exhaust box in order to renew heat shield	New	80.00 ?
3	To dismantle + renew rear bumper	New	200.00 ✓
Gross Labour Cost (S\$)			580.00

Lai Huat (Meng Kee) Motor Pte Ltd/SGK1433L/16/04/2019 09:59. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

來發(明記)摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity
160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722
Tel: 64538110 Fax: 64596267 Email: info@laihuat.com.sg
UEN: 199407592C

INSURER: Sompoo Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	70420
Policy No:	D18MTPV01018959	Date of Loss:	12/04/2019
Vehicle Reg. No.:	SGK1433L	Driveable?	
Driver Age/Info:	27 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	VOON SWEE SANG		
Driver:	JOEY VOON CHIN YONG		

Make/Model:	BMW 316I, 1.6 AT D/AB 4DR ABS HID (A)	Vehicle Reg. Date:	27/11/2014
Vehicle Colour:	White		
Engine No:	A751J775N13B16A	Chassis No:	WBA3A16090NS38209
Odometer:	85850 KM		

Paint Type:

Total Loss? **NO**

Est. Duration of Repair (day) *2 day,*

Not Notified
Recovery By painting
Rec. MS
Per: 62564315

Description of Accident/Loss: I WAS AT TERMINAL 4 CARPARK NO 4A. I WAS REVERSING MY VEHICLE AND I OVERLOOKED AND SLIGHTLY HIT VEHICLE SME7268T FRONT BUMPER. SLIGHT DENT ON MY REAR BUMPER. NO INJURIES WERE INVOLVED. WE STILL DECIDING TO DO PRIVATE SETTLING.

Remarks: VEHICLE IN: 22.04.2019

Present Location: LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING)

COST OF CLAIMS

	LKK Auto Consultants hence notify the Repairer of the following:	Amount
Parts	• To resurvey before/after spray painting	959.20
Miscellaneous Items	• To display damaged part(s) during resurvey	0.00
Labour	• Parts prices are subject to confirmation	280.00
Paintwork Labour	• Third party survey is on a "Without Prejudice" basis	300.00
Towing	• No illegal modification(s) is allowed	0.00
	• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	
Acknowledged by Repairer		
Signature:		
Date:		
Gross Total (\$\$)		1,539.20
+ GST 7.00% (\$\$)		107.74
Nett Amount (\$\$)		1,646.94

This claim is handled by: JENNY LIM LAI FOONG

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Apr 2019)
Parts: 143 BMW 316I 1.6 AT D/AB 4DR ABS HID (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Lai Huat (Meng Kee) Motor Pte Ltd/SGK1433L/16/04/2019 09:59
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*Rear bumper	<i>Bulim</i> 0.00	0.00	*820.00 F	<i>✓</i>
2	1		*Rear bumper PDC holders (1 set)	0.00	0.00	<i>NK</i> *22.00 F	<i>✓</i>
3	1		*Rear exhaust heat shield	0.00	0.00	<i>Pij</i> *30.00 F	<i>✓</i>
Sub Total (S\$)						872.00	
+ Margin on L,N Items 10.00% (S\$)						87.20	
Total Parts (S\$)						959.20	

F=Franchise part.

Lai Huat (Meng Kee) Motor Pte Ltd/SGK1433L/16/04/2019 09:59. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			2200
1	To spray paint (Pearl white)	New	300.00
<u>Labour Items</u>			
2	To dismantle + refix rear exhaust box in order to renew heat shield	New	80.00
3	To dismantle + renew rear bumper	New	200.00
Gross Labour Cost (S\$)			580.00

Lai Huat (Meng Kee) Motor Pte Ltd/SGK1433L/16/04/2019 09:59. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR DETAILS

SUPPLEMENTARY

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 May 2019)
 Parts: 143 BMW 316I 1.6 AT D/AB 4DR ABS HID (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Lai Huat (Meng Kee) Motor Pte Ltd/SGK1433L/10/05/2019 16:04
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front bumper reinforcement	0.00	0.00	*250.00 F
F=Franchise part.						
Sub Total (S\$)						250.00
+ Margin on L,N Items 10.00% (S\$)						25.00
Total Parts (S\$)						275.00

Lai Huat (Meng Kee) Motor Pte Ltd/SGK1433L/10/05/2019 16:04. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



明義純車私人有限公司
MIN GHEE AUTO PTE LTD

8, Jalan Lembah Kallang, #01-01 Min Ghee Building Singapore 339564
Main Tel: 6298 3888 Fax: 6291 2172, 6294 1450 Accounts Tel: 6291 6118 Accounts Fax: 6297 0863
Email: info@minghee.com (Main), account@minghee.com (Accounts)
Website: http://www.minghee.com

TAX INVOICE

INVOICE NO. 8144485

DATE	18/04/2019	PAGE	1
TERM	30 Days Net	SALESMAN	Alan Tan
CUSTOMER REF.	SGK1433L	OUR REF.	61024

GST REG.NO.: M2-0090482-6 CO REG.NO.: 198905613E

ACCOUNT NUMBER: LAIHUAT1 TIME:17:16
LAI HUAT (MENG KEE) MOTOR PTE LTD
160, SIN MING DRIVE
#04-01/#04-02 AND #07-03
SIN MING AUTOCITY
SINGAPORE 575722 575722
Telephone No: 64533757/4598162

ROUTE
SM1

DELIVER TO:

LAI HUAT (MENG KEE) MOTOR PTE LTD
160, SIN MING DRIVE
#04-01/#04-02 AND #07-03
SIN MING AUTOCITY
SINGAPORE 575722



PART NO.	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
1 BW51 12 7 312 724 2 BW51 12 7 312 750 3 BW51 48 7 321 619	RR BUMPER BASIS F30 PDC HOLDER HEAT SHIELD	6I-2A 6E-1BB 6F-3B	1 PC 1 PC 1 PC	820.00 22.00 30.00	820.00 22.00 30.00

GOODS RECEIVED IN GOOD ORDER
AND CONDITION.

*GOODS SOLD ARE NOT RETURNABLE.
*OVERDUE ACCOUNTS SHALL BEAR INTEREST AT UOB'S
PREVAILING LENDING RATE
*CASH INVOICE MUST BE PAID WITHIN 7 DAYS
FROM DATE OF INVOICE.

Exclusive Distributor

HDK

Stockists

Payment via telegraphic transfer to
Name of Bank: United Overseas Bank
Account Name: Min Ghee Auto Pte Ltd
Branch Code: 046
Account No.: 503-309-511-3
*Please send a screen shot of your payment/

transfer confirmation to
account@minghee.com.

SIGN & COMPANY'S STAMP



DATE
ALL CHEQUES MUST BE MADE PAYABLE TO
MIN GHEE AUTO PTE. LTD.

For MIN GHEE AUTO PTE. LTD.

TAX INVOICE

INVOICE NO. **8144711**

DATE	23/04/2019	PAGE	1
TERM	30 Days Net	SALESMAN	Jason Ooi
CUSTOMER REF.	SAK1433L	OUR REF.	62752

GST REG.NO.: M2-0090482-6 CO REG.NO.: 198905613E

ACCOUNT NUMBER: LAIHUAT1 TIME:09:23
 LAI HUAT (MENG KEE) MOTOR PTE LTD
 160,SIN MING DRIVE
 #04-01/#04-02 AND #07-03
 SIN MING AUTOCITY
 SINGAPORE 575722 575722
 Telephone No : 64533757/4598162

ROUTE
SMI

DELIVER TO :

LAI HUAT (MENG KEE) MOTOR PTE LTD
 160,SIN MING DRIVE
 #04-01/#04-02 AND #07-03
 SIN MING AUTOCITY
 SINGAPORE 575722



PART NO.	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
1 BW51 12 7 256 927	CARRIER	6F-02A	1 PC	250.00	250.00

GOODS RECEIVED IN GOOD ORDER AND CONDITION.

* GOODS SOLD ARE NOT RETURNABLE.
 * OVERDUE ACCOUNTS SHALL BEAR INTEREST AT UOB'S PREVALING LENDING RATE
 * CASH INVOICE MUST BE PAID WITHIN 7 DAYS FROM DATE OF INVOICE.

Exclusive Distributor

HDK
Stockists

Payment via telegraphic transfer to
 Name of Bank: United Overseas Bank
 Account Name: Min Ghee Auto Pte Ltd
 Branch Code: 0415
 Account No.: 503-309-511-3
 *Please send a screen shot of your payment/transfer confirmation to
 account@minghee.com.

SIGN & COMPANY'S STAMP



TOTAL	SIN	250.00
ADD GST	7%	17.50
AMOUNT DUE	SIN	267.50

DATE
 ALL CHEQUES MUST BE MADE PAYABLE TO
 MIN GHEE AUTO PTE. LTD.

For MIN GHEE AUTO PTE. LTD.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Apr 2019 Sendback Est	16 Apr 2019 09:59 S\$1,539.20	16 Apr 2019 10:42 Edit Adj Rpt	S\$1,734.20 Edit Estimates	S\$1,734.20 View Rpt		Pending for Survey Report Cancel Case
Supp #1	10 May 2019 16:03	10 May 2019 16:04 S\$275.00	10 May 2019 16:04			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	VOON SWEE SANG , ID: S18286451		
Vehicle Reg. No.:	SGK1433L	Date of Loss:	12/04/2019 19:00 - :59 [52 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / CMTD1901886	Policy/Cover Note No.:	D18MTPV01018959 (Comprehensive)
		Excess:	S\$0.00
Repairer:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 26/04/2019]		
Driver/Custodian:	JOEY VOON CHIN YONG (27 / Male) , NRIC: S9143462H, Tel: +6592221353 Email: traveleher@gmail.com		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- SOMPO_SG (23/05/2019): Alert - Adj Mandate Approved (S\$1734.20) - SGK1433L - Claim Handler: GNOH PAU LO...
- SOMPO_SG (22/04/2019): Alert - Adj Mandate Approved (S\$1459.20) - SGK1433L - Claim Handler: GNOH PAU LO...

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									


















Claim Documents

SGK1433L (CMTD1901886)
OD
Apr 12 2019 7:00PM
[VOON SWEE SANG]
Lai Huat (Meng Kee) Motor Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)						Thumbnail	Print	
1	13/04/19 20:52	Accident Statement						Load HTM		
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)						Thumbnail	Print	
1	16/04/19 09:59	Repairer Estimates						Load HTM		
2	10/05/19 16:04	Repairer Estimates Suppl. #1						Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	22/04/19 14:49	Adjuster Immediate Advice						Load HTM		
2	23/05/19 11:02	Adjuster Immediate Advice						Load HTM		
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)						Thumbnail	Print	
1	16/04/19 09:56	Rear View Right						Load JPG	<input checked="" type="checkbox"/>	
2	16/04/19 09:56	Rear View						Load JPG	<input checked="" type="checkbox"/>	
3	16/04/19 09:56	Chassis Number						Load JPG	<input checked="" type="checkbox"/>	
4	16/04/19 09:56	Tyre Size						Load JPG	<input checked="" type="checkbox"/>	
5	16/04/19 09:56	Tyre - Bridgestone						Load JPG	<input checked="" type="checkbox"/>	
6	16/04/19 09:56	Odometer Reading						Load JPG	<input checked="" type="checkbox"/>	
7	16/04/19 09:56	Rear View Left						Load JPG	<input checked="" type="checkbox"/>	
8	16/04/19 09:56	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
9	16/04/19 09:56	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
10	16/04/19 09:56	Chassis Number						Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	23/05/19 11:04	General View						Load JPG	<input checked="" type="checkbox"/>	
2	23/05/19 11:04	General View						Load JPG	<input checked="" type="checkbox"/>	
3	23/05/19 11:04	General View						Load JPG	<input checked="" type="checkbox"/>	
4	23/05/19 11:04	General View						Load JPG	<input checked="" type="checkbox"/>	
5	23/05/19 11:04	General View						Load JPG	<input checked="" type="checkbox"/>	
6	23/05/19 11:04	General View						Load JPG	<input checked="" type="checkbox"/>	
7	23/05/19 11:04	General View						Load JPG	<input checked="" type="checkbox"/>	
8	23/05/19 11:04	General View						Load JPG	<input checked="" type="checkbox"/>	
9	23/05/19 11:04	General View						Load JPG	<input checked="" type="checkbox"/>	
10	23/05/19 11:04	General View						Load JPG	<input checked="" type="checkbox"/>	
11	23/05/19 11:04	General View						Load JPG	<input checked="" type="checkbox"/>	
12	23/05/19 11:05	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
13	23/05/19 11:05	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
14	23/05/19 11:05	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
15	23/05/19 11:05	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
16	23/05/19 11:05	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
17	23/05/19 11:05	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
18	23/05/19 11:05	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
19	23/05/19 11:05	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	16/04/19 10:42	PRI - ACK	 Load HTM	
Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)			Thumbnail	Print
1	16/04/19 09:59	E-filed GIA report	 Load PDF	
2	16/04/19 09:59	Driver's NRIC & Driving Licence	 Load PDF	
3	16/04/19 09:59	Certificate of Insurance	 Load PDF	
4	16/04/19 09:59	Enquire PARF / COE Rebate for Registered Vehicle	 Load PDF	
LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print
1	22/04/19 14:50	ESTIMATE.pdf	 Load PDF	
2	23/05/19 11:03	ESTIMATE & SUPP MARKED.pdf	 Load PDF	
3	11/06/19 16:53	Parts Invoice	 Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On		Thumbnail	Print
1	13/04/19 20:52	Accident Statement	 Load HTM	
2	15/04/19 12:30	Addendum Sheet	 Load TIFF	
3	15/04/19 12:34	Accident Statement Addm. #1	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	13/04/19 18:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	13/04/19 18:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	13/04/19 18:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	13/04/19 18:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	13/04/19 18:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	13/04/19 18:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	13/04/19 18:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	13/04/19 18:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	13/04/19 18:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	13/04/19 18:29	Identification Card	 Load JPG	<input checked="" type="checkbox"/>
11	13/04/19 19:50	Identification Card	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	13/04/19 18:27	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	13/04/19 18:30	Common Statement	 Load TIFF	
3	15/04/19 12:30	Email Attachment	 Load TIFF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place, #05-01/06, Singapore Land Tower
Singapore 048623

Our File No: CS/SMO19006739/KSD3E2

Date: 11/06/2019

REFERENCE

Insured/Claimant: VOON SWEE SANG Policy No: D18MTPV01018959
Date of Loss: 12/04/2019 Nature of Claim: OD Claim No: CMTD1901886

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGK1433L**
Make & Model: BMW 316I, 1.6 AT D/AB 4DR ABS HID (A) Engine No: A751J775N13B16A
Reg. Date: 27/11/2014 (Man. Year: 2014) Chassis No: WBA3A16090NS38209
Colour: Metallic Pearl White Odometer: 86144 km
Engine Capacity: 1598 cc
Market Value/New Car Price: S\$74,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 7 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,234.20	1,234.20	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	280.00	280.00	0.00	0.00
Paintwork Labour	300.00	220.00	80.00	26.67
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,814.20	1,734.20	80.00	4.41
+ GST 7.00/7.00% (S\$)	126.99	121.39	5.60	4.41
Nett Amount (S\$)	1,941.19	1,855.59	85.60	4.41

INSPECTION

Date of Assignment: 16/04/2019 Present Location: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
Date Inspected: 22/04/2019 Inspected At: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
160 Sin Ming Drive #04-01, Sin Ming
AutoCity
Singapore 575722
Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Jun 2019)
Parts:	143	BMW 316I 1.6 AT D/AB 4DR ABS HID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGK1433L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Rear bumper (WCP)	Buckled / Cracked	820.00 F	*820.00 F
2	1		*Rear bumper PDC holders (1 set) (WCP)	Necessary	22.00 F	*22.00 F
3	1		*Rear exhaust heat shield (WCP)	Distorted	30.00 F	*30.00 F
Supplementary #1						
4	1		*Front bumper reinforcement (WCP)	Bent	250.00 F	*250.00 F

F=Franchise part.

Sub Total (S\$)	1,122.00	1,122.00
+ Margin on L,N Items 10.00/10.00% (S\$)	112.20	112.20
Total Parts (S\$)	1,234.20	1,234.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	To spray paint (Pearl white)	New	300.00	220.00
<u>Labour Items</u>				
2	To dismantle + refix rear exhaust box in order to renew heat shield	New	80.00	80.00
3	To dismantle + renew rear bumper	New	200.00	200.00
Gross Labour Cost (S\$)			580.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >