

22/03/2001

ASS. REC. BY:

REF: CS/CT119006756 | A9d3 | 172

Special Instruction:

Surveyor: Adnan

ASSIGNMENT (Office)

From (Person): Elaine Chong

of 011

Date/Time: 16.4.19 11.57 a.m

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKE 9762 T

Insured: SJV 719B

at Workshop m/s Dynamic Autowork

Tel: 63416789

of 8 Kaki Bukit Ave 4 #08-09

Policy No:

Claim No: SNM19D201638C02-9

Sum Insured:

Excess:

Make of Veh: (Client's Record)

D.O.A 12.4.2019

CA / REV / REP. / REV 24 HRS

mwp

H.O.D. Endorsement:

Date/Time: 16.4.2019

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate	✓
	1/3 @ 4350, 6 days Used @ 16381.40, 70%		

Est. Repairs: days Res.: Yes or No

D.O.A.

Lum Sum: % 3 Val.: Yes or No

Survey held at Dynamic

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date: Person Contacted: Vehicle: IN/OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP Chong.
	SKE 9762 T - X
	SJV 719B - X
	MV: 41K. Depreciation 10K. 3yr x 10K + min part = 30 + 11 = 41K.
	PV: 36K.
	Nett: 5K.

RECEIVED 28 MAY 2019

Date/Time, File Pass to?	Date/Time, File Return to?	Part Prices Check:	Survey Fee:	Date:
1) 28/5/19 Adnan	2)	IN	Basic & Add.	
3)	4)	OUT	__ S + RS, __ SI	
5)	6)		Photos	
Prel. Report:			Others	
Final Report:			TOTAL	220