

ASS. REC. BY:

REF: CS/CT1 19006781 / Atd 362

Special Instruction:

Survivor: Adrian
menmen

ASSIGNMENT (Office)

From (Person): Ong Chin Kiat

of CT1

Date/Time: 16.4.19 15.24p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SG C 2711U

Insured: GIBH 1243T

at Workshop m/s 96 motorsports

Tel: 67026996

of 62/64 kaki Buti Ave 6

Policy No: DM CVN 1802481901

Claim No: SNM 19D201659C02

Sum Insured:

Excess:

Make of Veh:

D.O.A 13.4.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

"wp"

H.O.D. Endorsement:

Date/Time: 16.4.19 4.29p.m

Person Contacted:

Jude

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate	
	SG C 2711U - NA / AIG 19006644/24	D.O.A - 13/4/2019
	GIBH 1243T - NA / CT1 19006714/24	D.O.A - 13/4/2019
	Lump Sum \$13600 (Red: 20633.67:60%)	

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Vehicle: IN / OUT

Person Contacted: _____

Veh No: SGC27114 Yr Regn: 2014 / Sept.Type: M:Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Altis c.c 1598Colour White A/C: Insured / Std / NI / NASp.Reading 40141 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MRO53REH104511287Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SiRim / STD A/Rim orTyre Size: F: 205/55R16R: 205/55R16BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 16/04/19Survey held at 96 MotorsportsDes. of Damages Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Chm.

RECEIVED 06 SEP 2019

MV : 60KPV : 44KNett: 16K.

Date/Time, File Pass to?

Date/Time, File Return to?

1) 619 Typist

2)

3)

4)

5)

6)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

220220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Apr 2019		16 Apr 2019 15:24 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:

Main Claimant:

LING ENG CHEONG, ID: S1144732E

Vehicle Reg. No.:

SGC2711U

Date of Loss:

13/04/2019 14:00 - :59

Claim Type:

TP / SNM19D201659C02

Policy/Cover Note No.:

DMCVSN1802481901

Vehicle Reg. No. (Insured):

GBH1243T

Policy No. (Claimant):

2100386731-04

Excess:

S\$500.00

Repairer:

96 Motorsports Pte Ltd (HQ) 62/64 Kaki Bukit Avenue 6, 417893 Kaki Bukit - Tel: 6702 6996

Handling Insurer:

China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]

Claimant's Insurer:

AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 26/04/2019]

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date

Priority

Type

Task Group

Subject

Handler

Assigned By

Completed On

Created On

Done?

No results.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID:	Singapore NRIC
Vehicle No.:	4732E
Vehicle to be Exported:	SGC2711U
Intended Deregistration Date:	No
Vehicle Make:	15 Apr 2019
Vehicle Model:	TOYOTA
Primary Colour:	TOYOTA COROLLA ALTIS 1.6L CVT
Manufacturing Year:	White
Engine No.:	2014
Maximum Power Output:	1ZRX425433
Open Market Value:	MR0538EH104511287
Original Registration Date:	90.0 kW (120 bhp)
First Registration Date:	\$18,761.00
Transfer Count:	26 Sep 2014
Actual ARF Paid:	26 Sep 2014
Intended PARF Rebate Details	0
PARF Eligibility:	\$13,761.00
PARF Rebate Amount:	Yes
Intended COE Rebate Details	25 Sep 2024
COE Expiry Date:	\$10,320.00
COE Category:	25 Sep 2024
COE Period (Years):	A - Car up to 1600cc & 97kW (130bhp)
QP Paid:	10
COE Rebate Amount:	\$61,899.00
Total Rebate Amount:	\$33,700.00
	\$44,020.00

The information contained herein is correct as at 15 Apr 2019

OK

Denise Tay (LKKAUTO)

From: estimator@96motorsports.com
Sent: Wednesday, 4 September 2019 3:10 PM
To: Denise Tay (LKKAUTO); Adrian Ling (LKKAUTO)
Cc: 'Royce'
Subject: RE: finalize of veh SGC 2711 U

Dear Denise,

We confirmed all. Thanks!

Best Regards,

BRYAN TENG

Estimator

96 MOTORSports

62/64 Kaki Bukit Avenue 6

Ark @ KB Singapore 417893

Tel : 6702 6996

Fax : 6384 6996

Email : Claims@96motorsports.com

Website: www.96motorsports.com

From: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Sent: Wednesday, 4 September, 2019 3:04 PM
To: estimator@96motorsports.com; Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>
Cc: 'Royce' <claims@96motorsports.com>
Subject: RE: finalize of veh SGC 2711 U

Dear Royce/Brian,

SGC 2711U – lump sum \$13,600, 12 Days

GBC 741M – lump sum \$2,800 , 5 Days

Please check and confirm final

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: estimator@96motorsports.com <estimator@96motorsports.com>
Sent: Wednesday, 22 May 2019 8:00 AM
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>

Denise Tay (LKKAUTO)

From: estimator@96motorsports.com
Sent: Wednesday, 22 May 2019 8:00 AM
To: Adrian Ling (LKKAUTO)
Cc: 'Royce'
Subject: finalize of veh SGC 2711 U
Attachments: 2711.pdf; 662dd157-9a13-4ed0-886e-783c3c5fc857.jpg; 56374c06-fbb0-4eda-9944-a63e8a6722c9.jpg; ec848a77-a996-4224-8016-8481718ff199.jpg; 6b694f74-c4b7-4405-a97d-c7b4facf19e8.jpg; 17df1a93-ffc3-4893-9f8b-367ba0155f07.jpg; 226c50f1-0cc7-4f8b-812a-bb8c243eda56.jpg

Dear Mr Adrian,

Please confirm L/S amount of \$14350 and 12days. Thanks!

Best Regards,

BRYAN TENG

Estimator

96 MOTORSports

62/64 Kaki Bukit Avenue 6

Ark @ KB Singapore 417893

Tel : 6702 6996

Fax : 6384 6996

Email : Claims@96motorsports.com

Website: www.96motorsports.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4732E
Vehicle Details	
Vehicle No.:	SGC2711U
Vehicle to be Exported:	Yes
Intended Deregistration Date:	16 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA COROLLA ALTIS 1.6L CVT
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	1ZRX425433
Chassis No.:	MR053REH104511287
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$18,761.00
Original Registration Date:	26 Sep 2014
First Registration Date:	26 Sep 2014
Transfer Count:	0
Actual ARF Paid:	\$13,761.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Sep 2024
PARF Rebate Amount:	\$10,320.00
Intended COE Rebate Details	
COE Expiry Date:	25 Sep 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$61,899.00
COE Rebate Amount:	\$33,683.00
Total Rebate Amount:	\$44,003.00

The information contained herein is correct as at 16 Apr 2019

OK



Free Car Valuation

Unsure of how much your car is worth?

Let us tell you how much is the value - no charges & no obligations!



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

New 10 Years Coe Renewal Toyota Wish 1.8A



2.88% P.A Low Interest @ Gv
Finance. 2 Years Warranty.
\$3800 Down Monthly From \$738
GV Credit Pte Ltd StarAd



Think One Automobile



Browse by Category

Save Search

Print

Sort by Date Posted

20 results/page

4 vehicles

Search altis

Advanced Search

Search

View All

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection

altis

Any

Any

2014

Any

Any

Any

Available



☐ Toyota Corolla Altis 1.6A Elegance

\$57,800

\$10,070 /yr

05-May-2014

1,598 cc

70,000 km

Sedan

Available

Fuel Efficient And Responsive Reliable Car! Only One Owner And Still Under Agent's Warranty. Original And Immaculate Condition. Flexible Loan Scheme Available And High Trade In. View To Believe!

Posted: 06-Apr-2019

Tags: 2014 Toyota Corolla, 2014 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

PREMIUM AD



☐ Toyota Corolla Altis 1.6A Elegance

\$60,800

\$9,920 /yr

22-Sep-2014

1,598 cc

33,667 km

Sedan

Available

Most Popular Toyota Sedan For Your Family. Well Maintained And Serviced With Agent. Spacious And Reliable. No Further Repairs Needed Flexible Bank/In House Loan Available, Subject To Approval Come Vie...

AL Autocar Pte Ltd

Posted: 20-Mar-2019

Tags: 2014 Toyota Corolla, 2014 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

PREMIUM AD



☐ Toyota Corolla Altis 1.6A Elegance

\$60,800

\$9,770 /yr

23-Oct-2014

1,598 cc

43,000 km

Sedan

Available

High Paper Value, Most Popular Toyota Sedan For Your Family. Well Maintained And Serviced With Agent. Spacious And Reliable. No Further Repairs Needed Flexible Bank/In House Loan Available, Subject To...

AL Autocar Pte Ltd

Posted: 03-Apr-2019

Tags: 2014 Toyota Corolla, 2014 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

PREMIUM AD



☐ Toyota Corolla Altis 1.6A

\$58,888

\$9,160 /yr

10-Dec-2014

1,598 cc

74,500 km

Sedan

Available

1 Owner. Well Maintained, New Paint, Call To View. Thanks.

Posted: 12-Apr-2019

Tags: 2014 Toyota Corolla, 2014 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

DIRECT OWNER

Save this search criteria, to get email alerts whenever a match is found.

Save Search

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view Expired ads

20 results/page



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/04/2019 12:04
Date Of Accident	13/04/2019 14:00
Exact Location Of Accident	PIE (CHANGI) BEFORE CTE (SLE) EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGC2711U
Insured/Policyholder	
Name Of Registered Owner	LING ENG CHEONG
NRIC No	S1144732E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96649987
Alternative Phone No	OFFICE-96649987

Vehicle Particulars

Manufacturer	TOYOTA
Model	TOYOTA COROLLA ALTIS 1.6L CVT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100386731-04
Cover Note Number	

Driver

Name of Driver	LING ENG CHEONG
NRIC No	S1144732E
Date Of Birth	27/09/1955
Occupation	INDOOR
Date Of Driving Pass	01/08/1977
Driving Experience	41 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96649987
Fax Number	
Contact Number	OFFICE-96649987
EMail Address	NOEMAIL

Address	23 SIMEI STREET 4 #10-02
Postcode	529880
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH1243T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SBS8827E
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

BUS

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

XD5569E

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same, as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time


Driver's Signature
(If driver is not the policyholder)
Date & Time


Reporting Centre Personnel's Signature
Name
NRIC/Fin No

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date, time and location I vehicle A was travelling along the stated venue. As the front vehicle stopped, I stopped. After about 40 seconds of stopping, I felt a huge impact from causing me to propel forward the rear. Within the 40 seconds of stopped time I witness vehicle B from the rear had also come to a complete stopped. My vehicle suffered damages from rear and the front. So there is a total of 4 cars chain collision.

DECLARATION

(/We declare the foregoing particulars are true in every respect.)

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Person's Signature
Name
NRIC/ID No

Accident Photo





96 MOTORSPORTS PTE LTD

64 Kaki Bukit Ave 6 Singapore (417893)

Email: estimator@96motorsports.com

Tel: 67026996/83118211

VEHICLE NUM:

MAKE & MODEL:

MILEAGE:

TYRE: FRONT

TYRE: REAR

CHASSIS NUM:

SGC 2711 U
T-ALITS

~~\$14350~~
\$14350
12 days
18/5/19

ATTN	NO.	DESCRIPTION - PARTS	QTY	PRICE	ADJUSTED PRICE
	1	BOOT LID <i>Detached</i>	1	871.60	871.60 ✓
	2	BOOT LID CHROME <i>Det</i>	1	298.70	298.70 ✓
	3	BOOT LAMP L+R <i>Det</i>	2	663.20	663.20 ✓
	4	BOOT HINGE L+R <i>Det</i>	2	145.20	
	5	BOOT CAMERA <i>Det</i>	1	1211.60	
	6	BOOT LID BADGE <i>Det</i>	1	65.20	65.20 ✓
	7	BOOT LID EMBLEM(DUAL) <i>Det</i>	1	64.30	64.30 ✓
	8	BOOT LID EMBLEM(1.6) <i>Det</i>	1	66.70	66.70 ✓
	9	BOOT LID EMBLEM(VTI) <i>Det</i>	1	69.80	69.80 ✓
	10	BOOT LID EMBLEM(COROLLA) <i>Det</i>	1	66.70	66.70 ✓
	11	BOOT LID EMBLEM(ALTIS) <i>Det</i>	1	67.80	67.80 ✓
	12	BOOT LID INNER LOCK <i>Det</i>	1	303.70	303.70 ✓
	13	BOOT LID LOCK CATCH <i>Det</i>	1	23.60	
	14	BOOT LID WEATHERSTRIP <i>Det</i>	1	185.70	185.70 ✓
	15	REAR BUMPER <i>Det</i>	1	511.90	511.90 ✓
	16	REAR BUMPER SIDE RETAINER L+R <i>Det</i>	2	151.60	151.60 ✓
	17	REAR BUMPER ATTACHMENT RETAINER L+R <i>Det</i>	2	136.84	136.84 ✓
	18	REAR BUMPER CLIP <i>Det</i>	1SET	50	50 ✓
	19	REAR BUMPER REFLECTOR L+R <i>Det</i>	2	197.40	
	20	REAR BUMPER REINFORCEMENT WITH SPONGE <i>Det</i>	1	377.60	377.60 ✓
	21	REAR BUMPER REINFORCEMENT BRACKET L+R <i>Det</i>	2	175.60	
	22	END PANEL <i>Det</i>	1	891.60	891.60 ✓
	23	END PANEL TOP TRIM <i>Det</i>	1	263.70	263.70 ✓
	24	END PANEL TOP TRIM CLIP <i>Det</i>	1SET	20	20 ✓
	25	REAR KEY ANTENNE SENSOR <i>Det</i>	1	178.60	178.60 ✓
	26	SPARE TYRE PANEL TOP BOARD <i>Det</i>	1	344.70	344.70 ✓
	27	SPARE WHEEL PANEL <i>Det</i>	1	151.60	
	28	REAR FENDER L+R (REPAIR) <i>Det</i>	2	72423.20	
	29	REAR EXHAUST PIPA <i>Det</i>	1	195.30	
	30	REAR EXHAUST PIPA MTG <i>Det</i>	1	351.70	
	31	REAR EXHAUST PIPA GASKET <i>Det</i>	1	48.20	
	32	REAR FENDER INNER TRIM L+R <i>Det</i>	2	135.60	

17053REH104511287

TP China

Denise

30

587

17216.04

33	REAR FENDER INNER TRIM CLIP	x	1SET	50	
34	REAR FENDER INNER SHIELD L+R	x	2	134.40	
35	REAR FENDER INNER SHIELD CLIP	x	1SET	50	
36	TAIL LAMP L+R	✓	2	711.20	711.20 ✓
37	TAIL LAMP PANEL L+R	x	2	356.80	
38	TAIL LAMP INNER SEAL L+R	x	2		
39	TAIL LAMP CLIP	✓	1SET	20	20 ✓
40	HEAD LAMP L+R	✓	2	563.40	563.40 ✓
41	HEAD LAMP CLIP	✓	1SET	20	20 ✓
42	BONNETS	✓	1	1240.40	1240.40 ✓
43	BONNET LOCK	✓	1	89.70	
44	BONNET HINGE L+R	x	2	127.60	
45	BONNET INSULATOR	x	1	248.40	
46	BONNET INSULATOR CLIP	✓	1SET	50	
47	FRONT BUMPER	✓	1	566.70	566.70 ✓
48	FRONT BUMPER SPONGE	✓	1	47.80	47.80 ✓
49	FRONT BUMPER SIDE RETAINER L+R	✓	2	138.70	138.70 ✓
50	FRONT BUMPER CLIP	✓	1SET	50	50 ✓
51	FRONT BUMPER REINFORCEMENT	✓	1	313.60	313.60 ✓
52	FRONT BUMPER LOWER GRILLE	x	1	121.60	
53	FRONT BUMPER FOG LAMP COVER L+R	x	2	179.60	
54	FRONT BUMPER BADGE	✓	1	51.63	51.63 ✓
55	FRONT GRILLE	✓	1		
56	FRONT GRILLE TOP CHROME Moulding	✓	1	464.70	464.70 ✓
57	FRONT GRILLE BOTTOM CHROME Moulding	✓	1		
58	FRONT GRILLE CLIP	✓	1SET	50	50 ✓
59	SUPPORT PANEL	✓	1	1074.30	1074.30 ✓
60	BRACE PANEL	✓	1	96.70	96.70 ✓
61	AIR CON CONDENSER	✓	1	141.60	141.60 ✓
62	AIR CON CONDENSER ELECTRIC FAN COWLING ASSY	✓	1	799.80	
63	RADIATOR	✓	1	1811.60	1811.60 ✓
64	RADIATOR ELECTRIC FAN COWLING ASSY	x	1		
65	FRONT FENDER L+R (REPAIR)	x	2	744.50	

16.000.234

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Apr 2019		16 Apr 2019 15:24 Edit Adj Rpt	S\$13,600.00 Edit Estimates	S\$13,600.00 View Rpt		Pending for Survey Report Cancel Case

Main		Reference	Claim Details	Documents	Show All
-------------	--	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	-, Co. Reg. No.: -				
Main Claimant:	LING ENG CHEONG, ID: S1144732E				
Vehicle Reg. No.:	SGC2711U	Date of Loss:	13/04/2019 14:00 - :59 [54 Months and 18 Days From LTA Reg Date (Man Yr)]		
Claim Type:	TP / SNM19D201659C02	Policy/Cover Note No.:	DMCVSN1802481901		
Vehicle Reg. No. (Insured):	GBH1243T	Policy No. (Claimant):	2100386731-04		
		Excess:	S\$500.00		
Repairer:	96 Motorsports Pte Ltd (HQ) 62 Kaki Bukit Avenue 6, The Ark@KB, 417893 Kaki Bukit - Tel: 6702 6996				
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]				
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000				
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 26/04/2019]				

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGC2711U (SNM19D201659C02)
[GBH1243T]
TP
LING ENG CHEONG
Apr 13 2019 2:00PM
[-]
96 Motorsports Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Assessment Reports									1 per page		☒
No	Finalized On	National Assessment Centre Services (Ubi)							Thumbnail	Print	
1	15/04/19 14:04	Accident Statement							Load HTM		
2	16/04/19 15:11	Addendum Sheet							Load JPG	☒	
3	16/04/19 15:11	Accident Statement Addm. #1							Load HTM		
Photos/Images									3 per page		☒
No	Finalized On	National Assessment Centre Services (Ubi)							Thumbnail	Print	
1	15/04/19 14:02	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
2	15/04/19 14:02	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
3	15/04/19 14:02	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
4	15/04/19 14:02	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
5	15/04/19 14:02	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
6	15/04/19 14:02	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
7	15/04/19 14:02	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
8	15/04/19 14:02	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
9	15/04/19 14:02	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
10	15/04/19 14:02	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
11	15/04/19 14:02	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
12	15/04/19 14:02	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
13	15/04/19 14:02	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
14	15/04/19 14:02	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
15	15/04/19 14:02	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
16	15/04/19 14:02	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
17	15/04/19 14:02	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
18	15/04/19 14:02	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	06/09/19 09:21	General View							Load JPG	☒	
2	06/09/19 09:21	General View							Load JPG	☒	
3	06/09/19 09:21	General View							Load JPG	☒	
4	06/09/19 09:21	General View							Load JPG	☒	
5	06/09/19 09:21	General View							Load JPG	☒	
6	06/09/19 09:21	General View							Load JPG	☒	
7	06/09/19 09:21	General View							Load JPG	☒	
8	06/09/19 09:21	General View							Load JPG	☒	
9	06/09/19 09:21	General View							Load JPG	☒	
10	06/09/19 09:21	General View							Load JPG	☒	
11	06/09/19 09:21	General View							Load JPG	☒	
12	06/09/19 09:21	General View							Load JPG	☒	
13	06/09/19 09:21	General View							Load JPG		

Assessment Reports				1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
					☒
14	06/09/19 09:21	General View		Load JPG	☒
15	06/09/19 09:21	General View		Load JPG	☒
16	06/09/19 09:21	General View		Load JPG	☒
17	06/09/19 09:21	General View		Load JPG	☒
18	06/09/19 09:21	General View		Load JPG	☒
19	06/09/19 09:21	General View		Load JPG	☒
20	06/09/19 09:21	General View		Load JPG	☒
21	06/09/19 09:21	General View		Load JPG	☒
22	06/09/19 09:21	General View		Load JPG	☒
23	06/09/19 09:21	General View		Load JPG	☒
24	06/09/19 09:21	General View		Load JPG	☒
25	06/09/19 09:21	General View		Load JPG	☒
26	06/09/19 09:21	General View		Load JPG	☒
27	06/09/19 09:21	General View		Load JPG	☒
28	06/09/19 09:21	General View		Load JPG	☒
29	06/09/19 09:21	General View		Load JPG	☒
30	06/09/19 09:21	General View		Load JPG	☒
31	06/09/19 09:21	General View		Load JPG	☒
32	06/09/19 09:21	General View		Load JPG	☒
33	06/09/19 09:21	General View		Load JPG	☒
34	06/09/19 09:21	General View		Load JPG	☒
35	06/09/19 09:21	General View		Load JPG	☒
36	06/09/19 09:21	General View		Load JPG	☒
37	06/09/19 09:21	General View		Load JPG	☒
38	06/09/19 09:21	General View		Load JPG	☒
39	06/09/19 09:21	General View		Load JPG	☒
40	06/09/19 09:21	General View		Load JPG	☒
41	06/09/19 09:21	General View		Load JPG	☒
42	06/09/19 09:21	General View		Load JPG	☒
43	06/09/19 09:21	General View		Load JPG	☒
44	06/09/19 09:21	General View		Load JPG	☒
45	06/09/19 09:21	General View		Load JPG	☒
46	06/09/19 09:21	General View		Load JPG	☒
47	06/09/19 09:21	General View		Load JPG	☒
48	06/09/19 09:21	General View		Load JPG	☒
49	06/09/19 09:21	General View		Load JPG	☒
50	06/09/19 09:21	General View		Load JPG	☒
51	06/09/19 09:21	General View		Load JPG	☒
52	06/09/19 09:21	General View		Load JPG	☒
53	06/09/19 09:21	General View		Load JPG	☒
54	06/09/19 09:21	General View		Load JPG	☒
55	06/09/19 09:21	General View		Load JPG	☒
56	06/09/19 09:21	General View		Load JPG	☒
57	06/09/19 09:21	General View		Load JPG	☒
58	06/09/19 09:21	General View		Load JPG	☒
59	06/09/19 09:21	General View		Load JPG	☒
60	06/09/19 09:21	General View		Load JPG	☒
61	06/09/19 09:21	General View		Load JPG	☒
62	06/09/19 09:21	General View		Load JPG	☒
63	06/09/19 09:21	General View		Load JPG	☒
64	06/09/19 09:21	General View		Load JPG	☒
65	06/09/19 09:21	General View		Load JPG	☒
66	06/09/19 09:22	Reinspection Photo		Load JPG	☒
67	06/09/19 09:22	Reinspection Photo		Load JPG	☒
68	06/09/19 09:22	Reinspection Photo		Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
69	06/09/19 09:22	Reinspection Photo	 Load JPG	☒
70	06/09/19 09:22	Reinspection Photo	 Load JPG	☒
71	06/09/19 09:22	Reinspection Photo	 Load JPG	☒
72	06/09/19 09:22	Reinspection Photo	 Load JPG	☒
73	06/09/19 09:22	Reinspection Photo	 Load JPG	☒
74	06/09/19 09:22	Reinspection Photo	 Load JPG	☒
75	06/09/19 09:22	Reinspection Photo	 Load JPG	☒
76	06/09/19 09:22	Reinspection Photo	 Load JPG	☒
77	06/09/19 09:22	Reinspection Photo	 Load JPG	☒
78	06/09/19 09:22	Reinspection Photo	 Load JPG	☒
79	06/09/19 09:22	Reinspection Photo	 Load JPG	☒
80	06/09/19 09:22	Reinspection Photo	 Load JPG	☒
81	06/09/19 09:22	Reinspection Photo	 Load JPG	☒
82	06/09/19 09:22	Reinspection Photo	 Load JPG	☒
83	06/09/19 09:22	Reinspection Photo	 Load JPG	☒
84	06/09/19 09:22	Reinspection Photo	 Load JPG	☒
85	06/09/19 09:23	Reinspection Photo	 Load JPG	☒
86	06/09/19 09:23	Reinspection Photo	 Load JPG	☒
87	06/09/19 09:23	Reinspection Photo	 Load JPG	☒
88	06/09/19 09:23	Reinspection Photo	 Load JPG	☒
89	06/09/19 09:23	Reinspection Photo	 Load JPG	☒
90	06/09/19 09:23	Reinspection Photo	 Load JPG	☒
91	06/09/19 09:23	Reinspection Photo	 Load JPG	☒
92	06/09/19 09:23	Reinspection Photo	 Load JPG	☒
93	06/09/19 09:23	Reinspection Photo	 Load JPG	☒
94	06/09/19 09:23	Reinspection Photo	 Load JPG	☒
95	06/09/19 09:23	Reinspection Photo	 Load JPG	☒
96	06/09/19 09:23	Reinspection Photo	 Load JPG	☒
97	06/09/19 09:23	Reinspection Photo	 Load JPG	☒
98	06/09/19 09:23	Reinspection Photo	 Load JPG	☒
99	06/09/19 09:23	Reinspection Photo	 Load JPG	☒
100	06/09/19 09:23	Reinspection Photo	 Load JPG	☒
101	06/09/19 09:23	Reinspection Photo	 Load JPG	☒
102	06/09/19 09:23	Reinspection Photo	 Load JPG	☒
103	06/09/19 09:23	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	16/04/19 15:25	PRS - SGC2711U	 Load PDF	
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	15/04/19 14:02	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	☒
2	15/04/19 14:02	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	☒

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	15/04/19 14:04	Accident Statement	 Load HTM	
2	16/04/19 15:11	Addendum Sheet	 Load JPG	☒
3	16/04/19 15:11	Accident Statement Addm. #1	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	15/04/19 14:02	Accident Photo	 Load JPG	☒
2	15/04/19 14:02	Accident Photo	 Load JPG	☒
3	15/04/19 14:02	Accident Photo	 Load JPG	☒

Assessment Reports				1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
4	15/04/19 14:02	Accident Photo		Load JPG	☒
5	15/04/19 14:02	Accident Photo		Load JPG	☒
6	15/04/19 14:02	Accident Photo		Load JPG	☒
7	15/04/19 14:02	Accident Photo		Load JPG	☒
8	15/04/19 14:02	Accident Photo		Load JPG	☒
9	15/04/19 14:02	Accident Photo		Load JPG	☒
10	15/04/19 14:02	Accident Photo		Load JPG	☒
11	15/04/19 14:02	Accident Photo		Load JPG	☒
12	15/04/19 14:02	Accident Photo		Load JPG	☒
13	15/04/19 14:02	Accident Photo		Load JPG	☒
14	15/04/19 14:02	Accident Photo		Load JPG	☒
15	15/04/19 14:02	Accident Photo		Load JPG	☒
16	15/04/19 14:02	Accident Photo		Load JPG	☒
17	15/04/19 14:02	Accident Photo		Load JPG	☒
18	15/04/19 14:02	Accident Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	15/04/19 14:02	Accident Sketch Plan		Load JPG	☒
2	15/04/19 14:02	Accident Sketch Plan		Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19006781/ATD3E2

Date: 27/09/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN1802481901

Claimant
Vehicle No : SGC2711UInsured Vehicle
No : GBH1243T

Date of Loss: 13/04/2019

Nature of Claim: TP

Claim
No: SNM19D201659C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGC2711U

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Engine No: 1ZRX425433

Reg. Date: 26/09/2014 (Man. Year: 2014)

Chassis No: MR053REH104511287

Colour: White

Odometer: 40141 km

Engine Capacity: 1598 cc

Market Value/New Car

N/A

Price:

Sum Insured (\$\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,669.13	13,763.93	7,905.20	36.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,440.00	3,370.00	2,070.00	38.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	27,109.13	17,133.93	9,975.20	36.80
Approved Total (Overridden) (\$\$)		13,600.00		
(\$\$)	27,109.13	13,600.00	13,509.13	49.83
+ GST 7.00/7.00% (\$\$)	1,897.64	952.00	945.64	49.83
Nett Amount (\$\$)	29,006.77	14,552.00	14,454.77	49.83

INSPECTION

Date of Assignment: 16/04/2019

Date Inspected: 16/04/2019 Inspected At:

96 Motorsports Pte Ltd (HQ)
62 Kaki Bukit Avenue 6, The Ark@KB
Singapore 417893

Estimated Period of Repair: 12.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Sep 2019)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGC2711U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	871.60 FL	*871.60 FL
2	1		*BOOT LID CHROME	Cut	298.70 FL	*298.70 FL
3	2		*BOOT LAMP L+R	Cracked	663.20 FL	*663.20 FL
4	2		*BOOT HINGE L+R	Not Necessary	145.20 FL	*- FL
5	1		*BOOT CAMERA	Not Necessary	1,211.60 FL	*- FL
6	1		*BOOT LID BADGE	Necessary	65.20 FL	*65.20 FL
7	1		*BOOT LID EMBLEM (DUAL)	Necessary	64.30 FL	*64.30 FL
8	1		*BOOT LID EMBLEM (1.6)	Necessary	66.70 FL	*66.70 FL
9	1		*BOOT LID EMBLEM (VVTI)	Necessary	69.80 FL	*69.80 FL
10	1		*BOOT LID EMBLEM (COROLLA)	Necessary	66.70 FL	*66.70 FL
11	1		*BOOT LID EMBLEM (ALTIS)	Necessary	67.80 FL	*67.80 FL
12	1		*BOOT LID INNER LOCK	Damaged	303.70 FL	*303.70 FL
13	1		*BOOT LID LOCK CATCH	Not Necessary	23.60 FL	*- FL
14	1		*BOOT LID WEATHERSTRIP	Cut	185.70 FL	*185.70 FL
15	1		*REAR BUMPER	Deformed	511.90 FL	*511.90 FL
16	2		*REAR BUMPER SIDE RETAINER L+R	Necessary	151.60 FL	*151.60 FL
17	2		*REAR BUMPER ATTACHMENT RETAINER L+R	Necessary	136.84 FL	*136.84 FL
18	1		*SET REAR BUMPER CLIP	Necessary	50.00 FL	*30.00 FL
19	2		*REAR BUMPER REFLECTOR L+R	Not Necessary	197.40 FL	*- FL
20	1		*REAR BUMPER REINFORCEMENT WITH SPONGE	Bent	377.60 FL	*377.60 FL
21	2		*REAR BUMPER REINFORCEMENT BRACKET L+R	Not Necessary	175.60 FL	*- FL
22	1		*END PANEL	Dented	891.60 FL	*587.00 FL
23	1		*END PANEL TOP TRIM	Deformed	263.70 FL	*263.70 FL
24	1		*SET END PANEL TOP TRIM CLIP	Necessary	20.00 FL	*20.00 FL
25	1		*REAR KEY ANTERNE SENSOR	Cracked	178.60 FL	*178.60 FL
26	1		*SPARE TYRE PANEL TOP BOARD	Deformed	344.70 FL	*344.70 FL
27	1		*SPARE WHEEL PANEL	Repair	751.60 FL	*- FL
28	2		*REAR FENDER L+R	Repair	2,423.20 FL	*- FL
29	1		*REAR EXHAUST PIPA	Not Necessary	795.30 FL	*- FL
30	1		*REAR EXHAUST PIPA MTG	Not Necessary	59.70 FL	*- FL
31	1		*REAR EXHAUST PIPA GASKET	Not Necessary	48.20 FL	*- FL
32	2		*REAR FENDER INNER TRIM L+R	Not Necessary	735.60 FL	*- FL
33	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	50.00 FL	*- FL
34	2		*REAR FENDER INNER SHIELD L+R		139.40 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Not Necessary		
35	1		*SET REAR FENDER INNER SHIELD CLIP	Not Necessary	50.00 FL	*- FL
36	2		*TAIL LAMP L+R	Cut	711.20 FL	*711.20 FL
37	2		*TAIL LAMP PANEL L+R	Repair	356.80 FL	*- FL
38	2		*TAIL LAMP INNER SEAL L+R (NPA)	Not Necessary	0.00 FL	*- FL
39	1		*SET TAIL LAMP CLIP	Necessary	20.00 FL	*20.00 FL
40	2		*HEAD LAMP L+R	Cracked	5,633.40 FL	*4,820.00 FL
41	1		*SET HEAD LAMP CLIP	Necessary	20.00 FL	*20.00 FL
42	1		*BONNETS	Dented	1,240.40 FL	*1,028.00 FL
43	1		*BONNET LOCK	Not Necessary	89.70 FL	*- FL
44	2		*BONNET HINGE L+R	Not Necessary	127.60 FL	*- FL
45	1		*BONNET INSULATOR	Not Necessary	278.40 FL	*- FL
46	1		*SET BONNET INSULATOR CLIP	Not Necessary	50.00 FL	*- FL
47	1		*FRONT BUMPER	Deformed	566.70 FL	*566.70 FL
48	1		*FRONT BUMPER SPONGE	Deformed	97.80 FL	*97.80 FL
49	2		*FRONT BUMPER SIDE RETAINER L+R	Necessary	138.70 FL	*138.70 FL
50	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FL	*30.00 FL
51	1		*FRONT BUMPER REINFORCEMENT	Bent	313.60 FL	*313.60 FL
52	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	121.60 FL	*- FL
53	2		*FRONT BUMPER FOG LAMP COVER L+R	Not Necessary	179.60 FL	*- FL
54	1		*FRONT BUMPER SPONGE	Necessary	51.63 FL	*51.63 FL
55	1		*SET FRONT GRILLE CLIP	Necessary	50.00 FL	*20.00 FL
56	1		*SUPPORT PANEL	Buckled	1,074.30 FL	*971.00 FL
57	1		*BRACE PANEL	Bent	96.70 FL	*96.70 FL
58	1		*AIR CON CONDENSER	Bent	1,411.60 FL	*1,411.60 FL
59	1		*AIR CON CONDENSER ELECTRIC FAN COWLING ASSY	Not Necessary	799.80 FL	*- FL
60	1		*RADIATOR	Bent	1,811.60 FL	*1,811.60 FL
61	1		*RADIATOR ELECTRIC FAN COWLING ASSY (NPA)	Not Necessary	0.00 FL	*- FL
62	2		*FRONT FENDER L+R (NPA)	Repair	0.00 FL	*- FL
63	1		*REAR NUMBER PLATE WITH COVER	Not Necessary	40.00 FS	*- FS
64	1		*FRONT NUMBER PLATE WITH COVER	Bent	40.00 FS	*40.00 FS
65	1		*REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
66	1		*RADIATOR COOLANT	Necessary	120.00 FS	*40.00 FS
67	1		*END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
68	1		*FRONT GRILLE }	Cut	464.70 FL	*464.70 FL
69	1		*FRONT GRILLE TOP CHROME MOULDING }		0.00 FL	*- FL
70	1		*FRONT GRILLE BOTTOM CHROME MOULDING }		0.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 28,722.17 18,238.57
 - List Item Discount on L Items 25.00/25.00% (\$\$) 7,053.04 4,474.64

Total Parts (\$\$) 21,669.13 13,763.93

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK, STRAIGHTEN AND REALIGN ACCIDENT AFFECTED AREA	New	2,200.00	1,600.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	2,000.00	1,400.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	New	120.00	60.00
4	TO R&R REVERSE SENSOR FUNCTION	New	60.00	50.00
5	TO R&R AIR CON CONDENSOR AND REFILL GAS	New	120.00	120.00
6	TO R&R REVERSE CAMERA AND CHECK FUNCTION	New	80.00	50.00
7	TO CHECK WATER SEEPAGE	New	60.00	0.00
8	TO CHECK WIRING LAYOUT AND H/LAMP FOCUS	New	80.00	30.00
9	TO R&R RR BOOT MECH	New	120.00	0.00
10	TO R&R RR BOOT COMPARTMENT	New	120.00	60.00
11	TO CHECK CHASSIS ALIGNMENT	New	300.00	0.00
12	TO R&R RR EXHAUST PIPA SYSTEM	New	180.00	0.00
Gross Labour Cost (\$\$)			5,440.00	3,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >