

ASS. REC. BY:

REF:

CS/INC/1906793/Isd3er

Special Instruction:

Surveyor:

Hue Jie

ASSIGNMENT (Office)

From (Person):

Annie Koh

of

INC

Date/Time:

16/4/19 @ 9.47am

Estimated Cost:

Bill to:

OD ☒ TD / WS / TT RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SKW 3185D

Insured:

YP130C

at Workshop m/s:

Hua Hong

Tel:

6661 9688

of

25D Sungai Kerdut street

Policy No:

Claim No:

MT/1032714-002

Sum Insured:

Excess:

Make of Veh:

D.O.A.

18/2/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9.50am @ 16/4/19

Person Contacted:

Jerleen

Vehicle:

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKW 3185D - x

YP130C - x

Surveyor Hwee Jie

ASSIGNMENT

From: Date: 16/4/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKW 318SD

at Workshop m/s

of 25 D Sungai Kadut street 1

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh: Car In

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{1 up}

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKW 318SD Yr Regn: 26 Oct 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 3

C.C. 1496

Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 79194

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JM6Bm42 A8G0320890

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60 R16

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 18/02/19

D.O.I. 16/4/19 1151am

Survey held at

Hua Hong

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

04/07/19 Continued P/P \$ 1,683.20 @ 2 days with Ashley
(\$ 1,207.84 Red - 42%)

RECEIVED 04 JUL 2019

Date/Time, File Pass to?

04/07/19

☐ : Preli. Report☒ : Final Report1) Typist
Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum (I.B.): (\$ 1,683.20 P/P)

250

250

Nivitha (LKK Auto)

From: Annie Koh <annie.koh@income.com.sg>
Sent: Tuesday, 16 April 2019 9:55 AM
To: 'assignments@lkkauto.com'
Cc: Thio Tse Kiat; Teng Ken Leong
Subject: RE: TP CASES FARMED OUT TO LKK ON 16/04/2019

Re-send

Warmest Regards

Annie Koh
Senior Admin,
Motor Insurance
T +65 64307899
www.income.com.sg



From: Annie Koh
Sent: Tuesday, 16 April 2019 9:47 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Teng Ken Leong <kenleong.teng@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 16/04/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Serene Lim	MT/1040072-002	SMJ1436M	BP AUTO	48 TOH GUAN ROAD EAST #01-121 ENTERPRISE HUB SINGAPORE 608586	/ 6266 0555		SDA8856S	12/4/19	
2	Muhammad Airwan	MT/1032714-002	SKW3185D	HUA HONG PTE LTD	25D SUNGEI KADUT STREET 1 SINGAPORE 729332	Jerleen / Mrs Tan / 6661 9688	14:00-16:00	YP130C	18/2/19	
3	David Phua	MT/1034482-002	SLM4505Z	MUNICH AUTOMOBILES PTE LTD	30 TEBAN GARDENS CRESCENT SINGAPORE 608927	Tan Kok Ting / 6566 7666	13:00-15:00	SKA5008K	2/3/19	9051 5581

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Annie Koh

Senior Admin Assistant, Motor Insurance

T +65 6430 7899

www.income.com.sg



Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3838G
Vehicle Details	
Vehicle No.:	SKW3185D
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Apr 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	P520322822
Chassis No.:	JM6BM42A8G0320890
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$15,197.00
Original Registration Date:	26 Oct 2015
First Registration Date:	26 Oct 2015
Transfer Count:	0
Actual ARF Paid:	\$10,197.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Oct 2025
PARF Rebate Amount:	\$7,647.00
Intended COE Rebate Details	
COE Expiry Date:	25 Oct 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,498.00
COE Rebate Amount:	\$37,497.00
Total Rebate Amount:	\$45,144.00

The information contained herein is correct as at 17 Apr 2019

OK

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 4 July 2019 10:33 AM
To: 'Ashley Tan'
Cc: SUR
Subject: RE: Finalisation for Vehicle No. SKW3185D

Dear Ashley,

Finalize amount confirmed.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]
Sent: Thursday, 4 July 2019 8:43 AM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Subject: FW: Finalisation for Vehicle No. SKW3185D

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ashley Tan <ashley@huahong.com.sg>
Sent: Wednesday, 3 July 2019 6:09 PM
To: Hwee Jie (LKK Auto) <hweejie@lkkauto.com>
Cc: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Subject: Finalisation for Vehicle No. SKW3185D

Dear all

Please refer to the photos attached and confirm part by part \$1683.20.

Thanks & Regards

Ashley Tan



HUA HONG PRIVATE LIMITED

25D SUNGEI KADUT STREET 1 SINGAPORE 729332

T. 6661 9690 | M. 9816 4151 | F. 6661 9699

Follow us @ huahong.com.sg



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	19/02/2019 10:27
Date Of Accident	18/02/2019 21:00
Exact Location Of Accident	ALONG KJE TOWARDS CHOA CHU KANG WAY
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKW3185D
Insured/Policyholder	
Name Of Registered Owner	LEE AH TUAN
NRIC No	S1283838G
Email Address	MICHAEELEE29@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-97476329
Alternative Phone No	OFFICE-97476329
Vehicle Particulars	
Manufacturer	MAZDA
Model	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	HL ASSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MP306175
Cover Note Number	
Driver	
Name of Driver	LEE AH TUAN
NRIC No	S1283838G
Date Of Birth	04/10/1958
Occupation	OUTDOOR
Date Of Driving Pass	21/08/1978
Driving Experience	40 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97476329
Fax Number	
Contact Number	OFFICE-97476329
Email Address	MICHAEELEE29@YAHOO.COM.SG

Address	APT BLK 679 CHOA CHU KANG CRESCENT #07-594
Postcode	680679
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP130C
Vehicle Make/Model/Colour	ISUZU
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	CHUA TEK MENG
NRIC/Passport Number	G6571253P
Contact Number	86189395
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Accident Date & Time : 18/2/2019 2100

Accident Location : KJE twds choa chulakang way

I was travelling along the mentioned location.
I stopped to check for oncoming traffic. Suddenly
I felt an impact on the rear portion. The impact
caused my vehicle to roll forward. I noted that vehicle
B had collided onto my vehicle rear portion.
Vehicle B driver admitted it was his fault.

☐ Reporting Only ☐ Own Damage ☒ Third Party ☐ Claim at other workshop (OD/TP)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

*** IMPORTANT NOTE:**

*** IMPORTANT NOTE:**
You had been advised by the workshop that in the event that you wish to claim against your own policy (Own Damage Claim), there is a **FOURTEEN (14) days** clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.

Policyholder's Signature _____
Date & Time: _____

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



HUA HONG PRIVATE LIMITED

25D Sungei Kadut Street 1 Singapore 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

HHTPClaims19-20

20 February 2019

NTUC Income Cooperative Ltd
73 Bras Basah Road #05-01
NTUC Trade Union House
Singapore 189556

Attn: Motor Claims Department

ACCIDENT INVOLVING SKW 3185 D & YP 130 C ON 18/02/2019 ALONG KJE TOWARDS CHOA CHU KANG WAY AT ABOUT 2100 HOURS

Insured : LEE AH TUAN
Vehicle Registration No : SKW 3185 D
Vehicle Make : MAZDA
Vehicle Model : MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Vehicle Chassis No : JM6BM42A8G0320890
Policy No : MP306175
Date of Accident : 18/02/2019

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Rear Bumper DEF -		\$ 1,074.00
2	10	Rear Bumper Clip rec -	\$ 4.80	\$ 48.00 30
3	2	Rear Bumper Retainer (LH/RH) ~ x	\$ 36.10	\$ 72.20
4	2	Rear Bumper Tow Cover (LH/RH) ~ x	\$ 16.20	\$ 32.40
5	1	Rear Reinforcement ?X ~		\$ 537.20
				\$ 1,763.80
			Less 20%	\$ (352.76)
				\$ 1,411.04
6	1	Rear Reverse Sensor Shorted /	NETT	\$ 200.00
		To dismantle & change rear bumper, rear reinforcement, knocking & pull straight rear end panel and all area affected by accident		\$ 600.00 300
		To perform wire checking		\$ 20.00 /
		To dismantle & refit rear bumper sensor		\$ 30 60.00 /
		To spray rear bumper, rear reinforcement and rear panel		\$ 600.00 250
				\$ 2,891.04
				\$ 202.37
				\$ 3,093.41

7% GST
Total

Authorised by Claims Dept
Mrs Tan @ 9639 9195

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Co. Reg. No. 200900309M

huahong.com.sg

GST Reg. No. 200900309M

18/4/19
Hwee Jie - LKK
16/4/19
P/P 2days

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19006793/Jsd3e2

73 BRAS BASAH ROAD

Date: 04-07-2019

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556



ATTN : MUHAMMAD AIRWAN

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YP 130C	Veh. Inspected	SKW 3185D
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1032714-002	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	16/04/2019

2. Vehicle Particulars & Condition

Make & Model	MAZDA 3	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JM6BM42A8G0320890	Colour	BLUE
Odometer	79194 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	YOKOHAMA	6 mm
L/H Front Tyre	205/60 R16	YOKOHAMA	6 mm
R/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm
L/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	18/02/2019	Inspect Date / Time	16/04/2019 (11:51 AM)
Survey held at	HUA HONG PTE LTD 25D SUNGEI KADUT STREET 1 SINGAPORE 729332		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
--	-----------------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 3185D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	1,074.00	1,074.00
10	REAR BUMPER CLIP @\$4.80	NECESSARY	48.00	30.00
2	REAR BUMPER RETAINER (LH/RH) @\$36.10	NOT NECESSARY	72.20	-
2	REAR BUMPER TOW COVER (LH/RH) @\$16.20	NOT NECESSARY	32.40	-
1	REAR REINFORCEMENT	NOT NECESSARY	537.20	-
	LESS 20% DISCOUNT		-352.76	-220.80
			1,411.04	883.20
<u>SPECIAL NETT ITEMS</u>				
1	REAR REVERSE SENSOR (SN)	SHORTED	200.00	200.00
			200.00	200.00
<u>LABOUR</u>				
	TO DISMANTLE & CHANGE REAR BUMPER, REAR REINFORCEMENT, KNOCKING & PULL STRAIGHT REAR END PANEL AND ALL AREA AFFECTED BY ACCIDENT.		600.00	300.00
	TO PERFORM WIRE CHECKING.		20.00	20.00
	TO DISMANTLE & REFIT REAR BUMPER SENSOR.		60.00	30.00
	TO SPRAY REAR BUMPER, REAR REINFORCEMENT AND REAR PANEL.		600.00	250.00
			1,280.00	600.00
GRAND TOTAL			2,891.04	1,683.20
RECOMMENDED COST OF REPAIRS (CONFIRMED)				1,683.20

Report Ref No. CS/INC19006793/Jsd3e2

ONG HWEE JIE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.