

Form 12000

ASS. REC. BY:

REF: CS/FCI19006800/ES d35

Special Instruction:

Surveyor:

Steve

ASSIGNMENT (Office)

CWS

May chun

of

FCI

Date/Time: 9:28am @ 16/4/19

Estimated Cost:

Bill to:

OD / TP WS / TT RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SKR 7963A

Insured:

8HC3140Z

at Workshop m/s

Mova Automotive

Tel:

6272 3892

of

Blk 1008 Bukit Merah Lane 3 #01-04

Policy No:

Claim No:

D1900253SMFST

Sum Insured:

Excess:

Make of Veh:

D.O.A:

11/4/19

(Client's Record)

CA / REV / REP. / REV 24 HRS (DS)

H.O.D. Endorsement:

Date/Time:

11:27am @ 16/4/19

Person Contacted:

Nitha

Vehicle IN:

OUT

Date/Time	Action/Instruction (✓) Estimate
	SKR 7963A - X
	8HC3140Z - CC3-A19/501360/H1na3c2
24/04/19 @ 17:51 p.m.	revised P1 to May via email.

D.O.A: 4/7/2015

2001-1-19

Surveyor

Steve

REF:

SMO PCI

ASSIGNMENT

From:

Date:

22/4/19

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Morning

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^(up)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKR 7963A

Yr Regn:

10/3/15

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota A/His

C.C.

1598

Colour

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

55815

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR 053REH1045 23113

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

11/4/19

D.O.I.

22/4/19

Survey held at

Mova

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 24 MAY 2019

24/5/2019

Date / Time

Action / Instruction

28/5/19 Finalize Cont'n \$1820.88, 3 days (Email sent to Ah Keng Mbr)
(\$ 888.02 Red - 33%)

Date/Time, File Pass to?



: Preli. Report

1)

24/05/19
Typist

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Invs (\$)



: Weekend (\$)

Survey Fee:

Transportation:

\$ + RS. SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ 1820.90 P/P)

110
50
50
52
262

MOTOR SURVEY ASSIGNMENT

Date	15-04-2019	Our Ref No. D19002535MFSH
Accident Date	11-04-2019	Claim Type. Third Party
Insured Vehicle	SHC3140Z	Third Party Vehicle. SKR7963A
Survey Location	BLOCK 1008 BUKIT MERAH LANE 3 #01-04/06/08	
Contact Person.	NITHA	
Contact No.	62723892/ 0	Fax No. 62708314
Survey Type	DIRECT SETTLEMENT: QUANTUM TO BE AGREED (EST. COR - \$2,898.52)	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MOVA AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Steve Chen (LKK Auto)

From: Keong <keong@moval.com.sg>
Sent: Thursday, May 23, 2019 11:29 AM
To: Steve Chen (LKK Auto)
Cc: 'Enny'; 'Suann'; 'JIAYU'
Subject: RE: SKR7963A Ready For Finalise

Dear Steve
Confirmed

Best Regards,
Goh Chai Hock (Keong)
Claims Estimator
Mova Automotive Pte Ltd
HP : 96510098
Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

From: Steve Chen (LKK Auto) [<mailto:SteveChen@lkkauto.com>]
Sent: Tuesday, 7 May 2019 8:58 AM
To: Keong
Subject: SKR7963A Ready For Finalise

Hi Keong,

The finalize is \$1,820.90 (P/P, before GST). 3 days.

Kindly confirm

Thanks

Best Regards,
Steve Chen | Assistant Automotive Assessor
LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Keong [<mailto:keong@moval.com.sg>]
Sent: Monday, May 06, 2019 1:38 PM
To: Steve Chen (LKK Auto)
Subject: SKR7963A Ready For Finalise

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 26 April 2019 5:43 PM
To: 'May Chua Hui Chin'; 'CWS Motor Claims'
Cc: assignments; SUR; Admin-D (LKKAuto)
Subject: RE: SURVEY ASSESSMENT - D19002535MFSH/1
Attachments: SKR 7963A - Preli Advise -.pdf

RE-SEND

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Wednesday, 24 April 2019 5:51 PM
To: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>
Cc: 'assignments' <assignments@lkkauto.com>; 'SUR' <sur@lkkauto.com>; 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19002535MFSH/1

Dear May,

Enclosed preliminary revised of vehicle SKR 7963A.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 16 April 2019 11:29 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19002535MFSH/1

Dear Sir/Mdm,,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 24 April 2019 5:51 PM
To: 'May Chua Hui Chin'; 'CWS Motor Claims'
Cc: assignments; SUR; Admin-D (LKKAuto)
Subject: RE: SURVEY ASSESSMENT - D19002535MFSH/1
Attachments: SKR 7963A - Preli Advise -.pdf

Dear May,

Enclosed preliminary revised of vehicle SKR 7963A.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 16 April 2019 11:29 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19002535MFSH/1

Dear Sir/Mdm,,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Tuesday, 16 April 2019 9:28 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua Hui Chin <maychua@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19002535MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19002535MFSH

Date: 24 April 2019

Our Ref: CS/FCI19006800/Esd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKR 7963A

Please be informed that we had conducted the inspection of the abovementioned vehicle on 22/04/2019 at the premises of M/s Mova Automotive Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ 2,708.90
Revised Estimate Amount	: S\$ 1,730.00
"Check" Items Amount	: S\$ 571.50
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 3 Days

Yours faithfully,
Chen Tsue Yee
Automotive Assessor



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19002535MFSH

Date: 24 April 2019

Our Ref: CS/FCI19006800/Esd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKR 7963A .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 22/04/2019 at the premises of M/s Mova Automotive Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ 2,708.90 .
Revised Estimate Amount (lump sum)	: S\$ 1,730.00 .
"Check" Items Amount	: S\$ 571.50 .
Market Value	: S\$.
LTA Reimbursement Value	: S\$.
Nett Value	: S\$.

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 3 Days

Yours faithfully,
Chen Tsue Yee
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/04/2019 16:27
Date Of Accident	11/04/2019 18:00
Exact Location Of Accident	JURONG TOWN HALL RD (AFT JUNC JURONG EAST ST 11)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKR7963A
Insured/Policyholder	
Name Of Registered Owner	LIM SIOK MUI
NRIC No	S1443630H
Email Address	SUMAYLIN@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-91374188
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VA1/GA446094
Cover Note Number	

Driver

Name of Driver	LIM SIOK MUI
NRIC No	S1443630H
Date Of Birth	25/03/1960
Occupation	INDOOR
Date Of Driving Pass	09/09/1986
Driving Experience	32 YEARS AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91374188
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	SUMAYLIN@HOTMAIL.COM

Address	BLK 526 BUKIT BATOK STREET 51 #02-116
Postcode	2365
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	SHC3140Z
Vehicle Make/Model/Colour	HYUNDAI
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	TAY KIAN HENG
NRIC/Passport Number	
Contact Number	8209 7577
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims;
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time
12/4/19
8am

Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

Sketch Plan



Sketch Plan #2 Pg. 1

Describe Circumstances of the Accident

I was driving along Jurong Town Hall Road heading towards Jurong East After junction at DE St 11, there was a build up of cars in front. The cars in front braked and I was braked. The taxi behind me did not stop on a time and bumped into the back of my car.

Taxi driver Mr. [unclear] admitted that he was at fault and apologised. Later, he called me to ask me to report and claim through insurance.

Declaration

We declare the foregoing particulars are true in every respect.

[Signature]

12/4/19

Policyholder's Signature / Date & Time

8am

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3630H
Vehicle Details	
Vehicle No.:	SKR7963A
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS CLASSIC 1.6 CVT
Primary Colour:	Grey
Manufacturing Year:	2014
Engine No.:	1ZRY135140
Chassis No.:	MR053REH104523113
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$17,398.00
Original Registration Date:	10 Mar 2015
First Registration Date:	10 Mar 2015
Transfer Count:	0
Actual ARF Paid:	\$12,398.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Mar 2025
PARF Rebate Amount:	\$9,298.00
Intended COE Rebate Details	
COE Expiry Date:	09 Mar 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,199.00
COE Rebate Amount:	\$33,606.00
Total Rebate Amount:	\$42,904.00

The information contained herein is correct as at 22 Apr 2019

OK

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

13/04/2019

MS FIRST CAPITAL INSURANCE LIMITED
36 Robinson Road
#16-01 City House
Singapore 068877.

Attention :- XA026

Page # :- 1
Veh # :- SKR7963A
Veh Model :- TOYOTA ALTIS
Estimate# :- CK418997
Claim # :-
ACC. Date :- 12/04/19
Terms :- C.O.D Days
Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR BUMPER / DD	1 PC	530.20	579.60
2.	REAR BUMPER REINFORCEMENT	1 PC	378.90	378.90
3.	REAR BUMPER BRACKET LH X	1 PC	171.40	171.40
4.	REAR BUMPER SIDE RETAINER LH / BR	1 PC	133.90	181.40
5.	REAR BUMPER CLIPS / NER	10 PC	3.90	39.00
6.	REAR BUMPER REVERSE SENSOR / BR	1 PC	200.00	383.10
7.	REAR LAMP LH X NAI	1 PC	371.80	371.80
8.	REAR PANEL - REPAIR X R	1 PC		
9.	REAR FENDER LH - REPAIR X R	1 PC		
LIST TOTAL S\$				2,105.20
25% DISCOUNT S\$				-526.30
				1,578.90
LABOUR :				
TO REPAIR REAR PANEL, REAR FENDER LH, REAR FLOOR PANEL, REMOVE & REFIX DAMAGED PARTS. STRAIGHTEN AND REALIGN AFFECTED AREAS				
TO SPRAY AFFECTED AREAS				480.00
TO INSTALL REVERSE SENSOR & CHECK WATER SEEPAGE				600.00
LABOUR TOTAL S\$				50.00
				1,130.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Customer's Signature/Co. Stamp

Signature:
Date:

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 2,708.90

GST @ 7 % 189.62

AMOUNT DUE S\$ 2,898.52

MOVA AUTOMOTIVE PTE LTD

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159418
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

13/04/2019

MS FIRST CAPITAL INSURANCE LIMITED

36 Robinson Road

#16-01 City House

Singapore 068877.

Attention :- XA026

Page # :- 1

Veh # :- SKR7963A

Veh Model :- TOYOTA ALTIS

Estimate# :- CK418997

Claim # :-

ACC. Date :- 12/04/19

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

LIST ITEMS :

1.	REAR BUMPER / DD	1	PC	579.60	579.60	✓
2.	REAR BUMPER REINFORCEMENT	1	PC	378.90	378.90	✓
3.	REAR BUMPER BRACKET LH X	1	PC	171.40	171.40	✓
4.	REAR BUMPER SIDE RETAINER LH	1	PC	181.40	181.40	✓
5.	REAR BUMPER CLIPS / NER	101	PC	3.90	399.00	✓
6.	REAR BUMPER REVERSE SENSOR	1	PC	383.10	383.10	✓
7.	REAR LAMP LH X	1	PC	371.80	371.80	✓
8.	REAR PANEL - REPAIR X R	1	PC			
9.	REAR FENDER LH - REPAIR X R	1	PC			

LIST TOTAL S\$

2,105.20

25% DISCOUNT S\$

-526.30

1,578.90

LABOUR :

TO REPAIR REAR PANEL, REAR FENDER LH, REAR
FLOOR PANEL, REMOVE & REFIX DAMAGED PARTS.
STRAIGHTEN AND REALIGN AFFECTED AREAS

TO SPRAY AFFECTED AREAS

TO INSTALL REVERSE SENSOR & CHECK WATER
SEEPAGE

LABOUR TOTAL S\$

1733.40

433.35

1300.05

680.00

\$1980.05

3 days

300 480.00

350 600.00

30 50.00

680 1,130.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$

2,708.90

GST @ 7 %

189.62

AMOUNT DUE S\$

2,898.52

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19006800/Esd3s2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 29-05-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3140Z	Veh. Inspected	SKR 7963A	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19002535MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	16/04/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	MR053REH104523113	Colour	GREY	
Odometer	55815	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55R16	YOKOHAMA	6 mm	
L/H Front Tyre	205/55R16	YOKOHAMA	6 mm	
R/H Rear Tyre	205/55R16	YOKOHAMA	6 mm	
L/H Rear Tyre	205/55R16	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/04/2019	Inspection Date	22/04/2019	
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKR 7963A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DENTED	579.60	530.30
1	REAR BUMPER REINFORCEMENT	DENTED	378.90	378.90
1	REAR BUMPER BRACKET LH	DENTED	171.40	171.40
1	REAR BUMPER SIDE RETAINER LH	BROKEN	181.40	133.90
1	REAR LAMP LH	NOT NECESSARY	371.80	-
1	REAR PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR FENDER LH (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 25% DISCOUNT		-420.77	-303.62
			1,262.33	910.88
1	REAR BUMPER CLIPS (SN)	NECESSARY	39.00	30.00
1	REAR BUMPER REVERSE SENSOR (SN)	BROKEN	383.10	200.00
	LESS 25% DISCOUNT		-105.53	-
			316.57	230.00
	<u>LABOUR</u>			
	TO REPAIR REAR PANE, REAR FENDER LH, REAR FLOOR PANEL. REMOVE & REFIX DAMAGED PARTS. STRAIGHTEN AND REALIGN AFFECTED AREAS.		480.00	300.00
	TO SPRAY AFFECTED AREAS.		600.00	350.00
	TO INSTALL REVERSE SENSOR & CHECK WATER SEEPAGE.		50.00	30.00
			1,130.00	680.00
	GRAND TOTAL		2,708.90	1,820.88
RECOMMENDED COST OF REPAIRS				1,820.88

Report Ref No. CS/FC119006800/Esd3s2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.