

CWS
 From (Person) marcus Eileen Lee of FCI Date/Time 9:30am @ 16/4/11
 Estimated Cost Bill to
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS
 To Inspect Vehicle No SJZ 2931U Insured SHD 7088K
 at Workshop no Hock wah Tel 67853933
 of Bllc 9006 Tampines Ind. park A #01-204
 Policy No Claim No D19002350 MPST
 Sum Insured Excess
 Make of Vehr (Client's Record) D.O.A 05/04/2011

CA / REV / REP. / REV 24 HRS
 Date/Time 11:46am @ 16/4/11 Person Contacted Mr. Hun H.O.D. Endorsement
 Vehicle IN / OUT OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SJZ 2931U - X</u>
	<u>SHD 7088K - NS/INC 18019434 / K1 vbn 2</u> D.O.A. <u>24/10/18</u>

(08/11/13) wef

REF:

ASS. REC. BY: *Marcus***ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: *53229314*at Workshop m/s *Woch Woch Tanjong*of *10.30*Insured: *SHD 7088*

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: *18k*

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: *2*

days

Res.: Yes or No

Lum Sum: *20*

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: *53229314*Yr Regn: *1.07*Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or *CA*Make: *Toyota*c.c. *1794*Colour: *Grey*

A/C: Insured / Std / NI / NA

Sp. Reading: *256802*

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *2NE100329.892*Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: *205/55-16*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /TOYO / YOKO or *contenuto*

Front

Rear

R/Bal. *5*

mm

R/Bal. *5*

mm

L/Bal. *5*

mm

L/Bal. *5*

mm

D.O.A. *5/4/19*D.O.I. *22/4/19*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

*9/1/2022 2yos fuh.**22/4/19 confirmed 1/5 #900 with Man. (Red. 957.99/51%)*

RECEIVED 24 APR 2019

MV: \$18k (EST) - LTA: \$14297 = NV: \$3703.00

Date/Time, File Pass to?



Preli. Report

duh tyast

Final Report

Date/Time, File Return to?

2)

Days Of Repair: *2*

Resurvey No. of Trip: _____

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

100

50

25

175

Report Format: *TP*Lump Sum / I.B.I: (\$ *900f*)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19002350MFSH

Date: 23/4/2019

Our Ref: CS/FCI19006801/Utd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJZ 2931U

Please be informed that we had conducted the inspection of the abovementioned vehicle 22/4/2019 at the premises of M/s Hock Wah have the following to report: -

Workshop Estimate Amount	: S\$	<u>1,857.99</u>
Revised Estimate Amount	: S\$	<u>1,368.30</u>
"Check" Items Amount	: S\$	<u>0.00</u>
Market Value	: S\$	<u> </u>
LTA Reimbursement Value	: S\$	<u> </u>
Nett Value	: S\$	<u> </u>

Description of Damage:

The vehicle sustained damages at the o/s front portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Marcus

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	08-04-2019	Our Ref No. D19002350MFSH
Accident Date	05-04-2019	Claim Type. Third Party
Insured Vehicle	SHD7088K	Third Party Vehicle. SJZ2931U
Survey Location	BLK 9006 TAMPINES INDUSTRIAL PARK A, #01-204	
Contact Person.	DEHAN	
Contact No.	67853933/ 0	Fax No. 0
Survey Type	WITHOUT PREJUDICE: LIABILITY UNCLEAR:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HOCK WAH MOTOR WORKSHOP PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 23 April 2019 5:59 PM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments
Cc: 'Eileen Lee'; SUR
Subject: RE: SURVEY ASSESSMENT - D19002350MFSH/1
Attachments: PRELI ADVISED SJZ 2931U.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SJZ 2931U**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 16 April 2019 11:48 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19002350MFSH/1

Dear Sir/Mdm,,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 16 April 2019 9:38 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19002350MFSH/1

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 1535A

Vehicle Details

Vehicle No.: SJZ2931U
Vehicle to be Exported: No
Intended Deregistration Date: 22 Apr 2019
Vehicle Make: TOYOTA
Vehicle Model: WISH 1.8 A
Primary Colour: Grey
Manufacturing Year: 2006
Engine No.: 1ZZ2713767
Chassis No.: ZNE100329892
Maximum Power Output: 97.0 kW (130 bhp)
Open Market Value: \$18,951.00
Original Registration Date: 10 Jan 2007
First Registration Date: 10 Jan 2007
Transfer Count: 1
Actual ARF Paid: \$20,847.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 09 Jan 2022
COE Category: B - Car (1601cc & above)
COE Period(Years): 5
PQP Paid: \$26,330.00
COE Rebate Amount: \$14,297.00
Total Rebate Amount: \$14,297.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 22 Apr 2019

OK

AVIVA

...you can go to any workshop you preferred!

Toyota Wish

Price Range

Depreciation

> 10 year

Vehicle Type



Submit

Advanced Search

Home » Used Cars » Car House Pte Ltd » Toyota Wish 1.8A X (COE till 08/2022)

Toyota Wish 1.8A X (COE till 08/2022)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

CAR HOUSE PTE LTD

Price \$29,800

Depreciation \$9,090 /yr

Reg Date 02-Aug-2007
(3yrs 3mths 10days COE left)

Mileage 118,300 km (10.1k /yr)

Manufactured 2007

Road Tax \$1,166 /yr

Transmission Auto

Dereg Value \$16,716 as of today (change)

OMV \$19,703

COE \$25,486

ARF \$21,674

Engine Cap 1,794 cc

Power 97.0 kW (130 bhp)

Curb Weight 1,300 kg

No. of Owners 2

Type of Vehicle MPV

Features

Powerful And Reliable 16 Valves VVT-i DOHC Engine, Smooth 4 Speed Steptronic Gearbox. Digital Climate Control Aircon. Airbags. ABS. 7 Seaters. View specs of the Toyota Wish (2008-2009)

Accessories

Stock Rims, Factory Fitted Audio System, Reverse Sensors, Electrical Retractable Side Mirrors, Leather Seats, Etc

Description

Sporty Black Colour Unit. Low Mileage. Well Maintained By Previous Owner. The Most Reliable And Low Maintenance. Smooth Gearbox And Engine. Flexible Loan And Trade In Are Welcome. Please Contact Our Friendly Sales Consultant For A Viewing Appointment. Price Exclude Booking Fee.

Category

COE Car

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started

Compare

Vehicle Evaluation



Location Map

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company

Car House Pte Ltd

» dealer's pricelist
» 37 vehs sold | 39 vehs available

Address

210 Turf Club Road Lot B23

Search cars nearby this location

Location

Car Mall @ The Grandstand

Office No

64631939

Contact Person(s)

Michelle	86063381
Teo	96116191
Damien	87848949
Wing	82273461

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 9006 TAMPINES ST 93 #01-204
SINGAPORE 528840
TEL : 67853933 FAX: 67883933
R.O.C No. 200104141D GST Reg No. 20-0104141-D

TO : S7031535A
LOEW LOKE HOON
NO

SINGAPORE
TEL : FAX :
PH : 96725879
ATTN :

ESTIMATE BILL

Number : EBK0000269
Date : 22/04/2019
Case No : ADK0000342
Vehicle No : SJZ2931U
Chassis:
Year of Mfr
Policy No
Model : TOYOTA WISH

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	FRT BUMPER SIDE RETAINER LH RH	2.0	78.84	25	118.26
2	FRT BUMPER	1.0	927.50	25	695.63
3	FRT BUMPER CLIPS	12.0	4.90	25	44.10
List Price - Parts Sub Total					857.99
Parts Total					857.99
4	LABOUR TO REMOVE AND REFIT NECESSARY PARTS	1.0	500.00	0	500.00
5	SPRAY PAINT ON THE AFFECTED AREAS	1.0	500.00	0	500.00
Labour 1 Sub Total					1,000.00
SINGAPORE DOLLARS : ONE THOUSAND NINE HUNDRED EIGHTY-EIGHT AND CENTS FIVE ONLY					
Less Excess					0.00
SUBTOTAL					1,857.99
GST 7.00%					130.06
TOTAL					1,988.05

Date of accident : 22/04/2019 10:30 AM. Place:

E. & O. E.

Signature:

Date:

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19006801/Utd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 02-05-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 7088K	Veh. Inspected	SJZ 2931U
	Policy No.		Coverage (\$)	0.00
	Claim No.	D19002350MFSH	Excess (\$)	0.00
	Assign From	EILEEN LEE	Assign Date	16/04/2019
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA WISH (A)	c.c	1794
	Engine No.	HIDDEN	Year of Reg.	2007
	Chassis No.	ZNE100329892	Colour	GREY
	Odometer	256802	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	CONTINENTAL	5 mm
	L/H Front Tyre	205/55 R16	CONTINENTAL	5 mm
	R/H Rear Tyre	205/55 R16	CONTINENTAL	5 mm
	L/H Rear Tyre	205/55 R16	CONTINENTAL	5 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date	05/04/2019	Inspection Date	22/04/2019
	Survey held at	BLK 9006 TAMPINES INDUSTRIAL PARK A #01-204		
	Repairer	HOCK WAH MOTOR WORKSHOP PTE LTD		
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJZ 2931U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
2	FRT BUMPER SIDE RETAINER LH & RH @\$78.84	NOT NECESSARY	157.68	-
1	FRT BUMPER	DEEP CUT	927.50	665.40
12	FRT BUMPER CLIPS @\$4.90	NECESSARY	58.80	58.80
	LESS 25% DISCOUNT		-285.99	-181.05
			857.99	543.15
LABOUR				
	LABOUR TO REMOVE AND REFIT NECESSARY PARTS.		500.00	200.00
	SPRAY PAINT ON THE AFFECTED AREAS.		500.00	400.00
			1,000.00	600.00
GRAND TOTAL			1,857.99	1,143.15
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				900.00

Report Ref No. CS/FCI19006801/Utd3n2

MARKET VALUE: \$18,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$14,297.00=NETT VALUE: \$3,703.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.