

ASS. REC. BY:

REF: CS/LPC 19006802/R19d301 Special Instruction:

Survey: RASU

ASSIGNMENT (Office)

From (Person): Gerald Poh of LPC Date/Time: 16.4.19 12.38PM

Estimated Cost: Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SJJ 2522B Insured:

at Workshop m/s Wah Hong & Credit Tel: 65 15 5 9 8 8

of 38 Toh Guan Road East # 01 - 57

Policy No: Z18VP05070047 Claim No: 18/19/19/VP05/071667

Sum Insured: Excess: 1500

Make of Veh: (Client's Record) D.O.A. 10/4/19

CA / REV / REP. / REV 24 HRS 17.4.2019

Date/Time: 16.4.19 3.40PM Person Contacted: Michael H.O.D. Endorsement:

Vehicle: IN/OUT

Date/Time	Action/Instruction	Eshimatr (X)
	SJJ 2522B - AA / AIG 19006607 / AA	D.O.A. - 10/04/2019
	Rasul inform say that utsp no provide Eshimatr.	
18/4@2:33pm	revert via email preli advise.	

Forme

ASSIGNMENT

05/08/08

From: _____ Date: _____
 Estimated Cost: _____
 TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No. SJJ 25 22B
 at Workshop with WAH HONG
 of 38, TOH KUAN RD EAST #01-57
 Insured LPC
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: NIL
 (Client's Record)
 Make of Velt: _____
 (Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 65K
 IDAC Accident Rport: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lump Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJJ 25 22B Vr Regn: _____
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: MAZDA RX 8 c.c.: 1308
 Colour: PINK A/C: Insured / Std / NI / NA
 Sp. Reading: 180619 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: SE3P301701
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 235/45R17
 R: _____
 BS / DUM / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front _____ Rear _____
 R/Bal: 5 mm R/Bal: 5 mm
 L/Bal: 5 mm L/Bal: 5 mm
 D.O.A: _____ D.O.I: 17/04/19
 Survey held at WAH HONG
 Des. of Damage: Fr / Rear / O/S / N/S / UIC / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
23/04/08 @ 10.30am	2nd report to Gerald Poh via Meisner.
23/04/08 @ 12.15pm	Chew Bang Lee informed CLA via Meisner.
23/04/08 @ 4.57pm	Informed Michael CLA on US basis of EX: \$1500 by email. Loss finalises by \$14150, 9 days. (Cost \$ 4187.10, 30%)

RECEIVED 1 JUN 2019

Date/Time: File Pass to? Prell. Report
 Final Report
 Date/Time: File Return to?
 Report Format: MER-01
 Lump Sum / I.B.I. (\$) 14150

Days Of Repair: 9
 Resurvey No. of Trip: 2
 Add Fee: Site Insp (\$) Interview (\$) Tech. Invs (\$) Weekend (\$)

10 x 15 = 150
 170 + 150 = 320
 320 + 20% = 384

Survey Fee:	384
Transportation:	50
_____	50
_____	132
_____	591
_____	623+11
_____	633

17/6/19

Nivitha (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Tuesday, 16 April 2019 12:38 PM
To: assignments@lkkauto.com
Cc: MT_Claim_SG; Tee Sunny
Subject: OD SURVEY - SJJ2522B [External Confidential]

65155988

⇒ in

Toh Guan

Lonpac External - Confidential


Our Ref : 18/19/19/VP05/021667

Dear Nivitha,

Kindly arrange for Bryan or Kenneth to survey the vehicle now lying at Wah Hong Motors & Credit Pte Ltd and establish if it has undergo any modifications.

The workshop is in the process of sourcing for the parts and shall upload into Merimen once they are available. [

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 23 April 2019 4:57 PM
To: michael@wahhong.sg
Cc: SUR
Subject: OD VEHICLE SJJ 2522B (DOA: 10/04/2019)

Dear Michael,

As instructed by our client, please proceed to repair the insured vehicle **SJJ 2522B** at repair cost on Lump Sum basis (Excess \$1,500/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	19 Apr 2019 09:52	Cim Veh Model Changed	(205498) MAZDA RX-8 1.3 (M).	[R] Michael Tee Lian Huat [R]
2	19 Apr 2019 09:52	Cim Created	Reg No: SJ2522B. Policy No: Z18VP05020042. Acct Date: 2019/04/10. Claim Type: OD. Insurer: Lonpac Insurance Bhd (HQ), Workshop: Wah Hong Motors & Credit Pte Ltd (H Q)	[R] Michael Tee Lian Huat [R]
3	20 Apr 2019 12:45	Cim Submitted	19314.60.	[R] Michael Tee Lian Huat [R]
4	22 Apr 2019 08:59	Cim Registration Modified	Excess: -> 1500.00.	[I] Gerald Poh [I]
5	22 Apr 2019 08:59	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):SURVEY & REVERT	[I] Gerald Poh [I]
6	22 Apr 2019 08:59	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/05/02	[I] Gerald Poh [I]
7	22 Apr 2019 08:59	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[I] Gerald Poh [A]
8	22 Apr 2019 09:02	Assignment 1st Accessed		[A] DENISE TAY KWEE CHENG [I]
9	22 Apr 2019 09:05	Ins Sent Back Est	VEHICLE NUMBER INCORRECT	[I] Gerald Poh [P]
10	22 Apr 2019 09:07	Cim Registration Modified	Reg No: SJ2522B->SJ2522B.	[R] Michael Tee Lian Huat [R]
11	22 Apr 2019 09:08	Cim Submitted	19314.60.	[R] Michael Tee Lian Huat [A]
12	22 Apr 2019 09:31	Adj Adjuster Assigned	[None] -> MOHD RASUL	[A] LEE SU THING [A]
13	23 Apr 2019 10:29	Adj Rpt Initiated		[A] SHIAU CHAN [A]
14	23 Apr 2019 10:32	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/05/02	[A] SHIAU CHAN [A]
15	23 Apr 2019 10:34	Adj Mandate Request	Cur.Req:18344.60:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. THE VEHICLE REPAIR ON LUMP SUM BASIS. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN [I]
16	23 Apr 2019 12:15	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/05/02	[I] Chew Beng Kee [I]
17	23 Apr 2019 12:15	Adj Mandate Set	Approved:14650.00.	[I] Chew Beng Kee

Date From Date To Audit Type

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2121419	19/04/2019 09:52	Motor	Wah Hong Motors & Credit Pte Ltd (HQ)	Wah Hong Motors & Credit Pte Ltd (HQ)	SJ2522B		xx.xx

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Gerald Poh

Date: 23 Apr 2019

Preliminary Advice

Vehicle No	: SJJ2522B	Accident Date	: 10/04/2019
Make	: MAZDA RX-8	Policy No.	: Z18VP05020042
Assignment Date	: 22/04/2019	Excess	: S\$1,500.00
Date of Inspection	: 17/04/2019	Est. Duration of Repair	: 9.00
Inspection At	: WAH HONG MOTORS & CREDIT PTE LTD (HQ) 38 TOH GUAN ROAD EAST, #01-57, ENTERPRISE HUB SINGAPORE 608581		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,314.60
Revised Amount	:S\$	16,760.60
Check Items (Estimated)	:S\$	1,584.00
Total	:S\$	18,344.60
Lump Sum Repair	:S\$	14,650.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	65,000.00
COE / PARF Rebate	:S\$	30,384.00
Salvage Value	:S\$	
Margin for Repair	:S\$	34,616.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : THE VEHICLE REPAIR ON LUMP SUM BASIS.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Thursday, 18 April 2019 2:33 PM
To: Admin-D (LKKAuto); 'GERALD POH WEE BIN'; assignments
Cc: 'MT_Claim_SG'; SUR
Subject: RE: OD SURVEY - SJJ2522B [External Confidential]
Attachments: PRELI ADVISED SJJ 2522B.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SJJ 2522B**

**We have not authorise repair.
Pending estimate.**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 16 April 2019 4:52 PM
To: 'GERALD POH WEE BIN' <geraldpoh@lonpac.com>; assignments <assignments@lkkauto.com>
Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; SUR <sur@lkkauto.com>
Subject: RE: OD SURVEY - SJJ2522B [External Confidential]

Dear Gerald,

Thank you for the assignment.

Please be informed that repairer agreed survey on 17/04/2019.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN [<mailto:geraldpoh@lonpac.com>]
Sent: Tuesday, 16 April 2019 12:38 PM
To: assignments@lkkauto.com



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX : (065) 62564315

Your Ref: TBA

Date: 18/4/2019

Our Ref: CS/LPC19006802/R1qd3

The Motor Claims Department
LONPAC INSURANCE BHD


PRELIMINARY ADVICE OF VEHICLE NO. SJJ 2522B

Dear Sir/Madam,

Please be informed that we had conducted the inspection of the above mentioned vehicle on 18/4/2018 at the premises of M/s Wah Hong and have the following to report: -

Workshop Estimate Amount	: <u>S\$ Pending Estimate</u>
Revised Estimate Amount	: <u>S\$ -</u>
"Check" Items Amount	: <u>S\$ -</u>
Market Value	: <u>S\$ 65,000.00</u>
LTA Reimbursement Value	: <u>S\$ 30,384.00</u>
Nett Value	: <u>S\$ 34,616.00</u>

Description of Damage:
The vehicle sustained damages at the front portion.



Comments/ Present Status:
Damages Consistent.

Repair days: TBA

Yours faithfully

Rasul
Automotive Assessor

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0895E
Vehicle Details	
Vehicle No.:	SJJ2522B
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Apr 2019
Vehicle Make:	MAZDA
Vehicle Model:	RX-8 TYPE-S 1.3 M
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	138544793
Chassis No.:	SE3P301701
Maximum Power Output:	184.0 kW (246 bhp)
Open Market Value:	\$28,292.00
Original Registration Date:	05 Sep 2008
First Registration Date:	05 Sep 2008
Transfer Count:	4
Actual ARF Paid:	\$28,292.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	04 Sep 2028
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$32,339.00
COE Rebate Amount:	\$30,384.00
Total Rebate Amount:	\$30,384.00

The information contained herein is correct as at 12 Apr 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/04/2019 17:29
Date Of Accident	10/04/2019 23:45
Exact Location Of Accident	PIE TOWARD TUAS BEFORE CORPORATION EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJJ2522B
Insured/Policyholder	
Name Of Registered Owner	LOH KAILING
NRIC No	S9030895E
Email Address	KAILINQQ@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90304922
Alternative Phone No	OFFICE-90304922

Vehicle Particulars

Manufacturer	MAZDA
Model	RX-8-1.3 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z18VP05020042
Cover Note Number	

Driver

Name of Driver	LOH KAILING
NRIC No	S9030895E
Date Of Birth	25/08/1990
Occupation	INDOOR
Date Of Driving Pass	24/12/2010
Driving Experience	8 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-90304922
Fax Number	
Contact Number	OFFICE-90304922
EMail Address	KAILINQQ@GMAIL.COM

Address	BLK 513 JURONG WEST STREET 52 #12-34
Postcode	640513
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO THE SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GX7940G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




 Policyholder's Signature
 Date & Time: 11/04/19
 11:51 AM

 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS TRAVELING TOWARDS TUAS ON THE LEFT LANG.
AND I HIT THE CAR IN FRONT OF ME.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 110411A
11:51 AM

Driver's Signature

(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name:
NRIC/FIN No.:


LONPAC INSURANCE BHD (598FC9639C)

Incorporated in Malaysia

Singapore Office: 300 Beach Road #17-04/07, The Concourse, Singapore 189556

Tel: (65) 6236 7388 Fax: (65) 6256 2747 Website: www.lonpac.com.sg

GST Reg No. FS-0009635-C

MX1

CERTIFICATE OF INSURANCE

 MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CAP 189) REPUBLIC OF SINGAPORE
 MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES 1960 (REPUBLIC OF SINGAPORE)
 ROAD TRANSPORT ACT 1987 (MALAYSIA)
 MOTOR VEHICLES (THIRD PARTY RISKS) RULES: 1959 (MALAYSIA)

Certificate No. : Z18VP09020042

Type of Cover : COMPREHENSIVE

1. Index Mark and Vehicle Registration Number

 MAZDA RX-8 1.3
 - SJJ2522B

2. Name of Policy Holder

LOH KAI LING

 3. Effective Date of the Commencement of Insurance
 for the purpose of the Act

03/09/2018

4. Date of Expiry of the Insurance

04/09/2019

5. Persons or Classes of Persons entitled to drive

(A) THE POLICYHOLDER (B) ANY OTHER PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH HIS/HER PERMISSION

Provided that the person driving is permitted in accordance with the Licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use

USE ONLY FOR SOCIAL, DOMESTIC AND PLEASURE PURPOSES AND FOR THE POLICYHOLDER'S BUSINESS. THE POLICY DOES NOT COVER USE FOR HIRE OR REWARD, RACING, PACE-MAKING, RELIABILITY TRIAL, SPEED-TESTING OR THE CARRIAGE OF GOODS (OTHER THAN SAMPLES) IN CONNECTION WITH ANY TRADE OR BUSINESS OR USED FOR ANY PURPOSE IN CONNECTION WITH THE MOTOR TRADE.

Excess : S\$ 1,500.00 (SECTION 1) INSURED / NAMED DRIVERS

S\$ 3,000.00 (SECTION 1) UNNAMED DRIVERS

S\$ 3,000.00 (SECTION 1) ADDITIONAL EXCESS FOR ELDERLY OR YOUNG AND/OR INEXPERIENCED DRIVERS

S\$ 100.00 WINDSCREEN EXCESS

Condition : ACCIDENT REPAIRS AT LONPAC'S AUTHORISED WORKSHOPS

* Limitations rendered inoperative by Section 95 of the Road Transport Act 1987 (Malaysia) or Section 6 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore are not included under heading

I/WE hereby certify that this covering Note is issued in accordance with the provisions of Part IV of the Road Transport Act 1987 (Malaysia) and Motor Vehicles (Third-Party Risks and Compensation) Act (Cap 189) Republic of Singapore

H.P. Owner : TOKYO CENTURY LEASING (SINGAPORE) PTE LTD

 CHIEF EXECUTIVE
 (Singapore Branch)

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S9030895E**



Name

LOH KAI LING

罗 凯 凌

Race

CHINESE

Date of birth

25-08-1990

Sex

F

S9030895E

Country of birth

SINGAPORE

3765672



NRIC No. **S9030895E**

Date of issue

07-09-2005

Address

**APT BLK 513 JURONG WEST STREET 52
#12-34
SINGAPORE 640513**

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S9030895E



Name

LOH KAI LING

罗 凯 凌

Race

CHINESE

Date of birth Sex

25-08-1990 F

Country of birth

SINGAPORE



3765672

NSIC No. S9030895E



Date of issue

07-09-2005

Address

APT BLK 513 JURONG WEST STREET #2
#12-34
SINGAPORE 640513

REPUBLIC OF SINGAPORE DRIVING LICENCE



License Number: **S9030895E**
Name: **LOH KAI LING**

Birth Date: **25 Aug 1990**
Issue Date: **23 Jul 2015**

002454270C



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIFICATION


CLASSIFICATION

Class 3 Motor Cars \leq 3000kg with \leq 7 passengers, exclusive 20% of the driver; and other motor vehicles \leq 2500kg


NP 428A *




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Wah Hong Motors & Credit Pte Ltd (Co.Reg.No:199806235M)38 Toh Guan Road East, #01-57, Enterprise Hub
Singapore 608581

Tel: +65 6773 7377 Fax: +65 6896 6321 Email: nicholas@wahhong.sg;michael@wahhong.sg

INSURER: Lonpac Insurance Bhd (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	190410
Policy No:	Z18VP05020042	Date of Loss:	10/04/2019
Vehicle Reg. No.:	SJ2522B	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LOH KAILING		

Make/Model:	MAZDA RX-8, 1.3 (M)	Vehicle Reg. Date:	05/09/2008
Vehicle Colour:	PURPLE/SILVER		
Engine No:	13B544793	Chassis No:	SE3P301701
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	12

Present Location: WAH HONG MOTORS & CREDIT PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	16,264.60
Miscellaneous Items	0.00
Labour	3,050.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	19,314.60
+ GST 7.00% (S\$)	1,352.02
Nett Amount (S\$)	20,666.62

This claim is handled by: MICHAEL TEE LIAN HUAT

Generated using Merimen e-Claims Internet Estimation & Adjusting System

20332.10

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Apr 2019)
Parts: M1-COUPE MAZDA RX-8 1.3 (M) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Wah Hong Motors & Credit Pte Ltd/SJ2522B/20/04/2019 12:45
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 Pc Front Bonnet <i>CR4</i>	0.00	0.00	*855.00 F
2	1		*1 Pc Front Bumper <i>CR4</i>	0.00	0.00	*620.00 F
3	1		*1 Pc Front R/H Fender <i>BT</i>	0.00	0.00	*720.00 F
4	1		*1 Pc Front L/H Fender <i>BT</i>	0.00	0.00	*750.00 F
5	1		*1 Pc Front Bumper Lower Lid <i>CR4</i>	0.00	0.00	*320.00 F
6	1		*1 Pc Front R/H Headlamp <i>TR4</i>	0.00	0.00	*1,328.00 F
7	1		*1 Pc Front L/H Headlamp <i>TR4</i>	0.00	0.00	*1,328.00 F
8	1		*1 Pc Front Support Panel <i>BT</i>	0.00	0.00	*520.00 F
9	1		*1 Pc Front R/H Fog Lamp <i>CR4</i>	0.00	0.00	*320.00 F
10	1		*1 Pc Front L/H Fog Lamp <i>CR4</i>	0.00	0.00	*320.00 F
11	1		*1 Pc Radiator <i>? CR4</i>	0.00	0.00	*860.00 F
12	1		*1 Pc Front R/H Fog Lamp Cover <i>CR4</i>	0.00	0.00	*155.00 F
13	1		*1 Pc Front L/H Fog Lamp Cover <i>CR4</i>	0.00	0.00	*155.00 F
14	1		*1 Pc Engine Fuse Box Housing <i>CR4</i>	0.00	0.00	*1,250.00 F
15	1		*1 Pc Radiator Spare Tank <i>TR4</i>	0.00	0.00	*320.00 F
16	1		*1 Pc Air Cleaner With Inlet Duct <i>TR4</i>	0.00	0.00	*820.00 F
17	1		*1 Pc Havdness With Fuse Box Housing <i>CR4</i>	0.00	0.00	*3,100.00 F
18	1		*1 pc Air Con Condenser <i>? X 500</i>	0.00	0.00	*580.00 F ^X
19	1		*1 Pc Front Bumper Reinforcement <i>BT</i>	0.00	0.00	*465.00 F

F=Franchise part.

Sub Total (S\$)	<i>14,206</i>	14,786.00
+ Margin on L,N Items 10.00% (S\$)	<i>+ 106</i>	1,478.60
Total Parts (S\$)	<i>15,626.60</i>	16,264.60

Wah Hong Motors & Credit Pte Ltd/SJ2522B/20/04/2019 12:45. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	remove and replace all the parts mentioned above and knocking and straighten up the necessary affected areas	New	1200 2,100.00
2	spray painting on affected areas	New	800.00
3	check wiring system engine	New	80 150.00
Gross Labour Cost (S\$)			2080 <u>3,050.00</u>

Wah Hong Motors & Credit Pte Ltd/SJ2522B/20/04/2019 12:45. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Handwritten: Pasol
Hp 900 10068
23/4/19

Handwritten calculations:
9 days 15,626.60
HS 2080.00
22/04/19 @ 1150 17,706.60
EXCESS: TBA 20%
14,165.28

Handwritten: Resur
Resur after repair 41,141.50
9 days
HS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Ben(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature
Date

Wah Hong Motors & Credit Pte Ltd (Co.Reg.No:199806235M)38 Toh Guan Road East, #01-57, Enterprise Hub
Singapore 608581

Tel: +65 6773 7377 Fax: +65 6896 6321 Email: nicholas@wahhong.sg;michael@wahhong.sg

(SUPPLEMENTARY)INSURER: **Lonpac Insurance Bhd (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	190410
Policy No:	Z18VP05020042	Date of Loss:	10/04/2019
Vehicle Reg. No.:	SJJ2522B	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LOH KAILING		

Make/Model:	MAZDA RX-8, 1.3 (M)	Vehicle Reg. Date:	05/09/2008
Vehicle Colour:	PINK		
Engine No:	13B544793	Chassis No:	SE3P301701
Odometer:	180619 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	12

Remarks:	INTAKE MANIFOLD ASSEMBLE
Present Location:	WAH HONG MOTORS & CREDIT PTE LTD (HQ)

COST OF CLAIMS	Amount
Parts	1,017.50
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	1,017.50
+ GST 7.00% (\$\$)	71.23
Nett Amount (\$\$)	1,088.73
+ Previous Estimates (\$\$)	20,666.62
Claim Total (\$\$)	21,755.35

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 May 2019)

Parts: M1-COUPE MAZDA RX-8 1.3 (M) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Wah Hong Motors & Credit Pte Ltd/SJJ2522B/16/05/2019 16:06

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 Pc Intake Manifold Assemble	0.00	0.00	*860.00 F X
2	1		*1 Set Intake Manifold Gasket	0.00	0.00	*65.00 F X
Sub Total (\$\$)						925.00
+ Margin on L,N Items 10.00% (\$\$)						92.50
Total Parts (\$\$)						1,017.50

F=Franchise part.

Wah Hong Motors & Credit Pte Ltd/SJJ2522B/16/05/2019 16:06. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Wah Hong Motors & Credit Pte Ltd/SJJ2522B/16/05/2019 16:06. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est. Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Apr 2019 09:58 Sendback Est	22 Apr 2019 09:08 S\$19,314.60	22 Apr 2019 08:59 Edit Adj Rpt	S\$14,150.00 Edit Estimates	S\$14,150.00 View Rpt		Pending for Survey Report Cancel Case
Supp #1	16 May 2019 15:46	16 May 2019 16:06 S\$1,017.50	16 May 2019 16:06			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	LOH KAILING , ID: S9030895E								
Vehicle Reg. No.:	SJJ2522B	Date of Loss:	10/04/2019 23:00 - :59 [127 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD	Policy/Cover Note No.:	Z18VP05020042 (Comprehensive)						
		Excess:	S\$1,500.00						
Repairer:	Wah Hong Motors & Credit Pte Ltd (HQ) 38 Toh Guan Road East, #01-57, Enterprise Hub, 608581 Jurong East - Tel: +65 6773 7377								
Handling Insurer:	Longpac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Gerald Poh - 6250 7388 ext 240]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 02/05/2019]								
Adj Asg. Remarks:	SURVEY & REVERT								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• LONPAC_HQ (23/04/2019): Alert - Adj Mandate Approved (S\$14650.00) - SJJ2522B - Claim Handler: Gerald Poh									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJJ2522B
OD
Apr 10 2019 11:00PM
[LOH KAILING]
Wah Hong Motors & Credit Pte Ltd

Upload Documents Upload Photos Compose New Letter			View	View in Browser <input type="button" value="v"/>
Assessment Reports			1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	Wah Hong Motors & Credit Pte Ltd (HQ)		Thumbnail Print
1	22/04/19 09:08	Repairer Estimates		Load HTM <input type="checkbox"/>
2	16/05/19 16:06	Repairer Estimates Suppl. #1		Load HTM <input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	23/04/19 10:32	Adjuster Immediate Advice		Load HTM <input type="checkbox"/>
Photos/Images			3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	Wah Hong Motors & Credit Pte Ltd (HQ)		Thumbnail Print
1	30/04/19 14:23	Photos - Before		Load JPG <input checked="" type="checkbox"/>
2	30/04/19 14:23	Photos - Before		Load JPG <input checked="" type="checkbox"/>
3	30/04/19 15:59	Photos - Before		Load JPG <input checked="" type="checkbox"/>
4	30/04/19 15:59	Photos - Before		Load JPG <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	23/04/19 10:33	Odometer Reading		Load JPG <input checked="" type="checkbox"/>
2	23/04/19 10:33	Chassis Number		Load JPG <input checked="" type="checkbox"/>
3	23/04/19 10:33	General View		Load JPG <input checked="" type="checkbox"/>
4	23/04/19 10:33	General View		Load JPG <input checked="" type="checkbox"/>
5	23/04/19 10:33	General View		Load JPG <input checked="" type="checkbox"/>
6	23/04/19 10:33	General View		Load JPG <input checked="" type="checkbox"/>
7	23/04/19 10:33	General View		Load JPG <input checked="" type="checkbox"/>
8	23/04/19 10:33	General View		Load JPG <input checked="" type="checkbox"/>
9	23/04/19 10:33	General View		Load JPG <input checked="" type="checkbox"/>
10	23/04/19 10:33	General View		Load JPG <input checked="" type="checkbox"/>
11	23/04/19 10:33	General View		Load JPG <input checked="" type="checkbox"/>
12	23/04/19 10:33	General View		Load JPG <input checked="" type="checkbox"/>
13	23/04/19 10:33	General View		Load JPG <input checked="" type="checkbox"/>
14	23/04/19 10:33	General View		Load JPG <input checked="" type="checkbox"/>
15	23/04/19 10:33	General View		Load JPG <input checked="" type="checkbox"/>
16	23/04/19 10:33	General View		Load JPG <input checked="" type="checkbox"/>
17	23/04/19 10:33	General View		Load JPG <input checked="" type="checkbox"/>
18	23/04/19 10:33	General View		Load JPG <input checked="" type="checkbox"/>
19	23/04/19 10:33	General View		Load JPG <input checked="" type="checkbox"/>
20	23/04/19 10:33	General View		Load JPG <input checked="" type="checkbox"/>
21	23/04/19 10:33	General View		Load JPG <input checked="" type="checkbox"/>
22	23/04/19 10:33	General View		Load JPG <input checked="" type="checkbox"/>
23	23/04/19 10:33	General View		Load JPG <input checked="" type="checkbox"/>
24	23/04/19 10:33	General View		Load JPG <input checked="" type="checkbox"/>
25	23/04/19 10:33	General View		Load JPG <input checked="" type="checkbox"/>
26	23/04/19 10:33	General View		Load JPG <input checked="" type="checkbox"/>
27	23/04/19 10:33	General View		Load JPG <input checked="" type="checkbox"/>
28	23/04/19 10:33	General View		Load JPG <input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Wah Hong Motors & Credit Pte Ltd (HQ)	Thumbnail	Print
29	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
30	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
31	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
32	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
33	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
34	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
35	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
36	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
37	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
38	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
39	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
40	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
41	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
42	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
43	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
44	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
45	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
46	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
47	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
48	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
49	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
50	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
51	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
52	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
53	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
54	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
55	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
56	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
57	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
58	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
59	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
60	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
61	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
62	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
63	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
64	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
65	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
66	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
67	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
68	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
69	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
70	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
71	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
72	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
73	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
74	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
75	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
76	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
77	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
78	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Wah Hong Motors & Credit Pte Ltd (HQ)	Thumbnail	Print
79	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
80	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
81	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
82	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
83	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
84	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
85	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
86	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
87	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
88	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
89	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
90	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
91	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
92	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
93	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
94	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
95	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
96	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
97	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
98	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
99	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
100	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
101	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
102	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
103	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
104	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
105	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
106	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
107	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
108	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
109	23/04/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
110	14/06/19 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	14/06/19 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	14/06/19 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	14/06/19 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	14/06/19 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	14/06/19 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	14/06/19 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	14/06/19 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	14/06/19 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	14/06/19 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	14/06/19 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	14/06/19 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	14/06/19 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	14/06/19 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	14/06/19 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	14/06/19 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	14/06/19 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	14/06/19 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	14/06/19 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Wah Hong Motors & Credit Pte Ltd (HQ)	Thumbnail	Print
129	14/06/19 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	14/06/19 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
131	14/06/19 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	14/06/19 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	14/06/19 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
134	14/06/19 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	14/06/19 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	14/06/19 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	14/06/19 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
138	14/06/19 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/04/19 10:33	ESTIMATE	 Load PDF	
2	17/06/19 15:26	Supplementary	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse
Singapore 199555

Our File No: CS/LPC19006802/R1QD3E2

Date: 17/06/2019

REFERENCE

Insured/Claimant:	LOH KAILING	Policy No:	Z18VP05020042
Date of Loss:	10/04/2019	Nature of Claim:	OD
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJJ2522B	Engine No:	13B544793
Make & Model:	MAZDA RX-8, 1.3 (M)	Chassis No:	SE3P301701
Reg. Date:	05/09/2008 (Man. Year: 2008)	Odometer:	180619 km
Colour:	Pink		
Engine Capacity:	1308 cc		
Market Value/New Car Price:	S\$65,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45 R17	Rear Tyre Size:	235/45 R17
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,282.10	15,626.60	1,655.50	9.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,050.00	2,080.00	970.00	31.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,332.10	17,706.60	2,625.50	12.91
Approved Total (Overridden) (S\$)		14,150.00		
- Excess (S\$)	0.00	1,500.00	-1,500.00	
	(S\$)	20,332.10	12,650.00	7,682.10
+ GST 7.00/7.00% (S\$)	1,423.25	885.50	537.75	37.78
Nett Amount (S\$)	21,755.35	13,535.50	8,219.85	37.78

INSPECTION

Date of Assignment:	22/04/2019 Present Location:	Wah Hong Motors & Credit Pte Ltd (HQ)
Date Inspected:	17/04/2019 Inspected At:	Wah Hong Motors & Credit Pte Ltd (HQ) 38 Toh Guan Road East, #01-57, Enterprise Hub Singapore 608581

Estimated Period of Repair: 9.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Jun 2019)
Parts:	M1-COUPE	MAZDA RX-8 1.3 (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJJ2522B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 Pc Front Bonnet (WCP)	Cracked	855.00 F	*855.00 F
2	1		*1 Pc Front Bumper (WCP)	Cracked	620.00 F	*620.00 F
3	1		*1 Pc Front R/H Fender (WCP)	Bent	720.00 F	*720.00 F
4	1		*1 Pc Front L/H Fender (WCP)	Bent	750.00 F	*750.00 F
5	1		*1 Pc Front Bumper Lower Lid (WCP)	Cracked	320.00 F	*320.00 F
6	1		*1 Pc Front R/H Headlamp (WCP)	Broken	1,328.00 F	*1,328.00 F
7	1		*1 Pc Front L/H Headlamp (WCP)	Broken	1,328.00 F	*1,328.00 F
8	1		*1 Pc Front Support Panel (WCP)	Bent	520.00 F	*520.00 F
9	1		*1 Pc Front R/H Fog Lamp (WCP)	Cracked	320.00 F	*320.00 F
10	1		*1 Pc Front L/H Fog Lamp (WCP)	Cracked	320.00 F	*320.00 F
11	1		*1 Pc Radiator (WCP)	Cracked	860.00 F	*860.00 F
12	1		*1 Pc Front R/H Fog Lamp Cover (WCP)	Cracked	155.00 F	*155.00 F
13	1		*1 Pc Front L/H Fog Lamp Cover (WCP)	Cracked	155.00 F	*155.00 F
14	1		*1 Pc Engine Fuse Box Housing (WCP)	Cracked	1,250.00 F	*1,250.00 F
15	1		*1 Pc Radiator Spare Tank (WCP)	Broken	320.00 F	*320.00 F
16	1		*1 Pc Air Cleaner With Inlet Duct (WCP)	Deformed	820.00 F	*820.00 F
17	1		*1 Pc Havdness With Fuse Box Housing (WCP)	Cut	3,100.00 F	*3,100.00 F
18	1		*1 pc Air Con Condenser (WCP)	Serviceable	580.00 F	*- F
19	1		*1 Pc Front Bumper Reinforcement (WCP)	Bent	465.00 F	*465.00 F
Supplementary #1						
20	1		*1 Pc Intake Manifold Assemble (WCP)	Serviceable	860.00 F	*- F
21	1		*1 Set Intake Manifold Gasket (WCP)	Serviceable	65.00 F	*- F

F=Franchise part.

Sub Total (S\$)	15,711.00	14,206.00
+ Margin on L,N Items 10.00/10.00% (S\$)	1,571.10	1,420.60

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Total Parts (S\$)	17,282.10	15,626.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	remove and replace all the parts mentioned above and knocking and straighten up the necessary affected areas	New	2,100.00	1,200.00
2	spray painting on affected areas	New	800.00	800.00
3	check wiring system engine	New	150.00	80.00
Gross Labour Cost (S\$)			3,050.00	2,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >