

ASS. REC. BY: mevimen REF: CS3/MSG18014646/Tisd
 Surveyor: Tan Kah ASSIGNMENT (Office)
 From (Person): Koh Ming Shao of MS/G Date/Time: 12/04/2019
 Estimated Cost: _____ Bill to: _____
 OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS
 To Inspect Vehicle No: FBE 8893L Insured: SJS 9827D
 at Workshop n/s: Asia Motorsports Tel: 6745 3811
 of: 568 Geylang Road
 Policy No: 29012666 SMA Claim No: 566 781
 Sum Insured: _____ Excess: _____
 Make of Veh: _____ D.O.A. 06/08/2018
 (Client's Record)
 CA / REV / REP. / REV 24 HRS lup H.O.D. Endorsement: _____
 Date/Time: 9:17am @ 14/8/18 Person Contacted: Mr. Loo Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (X) Estimate
	<u>FBE 8933L - X</u>
	<u>SJS 9827D -</u>
	<u>Dismantle: 20/8/2018</u>
	<u>Submit HS \$2,500/- @ 5 days</u>
	<u>(\$900/- Red - 27%)</u>

Do Not Finalise

4/5/2500 5 days

RECEIVED 25 APR 2019


Tanpoh

REF:

MSIG

From: _____ Date: _____
 Estimated Cost: _____
 OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop no: _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark The veh had commenced its
 repair at the time of inspection.



Bal or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? Yes or No
 GIA / PR Seen: _____ Consistent? Yes or No
 Est. Repairs: _____ days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle IN / OUT

Veh No: FBE 8893 L
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Yamaha
 Colour: Black / Red
 Sp Reading: _____
 Eng/No: _____
 C/No: ME120P022A2005727
 Gen Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size F: 90/80 R12
 R: 110/70 R12
 BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front: _____ Rear: _____
 R/Bal: _____ mm R/Bal: _____ mm
 L/Bal: _____ mm L/Bal: _____ mm
 D.O.A: _____ D.O.I: 14/8/18
 Survey held at: Asin Motorsport
 Des of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction NO 6/1A

FY 7/9/13 running
 Estimated repair range \$3,600 - \$4,600

Range + No of days

30/8/18 submit for report -

30/8/2018

Order Time File Pass in: ☐ Preli. Report

II: ☐ Final Report

Date Time File Return: _____

II

Report Format: PRS

Lump Sum / LB: _____

Days Of Repair:

Resurvey No. of Trip: 1

Survey Fee

Transportation

30/8/2018

20/8/2018

10/8/2018

Add Fee: ☐ Site Insp \$

☐ Interview \$

☐ Test Insp \$

☐ Repairs \$

120

10

130

Nivitha (LKK Auto)

From: Accounts (LKKAuto) <account@lkkauto.com>
Sent: Monday, 15 April 2019 11:14 AM
To: Admin-D (LKKAuto)
Cc: assignments
Subject: Report Send Back Alerts - FBE8893L (TP)

Dear Nivitha,

FYNA Please...

Pending for Survey Report- CS3/MSG18014696/T1Z4D3E2

12 Apr 2019 13:59	Ins Send Back Adj Rpt	Please conduct paper resurvey	[I] Koh Ming Shao
12 Apr 2019 13:59	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/04/16	[I] Merimen Administrator

Thank You

Best Regards,

SuthaShelia (Shelia) | Accounts Dept.

LKK Auto Consultants Pte Ltd

Phone: 6742 9588 | email: account@lkkauto.com | fax: 6844-8805

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Do-Not-Reply [mailto:do-not-reply@merimen.com]

Sent: Friday, 12 April 2019 2:00 PM

To: account@lkkauto.com

Subject: Report Send Back Alerts - FBE8893L (TP)

Dear Sir / Madam,

Please login to Merimen Online at www.merimen.com.sg for more information.

Thanks,
The Merimen Team



This email has been checked for viruses by AVG antivirus software.
www.avg.com



Y B LIM APPRAISAL SERVICES

835 Hougang Central #11-558 Singapore 530835
Mobile: 9783 3518 Email: yblimappraisals@gmail.com
Registration No. 53224663B

VEHICLE ASSESSMENT REPORT

Mr. Muhammad Amsyar Bin Mohamed Akbar
Blk 369 Tampines Street 34
#10-35
Singapore 520369

Ref. No : YBL/1808/FBE8893
Date : 30 November 2018

PARTICULARS OF DAMAGED VEHICLE

Vehicle No.	: FBE 8893 L	Date of Accident	: 06 August 2018
Make	: Yamaha	Date of Assignment	: 13 August 2018
Model	: YZF-R15	Date of Inspection	: 13 August 2018
Year	: 2010	Date of Re-inspn.	: 30 August 2018
Chassis No	: ME120P022A2005727	Odometer	: 82643 km
Engine No	: Blocked	Color	: Black/red

TYRE CONDITION

	<u>Make</u>	<u>Size</u>	<u>Thread Balance</u>
Front	Pirelli	90/80-17	4 mm
Rear	Pirelli	110/70-17	4 mm

GENERAL DESCRIPTION OF DAMAGE (Photographs Attached)

The motor cycle sustained damage at rear and right side.

INSPECTION AND ADJUSTMENT

Original Quotation : \$ 4,910.60.

Revised Assessment : \$ 3,400.00 Lump sum.

In accordance to your instruction, we have not authorized repairs.

In normal circumstances, repairs to the vehicle would take approximately Five (5) days to complete.

Inspection conduct at : Asia Motorsports Solution Pte Ltd.

Enclosed Twenty Five (25) photographs depicting damage to the vehicle and after repairs.

This survey was conducted on a "WITHOUT PREJUDICE" basis.

Y B LIM APPRAISAL SERVICES

Vehicle No: FBE 8893 L

Ref. No: YBL/1808/FBE8893

<u>S/N</u>	<u>Description</u> <u>Material</u>	<u>Qty</u>	<u>Condition</u>	<u>Original</u> <u>Quotation</u>	<u>Revised</u> <u>Quotation</u>
1	Top cowling assy	1 pc	Grazed	290.00	290.00
2	Cowling screen	1 pc	Scratches	90.00	90.00
3	Cowling stay	1 pc	Bent	85.00	85.00
4	Handle bar	1 pc	Bent	80.00	80.00
5	Handle balancer	1 set	Grazed RH	50.00	25.00
6	Brake lever	1 pc	Cut	22.00	22.00
7	Mirror assy RH	1 pc	Grazed	75.00	75.00
8	Head lamp	1 pc	Cut/grazed	240.00	240.00
9	Front signal RH	1 pc	Grazed	60.00	60.00
10	Front fender	1 pc	Deformed	95.00	95.00
11	Front side fairing RH	1 pc	Grazed	185.00	185.00
12	Side fairing inner cover RH	1 pc	Cracked	105.00	105.00
13	Fuel tank	1 pc	Repair	640.00	S.N. 180.00
14	Front footrest RH	1 pc	Bent	45.00	45.00
15	Brake pedal	1 pc	Bent	58.00	58.00
16	Pillion footrest RH	1 pc	Usable	42.00	~
17	Rear seat bar	1 pc	Cut	48.00	48.00
18	Rear centre top cover	1 pc	Deformed	38.00	38.00
19	Rear side fairing @ \$185/-	2 pcs	Graze/deformed	370.00	370.00
20	Tail lamp	1 pc	Broken	115.00	115.00
21	Rear rim	1 pc	Warped	390.00	390.00
22	Rear mudguard	1 pc	Deformed	98.00	98.00
23	Rear number plate lamp	1 pc	Usable	55.00	~
24	Rear signal @ \$60/-	2 pcs	Grazed/cut	120.00	120.00
25	Exhaust protector	1 pc	Dented	108.00	108.00
26	Exhaust pipe assy	1 pc	Graze/dented	850.00	850.00
				4,354.00	3,592.00
			Less 10%	435.40	359.20
				3,918.60	3,232.80
	Add special nett from above				180.00
27	Front number plate	1 pc	Necessary	12.00	12.00
28	Rear number plate	1 pc	Bent	12.00	12.00
29	Rear number plate holder	1 pc	Bent	68.00	68.00
			Total parts	4,010.60	3,504.80

Y B LIM APPRAISAL SERVICES

Vehicle No: FBE 8893 L

Ref. No: YBL/1808/FBE8893

<u>Labour & Misc</u>		
1) Transportation x 2	70.00	✓ 60.00
2) Front rim realign	80.00	40 60.00
3) Front fork realign	120.00	✓ 100.00
4) Chassis frame /swing arm realign	350.00	200 300.00
5) Workmanship	280.00	200 250.00
Total parts and labour charges	<u>4,910.60</u>	<u>4,274.80</u>
Final lump sum repair adjustment	600	<u>3,400.00</u>

RECOMMENDATION

We have inspected thoroughly the actual damages found on the vehicle. We have listed the breakdown of our findings and our recommendation as per assessment above.

Y B Lim Appraisal Services



Lim Yew Boon Eddie
Automobile Appraiser

3/30-10
4/5/2500
5 days

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/08/2018 11:55
Date Of Accident	06/08/2018 22:45
Exact Location Of Accident	TAMPINES EAST MRT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBE8893L
Insured/Policyholder	
Name Of Registered Owner	MUHAMMAD AMSYAR BIN MOHAMED AKBAR
NRIC No	S9616492J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96710452
Alternative Phone No	OTHERS-96710452

Vehicle Particulars

Manufacturer	YAMAHA
Model	YZF-R15
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5087310624-01
Cover Note Number	

Driver

Name of Driver	MUHAMMAD AMSYAR BIN MOHAMED AKBAR
NRIC No	S9616492J
Date Of Birth	16/05/1996
Occupation	INDOOR
Date Of Driving Pass	30/11/2016
Driving Experience	1 YEAR AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96710452
Fax Number	
Contact Number	OTHERS-96710452
Email Address	NOEMAIL

Address	BLK 369 #10-35 TAMPINES STREET 34
Postcode	520369
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN:

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJS9827D
Vehicle Make/Model/Colour	TOYOTA ESTIMA 2.4X A
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

- 7 AUG 2018

Policyholder's Signature
Date & Time:


07/08/18

1200 hours

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
Reporting Centre 23 Kaki Bukit Ave 4
Name: Singapore 415933
Tel: 67416697 Fax: 67492305
NRIC/ID:
Email: vackb@singnet.com.sg

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was at a filter lane and the car was behind me. At the give way line I stopped to give way to an approaching bus. The car did not manage to break and crash at the rear of my bike.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 07/08/2018

1200 hours

Driver's Signature

(If driver is not the policyholder)

Date & Time:

- 7 AUG 2018
IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Singapore 415933

Name:
Tel: 67416697 Fax: 67492305
Email: vackb@singnet.com.sg

Driving License



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours : Monday to Friday, 09:00 – 17:00
UEN: S66550020G / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MVA 318101926 Vehicle Registration No: FBE 8893L
Name(as shown in NRIC) : MUHAMMAD AMSYAR NRIC/FIN/Passport No : 59616492J
BIN MOHAMED AKBAR
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : BLK 369 TAMPINES STREET 34 #10-35 Singapore(620369)
Contact (Tel) : 65441952 Mobile No. : 96710452
Email Address : amsyar_1996@hotmail.com
Date of Accident : 06/08/2018 Time of Accident : 1045 pm
Place of Accident : TAMPINES EAST MRT
Insurance Company: NTUC INCOME INSURANCE CO-OPERATIVE LTD

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

The vehicle registration plate is SJS 9827D
instead of SJS 8827 D as mention in the report.

Policyholder / Driver's Signature
Date: 11/08/18

IDAC KAKI BUKIT (VAC)
Reporting Centre Personnel's Signature
Name: Singapore 415933
NRIC/FIN No: 67416697 Fax: 67492305
Date: Email: vac@singnet.com.sg

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/08/2018 12:49
Date Of Accident	06/08/2018 22:45
Exact Location Of Accident	TAMPINES AVE 7 TURNING TO TAMPINES AVE 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJS9827D
Insured/Policyholder	
Name Of Registered Owner	TOH CHIN TENG
NRIC No	S2646895G
Email Address	TCT1167@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-91848682
Alternative Phone No	OFFICE-91848682

Vehicle Particulars

Manufacturer	TOYOTA
Model	ESTIMA-2.4 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE

Fleet Policy	NO
Policy Number	29012666

Cover Note Number

Driver

Name of Driver	TOH CHIN TENG
NRIC No	S2646895G
Date Of Birth	05/11/1967
Occupation	INDOOR
Date Of Driving Pass	02/01/1994
Driving Experience	24 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91848682

Fax Number	
Contact Number	OFFICE-91848682

Email Address	TCT1167@HOTMAIL.COM
---------------	---------------------

Address	BLK 278 TAMPINES STREET 22
	#09-198
Postcode	520278
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS DRIVING ALONG TAMPINES AVE 7 TURNING TO TAMPINES AVE 2, IN FRONT A MOTOR BIKE FBE8893L IN FRONT OF ME DID NOT MAKE UP HIS MIND TO GO THE WHICH DIRECTION TO PROCEED TO MOVE AND I HIT ONTO THE MOTORBIKE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBE8893L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on 6/8/18 at about 22-45pm

Driving along Tampine Ave 7, turn to Tampine Ave 2,

A motorbike FBE 8893L in front of me going out but

do not process to move and I hit onto my motorbike.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No :

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Aug 2018		13 Aug 2018 16:09 Edit Adj Rpt	S\$2,500.00 Edit Estimates	S\$2,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TOH CHIN TENG, ID: S2646895G, Tel: +6591848682								
Main Claimant:	MUHAMMAD AMSYAR BIN MOHAMED AKBAR, ID: S9616492J								
Vehicle Reg. No.:	FBE8893L	Date of Loss:	06/08/2018 22:00 - :59 [93 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 566781	Policy/Cover Note No.:	29012666SMA (Comprehensive) Coverage: 17/09/2017 - 16/09/2018						
Vehicle Reg. No. (Insured):	SJS9827D	Policy No. (Claimant):							
		Excess:	S\$1,000.00						
Repairer:	Asia Motorsports (HQ) 568 Geylang Road, 389514 Geylang - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 16/04/2019]								
Driver/Custodian (Insured):	TOH CHIN TENG (50 / Male) , NRIC: S2646895G, Tel: +6591848682 Email:								
Adj Asg. Remarks:	Liability 100%. TP disagree with our SJE list, proceed to appoint LKK Auto Consultant. Contact No: 6745 3811								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (12/04/2019): FBE 8893L - PAPER RESURVEY MSIG_SG (12/04/2019): Report Send Back Alerts - FBE8893L (TP) 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBE8893L (566781)

[SJS9827D]






































TP
















































MUHAMMAD AMSYAR BIN MOHAMED AKBAR

Aug 6 2018 10:00PM

[TOH CHIN TENG]

Asia Motorsports

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	16/08/18 16:19	General View		Load JPG	<input checked="" type="checkbox"/>					
2	16/08/18 16:19	General View		Load JPG	<input checked="" type="checkbox"/>					
3	16/08/18 16:19	General View		Load JPG	<input checked="" type="checkbox"/>					
4	16/08/18 16:19	General View		Load JPG	<input checked="" type="checkbox"/>					
5	16/08/18 16:19	General View		Load JPG	<input checked="" type="checkbox"/>					
6	16/08/18 16:19	General View		Load JPG	<input checked="" type="checkbox"/>					
7	16/08/18 16:19	General View		Load JPG	<input checked="" type="checkbox"/>					
8	16/08/18 16:19	General View		Load JPG	<input checked="" type="checkbox"/>					
9	16/08/18 16:19	General View		Load JPG	<input checked="" type="checkbox"/>					
10	16/08/18 16:19	General View		Load JPG	<input checked="" type="checkbox"/>					
11	16/08/18 16:19	General View		Load JPG	<input checked="" type="checkbox"/>					
12	16/08/18 16:19	General View		Load JPG	<input checked="" type="checkbox"/>					
13	16/08/18 16:19	General View		Load JPG	<input checked="" type="checkbox"/>					
14	16/08/18 16:19	General View		Load JPG	<input checked="" type="checkbox"/>					
15	16/08/18 16:19	General View		Load JPG	<input checked="" type="checkbox"/>					
16	16/08/18 16:19	General View		Load JPG	<input checked="" type="checkbox"/>					
17	16/08/18 16:19	General View		Load JPG	<input checked="" type="checkbox"/>					
18	16/08/18 16:19	General View		Load JPG	<input checked="" type="checkbox"/>					
19	16/08/18 16:19	General View		Load JPG	<input checked="" type="checkbox"/>					
20	16/08/18 16:19	General View		Load JPG	<input checked="" type="checkbox"/>					
21	16/08/18 16:19	General View		Load JPG	<input checked="" type="checkbox"/>					
22	16/08/18 16:19	General View		Load JPG	<input checked="" type="checkbox"/>					
23	16/08/18 16:19	General View		Load JPG	<input checked="" type="checkbox"/>					
24	16/08/18 16:19	General View		Load JPG	<input checked="" type="checkbox"/>					
25	16/08/18 16:19	General View		Load JPG	<input checked="" type="checkbox"/>					
26	16/08/18 16:19	General View		Load JPG	<input checked="" type="checkbox"/>					
27	16/08/18 16:19	General View		Load JPG	<input checked="" type="checkbox"/>					
28	16/08/18 16:19	General View		Load JPG	<input checked="" type="checkbox"/>					
29	16/08/18 16:19	General View		Load JPG	<input checked="" type="checkbox"/>					
30	16/08/18 16:19	General View		Load JPG	<input checked="" type="checkbox"/>					
31	16/08/18 16:19	General View		Load JPG	<input checked="" type="checkbox"/>					
32	16/08/18 16:19	General View		Load JPG	<input checked="" type="checkbox"/>					
33	16/08/18 16:19	General View		Load JPG	<input checked="" type="checkbox"/>					
34	16/08/18 16:19	General View		Load JPG	<input checked="" type="checkbox"/>					
35	16/08/18 16:19	General View		Load JPG	<input checked="" type="checkbox"/>					
36	16/08/18 16:19	General View		Load JPG	<input checked="" type="checkbox"/>					
37	16/08/18 16:19	General View		Load JPG	<input checked="" type="checkbox"/>					

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	16/08/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
39	16/08/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
40	16/08/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
41	16/08/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
42	16/08/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
43	16/08/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
44	16/08/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
45	16/08/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
46	27/08/18 12:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	27/08/18 12:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	27/08/18 12:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	27/08/18 12:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	27/08/18 12:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	27/08/18 12:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	27/08/18 12:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	27/08/18 12:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	27/08/18 12:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	27/08/18 12:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	27/08/18 12:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	27/08/18 12:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	27/08/18 12:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	24/04/19 15:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	24/04/19 15:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	24/04/19 15:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	24/04/19 15:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	24/04/19 15:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	24/04/19 15:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	24/04/19 15:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	24/04/19 15:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	24/04/19 15:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	24/04/19 15:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	24/04/19 15:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	24/04/19 15:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	24/04/19 15:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	24/04/19 15:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	24/04/19 15:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	24/04/19 15:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	24/04/19 15:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	24/04/19 15:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	24/04/19 15:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	24/04/19 15:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	24/04/19 15:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	24/04/19 15:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/08/18 14:11	E-filed GIA report From:OD - Reg. No: SJS9827D, Claimant: TOH CHIN TENG	 Load PDF	
2	13/08/18 14:12	FBE8893L GIA Rpt	 Load PDF	
3	13/08/18 14:13	Email frm TP - PRI & liability frm OIC	 Load PDF	
4	13/08/18 14:15	Email correspondence with TP on SJE list, TP reject our list, we proceed to appoint LKK	 Load PDF	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
5	03/04/19 16:54	FBE8893L POLICE REPORT		Load PDF
6	03/04/19 16:55	SJS9827D POLICE REPORT		Load PDF
7	03/04/19 16:56	SURVEY REPORT		Load PDF
8	03/04/19 16:58	SURVEY PHOTO		Load PDF
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	25/04/19 11:01	Colour Photo		Load PDF
2	25/04/19 11:02	PRS Invoice		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18014696/T1SD3E2-1

Date: 25/04/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29012666SMA

Claimant Vehicle No: FBE8893L

Insured Vehicle No: SJS9827D

Date of Loss: 06/08/2018

Nature of Claim: TP

Claim No: 566781

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBE8893L

Make & Model: YAMAHA YZF-R15, 150cc (M)

Reg. Date: 04/11/2010 (Man. Year: 2010)

Colour: Red/Black

Engine Capacity: 150 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 20P1027499

Chassis No: ME120P022A2005727

Odometer: 0 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 90/80 R17

Rear Tyre Size: 110/70 R17

Front Left Side: Pirelli 5 mm

Rear Left Side: Pirelli 5 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,010.60	2,530.10	1,480.50	36.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	900.00	600.00	300.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,910.60	3,130.10	1,780.50	36.26
Approved Total (Overridden) (S\$)		2,500.00		
Nett Amount (S\$)	4,910.60	2,500.00	2,410.60	49.09

INSPECTION

Date of Assignment: 13/08/2018

Date Inspected: 14/08/2018

Inspected At:

Asia Motorsports (HQ)

568 Geylang Road

Singapore 389514

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 25 Apr 2019)	
Parts:	N/A	YAMAHA YZF-R15 150cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBE8893L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOP COWLING ASSY	Grazed	290.00 FL	*290.00 FL
2	1		*COWLING SCREEN	Scratched	90.00 FL	*90.00 FL
3	1		*COWLING STAY	Bent	85.00 FL	*85.00 FL
4	1		*HANDLE BAR	Bent	80.00 FL	*80.00 FL
5	1		*SET HANDLE BALANCER	O/S Grazed	50.00 FL	*25.00 FL
6	1		*BRAKE LEVER	Cut	22.00 FL	*22.00 FL
7	1		*MIRROR ASSY RH	Grazed	75.00 FL	*75.00 FL
8	1		*HEAD LAMP	Cut / Grazed	240.00 FL	*240.00 FL
9	1		*FRONT SIGNAL RH	Grazed	60.00 FL	*60.00 FL
10	1		*FRONT FENDER	Deformed	95.00 FL	*95.00 FL
11	1		*FRONT SIDE FAIRING RH	Grazed	185.00 FL	*185.00 FL
12	1		*SIDE FAIRING INNER COVER RH	Cracked	105.00 FL	*105.00 FL
13	1		*FUEL TANK	Scratched	576.00 FS	*180.00 FS
14	1		*FRONT FOOTREST RH	Bent	45.00 FL	*45.00 FL
15	1		*BRAKE PEDAL	Bent	58.00 FL	*58.00 FL
16	1		*PILLION FOOTREST RH	Usable	42.00 FL	*- FL
17	1		*REAR SEAT BAR	Repair	48.00 FL	*- FL
18	1		*REAR CENTRE TOP COVER	Deformed	38.00 FL	*38.00 FL
19	1		*REAR SIDE FAIRING	O/S Cut / N/S Repair	370.00 FL	*185.00 FL
20	1		*TAIL LAMP	Broken	115.00 FL	*115.00 FL
21	1		*REAR RIM	Warped	390.00 FL	*390.00 FL
22	1		*REAR MUDGUARD	Deformed	98.00 FL	*98.00 FL
23	1		*REAR NUMBER PLATE LAMP	Usable	55.00 FL	*- FL
24	2		*REAR SIGNAL	Grazed / Cut	120.00 FL	*120.00 FL
25	1		*EXHAUST PROTECTOR	Dented	108.00 FL	*108.00 FL
26	1		*EXHAUST PIPE ASSY	Repair	850.00 FL	*- FL
27	1		*FRONT NUMBER PLATE	Necessary	12.00 FS	*12.00 FS
28	1		*REAR NUMBER PLATE	Bent	12.00 FS	*12.00 FS
29	1		*REAR NUMBER PLATE HOLDER	Bent	68.00 FS	*68.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,382.00	2,781.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	371.40	250.90
Total Parts (\$\$)	4,010.60	2,530.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TRANSPORTATION X 2	New	70.00	60.00
2	FRONT RIM REALIGN	New	80.00	40.00
3	FRONT FORK REALIGN	New	120.00	100.00
4	CHASSIS FRAME / SWING ARM REALIGN	New	350.00	200.00
5	WORKMANSHIP	New	280.00	200.00
Gross Labour Cost (\$\$)			900.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >