

Date: _____ Person Contacted: _____

The U/C / Chassis frame / Body Structure affected due to collision

N/S	O/S

[illegible]

Lump Sum / I.B.I: (\$)

☐ Weekend (\$)

TOTAL

--

Nivitha (LKK Auto)

From: bonnie kwok <litigation@bonniekwok.com>
Sent: Monday, 15 April 2019 12:41 PM
To: Richard Tan
Cc: SUR; assignments; Admin-D (LKK Auto); phien@tanchinhoe.com.sg; Tan Chin Hoe & Co; Ellice (TCH); Precise Auto
Subject: Re: Your Ref: to be advised; TCH Ref: RT/EK/407/2017/pl; Our Ref: BK.17930.17; MC Suit No. 17734/2017; ACCIDENT INVOLVING GN 9758 G & SGU 7537 D ON 14 DECEMBER 2016

Dear Sirs,

We refer to our email dated 11 April 2019.

Further to our said email, please arrange for either Mr. Adrian Ling or Mr. Marcus Chua, the Single Joint Expert ("SJE") to attend at No. 1 Kaki Bukit Avenue 6 #02-34/36 Singapore 417883 on 25 April 2019 at 2.00 p.m. for the re-inspection of our client's vehicle.

Please let us have your Single Joint Expert report within fourteen (14) days after the re-inspection.

Regards,

ST

--

BONNIE KWOK LLC

Advocates & Solicitors
101A Upper Cross Street
#08-12 People's Park Centre
Singapore 058358
TEL: 6536 6026
FAX: 6536 2279
email : litigation@bonniekwok.com
GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

c.c. M/s Tan Chin Hoe, please forward your re-inspection report to the SJE as soon as possible.

On Thu, 11 Apr 2019 at 14:05, Richard Tan <richard@tanchinhoe.com.sg> wrote:

Phien, please scan and email our survey report together with colour photographs to LKK Auto Consultants.

Richard Tan
Tan Chin Hoe & Co

From: bonnie kwok

Sent: Thursday, April 11, 2019 11:20 AM

To: SUR ; assignments ; Admin-D (LKK Auto)

Cc: Richard Tan ; phien@tanchinhoe.com.sg ; Tan Chin Hoe & Co ; mark@tanchinhoe.com.sg ; shanice@tanchinhoe.com.sg

Subject: Your Ref: to be advised; TCH Ref: RT/EK/407/2017/pl; Our Ref: BK.17930.17; MC Suit No. 17734/2017; ACCIDENT INVOLVING GN 9758 G & SGU 7537 D ON 14 DECEMBER 2016

Dear Sirs,

We are the solicitors acting for the owner of vehicle no. GN 9758 G, the Plaintiff in the above matter.

Please be informed that parties have agreed to the appointment of either Mr. Adrian Ling or Mr. Marcus Chua of M/s LKK Auto Consultants Pte Ltd as the Single Joint Expert (SJE) of the above matter.

Kindly note that the SJE report should not be prejudiced towards any party and that both set of reports should be fairly taken into consideration in the preparation of the said SJE report.

We attach herewith a copy of the Plaintiff's survey report and the scanned colour photographs for your attention.

The Defendant's solicitors, M/s Tan Chin Hoe & Co. will be forwarding to you their re-inspection report.

We will notify you of the re-inspection date and venue.

Kindly let us have the SJE report as soon as possible.

Regards,
ST

c.c. M/s Tan Chin Hoe & Co., please forward your re-inspection report to the SJE for his consideration.

--

BONNIE KWOK LLC

Advocates & Solicitors
101A Upper Cross Street
#08-12 People's Park Centre
Singapore 058358
TEL: 6536 6026
FAX: 6536 2279
email : litigation@bonniekwok.com
GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

Nivitha (LKK Auto)

From: bonnie kwok <litigation@bonniekwok.com>
Sent: Thursday, 11 April 2019 11:21 AM
To: SUR; assignments; Admin-D (LKK Auto)
Cc: Richard Tan; phien@tanchinhoe.com.sg; Tan Chin Hoe & Co; mark@tanchinhoe.com.sg; shanice@tanchinhoe.com.sg
Subject: Your Ref: to be advised; TCH Ref: RT/EK/407/2017/pl; Our Ref: BK.17930.17; MC Suit No. 17734/2017; ACCIDENT INVOLVING GN 9758 G & SGU 7537 D ON 14 DECEMBER 2016
Attachments: 17930.17.SyrRpt.pdf

Dear Sirs,

We are the solicitors acting for the owner of vehicle no. GN 9758 G, the Plaintiff in the above matter.

Please be informed that parties have agreed to the appointment of either Mr. Adrian Ling or Mr. Marcus Chua of M/s LKK Auto Consultants Pte Ltd as the Single Joint Expert (SJE) of the above matter.

Kindly note that the SJE report should not be prejudiced towards any party and that both set of reports should be fairly taken into consideration in the preparation of the said SJE report.

We attach herewith a copy of the Plaintiff's survey report and the scanned colour photographs for your attention.

The Defendant's solicitors, M/s Tan Chin Hoe & Co. will be forwarding to you their re-inspection report.

We will notify you of the re-inspection date and venue.

Kindly let us have the SJE report as soon as possible.

Regards,
ST

c.c. M/s Tan Chin Hoe & Co., please forward your re-inspection report to the SJE for his consideration.

--

BONNIE KWOK LLC

Advocates & Solicitors
101A Upper Cross Street
#08-12 People's Park Centre
Singapore 058358
TEL: 6536 6026
FAX: 6536 2279
email : litigation@bonniekwok.com
GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

CHARTERED AUTO ASSESSORS

17 Joo Seng Road #08-129 Joo Seng Heights Singapore 360017 Reg No. 26910200X
Tel: +65 9631 7008 Fax: +65 6281 9989 Email: charteredauto@gmail.com

BS Sons
1 North Bridge Road, #01-K1
High Street Centre
Singapore, 179094

Your Ref : GN 9758 G
Our Ref : 201612154/CA
Date : 11 May, 2017
Survey : Third Party

SURVEY REPORT

PARTICULARS OF VEHICLE

Vehicle No.	: GN 9758 G	Propellant	: Diesel
Make	: Nissan	Capacity	: 2953 cc
Type of Body	: Van	Mileage	: 250735
Year & Model	: 2005, Urvan	Engine No	: ZD30046632
Colour	: Blue	Chassis No	: JN1MG4E25Z0712746
Passenger-cap	: 1	Road Tax	: March, 2017

TYRES CONDITIONS

Front Left	: Bridgestone	Worn	: 30%	Size	: 195 R15
Front Right	: Bridgestone	Worn	: 30%	Size	: 195 R15
Rear Left	: Bridgestone	Worn	: 30%	Size	: 195 R15
Rear Right	: Bridgestone	Worn	: 30%	Size	: 195 R15

PRE-ACCIDENT CONDITION (Static Test Only)

Handbrake	: Serviceable	Steering	: Serviceable
Footbrake	: Serviceable	Paintwork	: Good

QUANTUM

Repair Estimate : \$ 15,366.40
Revised Amount : \$ 11,800.00 (Lump-sum Without Prejudice)

Under normal circumstances, the repair period would be: nine (9) days.
We have not authorised repairs.

Survey Done At : Precise Auto Service
1 Kaki Bukit Avenue 6, #02-34/36
Autobay @ Kaki Bukit
Singapore, 417883

Assignment Date : 21 December, 2016
Survey Date : 21 December, 2016
Accident Date : 14 December, 2016
Assignment Given By : BS Sons

Our Ref: 201612154/CA

Vehicle No. GN 9758 G

Description	Qty	Repair Estimate	Revised Amount	Remarks
Rear bumper assy	1	696.70	✓ 696.70	Torn/Deformed
Rear bumper side retainer	2	138.20	✓ 138.20	To replace
Rear bumper clip	8	28.00	✓ 28.00	To replace
Rear fender o/s	1	2,010.30	✓ 2,010.30	Badly Dented
		<u>2,873.20</u>	<u>2,873.20</u>	
		-	861.96	Less 30%
		<u>2,873.20</u>	<u>2,011.24</u>	
Rear mudflap o/s	Nett 1	✓ 113.60	✓ 113.60	Torn
Rear leaf spring assy o/s	Nett 1 set	✓ 1,328.10	x 1,328.10	Distorted
Rear leaf spring U bolt o/s	Nett 2	✓ 194.20	x 194.20	To replace
Rear leaf spring bolt	Nett 1	✓ 19.00	x 19.00	To replace
		<u>1,654.90</u>	<u>1,654.90</u>	
		-	165.49	Less 10%
		<u>1,654.90</u>	<u>1,489.41</u>	
Rear axle assy	S.Nett 1	6,405.10	x 6,405.10	Bent
Rear shock absorber o/s	S.Nett 1	133.20	133.20	Bent
Rear wheel rim assy o/s	S.Nett 1	300.00	220 300.00	Grazed/Bent
Rear tyre assy o/s (Dep. 30%)	S.Nett 1	360.00	200 252.00	Badly Cut
Page Total:		<u>11,726.40</u>	<u>11,618.40</u>	420

Our Ref: 201612154/CA

Vehicle No. GN 9758 G

Description	Qty	Repair Estimate	Revised Amount	Remarks
Balance brought forward		11,726.40	11,618.40	
To remove/refit rear boot compartment interior garnishes, carpets where necessary.		120.00	80.00 X	
To install reverse sensors, control unit. Re-connect wires harness. Check function.		180.00	150.00 60	
To apply underseal and rust-proofing on affected areas.		180.00	150.00 80	
To conduct wheel alignment (Before & After).		240.00	240.00 180	
To remove/refit rear undercarriage/suspension assembly with all attachments/components.		800.00	650.00 380	
To renew wheel rim/tyre and conduct wheel balancing.		120.00	80.00 50	
To spray paint replaced/repainted body parts inclusive of preparatory works and painting materials.		900.00	650.00 600	
To remove all damaged parts with all necessary components/attachments. To apply hot-works where necessary, straighten chassis members, repair/reshape dented body panels, in accordance with factory specifications. Replace damaged parts, refit and align into position. Refit all necessary components/attachments.		1,100.00	900.00 750	
Grand Total:		15,366.40	14,518.40	2080

Summary

Total Material	11,726.40	11,618.40
Total Labour/Painting	3,640.00	2,900.00
Grand Total	15,366.40	14,518.40
Lump-sum Amount		<u>11,800.00</u>

total 4613.48
H/S: 3.7K.
07 Days.

Our Ref: 201612154/CA

Vehicle No. GN 9758 G

CAUSE OF DAMAGE

The vehicle sustained impact along the offside rear.

REMARKS

Having checked the scope of repair works we were satisfied that it was in accordance with the damage sustained. We also checked each item and have indicated its nature of damage. It was our opinion that these items were found damaged beyond repair and require replacement.

We checked the damage carefully and were of the opinion that the vehicle could be repaired.
We would therefore recommend repairs to be carried out at: **\$ 11,800.00** on a lump-sum basis.

The survey was conducted on a without prejudice basis and we submit this report for your consideration.

CHARTERED AUTO ASSESSORS


Tan Chin Suan (Licensed Appraiser)
AMMIA, F040370 ALLEN & GAY



















FormTeam Consultancy Pte Ltd33 Ubi Avenue 3 #02-15 Vertex
Singapore 408668

Tel: 6500-1144 Fax: 6500-5227

UEN No: 2008192800

Bill To:NTUC Income Insurance Co-operative Limited
73 Bras Basah Road
#05-01
NTUC Trade Union House
Singapore 189556**Attn:** Ms Connie Hoo**Tax Invoice**

GST Reg No: 2008192800

Invoice No:	13023360
Date:	3/7/2017
Page:	1
Your Ref:	MT/0926958-002
Our Ref:	RRN16-125413/PRS/GS/ADJ/GST

Description**Amount (\$\$)**GN 9758G - Survey Fee
(inclusive of transport charges and photographs)

\$300.00

Pre-repair - 21-12-16
Disassemble items - 22-12-16
Post-repair - 27-12-16We would appreciate your cheque crossed and made payable to
FormTeam Consultancy Pte Ltd

F & O E

Total	\$300.00
Add: 7% GST	\$21.00
Total Inc GST	\$321.00
Less: Deposit	\$0.00
Balance Due	\$321.00

RECEIVED BY DATE COMPANY STAMP

FormTeam Consultancy Pte Ltd

FormTeam Consultancy Pte Ltd

No.33, Ulu Aye 3
#02-15, Vertex
Singapore 408668

Tel : (65) 6509 1755
Fax : (65) 6509 6221

Email: monitorsurvey@fta.com.sg

Co-Reg No: 200619250D

GST Reg No: 20091928011

Our Reference : RRN16-125413/PRS/GS/ADM/GS/bb

Your Reference: MT/0926958-002

Date : 01-Jul-2017

Motor Claims Department
NTUC Income Insurance Co-operative Limited
73 Bras Basah Road
#05-01 NTUC Trade Union House
Singapore 189556

Attention : Ms Corinne Hoo

Dear Sir/Mdm,

SURVEY OF VEHICLE NO. GN 9758G

Pursuant to your instruction on **29 June 2017**,

We recommend a repair cost of **\$3,600.00** (see report) based on lump sum repair and
the estimated duration of repairs would take **07 days**.

We also enclosed our note of charges for your consideration.

Thank you for this assignment.

Your faithfully

FormTeam Consultancy Pte Ltd
Adjusters & Surveyors (Licensed Appraiser)



Gary Soon
Automobile Appraiser

(Email : gary@fta.com.sg)

Encl: Survey Report

FormTeam Consultancy Pte Ltd

AUTOMOBILE ASSESSMENT REPORT

Page No. 1

Our Reference: RRN16-125011/PTCS/CS, A&A, US, bb

Your Reference: MT_190209AR-002

Date: 17 Dec 17

Attention: MS Customer Hero

TO: Motor Claims Department
NTUC Income Insurance Co-operative Limited
71 Bras Basah Road
#05-01 NTUC Trade Union House
Singapore 189556

Assessment of Vehicle No	GN 9758G
Date of Accident	14-December-2016
Date of Inspection	21-December-2016
Address of Inspection	1 Kaki Bukit Ave 6 #02-34 S 417883

We have carried out a physical assessment of **GN 9758G** at **M/S Precise Auto Service** according to your instructions on **21 December 2016**, dismantled items on **22 December 2016**, post-repair survey on **27 December 2016** and are pleased to submit our report herewith.

1. VEHICLE PARTICULARS

Registration No	GN 9758G
Make & Model	NISSAN URVAN 5DR
Year of Registration	2005
Engine Capacity	2953 cc
Chassis No.	JN1MG4E25Z0712746
Engine No.	ZD30046632
Colour	Blue
Mileage (km)	250735

2. VEHICLE CONDITION

Body Paint	Fair
Steering	Servicable
Foot Brake	Servicable
Parking Brake	Servicable

3. TYRE PARTICULARS & CONDITION

Front

RH Make/Size	Firestone 195R15 60
LH Make/Size	Firestone 195R15 60

Rear

RH Make/Size	Bridgestone 195R15 70
LH Make/Size	Bridgestone 195R15 70

Note: depicts the remaining percentage of the tyre.




FormTeam Consultancy Pte Ltd

Your Reference: SRN16-12-011/1988, GN, A011GS_b5
Your Reference: ML_09/26078_002
Vehicle Number: GN 97580

Page No. 2

4. DESCRIPTION OF DAMAGE

At the time of inspection, this vehicle sustained damages to the **Rear O/S** portion. Please see attached schedule for details.



5. REMARKS

Market Value: -
Salvage Value: -
Repair Limit (Nett Loss): -
Repairer's estimate: **Not Provided**
Nett Saving: -
Excess: -
Sum Insured: -
Our adjusted amount: **\$ 3,600.00**
Estimated Repair Days: **07 days**

Additional photographs will be submitted upon request by our principal.

Inherent to this instruction, we have **NOT AUTHORIZED** repair.

The assessment was conducted on a **Without Prejudice** basis.

If we are not notified of anything to the contrary within **14 days** from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by

FormTeam Consultancy Pte Ltd for any reliance on this report by any third party, unless with the permission of the addressee.

Page No. 3

Tel: 65 4344 1111 Fax: 65 4344 1112
Email: info@surveydata.com.sg

FormTeam Consultancy Pte Ltd

1047 Rendell Road
Your Reference
Vehicle Number


FORM 1047 (2014) PREPARED BY: ATLAS 1047
M1 1047 (2014) (2014)
1047 (2014)

Page No. 4

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	LABOUR		
1	To remove: refix & repair engine sensor		90.00
2	To remove: refix rear undercarriage		120.00
3	To remove: refix balance rim & tyre		30.00
4	To remove: refix rear trans.		80.00
5	To remove: cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts		700.00
6	To partly and regular painting on affected areas		600.00
7	To apply undercoating		60.00
8	To conduct computerised wheel alignment test		160.00
	Labour Total :	-	1,840.00
	TOTAL (PARTS & LABOUR) :	-	4,536.68

The final adjusted Lump Sum contract amount is **\$3,600.00**
(SINGAPORE DOLLARS THREE THOUSAND AND SIX HUNDRED ONLY)


Frankie Pang
AMSAE(AUST), AMIRTE, AMSOE,
MASPACI, MSAAA
Licensed Appraiser


Gary Soon
Automobile Appraiser

FormTeam Consultancy Pte Ltd

Vehicle No: GN 9758G

Workshop: Precise Auto Service

Accident Date: 14 December 2016

No. 331 Pte Ave 3
#02-153 Verdes
Singapore 437003

Tel: (65) 6346 1700
Fax: (65) 6346 1222


Email: info@formteam.sg
www.fta.com.sg


Co. Reg No: 200819280D

GST Reg No: 200819280D


















SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/12/2016 13:52
Date Of Accident	14/12/2016 22:40
Exact Location Of Accident	RIVERVALE LINK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GN9758G
Insured/Policyholder	
Name Of Registered Owner	BS SONS
Co Reg No	48823400W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-63391291
Vehicle Particulars	
Manufacturer	NISSAN
Model	URVAN
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5064691395-02
Cover Note Number	
Driver	
Name of Driver	TARANJIT SINGH
NRIC No	S9708017H
Date Of Birth	07/03/1997
Occupation	INDOOR
Date Of Driving Pass	29/04/2016
Driving Experience	0 YEAR AND 7 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-84681916
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 123 #04-115
RIVERVALE DRIVE
Postcode 540123

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -
-
-

Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident UNKNOWN - HIT BY TP MAKING A RIGHT TURN

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s)
soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name SERANGOON GARDENS NEIGHBOURHOOD POLICE POST

Police Station Address ROAD: 51 SERANGOON GARDEN WAY , POSTCODE: 555947 ,
COUNTRY: SINGAPORE

Police Station Contact TEL NO: 1800-2879999 - FAX NO: 62815969

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

I was travelling along Rivervale Link and suddenly vehicle B exited from one of the condo from opposite side of the road and made a right turn. Vehicle B hit into the right rear area of my vehicle A while making the right turn.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGU7537D

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver RONNIE NG HOCK HENG

NRIC/Passport Number S7226498C

Contact Number 81111150

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Sketch Plan Pg. 1

PTLC Income Motor Service Centre

Vehicle No: GN9758G

Report Date & Start Time: 16-12-16 / 13:50

Report No: MT/

D.O.A: 14-12-2016

Make / Model: NISSAN URVAN

Reporting Type: T.P

End Time: / /

Time: 2240 hrs

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



16-12-16 / 13:50

Policyholder's Signature / Date & Time

[Signature]

16-12-16 / 13:50

Driver's Signature (if driver is not the policyholder) / Date & Time

Alan Tang (S098825)
Customer Care Executive
Motor Service Centre

[Signature]

Witnessed by Reporting Centre Personnel

Sketch Plan

Vehicle A: GN9758G Vehicle B: SGU7537D Rivervale Link

Sketch Plan Pg. 2

Describe Circumstances of the Accident

I was travelling along Rivervale Link and suddenly vehicle B exited from one of the condo from opposite side of the road and made a right turn. Vehicle B hit into the right rear area of my vehicle A while making the right turn.

Declaration

I/We declare the foregoing particulars are true in every respect.



16-12-16 13:50

Policyholder's Signature / Date & Time


16-12-16 13:50

Driver's Signature (If driver is not the policyholder) / Date & Time

Alan Tang (S098825)
Customer Care Executive
Motor Service Centre

Witnessed by Reporting Centre Personnel

Sketch Plan #2 Pg. 1



CONFIDENTIAL

Annex E

NOTICE OF COMPLIANCE

This is to confirm that Tanranjit Singh Tel 84681916,
NRIC/FIN S9708017H, has reported to the Police a non-injury traffic accident
which occurred at Along Rivervale Link
on 14/12/2016 at 2238 HRS involving the following vehicles:
GN9758G - Complainant
SGU7537D - Mr Ronnie Ng Hock Heng, S7226498C, Tel 81111150

- 2 If this accident was reported to the Police within 24 hours of its occurrence,
Then he/she has complied with Sec 84(2) of the Road Traffic Act, Cap 276.

Rank/Name of Issuing Officer: SGT T140161 Ong Zhen Zuo

Date: 15/12/2016 Time: 1418 hrs

S/D Ref: 76

Police Post/Unit: Serangoon Garden NPP

Original - to be issued to informant
Duplicate - to be submitted to Traffic Police

Singapore Police
Sgt T140161 Ong Zhen Zuo
15/12/2016 1418 hrs

CONFIDENTIAL

Version as of 15 Jan 2002

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/12/2016 13:03
Date Of Accident	14/12/2016 22:40
Exact Location Of Accident	ALONG PARK GREEN RIVERVALE LINK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGU7537D
Insured/Policyholder	
Name Of Registered Owner	VINCAR LEASING AND RENTAL PTE LTD
Co Reg No	201414828K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-NOPHONE
Vehicle Particulars	
Manufacturer	HONDA
Model	AIRWAVE 1.5 A
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5082409493
Cover Note Number	
Driver	
Name of Driver	RONNIE NG HOCK HENG
NRIC No	S7228498C
Date Of Birth	20/07/1972
Occupation	OUTDOOR
Date Of Driving Pass	22/04/2015
Driving Experience	1 YEAR AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81111150
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 65 MARINE DRIVE #02-162
Postcode	440065
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	UNKNOWN - REFER TO SKETCH PLAN.
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Refer to sketch plan.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GN9758G
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
 8. Consent under the Personal Data Protection Act (PDPA)
- I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

I was travelling straight on the extreme right lane and I was going about 20km per hour when out of a sudden a span GN 975PG which was speeding make a sharp left turn and abruptly cut into my lane and collided onto my left front bumper. I have taken photos of the skid mark on the road to prove that he was speeding and failed to brake in time which caused the accident.

You had been advised by the workshop that in the event that you wish to claim against your own policy (OD claim), there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.

Reporting Only

Claim OD

☒ Claim TP

Claim OD/TP at other workshop

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199807198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
BONNIE KWOK LLC			Ref : CS/LAW19006804/Avd3e2	
101A UPPER CROSS STREET #08-12 PEOPLE'S PARK CENTRE SINGAPORE 058358			Date : 03-06-2019	
			Code : L094	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	SGU 7537D	Veh. Inspected	GN 9758G (GBH 4330E)	
Policy No.		Coverage (\$)	0.00	
Claim No.	BK 17930.17	Excess (\$)	0.00	
Assign From	BONNIE KWOK	Assign Date	11/04/2019	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN URVAN	c.c	2953	
Engine No.	HIDDEN	Year of Reg.	2005	
Chassis No.	JN1MG4E25Z0712746	Colour	BLUE	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	YOKOHAMA	6 mm	
L/H Front Tyre	195 R15C	YOKOHAMA	6 mm	
R/H Rear Tyre	195 R15C	YOKOHAMA	6 mm	
L/H Rear Tyre	195 R15C	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	14/12/2016	Inspection Date	26/04/2019	
Survey held at	PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GN 9758G (GBH 4330E)

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER ASSY	REPLACED	696.70	696.70
2	REAR BUMPER SIDE RETAINER	REPLACED	138.20	138.20
8	REAR BUMPER CLIP	REPLACED	28.00	28.00
1	REAR FENDER O/S	REPLACED	2,010.30	2,010.30
	LESS 30% DISCOUNT		-	-861.96
			2,873.20	2,011.24
NETT ITEMS				
1	REAR MUDFLAP O/S (N)	REPLACED	113.60	113.60
1	SET REAR LEAF SPRING ASSY O/S (N)	NOT CHANGED	1,328.10	-
2	REAR LEAF SPRING U BOLT O/S (N)	NOT CHANGED	194.20	-
1	REAR LEAF SPRING BOLT (N)	NOT CHANGED	19.00	-
	LESS 10% DISCOUNT		-	-11.36
			1,654.90	102.24
SPECIAL NETT ITEMS				
1	REAR AXLE ASSY (SN)	NOT CHANGED	6,405.10	-
1	REAR SHOCK ABSORBER O/S (SN)	NOT CHANGED	133.20	-
1	REAR WHEEL RIM ASSY O/S (SN)	REPLACED	300.00	220.00
1	REAR TYRE ASSY O/S (SN)	REPLACED	360.00	200.00
			7,198.30	420.00
LABOUR				
	TO REMOVE / REFIT REAR BOOT COMPARTMENT INTERIOR GARNISHES, CARPETS WHERE NECESSARY.	NOT NECESSARY	120.00	-
	TO INSTALL REVERSE SENSORS, CONTROL UNIT. RE-CONNECT WIRES HARNESS. CHECK FUNCTION.		180.00	60.00
	TO APPLY UNDERSEAL AND RUST-PROOFING ON AFFECTED AREAS.		180.00	80.00
	TO CONDUCT WHEEL ALIGNMENT (BEFORE & AFTER)		240.00	160.00
	TO REMOVE / REFIT REAR UNDERCARRIAGE / SUSPENSION ASSEMBLY WITH ALL ATTACHMENTS / COMPONENTS.		800.00	380.00
	TO RENEW WHEEL RIM / TYRE AND CONDUCT WHEEL BALANCING.		120.00	50.00

Report Ref No. CS/LAW19006804/Avd3e2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY PAINT REPLACED / REPAIRED BODY PARTS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS.		900.00	600.00
	TO REMOVE ALL DAMAGED PARTS WITH ALL NECESSARY COMPONENTS / ATTACHMENTS. TO APPLY HOT-WORKS WHERE NECESSARY, STRAIGHTEN CHASSIS MEMBERS, REPAIR / RESHAPE DENTED BODY PANELS, IN ACCORDANCE WITH FACTORY SPECIFICATIONS. REPLACE DAMAGED PARTS, REFIT AND ALIGN INTO POSITION. REFIT ALL NECESSARY COMPONENTS / ATTACHMENTS.		1,100.00	750.00
			3,640.00	2,080.00
GRAND TOTAL			15,366.40	4,613.48
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,700.00

Report Ref No. CS/LAW19006804/Avd3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.