

ASS. REC. BY:

REF: CS3/CTI/9006814/R1 cd32 Special Instruction:

Surveyor: Kusu

ASSIGNMENT (Office)

Mainman

From (Person): Ong chin kiat

of CTI

Date/Time: 16.4.19 16.49 p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FE 7080A

Insured: SLG 6773J

at Workshop m/s Hua chin

Tel: 62966619

of 50 Bukit Batok Street 23, #02-02

Policy No: DMPCS 306637/800

Claim No: SNM 190201673202/3

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 12.4.2019

17.4.2019

CA / REV / REP. / REV 24 HRS

"wp"

H.O.D. Endorsement:

Date/Time: 17.4.19

Person Contacted:

lim

Vehicle IN/OUT


Date/Time	Action/Instruction	Estimate (X)
	FE 7080A - X	
	SLG 6773J - CS3/AIG 170220149 / Sbr 2.	D.O.A - 02/12/2017
	According to WLS no estimate, pass lawyer.	
	Dismantle: 24/4/2019	
	After repair: 16/5/2019	

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: FE 7080A
 at Workshop m/s Hua CHIN
 of 50, Buckle frame cars #02-02
 Insured: CTL
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FE 7080A Yr Regn: 1986 / MUL
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: YAMAHA RX2 C.C. 133
 Colour: MULTI A/C: Insured / Std / NI / NA
 Sp. Reading: 3248 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: 55K001018
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / Rim / STD A/Rim or
 Tyre Size: F: 80/80-18
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or FKR

Front 3 mm Rear 3 mm
 R/Bal. 3 mm R/Bal. 3 mm
 L/Bal. _____ mm L/Bal. _____ mm
 D.O.A. 12/04/19 D.O.I. 17/04/19
 Survey held at Hua CHIN
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Estimated repair range \$2,000 - \$2,500

RECEIVED 28 MAY 2019

15/5/2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3Resurvey No. of Trip: 2

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Report Format: PRS

Lump Sum / I.B.I. (\$) _____

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

190

190

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Apr 2019		16 Apr 2019 16:49 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LOH YEW THIAM, ID: S18239801		
Main Claimant:	,UHAMMAD SYAMEEL BIN MOHD NOOR, ID: S9925327D		
Vehicle Reg. No.:	FE7080A	Date of Loss:	12/04/2019 17:00 - :59
Claim Type:	TP / SNM19D201673C02/3	Policy/Cover Note No.:	DMPCSN3066371800 (Comprehensive) Coverage: 11/10/2018 - 10/10/2019
Vehicle Reg. No. (Insured):	SLG6773J	Policy No. (Claimant):	
		Excess:	S\$1,600.00
Repairer:	Hua Chin (2000) Trading Motor Service Centre (HQ) 50 BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING, 659578 Bukit Batok - Tel: 68966619		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 26/04/2019]		
Adj Asg. Remarks:	Please survey third party & let us have us your report & bill.		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5327D
Vehicle Details	
Vehicle No.:	FE7080A
Vehicle to be Exported:	No
Intended Deregistration Date:	16 May 2019
Vehicle Make:	YAMAHA
Vehicle Model:	RXZ
Primary Colour:	Blue
Manufacturing Year:	1985
Engine No.:	55K001018
Chassis No.:	55K001018
Maximum Power Output:	-
Open Market Value:	\$0.00
Original Registration Date:	27 Aug 1986
First Registration Date:	27 Aug 1986
Transfer Count:	15
Actual ARF Paid:	\$0.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Feb 2024
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$1,952.00
COE Rebate Amount:	\$965.00
Total Rebate Amount:	\$965.00
Message	
Please note that the National Environment Agency (NEA) is offering an incentive for the owner of this motorcycle to deregister the motorcycle on or before 5 April 2023.	
This motorcycle is currently eligible for an incentive of \$3,500 from NEA. If the COE is renewed from now till its deregistration on or before 5 April 2023, the incentive will be reduced to \$2,000. The last registered owner of this motorcycle will receive the incentive from NEA.	
This motorcycle will no longer be allowed for use on Singapore's roads after 30 June 2028.	
For more information, please visit http://www.nea.gov.sg/mtcincentive or contact NEA at 1800-2255-632.	

The information contained herein is correct as at 16 May 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/04/2019 08:34
Date Of Accident	12/04/2019 17:45
Exact Location Of Accident	WEST COAST HIGHWAY TOWARDS PANDAN ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FE7080A
Insured/Policyholder	
Name Of Registered Owner	MUHAMMAD SYAMEEL BIN MOHD NOOR
NRIC No	S9925327D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-88003359
Alternative Phone No	OFFICE-88003359

Vehicle Particulars

Manufacturer	YAMAHA
Model	RXZ135-133CC (M)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5103230534
Cover Note Number	

Driver

Name of Driver	MUHAMMAD SYAMEEL BIN MOHD NOOR
NRIC No	S9925327D
Date Of Birth	16/07/1999
Occupation	OUTDOOR
Date Of Driving Pass	20/02/2018
Driving Experience	1 YEAR AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-88003359
Fax Number	
Contact Number	OFFICE-88003359
EMail Address	NOEMAIL

Address	BLK 407 PANDAN GARDENS #09-45
Postcode	600407
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	NANYANG N.P.C
Police Station Address	ROAD: 2 JURONG WEST AVE 5 , POSTCODE: 649482 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-7929999 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLG6773J
Vehicle Make/Model/Colour	MITSUBISHI
Details Of Properties	NA
Vehicle Category	PRIVATE CAR
Name of Driver	LOW YEW THIAM
NRIC/Passport Number	S1823980I
Contact Number	96906822
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	


No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	MUHAMMAD SYAMEEL BIN MOHD NOOR
Approximate Age	
Injuries Sustain	REFER REPORT
Injured person in which vehicle?	FE7080A
Were seat belts worn?	NO
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 407 PANDAN GARDENS #09-45
Postcode	60047

Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer Police Report

7/20190413/2046.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
 Policyholder's Signature
 Date & Time:

[Signature]
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

[Signature]
 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

15/4/2019
[Signature]

SHARAC Form 1 (Rev. 01)

Sketch Plan #2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

13/04/2019
1258

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

15/4/2019
Rand

Common Statement



**SINGAPORE
POLICE FORCE**



T/20190413/2046

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

1 of 3

Report No. T/20190413/2046

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 13/04/2019 11:39		Vide Report No.:		Station Diary No.: 53
Informant's Particulars				
Name of Informant: MUHAMMAD SYAMEEL BIN MOHD NOOR		Address: APT BLK 407 PANDAN GARDENS #09-45 SINGAPORE 600407		
ID Type / ID No.: NRIC NO / S9925327D		Contact No.: Home/Office: Mobile: 88003359		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 19	Date of Birth: 16/07/1999	Type of Informant: Rider	
Race: Malay		Language:	Institution / School Name:	
Occupation: Student		Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 12/04/2019 17:45	Type of Location: Straight Road
Location: Along Road 1 WEST COAST HIGHWAY PANDAN ROAD				
Weather: Clear	Road Surface: Dry	Road Speed Limit:		
Traffic Flow:	Traffic Control:	Traffic Volume: Heavy		
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FE7080A	Motorcycle	YAMAHA	RXZ	Blue	Seriously Damaged	0
SLG6773J	Car				Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FE7080A	NTUC Income Insurance Co-Operative Limited	5103230534	21/08/2018	20/08/2019

Common Statement



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999



T/20190413/2046

2 of 3

Report No. T/20190413/2046

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	MUHAMMAD SYAMEEL BIN MOHD NOOR	ID No.	S9925327D
Related Vehicle	FE7080A (Motorcycle)	Contact No.	88003359
Hospital/Clinic	NATIONAL UNIVERSITY HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	12/04/2019	Date Discharge	12/04/2019
No. of Days granted Medical Leave	05	Degree of Injury	Serious
Driver			
Name	Loh Yew Thiam	ID No.	S18239801
Related Vehicle	SLG6773J (Car)	Contact No.	96906822
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 12/04/19 at about 1745hrs, I was riding my bike, FE7080A along West Coast highway proceeding to work using the usual route. While proceeding along West Coast highway and reaching the traffic light junction, there was jam at the 2nd and 3rd lane and I was travelling along the 1st lane. I was reaching the yellow box and another vehicle, SLG6773J, was travelling from the minor road to the 1st lane. His vehicle then knock the side of my motorcycle and caused me to fell from my motorcycle. Subsequently, we exchanged particulars and he informed me that he did not saw me. Thereafter, I went to NUH with my friend. I was then given 05 days of MC. There is in-car recording in the other party's vehicle and I have no camera recording. I suffered a fracture collar bone and this is the first time such incident happened.

Common Statement



**SINGAPORE
POLICE FORCE**



T/20190413/2046

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

3 of 3

Report No. T/20190413/2046

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Sgt 2 WONG JUN WEI, DANIEL

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
13/04/2019 11:39

Officer In Charge Of Case:
TP / AEIT /
Sr Staff Sgt MOHAMAD ZULFAZLI BIN
ABDULLAH

Classification Of Case:

Contact No.: 65476204

SN 127

Authentication Stamp



Signature:

Singapore Police Force

...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Apr 2019		16 Apr 2019 16:49 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case



















































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	LOH YEW THIAM, ID: S18239801								
Main Claimant:	,UHAMMAD SYAMEEL BIN MOHD NOOR, ID: S9925327D								
Vehicle Reg. No.:	FE7080A	Date of Loss:	12/04/2019 17:00 - :59 [391 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D201673C02/3	Policy/Cover Note No.:	DMPCSN3066371800 (Comprehensive) Coverage: 11/10/2018 - 10/10/2019						
Vehicle Reg. No. (Insured):	SLG6773J	Policy No. (Claimant):							
		Excess:	S\$1,600.00						
Repairer:	Hua Chin (2000) Trading Motor Service Centre (HQ) 50 BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING, 659578 Bukit Batok - Tel: 68966619								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 26/04/2019]								
Adj Asg. Remarks:	Please survey third party & let us have us your report & bill.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FE7080A (SNM19D201673C02/3)
[SLG6773J]
TP
UHAMMAD SYAMEEL BIN MOHD NOOR
Apr 12 2019 5:00PM
[LOH YEW THIAM]
Hua Chin (2000) Trading Motor Service Centre

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images								3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print
1	16/05/19 11:44	General View							Load JPG	<input checked="" type="checkbox"/>
2	16/05/19 11:44	General View							Load JPG	<input checked="" type="checkbox"/>
3	16/05/19 11:44	General View							Load JPG	<input checked="" type="checkbox"/>
4	16/05/19 11:44	General View							Load JPG	<input checked="" type="checkbox"/>
5	16/05/19 11:44	General View							Load JPG	<input checked="" type="checkbox"/>
6	16/05/19 11:44	General View							Load JPG	<input checked="" type="checkbox"/>
7	16/05/19 11:44	General View							Load JPG	<input checked="" type="checkbox"/>
8	16/05/19 11:44	General View							Load JPG	<input checked="" type="checkbox"/>
9	16/05/19 11:44	General View							Load JPG	<input checked="" type="checkbox"/>
10	16/05/19 11:44	General View							Load JPG	<input checked="" type="checkbox"/>
11	16/05/19 11:44	General View							Load JPG	<input checked="" type="checkbox"/>
12	16/05/19 11:44	General View							Load JPG	<input checked="" type="checkbox"/>
13	16/05/19 11:44	General View							Load JPG	<input checked="" type="checkbox"/>
14	16/05/19 11:44	General View							Load JPG	<input checked="" type="checkbox"/>
15	16/05/19 11:44	General View							Load JPG	<input checked="" type="checkbox"/>
16	16/05/19 11:44	General View							Load JPG	<input checked="" type="checkbox"/>
17	16/05/19 11:44	General View							Load JPG	<input checked="" type="checkbox"/>
18	16/05/19 11:44	General View							Load JPG	<input checked="" type="checkbox"/>
19	16/05/19 11:44	General View							Load JPG	<input checked="" type="checkbox"/>
20	16/05/19 11:44	General View							Load JPG	<input checked="" type="checkbox"/>
21	16/05/19 11:44	General View							Load JPG	<input checked="" type="checkbox"/>
22	16/05/19 11:44	General View							Load JPG	<input checked="" type="checkbox"/>
23	16/05/19 11:44	General View							Load JPG	<input checked="" type="checkbox"/>
24	16/05/19 11:44	General View							Load JPG	<input checked="" type="checkbox"/>
25	16/05/19 11:44	General View							Load JPG	<input checked="" type="checkbox"/>
26	16/05/19 11:44	General View							Load JPG	<input checked="" type="checkbox"/>
27	16/05/19 11:44	General View							Load JPG	<input checked="" type="checkbox"/>
28	16/05/19 11:44	General View							Load JPG	<input checked="" type="checkbox"/>
29	16/05/19 11:44	General View							Load JPG	<input checked="" type="checkbox"/>
30	16/05/19 11:44	General View							Load JPG	<input checked="" type="checkbox"/>
31	16/05/19 11:44	General View							Load JPG	<input checked="" type="checkbox"/>
32	16/05/19 11:44	General View							Load JPG	<input checked="" type="checkbox"/>
33	16/05/19 11:44	General View							Load JPG	<input checked="" type="checkbox"/>
34	16/05/19 11:44	General View							Load JPG	<input checked="" type="checkbox"/>
35	16/05/19 11:44	General View							Load JPG	<input checked="" type="checkbox"/>
36	16/05/19 11:44	General View							Load JPG	<input checked="" type="checkbox"/>
37	16/05/19 11:44	General View							Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	16/05/19 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
39	16/05/19 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
40	16/05/19 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
41	16/05/19 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
42	16/05/19 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
43	16/05/19 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
44	16/05/19 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
45	16/05/19 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
46	16/05/19 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
47	16/05/19 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
48	16/05/19 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
49	16/05/19 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
50	16/05/19 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
51	16/05/19 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
52	16/05/19 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
53	16/05/19 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
54	16/05/19 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
55	16/05/19 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
56	16/05/19 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
57	16/05/19 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
58	16/05/19 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
59	16/05/19 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
60	16/05/19 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
61	16/05/19 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
62	16/05/19 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
63	16/05/19 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
64	16/05/19 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
65	16/05/19 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
66	16/05/19 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
67	16/05/19 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
68	16/05/19 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
69	16/05/19 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
70	16/05/19 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
71	16/05/19 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
72	16/05/19 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
73	16/05/19 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
74	16/05/19 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
75	16/05/19 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
76	16/05/19 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
77	16/05/19 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
78	16/05/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	16/05/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	16/05/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	16/05/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	16/05/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	16/05/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	16/05/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	16/05/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	16/05/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	16/05/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	16/05/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	16/05/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	16/05/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	16/05/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	16/05/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	16/05/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	16/05/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	16/05/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	16/05/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	16/05/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	16/05/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	16/05/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	16/05/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	16/05/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	16/05/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	16/05/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	16/05/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	16/05/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	16/05/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
107	16/05/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
108	16/05/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
109	16/05/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
110	16/05/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
111	16/05/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
112	16/05/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
113	16/05/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
114	28/05/19 14:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
115	28/05/19 14:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
116	28/05/19 14:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
117	28/05/19 14:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
118	28/05/19 14:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
119	28/05/19 14:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
120	28/05/19 14:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
121	28/05/19 14:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
122	28/05/19 14:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
123	28/05/19 14:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
124	28/05/19 14:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
125	28/05/19 14:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
126	28/05/19 14:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
127	28/05/19 14:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
128	28/05/19 14:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
129	28/05/19 14:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
130	28/05/19 14:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
131	28/05/19 14:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
132	28/05/19 14:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
133	28/05/19 14:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
134	28/05/19 14:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
135	28/05/19 14:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
136	28/05/19 14:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
137	28/05/19 14:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
138	28/05/19 14:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
139	28/05/19 14:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
140	28/05/19 14:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	16/04/19 16:47	EMAIL CORRESPONDENCES	 Load PDF	
2	16/04/19 16:47	REPORT OF FE7080A	 Load PDF	
3	16/04/19 16:47	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19006814/R1CD3E2

Date: 10/06/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3066371800

Claimant Vehicle
No: FE7080AInsured Vehicle
No: SLG6773J

Date of Loss: 12/04/2019

Nature of Claim: TP

Claim
No: SNM19D201673C02/3

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FE7080A

Make & Model: YAMAHA RXZ135, 133cc (M)

Reg. Date: 27/08/1986 (Man. Year: 1985)

Colour: Multi-colour

Engine Capacity: 133 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

Engine No: 55K001018

Chassis No: 55K001018

Odometer: 3248 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	80/80-18	Rear Tyre Size:	80/80-18
Front Left Side:	FKR 3 mm	Rear Left Side:	FKR 3 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 16/04/2019

Date Inspected: 17/04/2019 Inspected At:

Hua Chin (2000) Trading Motor Service
Centre (HQ)
50 BUKIT BATOK STREET 23, #02-02
MIDVIEW BUILDING
Singapore 659578

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 -\$2,500.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 10 Jun 2019)	
Parts:	N/A	YAMAHA RXZ135 133cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FE7080A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >