

ASS. REC. BY:

REF: C53/CT2 19006817/ GIC d30p

Special Instruction:

Surveyor: 90

Meritor

ASSIGNMENT (Office)

From (Person): Elaine Cheong

of CT1

Date/Time: 16.4.19 17.34p.m

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SLA 8957P

Insured:

SLN 1719m

at Workshop m/s Lian Heng Painter Company

Tel:

9863 2371

of 160 sin ming Drive, #06-10

Policy No: DMPCSN/308 1161800

Claim No:

SNM19D20/660002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

14.4.2019

17.4.2019

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

"wp"

Date/Time: 17.4.19 9.00a.m

Person Contacted:

Henry

Vehicle IN OUT

Date/Time	Action/Instruction	Estimate (X)
	SLA 8957P	-X
	SLN 1719m	-X
	Dismantle: 18/4/2019	
	After repair: 22/4/2019	

REF: CT1

4498A

## ASSIGNMENT

From:

Date:

17.4.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLA 8957P

at Workshop m/s

Lian Heng Painter

of 160 sin ming Drive # 06-10

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

or w/p

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLA8957P

Yr Regn:

21 Mar 2016

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Altis

c.c

1598

Colour:

Red

A/C:

Insured / Std / NI / NA

Sp. Reading

41899

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR053 REH 1045 46698

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55 R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

17-04-19

Survey held at

w/s

3:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$5000 - \$6000

18/4/2019

RECEIVED 26 APR 2019

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

6

Resurvey No. of Trip:

2

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

150

Transportation:

S + RS, SI

Photos

Others

TOTAL

150

Report Format: PRE

Lump Sum / I.B.I: (\$

### ...CLAIM SUBFOLDER...(New Assignment)

#### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Apr 2019		16 Apr 2019 17:34 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

#### CLAIM SUBFOLDER DETAILS

Insured:	<b>WU SHUWEN REBECCA</b> , ID: S8204498A <span>[Created by insurer]</span>		
Main Claimant:			
Vehicle Reg. No.:	<b>SLA8957P</b>	Date of Loss:	14/04/2019 11:00 - :59
Claim Type:	<b>TP / SNM19D201660C02</b>	Policy/Cover Note No.:	DMPCSN3081161800
Vehicle Reg. No. (Insured):	<b>SLN1719M</b>	Policy No. (Claimant):	GA451539/1
		Excess:	S\$750.00
Repairer:	<b>Lian Heng Painter Company ( )</b> 160 SIN MING DRIVE, #06-10 SIN MING AUTOCITY, 575722 Sin Ming - Tel:		
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Elaine Cheong</b> ]		
Claimant's Insurer:	<b>AXA Insurance Pte Ltd (HQ)</b> - Tel: 6338 7288		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... <b>[Final Rpt due 26/04/2019]</b>		

#### ASSOCIATED MAIL RECEIVED

There are no mail for this case. [View All](#) [Compose Case Mail](#)

#### ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>
						Assigned By	Completed On	Created On	Done?

No results.

# M NEDUMARAN & CO

Advocates & Solicitors  
Commissioner for Oaths

UEN NO. 53181067D

**Please reply to our Branch Office for this matter**

**Nedumaran Muthukrishnan**  
LLB (hons) [Buckingham]  
Barrister at Law (Lincoln's Inn)

➡ **Branch Office:** 11 Sin Ming Road  
#B2-09 (Unit 2) Thomson V Two  
Singapore 575629  
Tel : 6509-8480 / 6509-8481  
Fax : 6509-8482  
Email : [igene.lim@mneduco.com.sg](mailto:igene.lim@mneduco.com.sg)  
[serene.tan@mneduco.com.sg](mailto:serene.tan@mneduco.com.sg)

Our Reference : MN/IG/L1/1913014/st  
Your Reference : SLN 1719M

Date : 15<sup>th</sup> April 2019

BY EMAIL: [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com) ONLY

**CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD**  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

Dear Sirs,

1. **NOTICE OF ACCIDENT TO INSURERS AND PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF THE STATE COURTS PRACTICE DIRECTIONS (AMENDMENT NO. 1 OF 2016)**
2. **ACCIDENT ON 14/4/2019 INVOLVING VEHICLE NOS. SLA 8957P AND SLN 1719M ALONG JURONG EAST AVENUE 1 TOWARDS AYE.**

We are instructed by WU SHUWEN REBECCA (owner of motor vehicle no. SLA 8957P) and/or LIAN HENG PAINTER COMPANY (the motor workshop for SLA 8957P) to notify you of a road traffic accident on 14/4/2019 at about 1120 hours along JURONG EAST AVENUE 1 TOWARDS AYE involving our client's vehicle registration number [ SLA 8957P ] and [ SLN 1719M ] driven by you at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you with the stipulated timeline, we shall proceed to repair the vehicle without further reference to you.

Yours faithfully,

**M NEDUMARAN & CO**

**Nedumaran Muthukrishnan - (Branch Office)**

Encl

c.c. 1) YEIP POOI YEONG

(Vehicle : SLN 1719M )

- 2) **NAME OF WORKSHOP :**  
Lian Heng Painter Company  
160 Sin Ming Drive  
#06-10 Sin Ming AutoCity  
Singapore 575722  
Telephone : 6453-5779/ 9863-2371

(Vehicle : SLA 8957P )

(Attention : Nomy/ Henry )

## Nivitha (LKK Auto)

---

**From:** Elaine Cheong <elaine.cheong@sg.cntaiping.com>  
**Sent:** Tuesday, 16 April 2019 5:23 PM  
**To:** Serene Tan; 'assignments'  
**Cc:** Claims Dept of CTI; Igene Lim  
**Subject:** RE: PRE-REPAIR SURVEY (CLAIM REF: SNM19D201660C02-9)  
**Attachments:** FW: PRE-REPAIR SURVEY (151 KB)

WITHOUT PREJUDICE

Dear Serene,

We refer to your email of 16.04.19.

We are not agreeable to proposed list of surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below with attachment and liaise with third party workshop accordingly.

Thank you.

Regards,

**Elaine Cheong**  
Executive (Motor Claims)  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower  
Singapore 079909  
Co. Reg. No. 200208384E  
DID: 6389 6530  
Fax: 6224 7478 / 6224 7175  
Email: [elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

---

**From:** Serene Tan [mailto:serene.tan@mneduco.com.sg]  
**Sent:** Tuesday, 16 April, 2019 5:09 PM  
**To:** Elaine Cheong <elaine.cheong@sg.cntaiping.com>  
**Cc:** Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Igene Lim <igene.lim@mneduco.com.sg>  
**Subject:** RE: PRE-REPAIR SURVEY (CLAIM REF: SNM19D201660C02-9)

Our Ref : MN.IG.L1.1913014.st

WITHOUT PREJUDICE  
SAVE AS TO COSTS

**NOTICE TO INSURERS OBJECTING TO THE LIST OF MOTOR SURVEYORS PROVIDED  
WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2.6 OF THE STATE COURTS  
PRACTICE DIRECTIONS (AMENDMENT NO. 1 OF 2016)**

Dear Elaine,

1. We refer to your email below.
2. We are instructed by our client, WU SHUWEN REBECCA, the claimant and/or Lian Heng Painter Company, the motor workshop for **SLA 8957P** that they are not agreeable to the appointment of the motor surveyors as stated in your said email.
3. **In compliance with The State Courts Practice Directions (Amendment No. 1 of 2016)**, we propose to use one of the below mentioned motor surveyor to conduct the joint pre-repair survey ("hereinafter referred to as PRS") as a Single Joint Expert ("hereinafter referred to as a SJE").

1.	NICKY SEAH (Absolute Appraisal Services)	6.	ANDREW HOW (Prominent Appraiser Services)
2.	MICHAEL YAP TECK CHYE (MC-COY Appraiser Pte Ltd)	7.	NG KONG BENG PATRICK (Carlink Consultancy)
3.	DIXON YEO (Treasure Appraisal Services)	8.	ANANDA KUMAR BISWAS S/O B N BISWAS (United Appraisal & Management Pte Ltd)
4.	LOI BOON JUAN (PAR Automotive Consultancy)	9.	DENNIS YAP TECK WEE (PAL's Appraiser Pte Ltd)
5.	AMAS ONG (AEON Auto Consultants LLP)	10.	ANDY YAP TECK LEE (LCW Appraiser Pte Ltd)

4. Please let us know **within two (2) working days** whether you agree to the appointment of any of the above motor surveyors as proposed by the claimant and/or the motor workshop as a Single Joint Expert ("hereinafter referred to as "SJE").

Thanks & Best Regards,  
(For and on behalf of Mr Nedumaran Muthukrishnan)

Serene Tan (Ms)  
M NEDUMARAN & CO  
Advocates & Solicitors  
Commissioner for Oaths

**Branch Office:**

11 Sin Ming Road  
#B2-09 (Unit 2), Thomson V Two  
Singapore 575629  
Tel: 6509-8480 / 6509-8481  
Fax: 6509-8482

**Email : [serene.tan@mneduco.com.sg](mailto:serene.tan@mneduco.com.sg)**

**IMPORTANT NOTE:** This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) 6509 8480, if you have received this message in error. Thank you.

**From:** Elaine Cheong [<mailto:elaine.cheong@sg.cntaiping.com>]  
**Sent:** Tuesday, 16 April 2019 5:04 PM  
**To:** Serene Tan <[serene.tan@mneduco.com.sg](mailto:serene.tan@mneduco.com.sg)>  
**Cc:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>  
**Subject:** RE: PRE-REPAIR SURVEY (CLAIM REF: SNM19D201660C02-9)

**WITHOUT PREJUDICE**

Dear Serene,

We refer to your email of 16.04.19.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards,

**Elaine Cheong**  
Executive (Motor Claims)  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #16-00 Springleaf Tower  
Singapore 079909  
Co. Reg. No. 200208384E  
DID: 6389 6530  
Fax: 6224 7478 / 6224 7175  
Email: [elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

**From:** Serene Tan [<mailto:serene.tan@mneduco.com.sg>]  
**Sent:** Tuesday, 16 April, 2019 12:05 PM  
**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>  
**Cc:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>; Elaine Cheong <[elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)>  
**Subject:** FW: PRE-REPAIR SURVEY

Resent

---

**From:** Serene Tan  
**Sent:** Monday, 15 April 2019 10:59 AM  
**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>  
**Cc:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>; Igene Lim <[igene.lim@mneduco.com.sg](mailto:igene.lim@mneduco.com.sg)>; Irene Tay <[irene.tay@sg.cntaiping.com](mailto:irene.tay@sg.cntaiping.com)>; Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>  
**Subject:** PRE-REPAIR SURVEY

## URGENT

WITHOUT PREJUDICE

Our Ref: MN.IG.L1.1913014.st

Dear Sirs,

Notice of Accident dated **15/4/2019** attached herein.

Thanks & Best Regards,  
(For and on behalf of Mr Nedumaran Muthukrishnan)  
**Serene Tan (Ms)**  
**M NEDUMARAN & CO**  
Advocates & Solicitors  
Commissioner for Oaths

Branch Office:  
11 Sin Ming Road  
#B2-09 (Unit 2), Thomson V Two  
Singapore 575629  
Tel: 6509-8480 / 6509-8481  
Fax: 6509-8482  
**Email : [serene.tan@mneduco.com.sg](mailto:serene.tan@mneduco.com.sg)**

**IMPORTANT NOTE:** This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) 6509 8480, if you have received this message in error. Thank you.

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4498A
Vehicle Details	
Vehicle No.:	SLA8957P
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA COROLLA ALTIS 1.6L CVT
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	1ZRX556348
Chassis No.:	MR053REH104546698
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$19,589.00
Original Registration Date:	21 Mar 2016
First Registration Date:	21 Mar 2016
Transfer Count:	0
Actual ARF Paid:	\$19,589.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Mar 2026
PARF Rebate Amount:	\$14,691.00
Intended COE Rebate Details	
COE Expiry Date:	20 Mar 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,000.00
COE Rebate Amount:	\$31,149.00
<b>Total Rebate Amount:</b>	<b>\$45,840.00</b>

The information contained herein is correct as at 18 Apr 2019

OK

**► Altis Used Vehicle List (20 vehicles)**

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
<b>Toyota Corolla Altis 1.6A (New 5-yr COE)</b>	<b>\$28,800</b>	<b>\$5,750 /yr</b>	<b>01-Apr-2009</b>	<b>1,598 cc</b>	<b>-</b>	<b>GV Credit Pte Ltd</b>	<b>Available</b>
Lowest Interest At \$568 Monthly For Toyota Altis.\$0 Admin Fees For All GV Purchase. 2 Years Warranty For Engine And Gear Box. Add On Available. Office No. - 63443344 Wan - 82805406							
<b>Toyota Corolla Altis 1.6A (COE till 03/2024)</b>	<b>\$33,800</b>	<b>\$6,810 /yr</b>	<b>01-Apr-2009</b>	<b>1,598 cc</b>	<b>131,000 km</b>	<b>ABWIN (1994) Pte Ltd</b>	<b>Available</b>
Just Arrival And Best Buy With Assurance! Pristine Condition! Full Loan Available Subject To 100% Amount Approval. Feel Free To Contact Me For More Information Needed. Buy With A Peace Of Mind From Us... Office No. - - Jarrett Goh - 91013261							
<b>Toyota Corolla Altis 1.6A (New 5-yr COE)</b>	<b>\$31,800</b>	<b>\$6,350 /yr</b>	<b>01-Apr-2009</b>	<b>1,598 cc</b>	<b>120,000 km</b>	<b>Excel Motoring</b>	<b>Available</b>
Full Loan Available! Highest Offer For All Trade In! Vehicle Still In Tip Top Condition! Beautifully Polished! Accident-Free! Very Well Kept And Maintained! 6 Months Warranty! Good For 5 Years COE! No... Office No. - 67626693 Marcus - 81183131   Dan - 98975978   James - 97995575							
<b>Toyota Corolla Altis 1.6A (New 5-yr COE)</b>	<b>\$30,800</b>	<b>\$6,150 /yr</b>	<b>01-Apr-2009</b>	<b>1,598 cc</b>	<b>117,075 km</b>	<b>Motor-East Pte Ltd</b>	<b>Available</b>
No Gimmick! Easy And Flexible In House Loan Available, 2 Owner Only, Mileage Done 11700Km Per Year, Leather Seats, Sport Rims, Very Well Maintained And Service Regularly. Office No. - 67772200 Jing Jing - 98467878   Alvin Neo - 81886100   John Toh - 92717577   Vincent Lim - 86872202							
<b>Toyota Corolla Altis 1.6A (COE till 03/2024)</b>	<b>\$30,800</b>	<b>\$6,210 /yr</b>	<b>01-Apr-2009</b>	<b>1,598 cc</b>	<b>125,000 km</b>	<b>Jet E Motor Trading</b>	<b>Available</b>
High Loan Approval Rate! In House Financing Available, Low Mileage, New Paintwork, Excellent Exterior And Interior Conditions! Your Trustworthy And Reliable Japanese Sedan, Trade In Welcomed. View To ... Office No. - 64655645 Eric Ng - 97472427   Mark Chua - 97479226   Nigel Lim - 97295873							
<b>Toyota Corolla Altis 1.6A (New 5-yr COE)</b>	<b>\$31,800</b>	<b>\$6,350 /yr</b>	<b>01-Apr-2009</b>	<b>1,598 cc</b>	<b>-</b>	<b>Victory Cars Trading Pte Ltd</b>	<b>Available</b>
- Office No. - 63854916 Mr Lee - 86885879   Mr Lim - 92470299   Mr Quek - 90096473   Mr Tan - 90999505							
<b>Toyota Corolla Altis 1.6A (COE till 03/2024)</b>	<b>\$33,800</b>	<b>\$6,810 /yr</b>	<b>02-Apr-2009</b>	<b>1,598 cc</b>	<b>13,088 km</b>	<b>ABWIN (1994) Pte Ltd</b>	<b>Available</b>
Just Arrival And Best Buy With Assurance! Pristine Condition! Full Loan Available Subject To 100% Amount Approval. Feel Free To Contact Me For More Information Needed. Buy With A Peace Of Mind From Us... Office No. - - Jarrett Goh - 91013261							
<b>Toyota Corolla Altis 1.6A (New 5-yr COE)</b>	<b>\$30,200</b>	<b>\$6,030 /yr</b>	<b>02-Apr-2009</b>	<b>1,598 cc</b>	<b>125,600 km</b>	<b>EU Automobile Pte Ltd</b>	<b>Available</b>
COE Up Trend, Buy Now Or Pay More For The Same Car Next Month! Fully Restored New Parts With Proven Receipts. 3 Months Warranty Given To Ensure You With The Greatest Peace Of Mind. New Paintwork Vario... Office No. - 67771515 Jacky - 81066106   Louis - 86282886   Patrick - 98593180							
<b>Toyota Corolla Altis 1.6A (COE till 04/2024)</b>	<b>\$30,800</b>	<b>\$6,190 /yr</b>	<b>07-Apr-2009</b>	<b>1,598 cc</b>	<b>131,539 km</b>	<b>Rexy Motor Trading Company</b>	<b>Available</b>
Road Tax Till October 2019. Under-Usage Low Mileage. Most Reliable Japanese Sedan Altis Ideally For Daily Drives. Cheapest In The Market, Don't Hesitate Anymore Grab The Lower April PQP, COE Prices Ha...							

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	15/04/2019 16:25
Date Of Accident	14/04/2019 11:20
Exact Location Of Accident	ALONG JURONG EAST AVE 1 TOWARDS AYE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLA8957P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	WU SHUWEN REBECCA
NRIC No	S8204498A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97652997
Alternative Phone No	OFFICE-97652997

### Vehicle Particulars

Manufacturer	TOYOTA
Model	ALTIS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA451539/1
Cover Note Number	

### Driver

Name of Driver	TAN CHEN WAH
NRIC No	S8212598A
Date Of Birth	04/05/1982
Occupation	INDOOR
Date Of Driving Pass	29/10/2015
Driving Experience	3 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97652997
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address -  
Postcode -  
Was driver an employee of the Insured's Company NO  
If No, Relationship of the Driver with the Insured SPOUSE  
Vehicle Registration Number of Driver's Own Vehicle -  
-  
Insurance Company of Driver's Own Vehicle -  
-

#### General Information of the Accident

Type Of Accident SIDE SWIPE  
Weather Conditions CLEAR  
Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
Number of vehicles (including own vehicle) involved in the accident 2  
Was any body injured in the Accident? NO  
Was any injured conveyed to hospital by ambulance? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 2  
Passenger 1 NAME: : PASSENGER  
GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police? NO  
If Yes, Please state which Police Station  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

#### Circumstances of Accident

refer attached report.

#### Attachment(s)

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? NO  
Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number SLN1719M  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver  
NRIC/Passport Number S8383175H  
Contact Number 93823281  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)


**SKETCH PLAN****IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
 Policyholder's Signature  
 Date & Time:

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:





DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

'A' SLA 8957 P

'B' SLN 1719 M

I was driving along Jurong East Ave. 1 on the left lane. I was hit on the right side of my car from vehicle B filtering left without checking his blindspot.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Apr 2019		16 Apr 2019 17:34 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

















































Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by insurer]</b>							
Insured:	-, Co. Reg. No.: -								
Main Claimant:	<b>WU SHUWEN REBECCA</b> , ID: S8204498A								
Vehicle Reg. No.:	<b>SLA8957P</b>	Date of Loss:	14/04/2019 11:00 - :59 <b>[36 Months and 24 Days From LTA Reg Date (Man Yr)]</b>						
Claim Type:	<b>TP / SNM19D201660C01</b>	Policy/Cover Note No.:	DMPCSN3081161800						
Vehicle Reg. No. (Insured):	<b>SLN1719M</b>	Policy No. (Claimant):	GA451539/1						
		Excess:	S\$750.00						
Repairer:	<b>Lian Heng Painter Company ()</b> 160 SIN MING DRIVE, #06-10 SIN MING AUTOCITY, 575722 Sin Ming - Tel:								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Elaine Cheong</b> ]								
Claimant's Insurer:	<b>AXA Insurance Pte Ltd (HQ)</b> - Tel: 6338 7288								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... <b>[Final Rpt due 26/04/2019]</b>								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>							
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>							
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

\*SLA8957P (SNM19D201660C01)  
[SLN1719M]  
TP  
WU SHUWEN REBECCA  
Apr 14 2019 11:00AM  
[-]  
Lian Heng Painter Company

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Assessment Reports									1 per page			<input checked="" type="checkbox"/>		
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)								Thumbnail	Print			
1	15/04/19 16:35	Accident Statement							1	Load HTM				
Photos/Images									3 per page			<input checked="" type="checkbox"/>		
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)								Thumbnail	Print			
1	15/04/19 16:31	Accident Photo [Linked Accident Report Documents]							1	Load JPG	<input checked="" type="checkbox"/>			
2	15/04/19 16:31	Accident Photo [Linked Accident Report Documents]							1	Load JPG	<input checked="" type="checkbox"/>			
3	15/04/19 16:31	Accident Photo [Linked Accident Report Documents]							1	Load JPG	<input checked="" type="checkbox"/>			
4	15/04/19 16:31	Accident Photo [Linked Accident Report Documents]							1	Load JPG	<input checked="" type="checkbox"/>			
5	15/04/19 16:31	Accident Photo [Linked Accident Report Documents]							1	Load JPG	<input checked="" type="checkbox"/>			
6	15/04/19 16:31	Accident Photo [Linked Accident Report Documents]							1	Load JPG	<input checked="" type="checkbox"/>			
7	15/04/19 16:31	Accident Photo [Linked Accident Report Documents]							1	Load JPG	<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print			
1	26/04/19 11:36	General View							1	Load JPG	<input checked="" type="checkbox"/>			
2	26/04/19 11:36	General View							1	Load JPG	<input checked="" type="checkbox"/>			
3	26/04/19 11:36	General View							1	Load JPG	<input checked="" type="checkbox"/>			
4	26/04/19 11:36	General View							1	Load JPG	<input checked="" type="checkbox"/>			
5	26/04/19 11:36	General View							1	Load JPG	<input checked="" type="checkbox"/>			
6	26/04/19 11:36	General View							1	Load JPG	<input checked="" type="checkbox"/>			
7	26/04/19 11:36	General View							1	Load JPG	<input checked="" type="checkbox"/>			
8	26/04/19 11:36	General View							1	Load JPG	<input checked="" type="checkbox"/>			
9	26/04/19 11:36	General View							1	Load JPG	<input checked="" type="checkbox"/>			
10	26/04/19 11:36	General View							1	Load JPG	<input checked="" type="checkbox"/>			
11	26/04/19 11:36	General View							1	Load JPG	<input checked="" type="checkbox"/>			
12	26/04/19 11:36	General View							1	Load JPG	<input checked="" type="checkbox"/>			
13	26/04/19 11:36	General View							1	Load JPG	<input checked="" type="checkbox"/>			
14	26/04/19 11:36	General View							1	Load JPG	<input checked="" type="checkbox"/>			
15	26/04/19 11:36	General View							1	Load JPG	<input checked="" type="checkbox"/>			
16	26/04/19 11:36	General View							1	Load JPG	<input checked="" type="checkbox"/>			
17	26/04/19 11:36	General View							1	Load JPG	<input checked="" type="checkbox"/>			
18	26/04/19 11:36	General View							1	Load JPG	<input checked="" type="checkbox"/>			
19	26/04/19 11:36	General View							1	Load JPG	<input checked="" type="checkbox"/>			
20	26/04/19 11:36	General View							1	Load JPG	<input checked="" type="checkbox"/>			
21	26/04/19 11:36	General View							1	Load JPG	<input checked="" type="checkbox"/>			
22	26/04/19 11:36	General View							1	Load JPG	<input checked="" type="checkbox"/>			
23	26/04/19 11:36	General View							1	Load JPG	<input checked="" type="checkbox"/>			



Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
24	26/04/19 11:36	General View	 Load JPG	<input checked="" type="checkbox"/>
25	26/04/19 11:36	General View	 Load JPG	<input checked="" type="checkbox"/>
26	26/04/19 11:36	General View	 Load JPG	<input checked="" type="checkbox"/>
27	26/04/19 11:36	General View	 Load JPG	<input checked="" type="checkbox"/>
28	26/04/19 11:36	General View	 Load JPG	<input checked="" type="checkbox"/>
29	26/04/19 11:36	General View	 Load JPG	<input checked="" type="checkbox"/>
30	26/04/19 11:36	General View	 Load JPG	<input checked="" type="checkbox"/>
31	26/04/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	26/04/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	26/04/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	26/04/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	26/04/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	26/04/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	26/04/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	26/04/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	26/04/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	26/04/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	26/04/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	26/04/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	26/04/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	26/04/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	26/04/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	26/04/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	26/04/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	26/04/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	26/04/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	26/04/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	26/04/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	26/04/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	26/04/19 11:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
54	26/04/19 11:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
55	26/04/19 11:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
56	26/04/19 11:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
57	26/04/19 11:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
58	26/04/19 11:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
59	26/04/19 11:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
60	26/04/19 11:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
61	26/04/19 11:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	26/04/19 11:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	26/04/19 11:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	26/04/19 11:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	26/04/19 11:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	26/04/19 11:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	26/04/19 11:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	26/04/19 11:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	26/04/19 11:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	26/04/19 11:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	26/04/19 11:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	16/04/19 17:39	PRS - SLA8957P	Load PDF	
2	16/04/19 17:39	PRS	Load PDF	
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	15/04/19 16:31	Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	15/04/19 16:31	Sketch Plan #2 [Linked Accident Report Documents]	Load TIF	
3	15/04/19 16:31	Sketch Plan #3 [Linked Accident Report Documents]	Load TIF	
4	15/04/19 16:31	Sketch Plan #4 [Linked Accident Report Documents]	Load TIF	
5	15/04/19 16:31	Sketch Plan #5 [Linked Accident Report Documents]	Load TIF	

## Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	15/04/19 16:35	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	15/04/19 16:31	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	15/04/19 16:31	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	15/04/19 16:31	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	15/04/19 16:31	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	15/04/19 16:31	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	15/04/19 16:31	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	15/04/19 16:31	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	15/04/19 16:31	Sketch Plan	Load TIF	
2	15/04/19 16:31	Sketch Plan #2	Load TIF	
3	15/04/19 16:31	Sketch Plan #3	Load TIF	
4	15/04/19 16:31	Sketch Plan #4	Load TIF	
5	15/04/19 16:31	Sketch Plan #5	Load TIF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19006817/GCD3E2

Date: 07/06/2019

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSN3081161800

Claimant Vehicle  
No : SLA8957PInsured Vehicle  
No : SLN1719M

Date of Loss: 14/04/2019

Nature of Claim: TP

Claim  
No: SNM19D201660C01

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLA8957P

Make &amp; Model: TOYOTA COROLLA ALTIS, 1.6 L CVT (A)

Engine No: 1ZR556348

Reg. Date: 21/03/2016 (Man. Year: 2015)

Chassis No: MR053REH104546698

Colour: Red

Odometer: 41899 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 16/04/2019

Date Inspected: 17/04/2019 Inspected At:

Lian Heng Painter Company  
160 SIN MING DRIVE, #06-10 SIN MING  
AUTOCITY  
Singapore 575722

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 -\$6,000.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 05 Jun 2019)
<b>Parts:</b>	143	TOYOTA COROLLA ALTIS 1.6 L CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLA8957P)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >