

ASS. REC. BY:

REF: CS3/CT119006833/9cd3/12 Special Instruction:

Surveyor: GR**ASSIGNMENT (Office)**

Mr/Ms

From (Person): Ongchin Kiatof CTIDate/Time: 17.4.19 13.23 p.m

Estimated Cost: _____

Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLV 7979Insured: GBD 8323Xat Workshop m/s Motor Intelligencia AutomotTel: 8838 3318of 13 Kaki Bukit Road 4 #01-20Policy No: DMCVSN 30295318 000Claim No: SRM19D201626 C02

Sum Insured: _____

Excess: _____

Make of Veh: _____

D.O.A. 10.4.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 17.4.19Person Contacted: WilsonVehicle (IN) OUT

Date/Time	Action/Instruction (x) Estimate
	SLV 7979 - X
	GBD 8323X - X
	Dismantle: 18/4/2019
	After repair: 25/4/2019

PR5

60

REF: CTI

2037A

ASSIGNMENT

(-2022)

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLU 797G
at Workshop m/s Motor Intelligence Automoto
of 13 kaki Bukit Road 4 #01-20

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$52k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS "rup"

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLU 797G Yr Regn: 16 Apr 2012

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A4 c.c. 1798

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 73229 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZZ8K8CA032651

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 225 / 50 R17

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mm

R/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 17-04-19

Survey held at w/s Spm

Des. of Damages: Frt / Rear / N/S / U/C / Rooftop or

The Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>\$10k - \$12k</u>
	<u>18/4/2019</u>
	RECEIVED 26 APR 2019

Date/Time, File Pass to? Preli. Report

1) Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 12

Resurvey No. of Trip: 2

Survey Fee: 150

Transportation: _____ S + RS. _____

Photos _____

Others _____

TOTAL 150

Report Format: PR5

Lump Sum / I.B.I.: (\$ _____)

Add Fee: Site Insp (\$ _____)

Interview (\$ _____)

Tech. Invs (\$ _____)

Weekend (\$ _____)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Apr 2019		17 Apr 2019 13:23 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	TAY KIA KOON TRADING, Co. Reg. No.: 53137737K								
Main Claimant:	MUHAMMAD AFEEQ BIN IBRAHIM, ID: S9522037A								
Vehicle Reg. No.:	SLU797G	Date of Loss: 10/04/2019 10:00 - :59 [83 Months and 25 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / SNM19D201626C02	DMCVSN30295318000 (Comprehensive) Coverage: 23/05/2018 - 22/05/2019							
Vehicle Reg. No. (Insured):	GBD8323X	Policy No. (Claimant): 5104715983 Excess: S\$0.00							
Repairer:	Motor Intelligence Automo Pte Ltd (HQ) 13 KAKI BUKIT ROAD 4, #01-20 BARTLEY BIZ CENTRE, 417807 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 29/04/2019]								
Driver/Custodian (Insured):	ONG CHEE WAI (27 / Male) , NRIC: G6677504L Email:								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2037A
Vehicle Details	
Vehicle No.:	SLU797G
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Apr 2019
Vehicle Make:	AUDI
Vehicle Model:	A4 1.8 TFSI MU
Primary Colour:	Black
Manufacturing Year:	2011
Engine No.:	CDH143989
Chassis No.:	WAUZZZ8K8CA032651
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$31,666.00
Original Registration Date:	16 Apr 2012
First Registration Date:	16 Apr 2012
Transfer Count:	2
Actual ARF Paid:	\$31,666.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Apr 2022
PARF Rebate Amount:	\$18,999.00
Intended COE Rebate Details	
COE Expiry Date:	15 Apr 2022
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$76,881.00
COE Rebate Amount:	\$23,012.00
Total Rebate Amount:	\$42,011.00

The information contained herein is correct as at 18 Apr 2019

OK

▶ Audi A4 Used Vehicle List (4 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
Audi A4 1.8A TFSI MU	\$53,888	\$12,440 /yr	29-Feb-2012	1,798 cc	109,000 km	Bavarian Marques Pte Ltd	Availal

Very Well Done Up And Maintained Audi A4! Rare One Of A Kind On The Road, Regularly Maintained And Serviced With Receipts To Prove. A
 Out On Aesthetics, Wide Body Kit, Upgraded Rims, Brembo Brake Ki...

Office No. - 68162642

Aran - 87517624 | Shawn - 88188544 | Koen - 92233437 | Darren - 82007582

Audi A4 1.8A TFSI MU	\$62,000	\$12,760 /yr	21-Sep-2012	1,798 cc	24,000 km	SG Car Consign Pte Ltd	Availal
-----------------------------	-----------------	--------------	-------------	----------	-----------	------------------------	----------------

Look No Further! Best Value For Your Money. Direct Owner's Beautiful Black, Sept 2012 Audi A4 1.8 TFSI MU (Navigation & Xenon) With Gre
 Leather Upholstery. Selling Due To Upgrading To New Car. Low Fu...

Office No. - 61000200

Andy Tay - 94891030 | Danny Loh - 97622873

Audi A4 1.8 TFSI MU	\$66,000	\$13,570 /yr	24-Oct-2012	1,798 cc	89,000 km	360 VR Cars	Availal
----------------------------	-----------------	--------------	-------------	----------	-----------	-------------	----------------

1 Owner Only. Full Agent Serviced Record. Supreme Condition. Trade In Available. Viewing By Appointment.

Office No. - 69310005

James Tan - 90700005

Audi A4 1.8A TFSI MU Attraction	\$68,800	\$15,950 /yr	19-Jun-2012	1,798 cc	105,000 km	Prem Roy Motoring	Availal
--	-----------------	--------------	-------------	----------	------------	-------------------	----------------

Single Owner N Well Maintained, Face Lifted Model, Agent Unit, Serviced Regularly At Workshop, Original Factory Condition, Accident Free, C
 Workshop/STA Evaluation Welcome, Optional Warranty Can Be ...

Office No. - 66028046

Kana - 96435365 | Ashvini - 98896985

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale
 even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans,
 financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authori
 car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, ca
 reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car
 performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2019 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/04/2019 11:51
Date Of Accident	10/04/2019 10:35
Exact Location Of Accident	BLK 315 UBI AVENUE ONE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLU797G
Insured/Policyholder	
Name Of Registered Owner	MUHAMMAD AFEEQ BIN IBRAHIM
NRIC No	S9522037A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93870974
Alternative Phone No	OTHERS-93870974

Vehicle Particulars

Manufacturer	AUDI
Model	A4 1.8 TFSI MU

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5104715983
Cover Note Number	

Driver

Name of Driver	MUHAMMAD AFEEQ BIN IBRAHIM
NRIC No	S9522037A
Date Of Birth	27/05/1995
Occupation	INDOOR
Date Of Driving Pass	15/09/2017
Driving Experience	1 YEAR AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93870974
Fax Number	
Contact Number	OTHERS-93870974
E-Mail Address	NOEMAIL

Address	BLK 651 #03-12 JALAN TENAGA
Postcode	410651
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO BELOW STATEMEN/SKETCH PLAN:

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD8323X
Vehicle Make/Model/Colour	NISSAN NV350 PANEL VAN 2.5 5MT 5DR EURO V
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



[Handwritten Signature]




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

10 APR 2019

IDAC KAKI BUKIT (VAC)

Reporting Centre
Name: **Singapore 415933**
NRIC/TEL: **67416697** Fax: **67492305**
Email: **vackb@singnet.com.sg**



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 10th of April 2019 around 1030 hrs I entered a carpark at B1K 315 at Ubi Avenue I. I saw a stationary van GRD8323X which was on the opposite direction of the road and the van was facing ~~the~~ against the traffic flow of the lane. There were no signals of hazard light, turning ^{direction} light and reverse light. I proceeded as per normal. ~~write~~ ~~I was within the~~ as it was safe to do so. When my car's side mirror passed the head of the van, suddenly it turned to the left and hit the right side of my car and dragged all the way. I stopped my vehicle and got off the car, so my surprised I saw the car ^{body} was badly damaged from after the front tyre till the back of my car just before the tail light.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature: *[Signature]*
 Date & Time: *[Signature]*

Driver's Signature: *[Signature]*
 (If driver is not the policyholder)
 Date & Time:

10 APR 2019

IDAC KAKI BUKIT (VAC)
 23 Kaki Bukit Ave 4
 Reporting Centre Personnel's Division
 Singapore 415933
 Tel: 67416697 Fax: 67492305
 Email: yackb@singnet.com.sg

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Apr 2019		17 Apr 2019 13:23 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	TAY KIA KOON TRADING, Co. Reg. No.: 53137737K								
Main Claimant:	MUHAMMAD AFEEQ BIN IBRAHIM, ID: S9522037A								
Vehicle Reg. No.:	SLU797G	Date of Loss:	10/04/2019 10:00 - :59 [83 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D201626C02	Policy/Cover Note No.:	DMCVSN30295318000 (Comprehensive) Coverage: 23/05/2018 - 22/05/2019						
Vehicle Reg. No. (Insured):	GBD8323X	Policy No. (Claimant):	5104715983						
		Excess:	S\$0.00						
Repairer:	Motor Intelligence Automo Pte Ltd (HQ) 13 KAKI BUKIT ROAD 4, #01-20 BARTLEY BIZ CENTRE, 417807 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 29/04/2019]								
Driver/Custodian (Insured):	ONG CHEE WAI (27 / Male) , NRIC: G6677504L Email:								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLU797G (SNM19D201626C02)**
[GBD8323X]
 TP
MUHAMMAD AFEEQ BIN IBRAHIM
Apr 10 2019 10:00AM
[TAY KIA KOON TRADING]
Motor Intelligence Automo Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View View in Browser	
Assessment Reports						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)		Thumbnail	Print		
1	10/04/19 12:21	Accident Statement		Load HTM	<input checked="" type="checkbox"/>		
Photos/Images						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	26/04/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
2	26/04/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
3	26/04/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
4	26/04/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
5	26/04/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
6	26/04/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
7	26/04/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
8	26/04/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
9	26/04/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
10	26/04/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
11	26/04/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
12	26/04/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
13	26/04/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
14	26/04/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
15	26/04/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
16	26/04/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
17	26/04/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
18	26/04/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
19	26/04/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
20	26/04/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
21	26/04/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
22	26/04/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
23	26/04/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
24	26/04/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
25	26/04/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
26	26/04/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
27	26/04/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
28	26/04/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
29	26/04/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
30	26/04/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
31	26/04/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
32	26/04/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
33	26/04/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
34	26/04/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	26/04/19 12:08	General View	Load JPG	<input checked="" type="checkbox"/>
36	26/04/19 12:08	General View	Load JPG	<input checked="" type="checkbox"/>
37	26/04/19 12:08	General View	Load JPG	<input checked="" type="checkbox"/>
38	26/04/19 12:08	General View	Load JPG	<input checked="" type="checkbox"/>
39	26/04/19 12:08	General View	Load JPG	<input checked="" type="checkbox"/>
40	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
41	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
42	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
43	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
44	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
45	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
46	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
47	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
48	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
49	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
50	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
51	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
52	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
53	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
54	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
55	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
56	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
57	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
58	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
59	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
60	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
61	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
62	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
63	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
64	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
65	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
66	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
67	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
68	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
69	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
70	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
71	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
72	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
73	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
74	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
75	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
76	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
77	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
78	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
79	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
80	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
81	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
82	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
83	26/04/19 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
84	26/04/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	26/04/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	26/04/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	26/04/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	26/04/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	26/04/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	26/04/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	26/04/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	26/04/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	26/04/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	26/04/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	26/04/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	26/04/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	26/04/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	26/04/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	26/04/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	26/04/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	26/04/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	26/04/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	26/04/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	26/04/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	26/04/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	26/04/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
107	26/04/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
108	26/04/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
109	26/04/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
110	26/04/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
111	26/04/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
112	26/04/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
113	26/04/19 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
114	26/04/19 12:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
115	26/04/19 12:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
116	26/04/19 12:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
117	26/04/19 12:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
118	26/04/19 12:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
119	26/04/19 12:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
120	26/04/19 12:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
121	26/04/19 12:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
122	26/04/19 12:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
123	26/04/19 12:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
124	26/04/19 12:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
125	26/04/19 12:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
126	26/04/19 12:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
127	26/04/19 12:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
128	26/04/19 12:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
129	26/04/19 12:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
130	26/04/19 12:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
131	26/04/19 12:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
132	26/04/19 12:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
133	26/04/19 12:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
134	26/04/19 12:09	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
135	26/04/19 12:09	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
136	26/04/19 12:09	Photo After Spray		Load JPG <input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	17/04/19 13:23	INSD GBD8323X GIA REPORT		Load PDF
2	17/04/19 13:23	PRS		Load PDF

Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	10/04/19 12:21	Accident Statement		Load HTM

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	10/04/19 11:59	Accident Photo		Load JPG <input checked="" type="checkbox"/>
2	10/04/19 11:59	Accident Photo		Load JPG <input checked="" type="checkbox"/>
3	10/04/19 11:59	Accident Photo		Load JPG <input checked="" type="checkbox"/>
4	10/04/19 11:59	Accident Photo		Load JPG <input checked="" type="checkbox"/>
5	10/04/19 11:59	Accident Photo		Load JPG <input checked="" type="checkbox"/>
6	10/04/19 11:59	Accident Photo		Load JPG <input checked="" type="checkbox"/>
7	10/04/19 11:59	Accident Photo		Load JPG <input checked="" type="checkbox"/>
8	10/04/19 11:59	Accident Photo		Load JPG <input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	10/04/19 12:21	Sketch Plan		Load TIF
2	10/04/19 12:21	Sketch Plan #2		Load TIF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT119006833/ACD3E2

Date: 10/05/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMCVSN30295318000	
Claimant Vehicle No: SLU797G	Insured Vehicle No: GBD8323X	
Date of Loss: 10/04/2019	Nature of Claim: TP	Claim No: SNM19D201626C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU797G	Engine No:	CDH143989
Make & Model:	AUDI A4, 1.8 TFSI MU (B8) (A)	Chassis No:	WAUZZZ8K8CA032651
Reg. Date:	16/04/2012 (Man. Year: 2011)	Odometer:	73229 km
Colour:	Black		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	17/04/2019	
Date Inspected:	17/04/2019 Inspected At:	Motor Intelligence Automo Pte Ltd (HQ) 13 KAKI BUKIT ROAD 4, #01-20 BARTLEY BIZ CENTRE Singapore 417807
Estimated Period of Repair:	12.0 days	

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$10,000.00 - \$12,000.00

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 10 May 2019)
Parts: 143	AUDI A4 1.8 TFSI MU (B8) (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU797G)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >