

ASS. REC. BY:

REF: CS/TH 190068401 U 9 d3

Special Instruction:

Surveyor: MARCUS**ASSIGNMENT (Office)**From (Person): Gabriel Waeof THDate/Time: 17.4.19 1.35pm

Estimated Cost:

Bill to:

**OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS**To Inspect Vehicle No: SLB 9767JInsured: SHD 4395 Tat Workshop m/s Centre Line Spray PaintingTel: 96256931of Blk 2 Kati Bukit Ave 2 #02-18/23

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 14.4.2019

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time: 17.3.19 3.00 pmPerson Contacted: Hung

Vehicle IN (OUT)

Date/Time

Action/Instruction (✓) Estimate

SLB 9767J - X

SHD 4395T - X

08/11/13) wef

REF:

ASS. REC. BY: Marcus

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLB 9767Jat Workshop m/s centurion

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 80k.

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: 2 Consistent? : Yes or NoEst. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS L1A39933

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLB 9767J Yr Regn: 4 16Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: BMW 116 D c.c. 1496Colour: black A/C: Insured / Std / NI / NASp. Reading: 40890 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WBA1V72050V724312Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55-R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mmR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 14/4/19 D.O.I. 24/4/19

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
3/5/19	1/5 + 3500 confid note AM work (Ref 8371.52, 51%)

RECEIVED 06 MAY 2019

Date/Time, File Pass to?

☐ : Preli. Report1) 06/5/19 turnst☐ : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 4Resurvey No. of Trip: 2Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

TOTAL

250

10

260

Report Format: MER-TPLump Sum / I.B.I: (\$ 3500 )

## Nivitha (LKK Auto)

---

**From:** Motor Claim - III <motorclaim@iii.com.sg>  
**Sent:** Wednesday, 17 April 2019 1:35 PM  
**To:** ct-admin@visionlawllc.com; 'jactan@visionlawllc.com'; 'sur@lkkauto.com'; Admin-D (LKKAuto)  
**Cc:** Manivel Priyadarshini  
**Subject:** RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. SLB9767J(Accident involving SLB9767J and SHD4395T on 14.04.2019)  
**Attachments:** 1747\_001.pdf; 1820\_001.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SLB9767J and let us have your report urgently.

This claim will be handled by Ms Priya.

\*Kindly upload this survey request email to merimen.

Thank You.

*Best Regards,*  
**Gabriel Wee**



64 Cecil Street; #05 - IOB Building  
Singapore 049711  
Tel: 6347 6100, Ext – 248

---

**From:** Motor Claim - III  
**Sent:** 17 April, 2019 9:20 AM  
**To:** 'ct-admin@visionlawllc.com' <ct-admin@visionlawllc.com>; 'jactan@visionlawllc.com' <jactan@visionlawllc.com>  
**Subject:** PRE-REPAIR INSPECTION FOR VEHICLE NO. SLB9767J(Accident involving SLB9767J and SHD4395T on 14.04.2019)

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,  
**Gabriel Wee**



64 Cecil Street; #05 - IOB Building  
Singapore 049711  
Tel: 6347 6100, Ext - 248

**From:** [ct-admin@visionlawllc.com](mailto:ct-admin@visionlawllc.com) [<mailto:ct-admin@visionlawllc.com>]  
**Sent:** 17 April, 2019 8:59 AM  
**To:** Motor Claim - III <[motorclaim@iii.com.sg](mailto:motorclaim@iii.com.sg)>  
**Subject:** Scan Image

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

# VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths

Agents for Trade Marks

(Incorporated with limited liability)

ERIC NG CHING BOON  
WONG KENG LEONG RAYNEY  
AUDREY WONG SU-HSIEN  
PAUL YAP TAI SAN  
ANJALLI DIO MUNIANDY  
SEGA PARAM  
ANG KIM NOI DIANE  
RAVENDRA KRISHNASAMY  
TAN YINGXIAN, SELWYN  
CHEONG YUNHUI, CLARISSA  
EDISON TAM CHYI EU  
SONIA LIM WEI LEI

Unique Entity Number :200721148H  
✓ **HEAD OFFICE:** 133 New Bridge Road  
#18-01/02 Chinatown Point  
Singapore 059413

Branch: 490 Toa Payoh Lorong 6  
#03-11 HDB Hub  
Singapore 310490

## ✓ HEAD OFFICE

TEL : (65) 65342811 (Hunting)  
FAX ✓ : (65) 65356802 (General)  
: (65) 65355905 (Litigation)  
E-mail : jactan@visionlawllc.com

## BRANCH

TEL : 65 63580703  
FAX : 65 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE- KINDLY REPLY TO **HEAD OFFICE** FOR THIS MATTER

Our Ref: AM.jt.Ins.C80.110206.19 (sj)  
Your Ref: SHD 4395 T

17 April 2019

### INDIA INTERNATIONAL INSURANCE PTE LTD

64 Cecil Street  
#04/#05 IOB Building  
Singapore 049711  
Attention: Motor Claims Department

BY FAX: 6224 4174

motorclaim@iii.com.sg

Dear Sirs,

**ACCIDENT INVOLVING SLB 9767 J & SHD 4395 T ON 14 APRIL 2019 ALONG SUNSET WAY TOWARDS BLK 105 CLEMENTI STREET 12 AT ABOUT 2035 HOURS (NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)**

We refer to your email 17 April 2019 of even date informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of LKK Auto Consultants Pte Ltd as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

**Venue:** Centre Line Spray Painting  
Blk 2 Kaki Bukit Avenue 2  
#02-18/23 Kaki Bukit Auto Hub  
Singapore 417921  
**Contact Person:** Mr Heng Ju Leng (9625 6931)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

ANJALLI M  
(HEAD OFFICE)

cc: SLB 9767 J- By fax: 6538-4108 only

### FOR SURVEYOR

Please initial here after completion of pre-repair inspection.  
Thank you.

1<sup>st</sup> Survey on \_\_\_\_\_  
Appointed surveyor :  
(Name & Signature)

2<sup>nd</sup> Survey on \_\_\_\_\_  
Appointed surveyor  
(Name & Signature)

3<sup>rd</sup> Survey on \_\_\_\_\_  
Appointed Surveyor  
(Name & signature)

**NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.**

### CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

- More than 80000 Graves To Be Exhumed to Make Way For T...
- A New Chapter - Skoda Singapore
- COE renewal question

## Post an Advertisement

Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

## New 10 Years Coe Renewal Toyota Estima 2.4A



3.08%P.A Low Interest@GV  
Finance.2 Years Warranty.  
\$4800 Down Monthly From \$988  
GV Credit Pte Ltd StarAd








Browse by Category

Sort by Date Posted 20 results/page

9 vehicles

bmw 116

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	bmw 116		Any	Any	2016	Any	Any	Any	Available
	BMW 1 Series 116d		\$82,800	\$10,890 /yr	08-Jun-2016	1,496 cc	50,000 km	Hatchback	Available
<b>Fuel Type:</b> Diesel (Euro 5 Engine and Above) 1.98% Special Interest Rate! Cheapest In Town! Full Loan Available, Still Under PML Warranty! Immaculate Condition, Well Serviced & Maintained By PML, Only 1 Owner, Original Paintwork Since Day 1, Acc... Heritage Auto Enterprise Pte Ltd Posted: 24-Apr-2019 Tags: 2016 BMW 116d, 2016 bmw 116d, BMW 116d, bmw 116d, BMW, 116d, Used BMW									
	BMW 1 Series 116d		\$72,800	\$9,020 /yr	18-Oct-2016	1,496 cc	113,000 km	Hatchback	Available
<b>Fuel Type:</b> Diesel (Euro 5 Engine and Above) 1 Owner, Serviced And Maintained By Agent, Sporty Design With Super Fuel Efficiency, Very Low Depreciation. Posted: 23-Apr-2019 Tags: 2016 BMW 116d, 2016 bmw 116d, BMW 116d, bmw 116d, BMW, 116d, Used BMW									
	BMW 1 Series 116d		\$85,666	\$11,540 /yr	25-Apr-2016	1,496 cc	55,000 km	Hatchback	Available
<b>Fuel Type:</b> Diesel (Euro 5 Engine and Above) Just Arrived, 1 Owner, Low Mileage. 100% Loan Available From 2.18%, Well Maintained, 100% Accident Free, High Trade In, Cheapest In Town. Excellent Condition. Call Now. Privilege Motors Pte Ltd Posted: 23-Apr-2019 Tags: 2016 BMW 116d, 2016 bmw 116d, BMW 116d, bmw 116d, BMW, 116d, Used BMW									
	BMW 1 Series 116d		\$83,800	\$10,870 /yr	15-Jul-2016	1,496 cc	53,000 km	Hatchback	Available
<b>Fuel Type:</b> Diesel (Euro 5 Engine and Above) (100% Loan Available) Promo Bank Interest Rate From 1.98%. 1 Owner Fully Maintained By PML With 3 Years / 200,000km BMW Warranty Till July 2019. Extremely Fuel Efficient Engine Delivers 24km/L With Up... Dynamic Motoring Posted: 23-Apr-2019 Tags: 2016 BMW 116d, 2016 bmw 116d, BMW 116d, bmw 116d, BMW, 116d, Used BMW									
<div> <div>Car Buying</div> <div>Car Aftermarket</div> </div> <div> <div>Car Selling</div> <div>On The Move</div> </div> <div> <div>Car Ownership</div> <div>Lifestyle</div> </div> <div> <div>Buying a pre-owned car, but Unsure of its Condition?</div> <div>Get, STA Car Evaluation</div> </div>									
	BMW 1 Series 116d		\$76,488	\$10,230 /yr	13-Apr-2016	1,496 cc	37,400 km	Hatchback	Available
<b>Fuel Type:</b> Diesel (Euro 5 Engine and Above) Flexi-Loan Available! From \$1,100/Month. Fully Serviced And Maintained By PML! One Owner, Genuine Low Mileage. Last Serviced Apr'19. Executive Lady Driver, Immaculately Maintained. New Road Tax Till O... Cars 88 Pte Ltd Posted: 16-Apr-2019 Tags: 2016 BMW 116d, 2016 bmw 116d, BMW 116d, bmw 116d, BMW, 116d, Used BMW									
	BMW 1 Series 116d		\$87,800	\$11,450 /yr	08-Jul-2016	1,496 cc	38,561 km	Hatchback	Available
<b>Fuel Type:</b> Diesel (Euro 5 Engine and Above) \$2,000 Republic Auto Warranty Workshop Credit. PML Unit! Serviced And Maintained By Agent. Warranty Till Jul'2019. Latest Facelift And Euro 6 BMW Hatchback! Sporty Design With Excellent Fuel Efficiency... Republic Auto Compare									



> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 8846J

### Vehicle Details

Vehicle No.: SLB9767J

Vehicle to be Exported: No

Intended Deregistration Date: 24 Apr 2019

Vehicle Make: B.M.W.

Vehicle Model: 116D 5DR HATCHBACK DSC LED

Primary Colour: Black

Manufacturing Year: 2016

Engine No.: 34399524B37D15A

Chassis No.: WBA1V72050V724312

Maximum Power Output: 85.0 kW (113 bhp)

Open Market Value: \$23,752.00

Original Registration Date: 28 Apr 2016

First Registration Date: 28 Apr 2016

Transfer Count: 1

Actual ARF Paid: \$10,253.00

### Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 27 Apr 2026

PARF Rebate Amount: \$7,689.00

### Intended COE Rebate Details

COE Expiry Date: 27 Apr 2026

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$47,510.00

COE Rebate Amount: \$32,244.00

**Total Rebate Amount: \$39,933.00**

The information contained herein is correct as at 24 Apr 2019

OK

Not Authorized  
 Make 2/5 @ 3500  
 Telephone: 24/4/19 4 days.

# Centre Line Car Spray Painting

2 Kaki Bukit Avenue 2, #02-18/23, (Kaki Bukit Autohub), Singapore 417921

Telephone: 6846 8203 FAX: 6538 4108 Handphone: 9625 6931 (Ah JU)

Vehicle number: SLB9767J

Vehicle Made & Model: BMW 116

Qty	List Items	Amount \$
1	Front door - RH 1421.05	1,481.50
1	Front door mirror	491.35
1	Front door mirror cover	110.65
1	Front door glass outer moulding	181.93
1	Front door glass run channel	211.45
1	Front door glass regulator 343.25	461.35
1	Front door glass regulator motor	420.55
1	Front door w/strip	210.32
1	Front door seal	112.30
1	Front door insulation	141.35
1	Front door checker	89.95
2	Front door hinges @ 86.50	173.00
1	Front door pillar - RH	895.60
1	Front fender - RH	641.35

Sub-total 5,622.65

Less 5% 281.13

Total List 5,341.52

9-3305.15

52

9-3139.89

106-1250.00

4389.89

202

2591

## Labour charges

To check front electrical wiring	50.00
To respray undercoating	80.00
To respray painting and etc	800.00
Panel beating, cut, weld remove & replacing above parts	800.00
<b>Total Labour</b>	<b>1,730.00</b>

**ESTIMATE PARTS AND LABOUR GRAND TOTAL \$**

**7,071.52**

LKK Auto Consultants hence notify  
 the Registrar of the following:  
 • To resurvey before after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No work will be done until the insurance company is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III19006840/UQD3N2

Date: 08/05/2019

## REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SLB9767J	Insured Vehicle No :	SHD4395T
Date of Loss:	14/04/2019	Nature of Claim:	TP
		Claim No:	MCT19040408

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SLB9767J	Engine No:	34399524B37D15A
Make & Model:	BMW 116D, 1.5 (A)	Chassis No:	WBA1V72050V724312
Reg. Date:	28/04/2016 (Man. Year: 2016)	Odometer:	40890 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,341.52	3,139.89	2,201.63	41.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,730.00	1,250.00	480.00	27.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,071.52</b>	<b>4,389.89</b>	<b>2,681.63</b>	<b>37.92</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,500.00</b>		
<b>Nett Amount (S\$)</b>	<b>7,071.52</b>	<b>3,500.00</b>	<b>3,571.52</b>	<b>50.51</b>

## INSPECTION

Date of Assignment:	17/04/2019	
Date Inspected:	24/04/2019 Inspected At:	Centre Line Car Spray Painting (HQ) 2 KAKI BUKIT AVNEUE 2, #02-23 KAKI BUKIT AUTOHUB Singapore 417921
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 08 May 2019)
<b>Parts:</b> 144	BMW 116D 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SLB9767J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR - RH	Badly Dented	1,481.50 FL	*1,421.05 FL
2	1		*FRONT DOOR MIRROR	Serviceable	491.35 FL	*- FL
3	1		*FRONT DOOR MIRROR COVER	Not Necessary	110.65 FL	*- FL
4	1		*FRONT DOOR GLASS OUTER MOULDING	Necessary	181.93 FL	*181.93 FL
5	1		*FRONT DOOR GLASS RUN CHANNEL	Necessary	211.45 FL	*211.45 FL
6	1		*FRONT DOOR GLASS REGULATOR	Bent	461.35 FL	*343.25 FL
7	1		*FRONT DOOR GLASS REGULATOR MOTOR	Jammed	420.55 FL	*420.55 FL
8	1		*FRONT DOOR W/STRIP	Necessary	210.32 FL	*210.32 FL
9	1		*FRONT DOOR SEAL	Necessary	112.30 FL	*112.30 FL
10	1		*FRONT DOOR INSULATION	Necessary	141.35 FL	*141.35 FL
11	1		*FRONT DOOR CHECKER	Twisted	89.95 FL	*89.95 FL
12	1		*FRONT DOOR PILLAR - RH	Repair	895.60 FL	*- FL
13	1		*FRONT FENDER - RH	Repair	641.35 FL	*- FL
14	2		*FRONT DOOR HINGES	Twisted	173.00 FL	*173.00 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,622.65</b>	<b>3,305.15</b>
<b>- List Item Discount on L Items 5.00/5.00% (\$\$)</b>	<b>281.13</b>	<b>165.26</b>
<b>Total Parts (\$\$)</b>	<b>5,341.52</b>	<b>3,139.89</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK FRONT ELECTRICAL WIRING.	New	50.00	20.00
2	TO RESPRAY UNDERCOATING	New	80.00	50.00
3	TO RESPRAY PAINTING AND ETC.	New	800.00	680.00
4	PANEL BEATING, CUT, WELD REMOVE & REPLACING ABOVE PARTS.	New	800.00	500.00
<b>Gross Labour Cost (S\$)</b>			<b>1,730.00</b>	<b>1,250.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >