

22/03/2002

ASS. REC. BY:

REF: CS/AIG 19006849/ Ccd3/7

Special Instruction:

Suivador:

Steve

ASSIGNMENT (Office)

maining

From (Person): Har Yinru

of

AIG

Date/Time: 17.4.2019 3.49pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJW 1386R

Insured: SJD 6659x

at Workshop m/s Guan Auto

Tel: 9388 4210

of BIK 7 sm ming Industrial Sector C #01-82

Policy No:

Claim No:

523141702286

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 15.4.2019

18.4.2019

CA / REV / REP. / REV 24 HRS

"wp"

H.O.D. Endorsement:

Date/Time: 17.4.2019 4.09pm

Person Contacted:

Jacky

Vehicle IN/OUT

Date/Time

Action/Instruction ( X ) Estimate

SJW 1386R - x

SJD 6659x - CS/AWA 15013665/ Avbn

Dismantle: 22/4/2019

PRS

# ASSIGNMENT

From:

Date: 18.4.2019

Estimated Cost:

OD / (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJW 1386R

at Workshop m/s Guan Auto Services

of BIK 7 Sn ming Industrial Sector C 401-82

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS "wp"

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SJW 1386R

Yr Regn: 30/5/16

Type: (M) Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Shuttle

C.C. 1496

Colour: white

A/C: Insured / Std / NI / NA

Sp. Reading: 99698

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

GK8-1004212

Gen. Cond: (Good) / Fair / Poor / Burnt

Steering: (In order) / Jammed / Leaked / Burnt or

Brake: (In order) / Jammed / Leaked / Burnt or

Modi: Nil / (S) Rim / STD A/Rim or

Tyre Size: F:

185/60R15

R:

17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / (YOKO) or

Front

Rear

R/Bal. 7 mm

R/Bal. 7 mm

L/Bal. 7 mm

L/Bal. 7 mm

D.O.A.

D.O.I. 18/4/19

Survey held at

Guan Auto

Des. of Damages: Frt / (Rear) / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

repair day - 6

RECEIVED 26 APR 2019

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

\_\_\_ S + RS, \_\_\_ SI

Photos

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Report Format : DAR

Lump Sum / I.B.I.: (\$

180

10

190

**PRE-REPAIR INSPECTION REQUEST – SJW1386R vs SJD6659X (OI) on D.O.A.: 15/04/2019**

From: Hor, Yinrul  
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)  
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur  
Sent: Wednesday, 17 April, 2019 3:49:31 PM  
Attachments:  tmp2A41.tif

---

Hi,

Please refer to the enclosed request from **Daniel Poon & Co.**

Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Thanks & Regards,

Yin Rul, Hor (Viviane)

**AIG**

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

[Yinrul.Hor@aig.com](mailto:Yinrul.Hor@aig.com) | [www.aig.sg](http://www.aig.sg)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**Daniel Poon & Co.**Advocates & Solicitors  
Commissioners for OathsDaniel Poon Choon Kow  
LL.B. (Hons), LL.M133 New Bridge Road  
#11-02 Chinatown Point  
Singapore 059413  
Tel: +65 6227-2469  
Fax: +65 6225-2579  
Email: law@dpco.com.sg  
(UEN: 53130838C)

Our Ref: DP.sl.isk.10922.19.GA  
Your Ref: -----  
Please quote our reference number when replying

Date: 17 APRIL 2019

M/S AIG ASIA PACIFIC INSURANCE PTE. LTD.  
AIG BUILDING  
78 SHENTON WAY  
#08-16  
SINGAPORE 079120  
ATTN: MOTOR CLAIMS DEPARTMENT

FAX (6835-7416) ONLY

DEAR SIRs,

**PRE-REPAIR INSPECTION**

**YOUR INSURED VEHICLE REGISTRATION NO: SJD 6659X  
ACCIDENT ON 15 APRIL 2019 INVOLVING SJW 1386R AND SJD 6659X  
AT SLIP ROAD OF ALEXANDRA ROAD TOWARDS AYE (TUAS)**

We are instructed by Foo Yi Suenn to notify you of a road traffic accident on 15<sup>th</sup> April 2019 at about 18:25 at slip road of Alexandra Road towards AYE (Tuas) involving our client's vehicle registration number SJW 1386R and vehicle registration number SJD 6659X driven by your insured at the material time. A copy of the Singapore accident statement /traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair inspection of the vehicle, by the attached list of six (06) surveyor which our client deemed suitable to be appointed.

If the aforesaid is not agreeable, kindly therefore instruct your appointed surveyor for a pre-repair inspection of our client's vehicle at by making a prior appointment with the repairer stated below:-

M/S GUAN AUTO SERVICES  
BLK 7 SIN MING INDUSTRIAL ESTATE SECTOR C  
#01-82  
SINGAPORE 575642  
ATTN: JACKY (9388-4210)

... 2/-

Page 2

Date: 17<sup>th</sup> April 2019


Messrs Daniel Poon & Co.

Our Ref: DP.sl.isk.10922.19.GA

---

If we do not receive any agreement from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully,

A handwritten signature in black ink, appearing to be 'M/S Guan Auto Service'.

c.c. M/S GUAN AUTO SERVICE

FAX (6451-1706) ONLY

**NAME OF MOTOR SURVEYOR**

- 1) HOW ANDREW (PROMINENT APPRAISER SERVICES)
- 2) LEE KOK WENG (LEE AUTOMOBILE APPRAISERS SERVICES)
- 3) NG SOON AIK FRANCIS (PRESTIGE APPRAISER SERVICES)
- 4) ONG AH KENG, KENT (KTO AUTOMOBILE ASSESSORS)
- 5) ONG POH MENG (AEON AUTO CONSULTANTS LLP)
- 6) LKK AUTO CONSULTANTS PTE LTD

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	3147F
<b>Vehicle Details</b>	
Vehicle No.:	SJW1386R
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Apr 2019
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE 1.5G CVT ABS D/AIRBAG 2WD 5DR
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	L15B3534971
Chassis No.:	GK81004212
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$18,059.00
Original Registration Date:	30 May 2016
First Registration Date:	30 May 2016
Transfer Count:	0
Actual ARF Paid:	\$8,059.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 May 2026
PARF Rebate Amount:	\$6,044.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	29 May 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,020.00
COE Rebate Amount:	\$33,394.00
<b>Total Rebate Amount:</b>	<b>\$39,438.00</b>

The information contained herein is correct as at 22 Apr 2019

OK

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3147F
Vehicle Details	
Vehicle No.:	SJW1386R
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Apr 2019
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE 1.5G CVT ABS D/AIRBAG 2WD 5DR
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	L15B3534971
Chassis No.:	GK81004212
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$18,059.00
Original Registration Date:	30 May 2016
First Registration Date:	30 May 2016
Transfer Count:	0
Actual ARF Paid:	\$8,059.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 May 2026
PARF Rebate Amount:	\$6,044.00
Intended COE Rebate Details	
COE Expiry Date:	29 May 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,020.00
COE Rebate Amount:	\$33,394.00
<b>Total Rebate Amount:</b>	<b>\$39,438.00</b>

The information contained herein is correct as at 22 Apr 2019

OK



**Das WeltAuto.**  
Used cars you can trust. Guaranteed.

**Low on mileage. High on savings.**



**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

**Classic Promo! Best Deal! Fast Selling! Hurry Down Now!**



Flexible Loan. Trade In Are  
Welcome. 100% Deposit Refund  
For Unapproved Loan.  
Classic Credit StarAd



Browse by Category ▼

Sort by Date Posted ▼

20 results/page ▼

6 vehicles

Honda Shuttle

[Advanced Search](#)

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection

Honda Shuttle

Any

Any


2016

Any

Any

Any

Available



Honda Shuttle 1.5A G

\$59,800

\$7,830 /yr

16-May-2016

1,496 cc

-


Stationwagon

Available

Owner Upgrade To MPV, Excellent Condition. Accident Free, Elegance White Orchid Pearl, Pioneer DVD Player With Bluetooth, Parking Sensor/Camera & Dashboard View Cam. Super Fuel Consumption, Low Mainte...

Posted: 21-Mar-2019

Tags: 2016 Honda Shuttle, 2016 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda



Honda Shuttle 1.5A G

\$65,800

\$8,660 /yr

17-Jun-2016

1,496 cc

28,000 km

Stationwagon


Available

1 Owner Unit, In Excellent Pristine Condition. Low Mileage Done! Drive & Smell Like Brand New Car With Spacious Booth & Seating. Super Fuel Efficient Yet Reliable! Non Rental Unit Assured! Guaranteed ...

Creative Auto

Posted: 21-Apr-2019

Tags: 2016 Honda Shuttle, 2016 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda



Honda Shuttle 1.5A G

\$64,800

\$8,420 /yr

07-Jul-2016

1,496 cc

-

Stationwagon


Available

1 Owner Unit, In Excellent Condition. Kept In Good Condition. Spacious, Fuel Efficient And Reliable! Bank Loan Or High Loan Available! Contact Us Before This Unit Is Sold!

Car Times Automobile Pte Ltd

Posted: 21-Apr-2019

Tags: 2016 Honda Shuttle, 2016 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda



Honda Shuttle Hybrid 1.5A

\$69,800

\$8,980 /yr

19-Oct-2016

1,496 cc

31,113 km

Stationwagon


Available

Fuel Type: Petrol-Electric

Most Fuel Saving In It's Class! Well Maintained By Previous Owner, Low Mileage, Flexible Loan Available, Trade- In Welcome. View Now!

Posted: 04-Apr-2019


Tags: 2016 Honda Shuttle, 2016 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda



Bentley launches new Continental GT V8

Bentley is introducing two new versions of its third generation Continental GT and GT Convertible with new V8 powerplants.

Find out more!



Honda Shuttle 1.5A G

\$67,800

\$8,450 /yr

20-Oct-2016

1,496 cc

55,000 km

Stationwagon


Available

01 Owner! AA Trust Certified Quality 1 Owner Vehicle! Extremely Well Maintained By 1 Owner. 100% Accident Free. Tastefully Wrapped Up With Candy Blue. Spacious And Comfortable. Serviced And Maintained...

AA Trust Automotive

Posted: 19-Apr-2019

Tags: 2016 Honda Shuttle, 2016 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda



Honda Shuttle 1.5A G

\$66,500

\$8,090 /yr

19-Dec-2016

1,496 cc

42,300 km

Stationwagon

Available

1 Fussy Owner, Low Mileage Done. Accident Free, Conditions Like New Car. Fuel Economical, Spacious. Loan/ Trade In Available. Call Our Friendly Sales Consultant Today To Avoid Disappointment.

Compare

Posted: 20-Apr-2019

Tags: 2016 Honda Shuttle, 2016 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda

[Compare](#)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	16/04/2019 17:31
Date Of Accident	15/04/2019 18:25
Exact Location Of Accident	ALEXANDRA RD GOING INTO AYE SLIP RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJW1386R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	FOO YI SUENN
NRIC No	S6843147F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97619533
Alternative Phone No	OFFICE-97619533

### Vehicle Particulars

Manufacturer	HONDA
Model	SHUTTLE
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA206432
Cover Note Number	

### Driver

Name of Driver	FOO YI SUENN
NRIC No	S6843147F
Date Of Birth	08/11/1968
Occupation	INDOOR
Date Of Driving Pass	27/03/1999
Driving Experience	20 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97619533
Fax Number	
Contact Number	OFFICE-97619533
Email Address	NOEMAIL

Address -  
 Postcode -  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 2  
 Passenger 1  
 NAME: : PASSENGER  
 GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

refer attached report.

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJD6659X  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver TAN CHORH CHUAN  
 NRIC/Passport Number S1351693F  
 Contact Number 90260066  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purpose(s); and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purpose(s).
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 16/04/2019


Driver's Signature

(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature

Name:  
NRIC/FIN No.:

SKETCH PLAN



Vehicle  
A: SJW 1386R  
Vehicle  
B: SJD 6659X

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My Vehicle SJW 1386 was at a full stop at the turn (left) going into the Slip Road towards AYE (TUAS) from Alexandra when it was Collided from behind by Vehicle SJD 6659X.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time: 16/04/2019

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



redefining insurance

Date:

16/04/2019

To: Owner of Vehicle Number:

SJW 1386R

The following has been advised to you via your workshop, S & H Motor through their staff, Mr Wong.

Please tick the applicable box if you had been advice on the content as seen below:

- ☒ You had been advised by the workshop that in the case that you wish to claim against your own policy, there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.
- ☒ You had been advised by the workshop on the liability and merits of the case accordingly.
- ☒ You had been advised by the workshop on the claims procedure for the type of claim that you will be making due to this accident.
- ☒ There will be delay to your vehicle repair due to the unavailability of spare parts locally and there is no other option except to indent it from overseas.
- ☒ There will be no cancellation/withdrawal of the Own Damage claim once the order of the spare parts have been placed. If you wish to cancel/withdraw the claim, you shall bear all costs, expenses &/or related charges incurred directly &/or indirectly to the procurement of the spare parts.
- ☐ The estimated waiting time for the spare parts to arrive is \_\_\_\_\_. The estimated arrival time does not include the repair period.
- ☐ You will be driving the vehicle out despite being advised by the workshop mechanic/personnel that the vehicle may not be road worthy.
- ☒ For vehicles below Three (3) years old, your Insurance Company will use only genuine original parts to repair your vehicle.
- For vehicles above Three (3) years old, your Insurance Company will be carrying out repairs using **any combination** of genuine original parts and/or original equipment manufacturer (OEM) parts.
- ☒ You had been advised by the workshop of the Twelve (12) months warranty for Own Damage repairs on workmanship related to the accident.
- ☒ For vehicles that are under warranty with a local distributor, you have been advised by the workshop to check with your local distributor on any effect to your warranty prior to making this Own Damage claim.
- ☐ Others \_\_\_\_\_

Signed and acknowledge by:

FOO YI SUEN

Name and signature of policyholder/authorised driver

Name and signature of workshop personnel including company stamp



## Condition (CON)

(01)Dent (2)Distorted (3)Cracked (4)Cracked (5)Cut (6)Scratched  
(07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary  
(12)Missing (13)Torn (14)Unconfirmed (15)Not Working

## MOTORCAR (Rear)

(1)Replace (✓) (2)Repair(X) (3)Check (✓)  
(4)Not Consistent (NC)

Vehicle No:

SJW 1386 R

## Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish	CR	✓	
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DD	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	ALC	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	RR	✓	2
1149	993045	Rear Bumper Reinforcement	DD	✓	
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge	RR	✓	
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	RR	✓	
1159	993327	Rear End Panel	DD	✓	
1160	993339	Rear End Panel Top Garnish	RR	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	DD	✓	
1182	991328	Tailgate Emblem	ALC	✓	2
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish Trim board	CR	✓	
1186	994648	Tailgate Reflector Pull handle	CR	✓	
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding	NEC	✓	
1196	994607	Tailgate Glass Sealant	NEC	✓	
1197	994629	Tailgate Lock	DD	✓	
1198	994651	Tailgate Rubber	CR	✓	
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover	CR	✓	
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993491	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			
		Reverse Camera			

23/4/2017

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Apr 2019 <a href="#">Edit Reg</a>		17 Apr 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>\$0.00</b> <a href="#">Edit Estimates</a>	<b>\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<b>Show All</b>
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:

- , Co. Reg. No.: -

Main Claimant:

FOO YI SHUEN, ID: S6843147F

Vehicle Reg. No.:

SJW1386R

Date of Loss:

15/04/2019 18:00 - :59  
[34 Months and 16 Days From LTA Reg Date (Man Yr)]

Claim Type:

TP / 5231417022SG

Policy/Cover Note No.:

2100406820-04 (Comprehensive)

Vehicle Reg. No. (Insured):

SJD6659X

Policy No. (Claimant):

Excess:

Repairer:

Guan Auto Service (Sin Ming) Block 7 Sin Ming Industrial Estate Sector C, #01-80/ # 01-82, 575642 Sin Ming - Tel: 93884210

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 29/04/2019]

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

- AIG\_SG (18/04/2019): Request to upload TP GIA REPORT
- AIG\_SG (18/04/2019): NO OI GIA REPORT

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete





































Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*SJW1386R (5231417022SG)**  
**[SJD6659X]**  
**TP**  
**FOO YI SHUEN**  
**Apr 15 2019 6:20PM**  
**[-]**  
**Guan Auto Service**

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Photos/Images											3 per page		<input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print	
1	22/04/19 09:21	General View										Load JPG	<input checked="" type="checkbox"/>	
2	22/04/19 09:21	General View										Load JPG	<input checked="" type="checkbox"/>	
3	22/04/19 09:21	General View										Load JPG	<input checked="" type="checkbox"/>	
4	22/04/19 09:21	General View										Load JPG	<input checked="" type="checkbox"/>	
5	22/04/19 09:21	General View										Load JPG	<input checked="" type="checkbox"/>	
6	22/04/19 09:21	General View										Load JPG	<input checked="" type="checkbox"/>	
7	22/04/19 09:21	General View										Load JPG	<input checked="" type="checkbox"/>	
8	22/04/19 09:21	General View										Load JPG	<input checked="" type="checkbox"/>	
9	22/04/19 09:21	General View										Load JPG	<input checked="" type="checkbox"/>	
10	22/04/19 09:21	General View										Load JPG	<input checked="" type="checkbox"/>	
11	22/04/19 09:21	General View										Load JPG	<input checked="" type="checkbox"/>	
12	22/04/19 09:21	General View										Load JPG	<input checked="" type="checkbox"/>	
13	22/04/19 09:21	General View										Load JPG	<input checked="" type="checkbox"/>	
14	22/04/19 09:21	General View										Load JPG	<input checked="" type="checkbox"/>	
15	22/04/19 09:21	General View										Load JPG	<input checked="" type="checkbox"/>	
16	22/04/19 09:21	General View										Load JPG	<input checked="" type="checkbox"/>	
17	22/04/19 09:21	General View										Load JPG	<input checked="" type="checkbox"/>	
18	22/04/19 09:21	General View										Load JPG	<input checked="" type="checkbox"/>	
19	22/04/19 09:21	General View										Load JPG	<input checked="" type="checkbox"/>	
20	22/04/19 09:21	General View										Load JPG	<input checked="" type="checkbox"/>	
21	22/04/19 09:21	General View										Load JPG	<input checked="" type="checkbox"/>	
22	22/04/19 09:21	General View										Load JPG	<input checked="" type="checkbox"/>	
23	22/04/19 09:21	General View										Load JPG	<input checked="" type="checkbox"/>	
24	22/04/19 09:21	General View										Load JPG	<input checked="" type="checkbox"/>	
25	22/04/19 09:21	General View										Load JPG	<input checked="" type="checkbox"/>	
26	22/04/19 09:21	General View										Load JPG	<input checked="" type="checkbox"/>	
27	22/04/19 09:21	General View										Load JPG	<input checked="" type="checkbox"/>	
28	22/04/19 09:21	General View										Load JPG	<input checked="" type="checkbox"/>	
29	22/04/19 09:21	General View										Load JPG	<input checked="" type="checkbox"/>	
30	22/04/19 09:21	General View										Load JPG	<input checked="" type="checkbox"/>	
31	22/04/19 09:21	General View										Load JPG	<input checked="" type="checkbox"/>	
32	22/04/19 09:21	General View										Load JPG	<input checked="" type="checkbox"/>	
33	22/04/19 09:21	General View										Load JPG	<input checked="" type="checkbox"/>	
34	22/04/19 09:21	General View										Load JPG	<input checked="" type="checkbox"/>	
35	22/04/19 09:21	General View										Load JPG	<input checked="" type="checkbox"/>	
36	22/04/19 09:21	General View										Load JPG	<input checked="" type="checkbox"/>	
37	22/04/19 09:21	Odometer Reading										Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	22/04/19 09:21	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
39	26/04/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	26/04/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	26/04/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	26/04/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	26/04/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	26/04/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	26/04/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	26/04/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	26/04/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	26/04/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	26/04/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	26/04/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	26/04/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	26/04/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	26/04/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	26/04/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	26/04/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	26/04/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	26/04/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	26/04/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	26/04/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	26/04/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	26/04/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	26/04/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	26/04/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	26/04/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	26/04/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	26/04/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	26/04/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	26/04/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	26/04/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	26/04/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	26/04/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	26/04/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	26/04/19 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19006849/ECD3E2

Date: 14/05/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100406820-04  
**Claimant Vehicle No :** SJW1386R **Insured Vehicle No :** SJD6659X  
 Date of Loss: 15/04/2019 Nature of Claim: TP Claim No: 5231417022SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SJW1386R**  
 Make & Model: HONDA SHUTTLE, 1.5 (A) Engine No: L15B3534971  
 Reg. Date: 30/05/2016 (Man. Year: 2015) Chassis No: GK81004212  
 Colour: White Odometer: 99698 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (\$\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15  
 Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 7 mm  
 Front Right Side: Yokohama 7 mm Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 17/04/2019  
 Date Inspected: 18/04/2019 Inspected At: Guan Auto Service (Sin Ming)  
 Block 7 Sin Ming Industrial Estate Sector  
 C, #01-80/ # 01-82  
 Singapore 575642  
 Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE GARNISH	Cut	0.00 F	*- F
2	1		*REAR BUMPER	Dented	0.00 F	*- F
3	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	2		*REAR BUMPER SIDE RETAINER	Broken	0.00 F	*- F
5	1		*REAR BUMPER REINFORCEMENT	Dented	0.00 F	*- F
6	1		*REAR BUMPER SPONGE	Broken	0.00 F	*- F
7	1		*REAR BUMPER REFLECTOR	* Check	0.00 F	*- F
8	1		*REVERSE SENSOR	Broken	0.00 F	*- F
9	1		*REAR END PANEL	Dented	0.00 F	*- F
10	1		*REAR END PANEL TOP GARNISH	Crushed	0.00 F	*- F
11	1		*REAR LH TAILLAMP	* Check	0.00 F	*- F
12	1		*REAR RH TAILLAMP	* Check	0.00 F	*- F
13	1		*BOOTLID LAMP LH	* Check	0.00 F	*- F
14	1		*BOOTLID LAMP RH	* Check	0.00 F	*- F
15	1		*TAILGATE	Dented	0.00 F	*- F
16	2		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
17	1		*TAILGATE TRIM BOARD	Crushed	0.00 F	*- F
18	1		*TAILGATE PULL HANDLE	Crushed	0.00 F	*- F
19	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
20	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
21	1		*TAILGATE LOCK	Dented	0.00 F	*- F
22	1		*TAILGATE RUBBER	Crushed	0.00 F	*- F
23	1		*SPARE TYRE COVER	Cut	0.00 F	*- F
24	1		*REVERSE CAMERA	* Check	0.00 F	*- F

F=Franchise part.

<b>Total Parts (S\$)</b>	<b>0.00</b>	<b>0.00</b>
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >