

ASS. REC. BY:

REF:

03/11619006851/Gcd302

Special Instruction:

SW/VEH/

GWD Diang

ASSIGNMENT (Office)

From (Person):

chin lee ying

of

AIG

Date/Time:

17/4/19 @ 10:35am

Estimated Cost:

Bill to:

OD / TP / WS / TT RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SY 5821P

Insured:

SCJ 705L

at Workshop m/s:

Prestige Auto

Tel:

90210057

of

Blk 3023A ubi Rd Y # 0164

Policy No:

Claim No:

8083406285SG

Sum Insured:

Excess:

Make of Vch:

D.O.A

4/4/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:33am @ 17/4/19

Person Contacted:

Mr. Ten

Vehicle

IN

OUT

Date/Time

Action/Instruction (X) Estimate

SY 5821P-X

SCJ 705L - 03/11619006327 / ASD3

Est: 4/4/19

Diamondite: 18/4/2019

After repair: 22/4/2019

REF: AIG

ASSIGNMENT

From: _____ Date: 17/4/19

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJY 5821P

at Workshop m/s: Prestige Auto

of Blk 3023A Ubi Rd 1 #01-64

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: After / pm

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 1up

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJY 5821P Yr Regn: Sep, 10Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA Sorento 2.4 c.c 2359Colour: Brown A/C: Insured / Std / NI / NASp. Reading: 127858 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAKU 811MA 5082 796Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235 / 65 R17R: 11BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 17-04-19Survey held at w/s 4pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

24 O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Preli. Report☐ : Final ReportDays Of Repair: 4Resurvey No. of Trip: 2Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

Report Format: DAR

Lump Sum / I.B.I.: (\$ _____)

180

10

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 17/4/2019 10:38:01 AM
Attachments:  SJY5821P vs SCJ705L.PDF

Hi LKK,

Kindly assist to survey on this afternoon.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

CATHERINE LIM LLC

林 林 ADVOCATES & SOLICITORS
翠 NOTARY PUBLIC - 公证官
玲 COMMISSIONER FOR OATHS - 宣誓官
律
陈 CATHERINE C.L. LIM
馆 DIRECTOR
LL.B (HONS) SINGAPORE - 法律系 - 律师
M.B.A. (BUSINESS LAW) - 商业系 - 硕士

20 Havelock Road #03-01
Central Square Singapore 059765
UEN No. 201310922K

Tel: (65) 6438 5500
Fax: (65) 6438 0111
www.catherinelimllc.com
Email: info@catherinelimllc.com
CATHERINE LIM LLC is a law corporation
with limited liability

Your Ref: SCJ 705L
Our Ref: CL/190432/1/PA.sg

15 April 2019

AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way
#07-16
Singapore 079120
Attn: Motor Claims Department

via fax: 6415 3727 & By Hand

Lee Kwong Seng
317 Bukit Timah Road
#12-317
Singapore 259711

CERTIFICATE OF POSTING
(Please be informed that all supporting documents
have been forwarded to your insurer.)

Dear Sir

**RE: NOTICE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO
PRE-ACTION PROTOCOL FOR NON-INJURY MOTOR ACCIDENT CLAIMS (NIMA)**

**ACCIDENT INVOLVING SJY 5821P / SCJ 705L ON 4.4.2019 ALONG BALMORAL ROAD / BUKIT
TIMAH ROAD**

We are instructed by **Chang Lee Saleem Jan** to notify you of a road traffic accident involving our client's vehicle No. SJY 5821P and vehicle No. SCJ 705L driven by you at the material time. A copy of the Singapore Accident Statement and or Police Report is enclosed.


As a result of the accident, our client's motor vehicle has been damaged. Before our client proceed to repair the damaged motor vehicle, please let us know within 2 working days of your receipt of this notice whether you/your insurer would like to conduct a pre-repair survey of the motor vehicle. If we do not receive any reply from you/your insurer within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please let us know your appointed surveyor.

Venue: Prestige Auto
3023A Ubi Road 1
#01-64 S(408717)

Chong Hpi: 9021 0057 Fax: 6842 3217

Yours faithfully,


cc: clients

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0789I
Vehicle Details	
Vehicle No.:	SJY5821P
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Apr 2019
Vehicle Make:	KIA
Vehicle Model:	SORENTO 2.4L EX AT ABS D/AB 2WD 5DR
Primary Colour:	Brown
Manufacturing Year:	2010
Engine No.:	G4KEAH714816
Chassis No.:	KNAKU811MA5082796
Maximum Power Output:	128.0 kW (171 bhp)
Open Market Value:	\$21,024.00
Original Registration Date:	16 Sep 2010
First Registration Date:	16 Sep 2010
Transfer Count:	1
Actual ARF Paid:	\$21,024.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Sep 2020
PARF Rebate Amount:	\$11,563.00
Intended COE Rebate Details	
COE Expiry Date:	15 Sep 2020
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$41,010.00
COE Rebate Amount:	\$4,995.00
Total Rebate Amount:	\$16,558.00

The information contained herein is correct as at 25 Apr 2019

OK

MRQH19044820-01 / K Kim Hin Auto Pte Ltd - HQ
ENTRY DATE & TIME: 06/04/2019 13:20
SUBMITTED BY: Sandra Khong Yee Teng

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 06/04/2019 13:20
Date Of Accident 04/04/2019 22:30
Exact Location Of Accident BALMORAL ROAD / BUKIT TIMAH ROAD
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJY5821P
~~Insured Policyholder~~
Name Of Registered Owner CHANGEZ SALEEM JAN
NRIC No S7260789I
Email Address CHANGEZJAN@GMAIL.COM
Mobile Phone No (LOCAL) +65-91286801
Alternative Phone No OFFICE-91286801

~~Vehicle Details~~
Manufacturer KIA
Model SORENTO-2.4 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

~~Insurance Company~~
Name of Insurance Company AXA INSURANCE PTE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number GA105712

Cover Note Number

~~Driver Details~~
Name of Driver CHANGEZ SALEEM JAN
NRIC No S7260789I
Date Of Birth 06/09/1972
Occupation INDOOR
Date Of Driving Pass 28/01/2008
Driving Experience 11 YEARS AND 2 MONTHS
Gender MALE
Mobile Number +65-91286801
Fax Number
Contact Number OFFICE-91286801
Email Address CHANGEZJAN@GMAIL.COM

Address 2C BALMORAL CRESCENT
 Postcode 259884
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - CROSS JUNCTION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 3
 Passenger 1
 NAME: : SARA AI
 GENDER: : FEMALE
 Passenger 2
 NAME: : MEER
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachments

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SCJ705L
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver SEAN LEE JUNN KIT
 NRIC/Passport Number S91233148
 Contact Number
 Address
 Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (c) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time

Driver's Signature
(if driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name
NOC/TIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

② WAS DRIVING ON BALMORAL ROAD TOWARDS BRKIF
TIMAH ON A GREEN LIGHT. THE OTHER VEHICLE
FACE FACING THE OPPOSITE DIRECTION AND WANTING
TO MAKE A RIGHT TURN. HE DID NOT WAIT FOR
LIGHT TO TURN GREEN AND DROVE ON AND HIT
MY FRONT RIGHT SIDE.
HE ADMITTED HIS FAULT.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:
Company Chop (if applicable)

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate	BT	/	
1002	991887	Frt Number Plate Base	CRA	/	
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	RE	/	
1005	992341	Frt Bumper Clips	RG	/	
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer	RE	/	
1008	991433	Frt Bumper Reinforcement	BT	/	
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge	CRA	/	
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover	CRA	/	
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp	SCR	/	
1021	991793	Frt Grille	CRA	/	
1022	991328	Frt Grille Emblem	RG	/	
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel	CRA	/	
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy Bracket	CRA	/	
1030	991821	Frt RH Headlamp Assy	CRA	/	
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser	BT	/	
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

Vehicle No:

SIY5821P

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank	RE	/	
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender	Repair		
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector	RG	/	
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Apr 2019 Edit Reg		17 Apr 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	LEE KWONG SENG, ID: S1450102I		
Main Claimant:	CHANGEZ SALEEM JAN, ID: S7260789I		
Vehicle Reg. No.:	SJY5821P	Date of Loss:	04/04/2019 22:00 - :59 [102 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 8083406285SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SCJ705L	Policy No. (Claimant):	
		Excess:	
Repairer:	Prestige Motor Pte Ltd (HQ) 3023A UBI ROAD 1, #01-64, 408717 Ubi - Tel: 90210057		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 29/04/2019]		
Claimant's Solicitor:	CATHERINE LIM LLC - Tel: 6438 5500		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (18/04/2019): Request to upload TP GIA REPORT

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)






























Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJY5821P (8083406285SG)**
[SCJ705L]

TP
CHANGEZ SALEEM JAN
Apr 4 2019 10:00PM
[LEE KWONG SENG]
Prestige Motor Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Photos/Images												3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail	Print
1	24/04/19 09:47	General View											Load JPG	<input checked="" type="checkbox"/>
2	24/04/19 09:47	General View											Load JPG	<input checked="" type="checkbox"/>
3	24/04/19 09:47	General View											Load JPG	<input checked="" type="checkbox"/>
4	24/04/19 09:47	General View											Load JPG	<input checked="" type="checkbox"/>
5	24/04/19 09:47	General View											Load JPG	<input checked="" type="checkbox"/>
6	24/04/19 09:47	General View											Load JPG	<input checked="" type="checkbox"/>
7	24/04/19 09:47	General View											Load JPG	<input checked="" type="checkbox"/>
8	24/04/19 09:47	General View											Load JPG	<input checked="" type="checkbox"/>
9	24/04/19 09:47	General View											Load JPG	<input checked="" type="checkbox"/>
10	24/04/19 09:47	General View											Load JPG	<input checked="" type="checkbox"/>
11	24/04/19 09:47	General View											Load JPG	<input checked="" type="checkbox"/>
12	24/04/19 09:47	General View											Load JPG	<input checked="" type="checkbox"/>
13	24/04/19 09:47	General View											Load JPG	<input checked="" type="checkbox"/>
14	24/04/19 09:47	General View											Load JPG	<input checked="" type="checkbox"/>
15	24/04/19 09:48	General View											Load JPG	<input checked="" type="checkbox"/>
16	24/04/19 09:48	General View											Load JPG	<input checked="" type="checkbox"/>
17	24/04/19 09:48	General View											Load JPG	<input checked="" type="checkbox"/>
18	24/04/19 09:48	General View											Load JPG	<input checked="" type="checkbox"/>
19	24/04/19 09:48	General View											Load JPG	<input checked="" type="checkbox"/>
20	24/04/19 09:48	General View											Load JPG	<input checked="" type="checkbox"/>
21	24/04/19 09:48	General View											Load JPG	<input checked="" type="checkbox"/>
22	24/04/19 09:48	General View											Load JPG	<input checked="" type="checkbox"/>
23	24/04/19 09:48	General View											Load JPG	<input checked="" type="checkbox"/>
24	24/04/19 09:49	Odometer Reading											Load JPG	<input checked="" type="checkbox"/>
25	24/04/19 09:49	Chassis Number											Load JPG	<input checked="" type="checkbox"/>
26	24/04/19 09:50	Dismantled Parts											Load JPG	<input checked="" type="checkbox"/>
27	24/04/19 09:50	Dismantled Parts											Load JPG	<input checked="" type="checkbox"/>
28	24/04/19 09:50	Dismantled Parts											Load JPG	<input checked="" type="checkbox"/>
29	24/04/19 09:50	Dismantled Parts											Load JPG	<input checked="" type="checkbox"/>
30	24/04/19 09:50	Dismantled Parts											Load JPG	<input checked="" type="checkbox"/>
31	24/04/19 09:50	Dismantled Parts											Load JPG	<input checked="" type="checkbox"/>
32	24/04/19 09:50	Dismantled Parts											Load JPG	<input checked="" type="checkbox"/>
33	24/04/19 09:50	Dismantled Parts											Load JPG	<input checked="" type="checkbox"/>
34	24/04/19 09:50	Dismantled Parts											Load JPG	<input checked="" type="checkbox"/>
35	24/04/19 09:50	Dismantled Parts											Load JPG	<input checked="" type="checkbox"/>
36	24/04/19 09:50	Dismantled Parts											Load JPG	<input checked="" type="checkbox"/>
37	24/04/19 09:50	Dismantled Parts											Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	24/04/19 09:50	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
39	24/04/19 09:50	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	24/04/19 09:50	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	24/04/19 09:50	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	24/04/19 09:50	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	24/04/19 09:50	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	24/04/19 09:50	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	24/04/19 09:50	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	24/04/19 09:50	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	24/04/19 09:50	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	24/04/19 09:50	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	24/04/19 09:50	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	24/04/19 09:50	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	24/04/19 09:50	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	24/04/19 09:50	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	24/04/19 09:50	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	24/04/19 09:50	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
55	24/04/19 09:50	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
56	24/04/19 09:50	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
57	24/04/19 09:50	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
58	24/04/19 09:50	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
59	24/04/19 09:50	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
60	24/04/19 09:50	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
61	24/04/19 09:50	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	24/04/19 09:50	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	24/04/19 09:50	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	24/04/19 09:50	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	24/04/19 09:50	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	18/04/19 09:34	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19006851/GCD3E2

Date: 14/05/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SJY5821P

Insured Vehicle No : SCJ705L

Date of Loss: 04/04/2019

Nature of Claim: TP

Claim No: 8083406285SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJY5821P

Make & Model: KIA SORENTO, 2.4 (A)

Engine No: G4KEAH714816

Reg. Date: 16/09/2010 (Man. Year: 2010)

Chassis No: KNAKU811MA5082796

Colour: Brown

Odometer: 127858 km

Engine Capacity: 2359 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/65 R17

Rear Tyre Size: 235/65 R17

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 17/04/2019

Date Inspected: 17/04/2019

Inspected At:

Prestige Motor Pte Ltd (HQ)
3023A UBI ROAD 1, #01-64
Singapore 408717

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Bent	0.00 F	*- F
2	1		*FRT NUMBER PLATE BASE	Cracked	0.00 F	*- F
3	1		*FRT BUMPER	Deformed	0.00 F	*- F
4	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
5	1		*FRT BUMPER SIDE RETAINER RH	Necessary	0.00 F	*- F
6	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*- F
7	1		*FRT BUMPER SPONGE	Cracked	0.00 F	*- F
8	1		*FRT RH BUMPER FOG LAMP COVER	Cut	0.00 F	*- F
9	1		*FRT RH BUMPER FOG LAMP	Scratched	0.00 F	*- F
10	1		*FRT GRILLE	Cracked	0.00 F	*- F
11	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
12	1		*FRT SUPPORT PANEL	Cracked	0.00 F	*- F
13	1		*FRT HEADLAMP BRACKET	Cracked	0.00 F	*- F
14	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
15	1		*AIR CON CONDENSER	Bent	0.00 F	*- F
16	1		*WIPER WASHER TANK	Deformed	0.00 F	*- F
17	1		*FRT RH FENDER	Repair	0.00 F	*- F
18	1		*FRT RH FENDER PROTECTOR	Necessary	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items -

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >