

ASS. REC. BY:

REF: CS/MSG19006853/ R1s d3/r

Special Instruction:

Surveyor: RASU

ASSIGNMENT (Office)

From (Person): Jasmine Lok

of MSIG

Date/Time: 17.4.2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FB3 1544P

Insured: SLT 1474P

at Workshop m/s Southern Motor

Tel: 627 30369

of Blk 1006 Bukit Merah Lane 2 H01-10

Policy No: A29082976 QMY

Claim No: 588853

Sum Insured:

Excess:

Make of Veh:

D.O.A. 27.3.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

rup''

H.O.D. Endorsement:

Date/Time: 17.4.19 4.40p.m

Person Contacted: Lim

Vehicle IN (OUT)

Date/Time	Action/Instruction (✓) Estimate
	FB3 1544P - NBA / MSG 19005474 / Y
	SLT 1474P - X
06/11/19	@ 17:40 pm check with Lim Guevarra, Liability from Insurance. Vehicle has not repair.

Pending

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FBJ 1544 P

Yr Regt: 2018 / July

Type: M.Cat / M.Cycl / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

YAMAHA C20300A

c.c. 292

Colour:

MULTI

A/C: Insured / Std / NI / NA

Sp. Reading:

7256

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MH3SH 0842JK 003935

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

120/70-15

R:

180/70-15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

4

mm

R/Bal:

4

mm

L/Bal:

mm

L/Bal:

mm

D.O.A:

27/03/19

D.O.L:

18/04/19

Survey held at

SOUTHERN MOTOR

Des. of Damages: Fit / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

24/04/19 @ 16:03 p.m. received PA to Jermine Lok via memo.

RECEIVED 07 NOV 2019

Date/Time, For Pass to?

1)

Date/Time, For Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$)



Prel. Report



Final Report

Prel:

Days Of Repair:

3

Resurvey No. of Trip:

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

S + M, IN

Flares

Others

TOTAL

190

11

161

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Apr 2019		17 Apr 2019 16:16 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	POH ZHI YANG, FABIAN (FU ZHIYANG), ID: S8742646G, Tel: +6591522868, Email: POH.FABIAN1@GMAIL.COM								
Main Claimant:	SYED AHMED SAUFI BIN SYED MASHOR, ID: S9400784D								
Vehicle Reg. No.:	FBJ1544P	Date of Loss:	27/03/2019 08:00 - :59 [8 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 588853	Policy/Cover Note No.:	A29082976QMY (Comprehensive) Coverage: 23/06/2018 - 28/05/2019						
Vehicle Reg. No. (Insured):	SLJ1474P	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	Southern Motor (HQ) BLK 1006 BUKIT MERAH LANE 2, #01-10, 159762 Bukit Merah - Tel: 62730369								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 18/04/2019]								
Driver/Custodian (Insured):	POH ZHI YANG, FABIAN (FU ZHIYANG) (31 / Male), NRIC: S8742646G, Tel: +6591522868 Email: POH.FABIAN1@GMAIL.COM								
Adj Asg. Remarks:	TP REQ TO ASSIGN ON 18/04/19 AFTER 10AM. LIABILITY:100%. CONTACT: 6273 0369								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 24 Apr 2019

Preliminary Advice

Insured Vehicle No	: SLJ1474P	Accident Date	: 27/03/2019
TP Vehicle No	: FBJ1544P	Assignment Date	: 17/04/2019
Make	: YAMAHA CZD300A / XMAX300	Est. Duration of Repair	: 3 days
Date of Inspection	: 18/04/2019		
Inspection At	: Southern Motor (HQ) BLK 1006 BUKIT MERAH LANE 2, #01-10 Singapore 159762		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,637.60
Revised Amount	:S\$	2,268.60
Check Items (Estimated)	:S\$	369.00
Total	:S\$	2,637.60

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/04/2019 15:28
Date Of Accident	27/03/2019 08:40
Exact Location Of Accident	ALONG NICOLL HIGHWAY TOWARDS CITY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBJ1544P
Insured/Policyholder	
Name Of Registered Owner	SYED AHMED SAUFI BIN SYED MASHOR
NRIC No	S9400784D
Email Address	SAUFIBOB@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-81182094
Alternative Phone No	OFFICE-81182094

Vehicle Particulars

Manufacturer	YAMAHA
Model	CZD300A / XMAX300-292CC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	GREAT AMERICAN INSURANCE COMPANY
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MOMVM000002957-00-000
Cover Note Number	

Driver

Name of Driver	SYED AHMED SAUFI BIN SYED MASHOR
NRIC No	S9400784D
Date Of Birth	04/01/1994
Occupation	INDOOR
Date Of Driving Pass	17/07/2013
Driving Experience	5 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81182094
Fax Number	
Contact Number	OFFICE-81182094
Email Address	SAUFIBOB@HOTMAIL.COM

Address	BLK 123 BEDOK RESERVOIR ROAD #02-1003
Postcode	470123
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	EUNOS NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 629 BEDOK RESERVOIR ROAD #01-1620 , POSTCODE: 470629 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4439999 - FAX NO: 62444376
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLJ1474P	M214 Jussurane (Singapore) Pte Ltd
Vehicle Make/Model/Colour		4 Shenan Way # 21-01
Details Of Properties		S&K Centre 2
Vehicle Category	PRIVATE CAR	Singapore 068807
Name of Driver	POH ZHI YANG FABIAN	
NRIC/Passport Number	S8742646G	TEL 62277222
Contact Number		Fax 62257802
Address		
Postcode		
Insurance Company Name		

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	SYED AHMED SAUFI BIN SYED MASHOR
Approximate Age	25
Injuries Sustain	PARTS OF LIMBS
Injured person in which vehicle?	FBJ1544P
Were seat belts worn?	NO
Was this injured conveyed to hospital by ambulance?	YES
Address	BLK 123 BEDOK RESERVOIR ROAD #02-1003
Postcode	470123

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please see/refer to Police report.
Heavy traffic flow towards Sankar City
Time: Approx 0830 HRS
Not raining, dry.

Brief Details.

On the 27/03/2019 at about 0842hrs, I was riding my motorcycle, FBJ1544P along Nicoll Highway towards City on the right most lane. I signaled left as I intended to lane switch to the second lane vehicle, SLJ1474P was on the right most lane in front of me at that time. I proceeded to lane switch and my motorcycle was on the left side of vehicle SLJ1474P. All of a sudden, SLJ1474P side swiped me and the left side of his vehicle collided onto my right side. I fell off my motorcycle as a result. I was on the floor unable to move. Hence, the driver called for ambulance. We exchanged particulars before I was conveyed to Raffles Hospital. I was warded from 27/03/2019 to 30/03/2019 and subsequently given 13 days of MC until 12/04/2019. I received a call from TP IO Zayid and he advised me to lodge a police report hence I am doing so.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Amir A. alula
14/04/19

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Stamp/Signature of Police

Police Report



**SINGAPORE
POLICE FORCE**



700 9085 02 10

Police Station Of Origin:
Centre N/P
629 Bedok Reservoir Road #01-1020
SINGAPORE 470629
Tel No: 1800-4438888

Report No: 1201095512100

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 31/03/2019 20:23			Video Report No.:		Station Diary No.: 25
Name of Informant: SYED AHMED SALFI BIN SYED MASHOR			Address: APT BLK 123 BEDOK RESERVOIR ROAD #02-1003 SINGAPORE 470123		
ID Type / ID No.: NRIC NO / S6400754D			Contact No.: Home/Office: Mobile: 81182004		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 25	Date of Birth: 04/01/1994	Type of Informant: Rider		
Race: Malay			Language: English		Institution / School Name:
Occupation: Paramedic			Driving Licence Information: Class: 2,3,2A		Date of Expiry:

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive No	Date/Time of Accident: 27/03/2019 05:40	Type of Location: Straight Road
Location: Along Road 1 NICOLL HIGHWAY				
ALONG NICOLL HIGHWAY TOWARDS CITY				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction			Anyone conveyed by ambulance: Yes	

FBJ154P	Motorcycle	YAMAHA	CZ000A / XMAX300	Grey	Slightly Damaged	0
SLJ1474P	Car	BMW	116G 5DR HATCHBACK K DSC LED	Blue		0

Police Report



**SINGAPORE
POLICE FORCE**



TAXI: 963512105

Page 3

Police Station Of Origin:
Furness NDP
620 Bedok Reservoir Road #01-1620
SINGAPORE 470626
Tel No: 1800-4430889

Report No: T201803012105

CONTINUATION OF REPORT

FBJ1544P	GREAT AMERICAN INSURANCE COMPANY	M 02012TR01483	03/07/2018	05/07/2019
----------	----------------------------------	----------------	------------	------------

Any Pedestrian Involved: No			
No. of Pedestrians Injured: Nil		Use of Pedestrian Crossing: NA	
Name	SYED AHMED SAUFI B N SYED MASHOR	ID No.	S9403784D
Related Vehicle	FBJ1544P (Motorcycle)	Contact No.	61182004
Hospital/Clinic	RAFFLES HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B.2A Date of Expiry: Nil
Date Treatment	27/03/2019	Date Discharge	30/03/2019
No. of Days granted Medical Leave	13	Degree of Injury	Serious
Name	POH ZH YAN3 FARIAN	ID No.	S8742640G
Related Vehicle	SLJ1474P (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: Nil
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 27/03/2018 at about 0812hrs, I was riding my motorcycle, FBJ1544P along Niooli Highway towards City on the right most lane. I signaled left as I intended to lane switch to the second lane vehicle, SLJ1474P was on the right most lane in front of me at that time. I proceeded to lane switch and my motorcycle was on the left side of vehicle SLJ1474P. All of a sudden, SLJ1474P side swiped me and the left side of his vehicle collided onto my right side. I fell off my motorcycle as a result. I was on the floor unable to move. Hence, the driver called for ambulance. We exchanged particulars before I was conveyed to Raffles Hospital. I was warded from 27/03/2018 to 30/03/2019 and subsequently given 13 days of M/C until 12/04/2019. I received a call from T P IO Zay (d) and he advised me to lodge a police report hence I am doing so.

Police Report



SINGAPORE
POLICE FORCE

Police Station Of Origin
Sunnah P.P.
679 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No. 1800-4435989



17201903102102

2 of 2

Report No. 17201903102102

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recieving the Report:

G/
Sgt 2 KOH WEN RUJ

Signature Of Interpreter:

Not applicable

Officer in Charge Of Case:

TP: G.T. /
Sr Staff Sgt RAZIZ H'N TA'AR
Contact No.: 05476200

Signature Of Informant:

Date/Time:

31/03/2019 20:23

Classification Of Case:

Authenticating Stamp
MP108

RECEIVED
POLICE STATION

GREAT AMERICAN
INSURANCE COMPANY

REF: T13F00129R GST REG. NO: N00510061T
2 TEMASEK AVENUE, #16-01 CENTENNIAL TOWERS
SINGAPORE 039110
TEL: 65 6234 8000
FAX: 65 6235 2611

© 1999 by The McGraw-Hill Companies, Inc. All rights reserved. Printed in the United States of America. This publication is protected by copyright. Any unauthorized distribution or reproduction of this work in any form or by any means without the prior written permission of The McGraw-Hill Companies, Inc. is prohibited. All inquiries should be directed to The McGraw-Hill Companies, Inc., 1221 Avenue of the Americas, New York, NY 10020-1345.

Ce Certificate Number	MONTA00000289746-000	Owner	Motor Cycle Comprehensive
Polycheckler Name	Syed Ahmed Saib Bin Syed Masroor	Class & Number	WH391034240030505
Veho Enrollment	: Nil	Engine Number	: H505F00M0097
Hire Purchase	: SOUTHILIM WIND MOTOR CREDIT & TRADING PTE	Registration Number	: R021544P
Period of Insurance	: From 06/12/2019 To 05/07/2020 (Rs 50) (Both Dates Inclusive)		

Provide that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor or to use their Vehicle permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in disqualification driving the Motor Vehicle

Use only for social, domestic and pleasure purposes and for Policyholder's business.
This Policy does not cover:

- Use for Hire and Reward
- Use for racing, speed-making, triality trial or speed testing
- Use for carriage of goods (other than cargo) in connection with any trade or business
- Use for any purpose in connection with Motor Trade

* Limitations mentioned irrespective of Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 180) and Section 95 of the Road Traffic Act, 1987 (Malaysia), are not to be included under these headings.

Excess (Section 1)	SGD 600,00 - including Fire & Theft outside Singapore
Excess (Section 2)	N/A

Primary Judge	: Syed Ahmed Saifi Bin Syed Maskeen
Nagari Rider 1	: Muhammad Azmi Fekri Bin Subli
Nagari Rider 2	: N/A
Name of intermediary	: Tera Pak Solutions Pte Ltd
Date of issue	: 06/09/2016

We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 186) and Part IV of the Road Transport Act, 1987 (Malaysia).

Signed for and on behalf of
Great American Insurance Company

Author Address

15A

Date 15th April 2019

Your Ref Northern Motor

2111006 Blk Merah Lane 2

#01-10

Singapore 159762

Motor Claims Department

M&G Insurance (Singapore) Pte Ltd

4 Alankin Way # 21-01

S&A Centre 2

Singapore 068807

Dear Sirs,

RE: ACCIDENT INVOLVING 7BJ1544P AND 5LJ1474P ALONG
Nicoll Highway towards city ON 27-03-2019 AT 08.40

Please be informed that the above-said motorcycle bearing registration no: 7BJ1544P
was seriously damaged during the above-said accident and was beyond economic repair.

Kindly arrange for your surveyor to survey the above-mentioned motorcycle at Blk
1006, Blk Merah Lane 2, #01-10, Singapore 159762. (Tel. 62730369)

Thanking you in advance,

Yours Faithfully,


Enc.

Tel 62277888

Fax 62257402

MEDICAL CERTIFICATE

Raffles Hospital

MEDICAL CERTIFICATE

No: 435837

Name: Syed Ahmed Shah bin Syed Masha

NRIC: 99007840

This is to certify that the above mentioned is unfit for duty for
from 27/3/19 (date) to 12/04/19 (date)

Type of leave Granted:

- ☐ Outpatient Sick Leave
- ☐ Post Surgery Leave
- ☐ Maternity Leave
- ☒ Hospitalisation / Post Hospitalisation Leave

Admission Date: 27/3/19 Discharge Date: 30/3/19

This certificate is not valid for absence from court or other judicial proceedings.

DR DAVID WONG JIM CHON

MBBS, FRCG

General Practitioner

MClin

PhD

By: Syed Ahmed Shah bin Syed Masha

30/3/19

Doc. Office

1. 845 000001



南方摩哆
SOUTHERN MOTOR

Block 1006, Bukit Merah Lane 2, #01-10
Singapore 159762 Tel: 62730369 Fax: 62746614

Repair & Dealing in New & Second-hand Motor-cycles, Scooters & Insurance Agent

Date: 18th April 2019
Motor Claims Department
MSI & Insurance (Singapore) Pte Ltd
4 Raffles Way #21-01
S&A Centre 2
Singapore 068260

Dear Sirs

Re: Cost of repair to Yamaha C250V4/Keken 300 - P8315442

1 pc of	Body cover CR	✓	28	480.00	
"	Body cover bracket	? X		225.00	
"	Leftover	SC		85.00	
"	Front spoke light	SC		190.00	1954
"	Brake lever	SC		65.00	10%
"	Handle bar	? X		145.00	
"	Side bar	SC		195.00	
"	Body sliders	SC		120.00	
"	Kappa bar + 8	SC		207.00	1758.60
				2364.00	
				236.40	
				2127.60	

Less 10%

Nett

LKH Auto Consultants hence notify the Repairer of the following:

- To reserve before car body painting
- To display damaged car(s) during recovery
- Parts price are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- If, any work is carried out is allowed
- Supplementary cost(s) must be recovered and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Transport 40.00 / 300
Alignment fork 100.00 / 60
Alignment fork bracket 90.00 / 200
Labour 280.00 / 200
Reserve 25/4/19 2637.60 1758.60
Hq 90010068 300.00
3 days 2058.60
4/3 20% 1646.88
18/04/19 @ 1630 45-1,650
Tel 62277888
Fax 62257402
3 days!

Yours faithfully,
SOUTHERN MOTOR

Repair after report

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Apr 2019		17 Apr 2019 16:16 Edit Adj Rpt	S\$2,268.60 Edit Estimates	S\$2,268.60 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	POH ZHI YANG, FABIAN (FU ZHIYANG), ID: S8742646G, Tel: +6591522868, Email: POH.FABIAN1@GMAIL.COM								
Main Claimant:	SYED AHMED SAUFI BIN SYED MASHOR, ID: S9400784D								
Vehicle Reg. No.:	FBJ1544P	Date of Loss:	27/03/2019 08:00 - :59 [8 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 588853	Policy/Cover Note No.:	A290B2976QMY (Comprehensive) Coverage: 23/06/2018 - 28/05/2019						
Vehicle Reg. No. (Insured):	SLJ1474P	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	Southern Motor (HQ) BLK 1006 BUKIT MERAH LANE 2, #01-10, 159762 Bukit Merah - Tel: 62730369								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 17/05/2019]								
Driver/Custodian (Insured):	POH ZHI YANG, FABIAN (FU ZHIYANG) (31 / Male) , NRIC: S8742646G, Tel: +6591522868 Email: POH.FABIAN1@GMAIL.COM								
Adj Asp. Remarks:	TP REQ TO ASSIGN ON 18/04/19 AFTER 10AM. LIABILITY:100%. CONTACT: 6273 0369								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBJ1544P (588853)
[SLJ1474P]
TP
SYED AHMED SAUFI BIN SYED MASHOR
Mar 27 2019 8:00AM
[POH ZHI YANG, FABIAN (FU ZHIYANG)]
Southern Motor

Upload Documents | Upload Photos | Compose New Letter

View

Assessment Reports				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	16/04/19 14:51	Accident Statement Addm. #2 From: SC - Reg. No: SLJ1474P, Claimant: POH ZHI YANG, FABIAN (FU ZHIYANG)	 Load HTML		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	24/04/19 16:03	Adjuster Immediate Advice	 Load HTML		
Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	07/11/19 08:45	General View	 Load JPG	☒	
2	07/11/19 08:45	General View	 Load JPG	☒	
3	07/11/19 08:45	General View	 Load JPG	☒	
4	07/11/19 08:45	General View	 Load JPG	☒	
5	07/11/19 08:45	General View	 Load JPG	☒	
6	07/11/19 08:45	General View	 Load JPG	☒	
7	07/11/19 08:45	General View	 Load JPG	☒	
8	07/11/19 08:45	General View	 Load JPG	☒	
9	07/11/19 08:45	General View	 Load JPG	☒	
10	07/11/19 08:45	General View	 Load JPG	☒	
11	07/11/19 08:45	General View	 Load JPG	☒	
12	07/11/19 08:45	General View	 Load JPG	☒	
13	07/11/19 08:45	General View	 Load JPG	☒	
14	07/11/19 08:45	General View	 Load JPG	☒	
15	07/11/19 08:45	General View	 Load JPG	☒	
16	07/11/19 08:45	General View	 Load JPG	☒	
17	07/11/19 08:45	General View	 Load JPG	☒	
18	07/11/19 08:45	General View	 Load JPG	☒	
19	07/11/19 08:45	General View	 Load JPG	☒	
20	07/11/19 08:45	General View	 Load JPG	☒	
21	07/11/19 08:45	General View	 Load JPG	☒	
22	07/11/19 08:45	General View	 Load JPG	☒	
23	07/11/19 08:45	General View	 Load JPG	☒	
24	07/11/19 08:45	General View	 Load JPG	☒	
25	07/11/19 08:45	General View	 Load JPG	☒	
26	07/11/19 08:45	General View	 Load JPG	☒	
27	07/11/19 08:45	General View	 Load JPG	☒	
28	07/11/19 08:45	General View	 Load JPG	☒	
29	07/11/19 08:45	General View	 Load JPG	☒	
30	07/11/19 08:45	General View	 Load JPG	☒	
31	07/11/19 08:45	General View	 Load JPG	☒	
32	07/11/19 08:45	General View	 Load JPG	☒	
33	07/11/19 08:45	General View	Load JPG	☒	
34	07/11/19 08:45	General View	Load JPG	☒	
35	07/11/19 08:45	General View	Load JPG	☒	
36	07/11/19 08:45	General View	Load JPG	☒	
Documentation				1 per page	☐

Assessment Reports				1 per page	☒
No	Finalized On			Thumbnail	Print
		MSIG Insurance (Singapore) Pte. Ltd. (HQ)			☒
No	Finalized On			Thumbnail	Print
1	16/04/19 14:51	TPD FBJ1544P GIA REPORT From: SC - Reg. No: SJ1474P, Claimant: POH ZHI YANG, FABIAN (FU ZHIYANG)	1	Load PDF	
2	16/04/19 14:53	TPD FBJ1544P - ESTIMATE REPAIR	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) ^ v			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19006853/R1SD3E2

Date: 12/11/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29082976QMY

Claimant

Vehicle No : FBJ1544P

Insured Vehicle No : SLJ1474P

Date of Loss: 27/03/2019

Nature of Claim: TP

Claim No: 588853

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBJ1544P

Make & Model: YAMAHA CZD300A / XMAX300, 292cc

Engine No: H336E0032037

Reg. Date: 05/07/2018 (Man. Year: 2018)

Chassis No: MH3SH0842JK003935

Colour: Multi-colour

Odometer: 7256 km

Engine Capacity: 292 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70-15

Rear Tyre Size:

180/70-15

Front Left Side: Michelin 4 mm

Rear Left Side:

Michelin 4 mm

Front Right Side: 0 mm

Rear Right Side:

0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,127.60	1,758.60	369.00	17.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	510.00	510.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,637.60	2,268.60	369.00	13.99
+ GST 7.00/7.00% (S\$)	184.63	158.80	25.83	13.99
Nett Amount (S\$)	2,822.23	2,427.40	394.83	13.99

INSPECTION

Date of Assignment: 17/04/2019

Date Inspected: 18/04/2019 Inspected At:

Southern Motor (HQ)
BLK 1006 BUKIT MERAH LANE 2,
#01-10
Singapore 159762

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$369.00 NETT)

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 12 Nov 2019)	
Parts:	N/A	YAMAHA CZD300A / XMAX300 292cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBJ1544P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BODY COVER	Cracked	480.00 FL	*480.00 FL
2	1		*BODY COVER BRACKET	* Check	225.00 FL	*- FL
3	1		*MIRROR	Scratched	95.00 FL	*95.00 FL
4	1		*FRONT SPOKE LIGHT	Scratched	190.00 FL	*190.00 FL
5	1		*BRAKE LEVER	Scratched	65.00 FL	*65.00 FL
6	1		*HANDLE BAR	* Check	185.00 FL	*- FL
7	1		*SIDE BOX	Scratched	195.00 FL	*195.00 FL
8	1		*BODY SLIDERS	Scratched	120.00 FL	*120.00 FL
9	1		*KAPPA BOX 58	Scratched	809.00 FL	*809.00 FL
Sub Total (S\$)					2,364.00	1,954.00
- List Item Discount on L Items 10.00/10.00% (S\$)					236.40	195.40
Total Parts (S\$)					2,127.60	1,758.60

F=Franchise part. L=ListItemDisc

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSPORT	New	40.00	40.00
2	ALIGNMENT FORK	New	100.00	100.00
3	ALIGNMENT FORK BRACKET	New	90.00	90.00
4	LABOUR	New	280.00	280.00
Gross Labour Cost (\$\$)			510.00	510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >