

 SERVICE REQUESTSMESSAGESCLAIMS

Claim	S9M01KJ3
Reference	CS3/ASM19006857/Ucd3s2 
Loss Date	April 13, 2019
Report Date	Apr 16, 2019 4:40:38 PM
Request Date	April 17, 2019
Due Date	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pre-Repair Survey

Actions

Next Step

Wait for: Approve invoice

Add Invoice

Vehicle Information

Incident Vehicle Registration #SFD2182C

MakeTPVD HYUNDAI

ModelELANTRA AD 1.6 GLS AT (AMS)

Service Address

''

Primary Contact/Insured

TSS CONSTRUCTION & TRANSPORT PTE LTD
75 WHAMPOA DRIVE, #15-364, 320075, Singapore
63380083
JEUNESSE@VIRTUALINVEST.BIZ

Claim Handler

YONG Johnny
6568804733
johnny.yong@axa.com.sg

Additional Instructions

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
Document Type	Document SubType					
+ Upload Documents						
NAME	TYPE	SUB-TYPE	AUTHOR	DATE	UPLOADED	
 LKKInvoice1[1].pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	May 23, 2019		
 LKKPreRepairInspection[1].pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	May 23, 2019		
 Immediate Advice.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	May 6, 2019		
 Photo After Spray.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	May 6, 2019		
 Inspection Photographs.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	May 6, 2019		
 Photo of damaged parts.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	May 6, 2019		
 PRI EMAIL RECIEVED FROM LAWYER.msg	Letters and Correspondence	Solicitor / Advocate	RATAN BHOSALE Pragati	April 16, 2019		

English (default) ▾		LKK AUTO CONSULTANTS PTE LTD (TP) ▾		SUB-TYPE	AUTHOR	DATE UPLOADED
		SERVICE REQUESTS	MESSAGES	CLAIMS	GIA Report	RATAN BHOSALE Pragati
						April 16, 2019