

ASS. REC. BY:

REF: CS/CTI190062581 Kt d3

Special Instruction:

Surveyor: Kenneth

## ASSIGNMENT (Office)

From (Person): Ong chin kiat

of CTI

Date/Time: 17.4.2019 16.00 p.m.

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SLV 4941A

Insured: SLV 28834

at Workshop m/s MBM Wheelpower

Tel: 7328 8668

of 160 Sin ming Drive #106-02

Policy No: DMP/CSN 30284319000

Claim No: SNM19D20/63902

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 11.4.2019

CA / REV / REP. / REV 24 HRS

rup

H.O.D. Endorsement:

Date/Time: 17.4.19 4.45pm

Person Contacted: Danny

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate (✓)
	SLV 4941A - CC4/LPC190000361 K163	DEA - 58/12/2018
	SLV 28834 - MA/CTI19001024/24	D.O.A - 16/01/2019
25/4	11 Sm 83750 enoit & cc sin (Red: 4008.25, 51%)	

ASS. REC. BY:

REF: 6721

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_ MBM

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 2-3 days Res.: Yes or No

Lum Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLV 4941A Yr Regn: 12, 17

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy CHR c.c. 1797

Colour: M. Red A/C: Insured / Std / NI / NA

Sp. Reading: 104826 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: ZYX10 2025920

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / RIM or

Tyre Size: F: 225/50ZR18

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal. 7 mm

R/Bal. 4 mm

L/Bal. 7 mm

L/Bal. 4 mm

D.O.A. 11/4/19

D.O.A. 22/4/19

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FM O/S

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 26 APR 2019

Date/Time, File Pass to?

1) 26/4/19

☐ : Prel. Report☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS \$

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TP  
3750/-

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Apr 2019		17 Apr 2019 16:00 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by insurer]</b>							
Insured:	LIM BOON PIEU, ID: S7303504Z								
Main Claimant:	MBM WHEELPOWER PTE LTD, Co. Reg. No.: 200204110W								
Vehicle Reg. No.:	SLV4941A	Date of Loss:	11/04/2019 18:00 - :59 [15 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D201639C02	Policy/Cover Note No.:	DMPCSN30284318000 (Comprehensive) Coverage: 10/04/2018 - 26/04/2019						
Vehicle Reg. No. (Insured):	SLV2883Y	Policy No. (Claimant):	5097010515						
		Excess:	\$0.00						
Repairer:	MBM Wheelpower Pte Ltd (HQ) 160 Sin Ming Drive #06-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6262 8888								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 29/04/2019]								
Driver/Custodian (Insured):	LIM BOON PIEU (46 / Male) , NRIC: S7303504Z Email:								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a>   <a href="#">Compose Case Mail</a>							
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>									
<a href="#">View All</a>   <a href="#">Search Tasks</a>   <a href="#">Create New Task</a>   <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	12/04/2019 10:24
Date Of Accident	11/04/2019 18:50
Exact Location Of Accident	BLK 348 BUKIT BATOK ST 34 - OPEN CAR PARK (BBU25)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLV4941A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	MBM WHEELPOWER PTE LTD
Co Reg No	200204110W
Email Address	ALOYSIUS.SEAH69@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-62628888

### Vehicle Particulars

Manufacturer	TOYOTA
Model	C-HR HYBRID-1.8 S (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5097010515
Cover Note Number	

### Driver

Name of Driver	SEAH YONG HAW
NRIC No	S6930020J
Date Of Birth	26/08/1969
Occupation	OUTDOOR
Date Of Driving Pass	30/09/2004
Driving Experience	14 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88238396
Fax Number	
Contact Number	
Email Address	ALOYSIUS.SEAH69@GMAIL.COM

Address	BLK 289B BUKIT BATOK STREET 25 #16-19B
Postcode	651289
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : CHEONG GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE SIZE TOO BIG
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLV2883Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulatory, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 11/04/2019 THURSDAY AT ABOUT 1705HRS, I WAS DRIVING AT THE DRIVEWAY OF BUKIT BATOK STREET 34, CAR PARK NO. BBU 25, I WAS TRAVELLING STRAIGHT ON THE DRIVEWAY, VEHICLE NO. SLV 2883Y DRIVE OUT FROM PARKING LOT WITHOUT CHECKING CLEARANCE THAT RESULT THIS ACCIDENT

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



[Back to OneMotoring](#)

## Enquire Transfer Fee

### Vehicle Details

Vehicle No.:	SLV4941A
Vehicle Type:	Z10 - Private Hire (Chauffeur) Motor Car
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	TOYOTA
Vehicle Model:	C-HR HYBRID 1.8G CVT
Chassis No.:	ZYX102025920
Propellant:	Petrol-Electric
Engine No.:	2ZR8070597
Motor No.:	20A317221971
Engine Capacity:	1797 cc
Power Rating:	53.0 kW
Maximum Power Output:	90.0 kW ( 120 bhp)
Maximum Laden Weight:	1715 kg
Unladen Weight:	1440 kg
Year Of Manufacture:	2017
Original Registration Date:	29 Dec 2017
Lifespan Expiry Date:	-
COE Category:	B - Car above 1600cc or 97kW (130bhp)
Quota Premium:	\$53,711.00
COE Expiry Date:	28 Dec 2027
Road Tax Expiry Date:	28 Dec 2019
PARF Eligibility Expiry Date:	28 Dec 2027
Inspection Due Date:	28 Dec 2020
Intended Transfer Date:	12 Apr 2019
CO2 Emission:	88.00 (g/km)
CEV/VES Rebate Utilised	\$30,000.00
Amount:	
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

### Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
<b>Total Amount Payable:</b>			<b>25.00</b>

You may print this page for reference.

OK

Print

# MBM WHEELPOWER PTE LTD

Your Ref: SLV2883Y

Our Ref: SLV4941A

mbm wheelpower

To: CHINA TAIPING

CC

Fax

Date: 13/4/2019  
From: Danny  
Fax: 64525333  
Contact: 93288668  
Make / Model: TOYOTA C-HR HYBRID 1.8  
Chassis No.: ZYX102025920  
Engine No.: 2ZR8070597  
Year of Make: 2017  
Accident Date: 11 April 2019

*Not within  
Resurvey Bp pain  
2 days  
611pm @ 3750p*

ESTIMATE FOR VEHICLE NO.: SLV4941A

## DESCRIPTION

FRONT BUMPER → 423.80  
FRONT BUMPER CLIPS  
FRONT BUMPER LOWER COVER  
FRONT BUMPER RH SIDE RETAINER  
FRONT BUMPER RH HOLE COVER  
FRONT BUMPER SPONGE  
FRONT BUMPER SPONGE LOWER  
FRONT BUMPER RH STAY  
HEAD LAMP RH → 4450.00  
FRONT FENDER RH WHEEL ARCH MOULDING

QTY	List Price	
1	\$ 1,484.00	—
10	\$ 60.00	—
1	\$ 607.00	X
1	\$ 139.00	X
1	\$ 115.00	X
1	\$ 106.00	X
1	\$ 103.00	X
1	\$ 75.00	X
1	\$ 5,340.00	✓
1	\$ 182.00	X
Total: \$		8,211.00
LESS 25% \$		(2,052.75)
Parts Total: \$		6,158.25

## SPECIAL NETT

BODY SEALANT 1 \$ 80.00 X

## LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS. \$ 800.00 2501  
TO REMOVE & REPLACE BUMPER SENSORS \$ 40.00 ✓  
TO CHECK & RECONNECT ALL NECESSARY WIRING \$ 80.00 201  
TO SPRAY PAINT ON THE AFFECTED AREAS \$ 600.00 2201

Total: \$ 7,758.25

7% GST: \$ 543.08

Grand Total: \$ 8,301.33

*LKK Auto Consultants hence notify the Repairer of the following:*  
• To resurvey before/after spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice"  
• No illegal modification(s) is allowed  
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Mbm wheelpower pte ltd

160 SIN MING DRIVE

#06-02

SIN MING AUTOCITY

1 62828888 / 64525333

Company Registration Number : 200204110W

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Apr 2019		17 Apr 2019 16:00 <a href="#">Edit Adj Rpt</a>	<b>\$53,750.00</b> <a href="#">Edit Estimates</a>	<b>\$53,750.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by Insurer]</span>									
Insured: <b>LIM BOON PIEU</b> , ID: 57303504Z									
Main Claimant: <b>MBM WHEELPOWER PTE LTD</b> , Co. Reg. No.: 200204110W									
Vehicle Reg. No.: <b>SLV4941A</b>		Date of Loss: 11/04/2019 18:00 - :59 [15 Months and 13 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / SNM19D201639C02</b>		Policy/Cover Note No.: <b>DMPCSN30284318000</b> (Comprehensive) Coverage: 10/04/2018 - 26/04/2019							
Vehicle Reg. No. (Insured): <b>SLV2883Y</b>		Policy No. (Claimant): <b>5097010515</b>							
		Excess: <b>\$50.00</b>							
Repairer: <b>MBM Wheelpower Pte Ltd (HQ)</b> 160 Sin Ming Drive #06-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6262 8888									
Handling Insurer: <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Ong Chin Kiat</b> ]									
Claimant's Insurer: <b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... <b>[Final Rpt due 29/04/2019]</b>									
Driver/Custodian (Insured): <b>LIM BOON PIEU</b> (46 / Male) ; NRIC: 57303504Z Email:									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLV4941A (SNM19D201639C02)  
[SLV2883Y]  
TP  
MBM WHEELPOWER PTE LTD  
Apr 11 2019 6:00PM  
[LIM BOON PIEU]  
MBM Wheelpower Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View <span>View in Browser</span>	
<b>Assessment Reports</b>				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MBM Wheelpower Pte Ltd (HQ)		Thumbnail	Print
1	12/04/19 11:34	Accident Statement	1	Load HTM	
<b>Photos/Images</b>				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	26/04/19 14:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
2	26/04/19 14:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
3	26/04/19 14:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	26/04/19 14:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	26/04/19 14:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	26/04/19 14:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	26/04/19 14:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	26/04/19 14:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	26/04/19 14:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	26/04/19 14:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	26/04/19 14:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	26/04/19 14:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	26/04/19 14:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	26/04/19 14:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	26/04/19 14:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	26/04/19 14:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
17	26/04/19 14:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
18	26/04/19 14:15	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
19	26/04/19 14:15	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	17/04/19 15:55	Estimate	1	Load PDF	
2	17/04/19 15:55	INSD SLV2883Y GIA REPORT	1	Load PDF	

## Linked Accident Report Documents

				View	View in Browser
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MBM Wheelpower Pte Ltd (HQ)		Thumbnail	Print
1	12/04/19 11:34	Accident Statement	1	Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	MBM Wheelpower Pte Ltd (HQ)		Thumbnail	Print
1	12/04/19 11:33	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No.	Finalized On	MBM Wheelpower Pte Ltd (HQ)	Thumbnail	Print
2	12/04/19 11:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	12/04/19 11:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	12/04/19 11:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	12/04/19 11:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	12/04/19 11:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	12/04/19 11:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No.	Finalized On	MBM Wheelpower Pte Ltd (HQ)	Thumbnail	Print
1	12/04/19 10:54	Sketch Plan	 Load TIF	
2	12/04/19 10:54	Sketch Plan #2	 Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19006858/KTD3Q2

Date: 06/05/2019

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSN30284318000

Claimant Vehicle  
No: SLV4941AInsured Vehicle  
No: SLV2883Y

Date of Loss: 11/04/2019

Nature of Claim: TP

Claim  
No: SNM19D201639C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLV4941A

Make &amp; Model: TOYOTA C-HR HYBRID, 1.8 S (A)

Engine No: 2ZR8070597

Reg. Date: 29/12/2017 (Man. Year: 2017)

Chassis No: ZYX102025920

Colour: White

Odometer: 104626 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 225/50Z R18

Rear Tyre Size: 225/50Z R18

Front Left Side: Hankook 7 mm

Rear Left Side: Hankook 4 mm

Front Right Side: Hankook 7 mm

Rear Right Side: Hankook 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,238.25	4,155.67	2,082.58	33.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,520.00	530.00	990.00	65.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,758.25</b>	<b>4,685.67</b>	<b>3,072.58</b>	<b>39.60</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,750.00</b>		
<b>(S\$)</b>	<b>7,758.25</b>	<b>3,750.00</b>	<b>4,008.25</b>	<b>51.66</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>543.08</b>	<b>262.50</b>	<b>280.58</b>	<b>51.66</b>
<b>Nett Amount (S\$)</b>	<b>8,301.33</b>	<b>4,012.50</b>	<b>4,288.83</b>	<b>51.66</b>

## INSPECTION

Date of Assignment: 17/04/2019

Date Inspected: 22/04/2019 Inspected At:

 MBM Wheelpower Pte Ltd (HQ)  
 160 Sin Ming Drive #06-02, Sin Ming  
 AutoCity  
 Singapore 575722

Estimated Period of Repair: 2.0 days

---

**Adjuster:** KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 06 May 2019)
<b>Parts:</b> M1-SUV	TOYOTA C-HR HYBRID 1.8 S (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SLV4941A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	1,484.00 FL	*423.80 FL
2	10		*FRONT BUMPER CLIPS	Missing	60.00 FL	*60.00 FL
3	1		*FRONT BUMPER LOWER COVER	Scratched /Cut	607.00 FL	*607.00 FL
4	1		*FRONT BUMPER RH SIDE RETAINER	Serviceable	139.00 FL	*- FL
5	1		*FRONT BUMPER RH HOLE COVER	Serviceable	115.00 FL	*- FL
6	1		*FRONT BUMPER SPONGE	Serviceable	106.00 FL	*- FL
7	1		*FRONT BUMPER SPONGE LOWER	Serviceable	103.00 FL	*- FL
8	1		*FRONT BUMPER RH STAY	Serviceable	75.00 FL	*- FL
9	1		*HEAD LAMP RH	Cut	5,340.00 FL	*4,450.10 FL
10	1		*FRONT FENDER RH WHEEL ARCH MOULDING	Serviceable	182.00 FL	*- FL
11	1		*BODY SEALANT	Not Necessary	80.00 FS	*- FS
					<b>Sub Total (\$\$)</b>	<b>8,291.00 5,540.90</b>
					<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>2,052.75 1,385.23</b>
					<b>Total Parts (\$\$)</b>	<b>6,238.25 4,155.67</b>

F=Franchise part, S=SpcNett, L=ListItemDisc

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REFIT & REPAIR AFFECTED DAMAGED PARTS .INCLUDING TO KNOCK -OUT ,WELD & STRAIGHTEN ON THE AFFECTED PARTS	New	800.00	250.00
2	TO REMOVE & REPLACE BUMPER SENSORS	New	40.00	40.00
3	TO CHECK & RECONNECT ALL NECESSARY WIRING	New	80.00	20.00
4	TO SPRAY PAINT ON THE AFFECTED AREAS	New	600.00	220.00
Gross Labour Cost (S\$)			1,520.00	530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >