

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Owner : Nabil Rusydi Bin Asri

Accident Date : 4-Apr-19

Vehicle No : FBH 5863 C

Vehicle Model : Vespa GTS 300

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Front fender	\$ 160.00
1	Front fork assy	\$ 780.00
1	Front shock absorber	\$ 310.00
1	Front fork chrome cover	\$ 60.00
1	Front fork side cover	\$ 119.00
1	Front brake disc	\$ 150.00
1	Front cowling	\$ 328.00
2	Front cowling mouldings	\$ 190.00
1	Front cowling inner panel	\$ 387.00
1	Headlamp	\$ 370.00
1	Windshield	\$ 380.00
1	Front signal -L/H	\$ 75.00
1	Side mirror -L/H	\$ 155.00
1	Handle bar	\$ 320.00
1	Hand grip set	\$ 90.00
1	Handle bar balancer -L/H	\$ 42.00
1	Clutch lever	\$ 38.00
1	Lower belly panel	\$ 198.00
1	Rider footstep panel	\$ 550.00
1	Rider footstep rear cover	\$ 45.00
1	Side stand	\$ 115.00
1	Main stand	\$ 135.00
1	Engine mounting bracket	\$ 280.00
1	Seat lower panel -L/H	\$ 395.00
1	Rear taillamp	\$ 90.00
1	Rear box	\$ 650.00
2	Rear side lower panels	\$ 430.00
		\$ 6,842.00
	Less 10%	\$ 684.20
		\$ 6,157.80

c/f: \$ 6,157.80

Special Nett Items

1	Number plate (1 set)	\$ <u>14</u>	28.00	10
1	Steering cone (1 set)	\$ <u>11</u>	120.00	X
1	"VESPA" emblem	\$ <u>14</u>	38.00	
		\$	186.00	

S/No. **Labour**

1	To provide towing service.	\$ <u>35</u>	45.00	
2	To check wiring and reset headlamp focusing	\$ <u>11</u>	80.00	X
3	To provide labour.	\$ <u>280</u>	380.00	
4	To respray painting.	\$ <u>480</u>	800.00	
5	To repair body frame.	\$	350.00	✓
		\$	1,655.00	

Grand Total **\$ 7,998.80**



EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: