

Surveyor: Rasul

REF: CS / LAW 19006863 / RHD302

Special Instruction:

From (Person): Nisa Suzdi of Infinitus au Date/Time: 17/4/2019
 Estimated Cost: Bill to:

H/S: \$7515.50

Third Parties:

Claimant:

Surveyor: RT Appraisal

Workshop:

OD TP Re-inspection / Evaluation

To Inspect Vehicle No: SJW 4711 R Insured: SGC 1819A
 at Workshop m/s Wearnes Tel: SJB
 of

Policy No: Claim No: SGG.1802426.AxA.nks

Sum Insured: Excess:

Make of Veh: D.O.A. 27/02/2018

(Client's Record)

23/4/2019 @ 11am

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig days (Red \$ / %; Original days)

Date/Time: 17/5/2019 Submit Final Fig 7253.70 4 days (Red \$ 261.8, 3 %; Original days)

Date/Time	Action/Instruction
	SJW 4711 R - CS / TP 18005717 / RHD302
	SGC 1819A - X
	Call @ 9790 8863 - Ricky
	Open space carpark opposite Downtown East.
	Sen J. 17/5/19

URGENT
Do Not Finalise

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Original estimate and revised estimate use the independent report price

RECEIVED 21 MAY 2019

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Basic & Add
Transport
Photos
Others
Total

Date:

1000

1000

1) Date/Time 21/5/2019 File Pass to Typist

3) Date/Time File Pass to

5) Date/Time File Pass to

2) Date/Time File Return to

4) Date/Time File Return to

6) Date/Time File Return to

REF:

96649

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SGW 4711R Yr Regn: 2004 / NSWType: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: JAGUAR S-TYPE 2.5SE c.c. 2497Colour: BLACK A/C: Insured / Std / NI / NASp. Reading: 247294 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SASAL01A65JN 24470Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 235/50R17

R: _____

BS / DUN / EXNOVA G / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 27/02/18 D.O.I. 23/04/19Survey held at Don't know EXST CP

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

0/3 FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time. File Pass to?

☐ : Preli. Report☐ : Final Report

Date/Time. File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$ _____)

Days Of Repair:

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

) 3 + RS 50

) Photos

) Others

TOTAL

Nivitha (LKK Auto)

From: Nisa Sazali <nisa@infinituslaw.com.sg>
Sent: Wednesday, 17 April 2019 2:20 PM
To: Celine Fong (LKKAuto); assignments
Cc: Susila Ganesan; Sue Suhaimi; Oracle Law Corp
Subject: RE: Vehicle No. SJW 4711R | O/Ref: SGG.1802426.AXA.nks

Dear Celine,

Please see the email below from M/s Oracle Law Corporation.

Regards,
Nisa for Ms Susila Ganesan

INFINITUS LAW CORPORATION
77 Robinson Road | #16-00 Robinson 77 | Singapore 068896
DID : (+65) 6389 9193
FAX : (+65) 6224 2607
Email : nisa@infinituslaw.com.sg
Web : www.infinituslaw.com.sg

CONFIDENTIALITY NOTICE:

This e-message transmission contains information from the law firm of Infinitus Law Corporation that may be confidential or privileged. The information is intended solely for the recipient & use by any other party is not authorized. If you are not the intended recipient, be aware that any disclosure, copying, distribution or use of the contents of this information is prohibited. If you have received this electronic transmission in error, please notify us immediately by reply e-mail & delete the original transmission. Thank you.

From: Oracle Law Corp [mailto:mail@oraclelaw.sg]
Sent: Wednesday, 17 April 2019 1:32 PM
To: Nisa Sazali; Celine Fong (LKKAuto); assignments
Cc: Susila Ganesan; Sue Suhaimi
Subject: RE: Vehicle No. SJW 4711R | O/Ref: SGG.1802426.AXA.nks

Dear Nisa

MC/MC 11671/2018
ACCIDENT INVOLVING SJW 4711R & SGC 1819A ON 27-02-2018

Please arrange for Mr Mohammed Rasul Bin Mohd Yunus to contact our client on his mobile no. 9790-8863 to meet at the venue for the said re-inspection.

Regards

Pauline Ong

 **Oracle Law Corporation**

• Advocates & Solicitors • UEN/GST Reg No. 2009045722

237 Alexandra Road #04-11
The Alexcier, Singapore 159929
Telephone: 6538 6250 Facsimile: 6538 1860

From: Nisa Sazali [mailto:nisa@infinituslaw.com.sg]

Sent: Wednesday, 17 April 2019 12:23 PM

To: Celine Fong (LKKAuto) <celinefong@lkkauto.com>; assignments <assignments@lkkauto.com>

Cc: Susila Ganesan <susila@infinituslaw.com.sg>; Sue Suhaimi <sue@infinituslaw.com.sg>; Oracle Law Corp <mail@oraclelaw.sg>

Subject: RE: Vehicle No. SJW 4711R | O/Ref: SGG.1802426.AXA.nks

Importance: High

Dear Celine,

We refer to your email dated 16 April 2019.

Please find attached the following documents for your attention:

GIA report of SGC 1819A together with coloured photographs;
GIA report of SJW 4711R together with coloured photographs;
Repair bills for the sum of \$7,761.50 by Wearnes Automotive Pte Ltd;
Survey report dated 5 April 2018 by LKK Auto Consultants Pte Ltd together with coloured photographs;
Inspection report dated 18 March 2019 by RT Appraisal Pte Ltd.

Dear Ms Pauline,

Please provide the full address for your client's vehicle to be inspected to LKK Auto.

Regards,
Nisa for Ms Susila Ganesan

INFINITUS LAW CORPORATION
77 Robinson Road | #16-00 Robinson 77 | Singapore 068896
DID : (+65) 6389 9193
FAX : (+65) 6224 2607
Email : nisa@infinituslaw.com.sg
Web : www.infinituslaw.com.sg

CONFIDENTIALITY NOTICE:

This e-message transmission contains information from the law firm of Infinitus Law Corporation that may be confidential or privileged. The information is intended solely for the recipient & use by any other party is not authorized. If you are not the intended recipient, be aware that any disclosure, copying, distribution or use of the contents of this information is prohibited. If you have received this electronic transmission in error, please notify us immediately by reply e-mail & delete the original transmission. Thank you.

From: Celine Fong (LKKAuto) [mailto:celinefong@lkkauto.com]

Sent: Tuesday, 16 April 2019 2:02 PM

To: Nisa Sazali; assignments

Cc: Susila Ganesan; Sue Suhaimi; Oracle Law Corp

Subject: RE: Vehicle No. SJW 4711R | O/Ref: SGG.1802426.AXA.nks

Dear Nisa,

Can you provide us the full address the vehicle to be inspected at and all supporting documents (Accident report, survey report and photographs)

Best Regards,
Celine Fong

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nisa Sazali <nisa@infinituslaw.com.sg>

Sent: Tuesday, 16 April 2019 9:53 AM

To: Celine Fong (LKKAuto) <celinefong@lkkauto.com>; assignments <assignments@lkkauto.com>

Cc: Susila Ganesan <susila@infinituslaw.com.sg>; Sue Suhaimi <sue@infinituslaw.com.sg>; Oracle Law Corp <mail@oraclelaw.sg>

Subject: RE: Vehicle No. SJW 4711R | O/Ref: SGG.1802426.AXA.nks

Dear Celine,

Contents of your email is noted.

The location of the said inspection to be conducted at the open-space carpark opposite Downtown East.

Regards,

Nisa for Ms Susila Ganesan

INFINITUS LAW CORPORATION

77 Robinson Road | #16-00 Robinson 77 | Singapore 068896

DID : (+65) 6389 9193

FAX : (+65) 6224 2607

Email : nisa@infinituslaw.com.sg

Web : www.infinituslaw.com.sg

CONFIDENTIALITY NOTICE:

This e-message transmission contains information from the law firm of Infinitus Law Corporation that may be confidential or privileged. The information is intended solely for the recipient & use by any other party is not authorized. If you are not the intended recipient, be aware that any disclosure, copying, distribution or use of the contents of this information is prohibited. If you have received this electronic transmission in error, please notify us immediately by reply e-mail & delete the original transmission. Thank you.

From: Celine Fong (LKKAuto) [<mailto:celinefong@lkkauto.com>]

Sent: Tuesday, 16 April 2019 9:19 AM

To: Nisa Sazali; assignments

Cc: Susila Ganesan; Sue Suhaimi; Oracle Law Corp

Subject: RE: Vehicle No. SJW 4711R | O/Ref: SGG.1802426.AXA.nks

Dear Nisa,

Thank you for the email.

We write to confirm our surveyor, Mr Mohammed Rasul Bin Mohd Yunus will attend the reinspection on **Tuesday, 23 April 2019 at 11.00am.**

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nisa Sazali <nisa@infinituslaw.com.sg>
Sent: Monday, 15 April 2019 10:31 AM
To: Celine Fong (LKKAuto) <celinefong@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: Susila Ganesan <susila@infinituslaw.com.sg>; Sue Suhaimi <sue@infinituslaw.com.sg>; Oracle Law Corp <mail@oraclelaw.sg>
Subject: Vehicle No. SJW 4711R | O/Ref: SGG.1802426.AXA.nks
Importance: High

Dear Celine,

We refer to the above matter and to our telephone conversation minutes ago.

Please be informed that the Court has appointed Mr Mohammed Rasul Bin Mohd Yunus of LKK Auto Consultants Pte Ltd as the Single Joint Expert ("SJE") in this matter.

The Court has directed for the SJE report to be ready within 14 days from the date of inspection and no later than 15 May 2019.

The Plaintiff's solicitors have informed us that their client's car number SJW 4711R is available for an inspection on the following dates:

Thursday, 18 April 2019 at 11.00am;
Friday, 19 April 2019 at 11.00am; or
Tuesday, 23 April 2019 at 11.00am.

Kindly arrange with the Plaintiff's solicitors, M/s Oracle Law Corporation (who is copied in this email) on a date and time to conduct a re-inspection of the Plaintiff's car.

Regards,
Nisa for Ms Susila Ganesan

INFINITUS LAW CORPORATION
77 Robinson Road | #16-00 Robinson 77 | Singapore 068896
DID : (+65) 6389 9193
FAX : (+65) 6224 2607
Email : nisa@infinituslaw.com.sg
Web : www.infinituslaw.com.sg

CONFIDENTIALITY NOTICE:

This e-message transmission contains information from the law firm of Infinitus Law Corporation that may be confidential or privileged. The information is intended solely for the recipient & use by any other party is not authorized. If you are not the intended recipient, be aware that any disclosure, copying, distribution or use of the contents of this information is prohibited. If you have received this electronic transmission in error, please notify us immediately by reply e-mail & delete the original transmission. Thank you.

From: Nisa Sazali [mailto:nisa@infinituslaw.com.sg]
Sent: Wednesday, 3 April 2019 9:59 AM
To: 'Celine Fong (LKKAuto)'
Cc: 'Susila Ganesan'; 'Sue Suhaimi'; 'assignments'
Subject: [URGENT] RE: Your Ref: to be advised O/Ref: SGG.1802426.AXA.nks
Importance: High

Dear Celine,

Please extend us a copy of the survey report dated 5 April 2018 together with the coloured photographs of SJW 4711R without further delay.

Regards,
Nisa for Ms Susila Ganesan

INFINITUS LAW CORPORATION
77 Robinson Road | #16-00 Robinson 77 | Singapore 068896
DID : (+65) 6389 9193
FAX : (+65) 6224 2607
Email : nisa@infinituslaw.com.sg
Web : www.infinituslaw.com.sg

CONFIDENTIALITY NOTICE:

This e-message transmission contains information from the law firm of Infinitus Law Corporation that may be confidential or privileged. The information is intended solely for the recipient & use by any other party is not authorized. If you are not the intended recipient, be aware that any disclosure, copying, distribution or use of the contents of this information is prohibited. If you have received this electronic transmission in error, please notify us immediately by reply e-mail & delete the original transmission. Thank you.

From: Nisa Sazali [<mailto:nisa@infinituslaw.com.sg>]
Sent: Wednesday, 27 March 2019 3:23 PM
To: 'Celine Fong (LKKAuto)'
Cc: Susila Ganesan; Sue Suhaimi; 'assignments'
Subject: RE: Your Ref: to be advised O/Ref: SGG.1802426.AXA.nks
Importance: High

Dear Celine,

As spoken between your goodself and our Ms Sue this morning, kindly forward to us the survey report dated 5 April 2018 together with the coloured photographs of SJW 4711R on an urgent basis.

Regards,
Nisa for Ms Susila Ganesan

INFINITUS LAW CORPORATION
77 Robinson Road | #16-00 Robinson 77 | Singapore 068896
DID : (+65) 6389 9193
FAX : (+65) 6224 2607
Email : nisa@infinituslaw.com.sg
Web : www.infinituslaw.com.sg

CONFIDENTIALITY NOTICE:

This e-message transmission contains information from the law firm of Infinitus Law Corporation that may be confidential or privileged. The information is intended solely for the recipient & use by any other party is not authorized. If you are not the intended recipient, be aware that any disclosure, copying, distribution or use of the contents of this information is prohibited. If you have received this electronic transmission in error, please notify us immediately by reply e-mail & delete the original transmission. Thank you.

From: Celine Fong (LKKAuto) [<mailto:celinefong@lkkauto.com>]
Sent: Tuesday, 26 March 2019 6:25 PM
To: Nisa Sazali
Cc: Susila Ganesan; Sue Suhaimi; assignments
Subject: RE: RE: Your Ref: to be advised O/Ref: SGG.1802426.AXA.nks

Dear Ms Nisa ,

Attached herewith CV of our surveyor Mr Mohammed Rasul Bin Mohd Yunus for your attention.

Our surveyor needs approximately three to four weeks to complete the report.

We are pleased to submit our Professional Fee Charges (Single Joint Expert) as follows:

Paper Survey - \$700.00

Physical Re-inspection - \$1,000.00

Court Attendance Expert Witness Fee:

(a) State Courts

i) Half day: \$400.00

ii) Full day: \$800.00

All above charges are subject to GST 7%.

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nisa Sazali <nisa@infinituslaw.com.sg>

Sent: Friday, 22 March 2019 10:14 AM

To: Celine Fong (LKKAuto) <celinefong@lkkauto.com>

Cc: Susila Ganesan <susila@infinituslaw.com.sg>; Sue Suhaimi <sue@infinituslaw.com.sg>

Subject: RE: RE: Your Ref: to be advised O/Ref: SGG.1802426.AXA.nks

Importance: High

Dear Celine,

We refer to our email dated 18 March 2019.

Please let us have your reply urgently as the Court has directed parties to file and serve SJE affidavit by 1 April 2019.

Regards,

Nisa for Ms Susila Ganesan

INFINITUS LAW CORPORATION

77 Robinson Road | #16-00 Robinson 77 | Singapore 068896

DID : (+65) 6389 9193

FAX : (+65) 6224 2607

Email : nisa@infinituslaw.com.sg

Web : www.infinituslaw.com.sg

CONFIDENTIALITY NOTICE:

This e-message transmission contains information from the law firm of Infinitus Law Corporation that may be confidential or privileged. The information is intended solely for the recipient & use by any other party is not authorized. If you are not the intended recipient, be aware that any disclosure, copying, distribution or use of the contents of this information is prohibited. If you have received this electronic transmission in error, please notify us immediately by reply e-mail & delete the original transmission. Thank you.

From: Nisa Sazali [<mailto:nisa@infinituslaw.com.sg>]

Sent: Monday, 18 March 2019 11:53 AM

To: 'celinefong@lkkauto.com'

Cc: Susila Ganesan; Sue Suhaimi

Subject: RE: Your Ref: to be advised O/Ref: SGG.1802426.AXA.nks
Importance: High

Dear Celine,

We refer to the above matter and act for AXA Insurance Pte Ltd, the insurers of motor vehicle number SGC 1819A.

Kindly forward to us the survey report dated 5 April 2018 together with the coloured photographs of SJW 4711R.

We have been instructed to nominate a surveyor from your good office as a Single Joint Expert ("SJE"). As we will require to inform the Court of the nominees together with a CV and charges, we would appreciate if you could forward to us:

- (1) The name of the surveyor who can be the SJE
- (2) A copy of the surveyor's CV
- (3) His charges for carrying out re-inspection and preparing the report
- (4) The estimated number of days to prepare the report.
- (5) The charges for attending Court to give evidence, should the need arise.

We await your urgent reply on the above.

Regards,
Nisa for Ms Susila Ganesan

INFINITUS LAW CORPORATION
77 Robinson Road | #16-00 Robinson 77 | Singapore 068896
DID : (+65) 6389 9193
FAX : (+65) 6224 2607
Email : nisa@infinituslaw.com.sg
Web : www.infinituslaw.com.sg

CONFIDENTIALITY NOTICE:

This e-message transmission contains information from the law firm of Infinitus Law Corporation that may be confidential or privileged. The information is intended solely for the recipient & use by any other party is not authorized. If you are not the intended recipient, be aware that any disclosure, copying, distribution or use of the contents of this information is prohibited. If you have received this electronic transmission in error, please notify us immediately by reply e-mail & delete the original transmission. Thank you.

RT APPRAISAL PTE LTD

Block 305 #02-167 Ubi Avenue 1, Singapore 400305.
Tel: 6748-6076 Fax: 6748-0361

FIRE - AUTOMOBILE - LICENSED APPRAISERS.
Company Registration No: 199507108W

AUTOMOBILE INSPECTION REPORT

PAGE: 1

TO: AXA INSURANCE PTE LTD
8 SHENTON WAY
27-01 AXA TOWER
SINGAPORE 068811

DATE: 18/03/2019

REFERENCE:

THIRD PARTY CLAIM

VEHICLE NO	: SJW4711R	INSPECTION REQUEST BY	: The Claims Dept.
INSURED	: SGC1819A	ASSIGNMENT DATE	: 28/02/2018
INSURED OWNER	: -		
POLICY NO	: -	DATE OF INSPECTION	: 16/03/2018
CLAIM NO	: SBM009MY	OUR REFERENCE/INV#	: AXA/SJW4711R/270218
ACCIDENT DATE	: 27/02/2018		

PARTICULARS OF DAMAGED VEHICLE:


MAKE & MODEL	: Jaguar S-Type	PRE-ACCIDENT CONDITION:	Fairly good
DOR / CC	: 2004 2497 CC	STEERING	: Serviceable
ENGINE NO	: 452444358JC	BRAKES	: Serviceable
CHASSIS NO.	: SAJAC01A65JN24470	MILEAGE	: 233351 km
		COLOUR	: Black

TYRE CONDITION: SIZE (FRONT): (235/50 R 17) SIZE (BACK): (235/50 R 17)

	NEAR SIDE		OFF SIDE	
FRONT:	60	% Continental	60	% Continental
REAR :	80	% Continental	80	% Continental

The above percentages represent the remaining estimated life of the tyre treads.

GENERAL DESCRIPTION OF DAMAGE: (PHOTOGRAPHS ATTACHED)



The vehicle sustained damages at the RHS doors and front fender region. Please see schedule attached for details.

INSPECTION AND ADJUSTMENT:

ORIGINAL	REVISED
QUOTATION: \$13,336.50	QUOTATION: \$7,515.50 LESS EXCESS \$0.00 = \$7,515.50 NETT

IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS

SPECIAL REMARKS: (SUBJECT TO POLICY CONDITION)

This inspection has been conducted entirely 'Without Prejudice'. In normal circumstances, repairs to the vehicle would take approximately four (4)

working days to complete.

To date, we have yet to finalise the repair cost with the Repairers.

The information contained in these documents is privileged and confidential and is intended for the exclusive use of the addressee designation. If you are not the addressee any enclosure, reproduction, distributions or other dissemination or use of this communication is strictly prohibited. If you have received this document not meant for you, please contact us immediately to arrange for its return.

----- PLEASE SEE SCHEDULE ATTACHED -----

SERVICE TAX INVOICE

65524 - C00001 SL: SERVICE SALES - PC

Mr Ong Dicky Ong
45 Jalan Loyang Besar
#04-04 Celadon View

Singapore 507029

Closed by : Paul Ong Qing Yong
Svc Consultant : ACC
Remarks : Mr Dicky OngGST Reg.No:M28920628X
Inv.No. : B&P 7013233 Page 1
Inv.date. : 06/04/2018
WIP No. : 47405
Veh.In/Out: 21/03/2018 06/04/2018
*Tel.No. : Mobile: 97908863
Reg.No. : SJW4711R
Reg.date : 09/11/2004
Mileage .. : 226,798
Chassis No: SAJAC01A65JN24470

Parts/Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRT RH DOOR,	0		1700.00	0		1,700.00	S
	REPAIR RH FRT FENDER							
800	TO PUTTY SPRAYPAINT ON	0		1500.00	0		1,500.00	S
	RHF DOOR, RHF FENDER, RHR DOOR							
802	TO TRANSFER FRT RH DOOR	0		500.00	0		500.00	S
	EXC CONTRIBUTION 50%	0		3626.85	0		3,626.85	S
	DEPOSIT OF \$7,253.70							
XR845423	DOOR PANEL FRT RH XT	1.0	EA	2817.90			2,817.90	S
V089010007	NOISE DEADENING PAD	1.0	EA	500.00			500.00	S
XR845063	DOOR SEAL PRIMARY RH	1.0	EA	235.80			235.80	S

Labour Total 3,700.00
Parts Total 3,553.70
Package Total 0.00

Gross Total. 7,253.70
Less..... 3,626.85
Net..... 3,626.85
GST @ 7.0% 253.88
Total..... 3,880.75
Paid..... 0.00
Please Pay.. 3,880.75

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

Enquiries must be lodged within 14 days from the invoice date.
This is a computer generated invoice. No signature is required.

VEHICLE NO: SJW4711R
CLAIM NO: S8M009MY

POLICY NO: -
OUR REF : AXA/SJW4711R/270218C

ADJUSTMENT ON REPAIRS COST AND REPLACEMENT OF PARTS:

WORKSHOP: WEARNES AUTOMOTIVE PTE LTD

ADDR:45 LENG KEE ROAD
SINGAPORE 159103

S/N	QTY	DESCRIPTIONS	COMMENTS/CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION
		<u>MATERIALS</u>			
1	1	Door panel front RH	badly dented/ warped	2,630.00	2,630.00
2	1	Noise deadening pad	necessary	500.00	500.00
3	1	Fender panel front RH	to repair	1,145.40	0.00 X
4	1	Door seal primary RH	necessary	199.50	199.50
5	1	Moulding, body side	serviceable	367.30	0.00 X
6	1	Adhesive sealer	waived	358.30	0.00 X
		Total (Parts)		5,200.50	3,329.50
		<u>LABOUR & MISC.</u>			
1		To remove & replace the damaged parts as listed above, including reinstatements of the necessary attachments & fittings to facilitate repairs; jack, straighten, panel beat & reshape the affected parts & components, correct & realign the necessary parts		3,400.00	1,700.00
2		To supply paint materials, expandable items i.e. sand paper, masking tape, putty, primer chemical compounds & etc., to putty & respray paint on the relevant repaired areas		3,750.00	1,500.00
3		To transfer front RH door (necessary)		500.00	500.00
4		To check wiring include resetting of all electrical modules		486.00	486.00 X
		Total (Labour)		8,136.00	4,186.00
		Total Parts and Labour		13,336.50	7,515.50

4 days

SERVICE TAX INVOICE

65524 - c00001

SL: SERVICE SALES - PC

Mr Ong Dicky Ong
45 Jalan Loyang Besar
#04-04 Celadon View

Singapore 507029

Closed by : Paul Ong Qing Yong
Svc Consultant :
Remarks : Mr Dicky OngGST Reg.No:M28920628X
Inv.No. . : B&P 7013070 Page 1
Inv.date. : 21/03/2018
WIP No. . : 47405
Veh.In/Out: 21/03/2018
*Tel.No. . : Mobile: 97908863
Reg.No. . : SJW4711R
Reg.date . : 09/11/2004
Mileage ... : 226,798
Chassis No: SAJAC01A65JN24470

Parts/Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
EXC	CONTRIBUTION 50%		0	3626.85	0		3,626.85	S
DEPOSIT OF \$7,253.70								

COPY DOCUMENT

		Gross Total.	3,626.85
Labour Total	0.00	Net.....	3,626.85
Parts Total	0.00	GST @ 7.0%	253.88
Package Total	0.00	Total.....	3,880.75
		Paid.....	0.00
		Please Pay..	3,880.75

GST: S=StdRated; O=OutOfScope; Z=ZeroRated
 Enquiries must be lodged within 14 days from the invoice date.
 This is a computer generated invoice. No signature is required.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
-		Ref : CS/TP16005717/R1tbe2		
ONG POH GUAN DICKY 73, JALAN JARAK SINGAPORE 809237		Date : 05-04-2018		
		Code : TP2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	Veh. Inspected		SJW 4711R	
Policy No.	Coverage (\$)		0.00	
Claim No.	Excess (\$)		0.00	
Assign From	Assign Date		27/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	JAGUAR S-TYPE2.5SE	c.c	2497	
Engine No.	HIDDEN	Year of Reg.	2004	
Chassis No.	SAJAC01A65JN24470	Colour	BLACK	
Odometer	233592	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/50 R17	CONTINENTAL	6 mm	
L/H Front Tyre	235/50 R17	CONTINENTAL	6 mm	
R/H Rear Tyre	235/50 R17	CONTINENTAL	6 mm	
L/H Rear Tyre	235/50 R17	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY, DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/02/2018	Inspection Date	27/03/2018	
Survey held at	2 JALAN PESAWAT			
Repairer	WEARNES AUTOMOTIVE PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3661 FAX: 6256 4315

Reg. No: 199607196R GST Reg. No. 19-9607196-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJW 4711R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	DOOR PANEL FRT RH XT	BENT	2,817.90	2,817.90
1	NOISE DEADENING PAD	NECESSARY	500.00	500.00
1	DOOR SEAL PRIMARY RH	NECESSARY	235.80	235.80
1	FENDER PANEL FRT RH	TO REPAIR SEE LABOUR	1,227.30	-
1	MOULDING - BODY SIDE	NOT NECESSARY	434.10	-
1	ADHESIVE SEALER FL2	NOT NECESSARY	425.40	-
			5,640.50	3,553.70
	LABOUR			
	TO REPLACE FRT RH DOOR, RH FRT FENDER, RH BODY MOULDING, REPAIR REAR RH DOOR, ETC. INCLUSIVE OF THE REPAIR OF FENDER PANEL FRT RH.		3,400.00	1,700.00
	TO PUTTY SPRAY PAINT ON RHF DOOR, RHF FENDER, RHR DOOR, RH BODY MOULDING, ETC.		3,750.00	1,500.00
	TO TRANSFER FRT RH DOOR.		500.00	500.00
	TO CHECK WIRING INCLUDE RESETING OF ALL ELECTRICAL MODULES.		486.00	486.00
			8,136.00	4,186.00
	GRAND TOTAL		13,776.50	7,739.70
	RECOMMENDED COST OF REPAIRS			7,739.70

Report Ref No. CS/TP18005717/R1tbe2

MRB

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199807198R GST Reg. No. 19-9807198-R

PHOTOGRAPHS FOR VEHICLE NO. SJW 4711R

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3661 FAX: 6256 4316

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199507198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607188R GST Reg. No. 19-9607195-R








LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 196607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4316

Reg. No: 199607198R GST Reg. No: 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408033

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJW 4711R

RE-INSPECTION



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	27/02/2018 17:43
Date Of Accident	27/02/2018 07:40
Exact Location Of Accident	30 FERNVALE LINK ENTRANCE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJW4711R
Insured/Policyholder	
Name Of Registered Owner	ONG POH GUAN DICKY
NRIC No	S1269664G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97908863
Alternative Phone No	OFFICE-97908863
Vehicle Particulars	
Manufacturer	JAGUAR
Model	S-TYPE-2.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A29040642QMX
Cover Note Number	
Driver	
Name of Driver	ONG POH GUAN DICKY
NRIC No	S1269664G
Date Of Birth	14/10/1957
Occupation	INDOOR
Date Of Driving Pass	06/05/1980
Driving Experience	37 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97908863
Fax Number	
Contact Number	OFFICE-97908863
EMail Address	NOEMAIL

Address	30 FERNVALE LINK #03-03
Postcode	797530
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Refer to attached

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Details of Witness 1

Name
Phone Number
Email Address

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGC1819A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	AXA INSURANCE PTE LTD

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident [all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"], the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time


Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Car A = 55W 4711R (Resident Car.)

Car B = SGC 1819 A (Visitor Car) - Hyundai

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

The accident happened on Tue 27 February 2018 at around 7:40 am. There are two entrance barriers into H2O Residences in Fernvale Link. I entered through the "resident" barrier while Car B entered by the "visitor" entrance barrier. I was a head of Car B by half a car length and intended to head to the resident car park on the left. Car B was making (intending) a U-turn as claimed by the driver but did not see my car, therefore he took too much a swerve and hit my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

x 

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	27/02/2018 13:59
Date Of Accident	27/02/2018 07:40
Exact Location Of Accident	H2O RESIDENT SENGKANG
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SGC1819A
Insured/Policyholder	
Name Of Registered Owner	TOH KENG HONG
NRIC No	S0180198H
Email Address	TOHKENGHONG@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-96666219
Alternative Phone No	OFFICE-96666219
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	ELANTRA-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P1692566
Cover Note Number	
Driver	
Name of Driver	TOH KENG HONG
NRIC No	S0180198H
Date Of Birth	20/12/1953
Occupation	OUTDOOR
Date Of Driving Pass	10/06/1971
Driving Experience	46 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96666219
Fax Number	
Contact Number	OFFICE-96666219
EMail Address	TOHKENGHONG@YAHOO.COM.SG

Address	BLK 483 CASTLE GREEN SINGAPORE
Postcode	787057
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE ATTCAL SKETCH PLAN & STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJW4711R
Vehicle Make/Model/Colour	BLACK
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be used outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time

21-2-18
12:50 pm

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name
NRIC/FIN No.

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the above date time, I enter this condo and proceed to drop off point. Vehicle no came from my left side and hit my car my ~~Right~~ left side

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
Policyholder's Signature

Date & Time:
27.2.18. 1pm

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ORACLE LAW CORPORATION			Ref : CS/LAW19006863/R1td3e2	
237 ALEXANDRA ROAD #04-11 THE ALEXCIER SINGAPORE 159929			Date : 21-05-2019	
			Code : L143	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	SGC 1819A	Veh. Inspected	SJW 4711R	
Policy No.		Coverage (\$)	0.00	
Claim No.	SGG.1802426.AXA.NKS	Excess (\$)	0.00	
Assign From	NISA SAZALI	Assign Date	17/04/2019	
2. Vehicle Particulars & Condition				
Make & Model	JAGUAR S-TYPE2.5SE	c.c	2497	
Engine No.	HIDDEN	Year of Reg.	2004	
Chassis No.	SAJAC01A65JN24470	Colour	BLACK	
Odometer	247294	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/50 R17	GOODYEAR	6 mm	
L/H Front Tyre	235/50 R17	GOODYEAR	6 mm	
R/H Rear Tyre	235/50 R17	GOODYEAR	6 mm	
L/H Rear Tyre	235/50 R17	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	27/02/2018	Inspection Date	23/04/2019	
Survey held at	OPEN SPACE CARPARK OPPOSITE DOWNTOWN EAST			
Repairer	-			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJW 4711R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	DOOR PANEL FRONT RH	REPLACED	2,817.90	2,817.90
1	NOISE DEADENING PAD	REPLACED	500.00	500.00
1	FENDER PANEL FRONT RH	REPAIRED SEE LABOUR	1,227.30	-
1	DOOR SEAL PRIMARY RH	REPLACED	235.80	235.80
1	MOULDING, BODY SIDE	SERVICEABLE	434.10	-
1	ADHESIVE SEALER	NOT NECESSARY	425.40	-
			5,640.50	3,553.70
	LABOUR			
	TO REMOVE & REPLACE THE DAMAGED PARTS AS LISTED ABOVE, INCLUDING REINSTATEMENTS OF THE NECESSARY ATTACHMENTS & FITTINGS TO FACILITATE REPAIRS; JACK, STRAIGHTEN, PANEL BEAT & RESHAPE THE AFFECTED PARTS & COMPONENTS, CORRECT & REALIGN THE NECESSARY PARTS. INCLUSIVE OF THE REPAIR OF FENDER PANEL FRONT RH.		3,400.00	1,700.00
	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS I.E. SAND PAPER, MASKING TAPE, PUTTY, PRIMER CHEMICAL COMPOUNDS & ETC., TO PUTTY & RESPRAY PAINT ON THE RELEVANT REPAIRED AREAS.		3,750.00	1,500.00
	TO TRANSFER FRONT RH DOOR (NECESSARY).		500.00	500.00
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.	NOT NECESSARY	486.00	-
			8,136.00	3,700.00
	GRAND TOTAL		13,776.50	7,253.70
	RECOMMENDED COST OF REPAIRS			7,253.70

Report Ref No. CS/LAW19006863/R11d3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.