

Surveyor:

Kenneth

DOI:

ASSIGNMENT

30/9/19

Date / Time:

11/11/19

Insured in Meriten:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SBU 8313K

Name of Insured:

UM THANG WAH

Insured Tel No.:

HP:

Claim No.:

89m01jam

Policy No.:

Make / Model:

Place of Accident:

Excess Sec II : S5

D.O.A.:

5141209

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

GBL 3329 T



INSRS:

WSP:

Tel:

Liability:

RMKS:

L48



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

GBL 3329 T - 06/11/19 13:16:50 / Approved: 06/11/19

SBU 8313K - X

STAGE

DATE / PIC

Non-Reporting 1st (1st):

Non-Reporting 1st (2nd):

Non-Reporting 1st (Final):

Notification 1st (if non-pickup):

Call OI:

After call 1st to OI:

Documentation Check List: Handler Typist

Notification 1st (if non-pickup)

After call 1st to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: S\$ 5200.00

(7 - days) Reduction: 4000.00 % 44

Email:

Call:

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email:

Call:

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

Repair Cost:

S\$ 5200.00

Loss of Rental (LOR):

S\$

(days)

Loss of Use (LOU):

S\$

300

(\$60 x 5 days)

Loss of Income (LOI):

S\$

-

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search:

S\$

Medical:

S\$

Disbursement:

S\$

Legal Cost:

S\$

Total:

S\$ 5200.00

Global Sum S\$:

5200.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email:

Call:

Payee 1:

S\$ 5200.00

Name 1:

Lim Yew Poo Spray Paint Co

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

ASS. REC. BY:

REF: ALA /6066 / KP62Kenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$ 211C

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 07 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBC 3329TYr Regn: 12, 11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HyundaiColour: WhiteSp. Reading: 118156

Eng/No: _____

C/No: KMFNBX7JMCU428218Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/70R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Nexen

Front

R/Bal. 0 mmL/Bal. 0 mmD.O.A. 5/4/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass to2/5 \$ 5200.00 (Cost \$ 4,099.04/44%)

Data/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Data/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S - RS - SI

Fees

Others

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)



LIM YEW BOO SPRAY PAINT CO.

Page 1 / 2

Blk 10, Sector C, #01-10, Sin Ming Ind. Est. Singapore 575645
 No. 176, Sin Ming Drive, #03-05, Sin Ming AutoCare, Singapore 575721
 Tel: 6453 4177 Fax: 6459 3724
 Email: limyewboo@singnet.com.sg
 Company Reg. No. : 200514/001.

AXA INSURANCE SINGAPORE PTE LTD
 8 SHENTON WAY #27-01
 AXA TOWER SINGAPORE 068811

Attention : Motor Claim Department
 Contact : 63387288 Fax No. : 68804838

Estimate : TP19/022

Date : 30/04/2019
 Vehicle Num. : GBC 3329T
 Make/Model : HYUNDAI H1 STAREX 2.5-2011
 Chassis/Eng# : KMFVBX7JMCU428218/D4CBB931
 Accident Date : 05/04/2019
 Claim No. :
 Reference : LYB/GBC3329T/AXA/tp/sy
 Policy No. :

Not Withheld
11 Pump 8?
Recovery After Paint

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

		LIST ITEMS :	
1.	1	REAR TAILGATE	
2.	2	REAR TAILGATE ABSORBER	
3.	1	REAR TAILGATE RUBBER	
4.	1	REAR TAILAMP (LH)	
5.	1	REAR BUMPER	
6.	1	REAR BUMPER RETAINER	
7.	1	REAR BUMPER REINFORCEMENT	
8.	1	REAR BUMPER SPONGE	
9.	1	REAR FENDER/LH	
10.	1	REAR FENDER INNER SHIELD/LH	
11.	1	REAR TAILAMP LOWER PANEL GARNISH	
12.	8	REAR TAILAMP LOWER PANEL GARNISH CLIPS	
13.	1	REAR TAILAMP LOWER PANEL RETAINER	
14.	1	REAR SIDE AIR DUCT/LHS	

List TotalS\$:
 20.00% Discount S\$:

93.40	2,620.40	
	186.80	
	135.60	
	384.90	
	435.00	
	22.00	
	347.00	
	218.00	
	1,433.20	
	198.00	
	88.30	
5.00	40.00	
	56.10	
	25.00	
	6,190.30	
	1,238.06	
	4,952.24	

		SPECIAL NETT ITEMS :	
1.	1	REAR EMBLEM 'HYUNDAI'	
2.	1	REAR EMBLEM 'H1'	
3.	1	REAR EMBLEM 'H'	

30.20	
26.30	
26.30	

CONTINUE / ...



LIM YEW BOO SPRAY PAINT CO.

Page 2 / 2

Blk 10, Sector C, #01-10, Sin Ming Ind. Est. Singapore 575645
 No. 176, Sin Ming Drive, #03-05, Sin Ming AutoCare, Singapore 575721
 Tel: 6453 4177 Fax: 6459 3724
 Email: limyewboo@singnet.com.sg
 Company Reg. No.: 200514/00L

AXA INSURANCE SINGAPORE PTE LTD
 8 SHENTON WAY #27-01
 AXA TOWER SINGAPORE 068811

Attention : Motor Claim Department

Contact : 63387288 Fax No. : 68804838

Estimate : TP19/022

Date : 30/04/2019
 Vehicle Num. : GBC 3329T
 Make/Model : HYUNDAI H1 STAREX 2.5-2011
 Chassis/Eng# : KMFWBX7JMCU428218/D4C8B931
 Accident Date : 05/04/2019
 Claim No. :
 Reference : LYB/GBC3329T/AXA/tp/sy
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
4.	1	REAR '70 KM/H' STICKER		12.00 ✓
5.	2	REAR BUMPER CLIPS	5.00	10.00 ✓
6.	1 set	REAR FENDER INNER SHIELD CLIPS		12.00 ✓
7.	1 SET	REAR REVERSE SENSOR		250.00 X
Special Nett Total S\$:				366.80
LABOUR :				
TO APPLY RUST-PROOFING ON REPAIRED/ REPLACED PANELS			60h	120.00 ✓
LABOUR TO REMOVE & REFIX REAR W/SCREEN			120h	150.00 ✓
TO REMOVE & REFIX FUEL TANK IN ORDER TO FACILIATEREPAIR			60h	80.00 ✓
TO CHECK & REPAIR AFFECTED RIM			40h	120.00 X
TO REPLACE REVERSE SENSOR SET & CHECK WIRING FUNCTIONS			50h	60.00 ✓
TO CHECK COMPUTERISED WHEEL ALIGNMENT			20h	120.00 X
TO CHECK WATER SEEPAGE			20h	60.00 ✓
TO REMOVE LH RR INNER TRIMING,GARNISH TO FACILATE JOB			80h	120.00 ✓
MOUNT VEHICLE ON JIG BENCH TO FACILIATE REPAIR JOB			nn	350.00 X
TO CUT,WELD ON REAR FENDER,ALIGNMENT REAR AFFECTED AREA & LABOUR TO REPLACE ABOVE PARTS			1000h	1,800.00
TO PUTTY,PRIEMR & SPRAY PAINT ON RR TAILGATE,END PANEL, TAILLAMP LOWER PANEL,REAR FENDER USING 2K PAINT			800h	1,000.00
Labour Total S\$:				3,980.00

E & O.E.

Total S\$: 9,299.04

for LIM YEW BOO SPRAY PAINT CO.

All cheques should be crossed and made payable to
 Lim Yew Boo Spray Paint Co.

Customer

E. & O. E.



LIM YEW BOO SPRAY PAINT CO.

Blk 10, Sector C, #01-10, Sin Ming Ind. Est. Singapore 575645
 No. 176, Sin Ming Drive, #03-05, Sin Ming AutoCare, Singapore 575721
 Tel: 6453 4177 Fax: 6459 3724
 Email: limyewboo@singnet.com.sg
 Company Reg. No.: 200514/001.

AXA INSURANCE SINGAPORE PTE LTD
 8 SHENTON WAY #27-01
 AXA TOWER SINGAPORE 068811

Attention: Motor Claim Department
 Contact: 63387288 Fax No.: 68804838

Estimate: TP19/022

Date: 30/04/2019
 Vehicle Num: GBC 3329T
 Make/Model: HYUNDAI H1 STAREX 2.5-2011
 Chassis/Eng#: KMFWBX7JMCU428218/D4C8893
 Accident Date: 05/04/2019
 Claim No:
 Reference: LYB/GBC3329T/AXA/phys
 Policy No:

Not Insured
11 Pmg. 8?
Recovery After Paint

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS				
1.	1	REAR TAILGATE	93.40	2,620.40 L
2.	2	REAR TAILGATE ABSORBER		186.80 X
3.	1	REAR TAILGATE RUBBER		135.60 X
4.	1	REAR TAILLAMP (LH)		384.90 L
5.	1	REAR BUMPER		435.00 L
6.	1	REAR BUMPER RETAINER		22.00 L
7.	1	REAR BUMPER REINFORCEMENT		347.00 L
8.	1	REAR BUMPER SPONGE		216.00 L
9.	1	REAR FENDER/LH		1,433.20 L
10.	1	REAR FENDER INNER SHIELD/LH		198.00 L
11.	1	REAR TAILLAMP LOWER PANEL GARNISH		88.30 L
12.	8	REAR TAILLAMP LOWER PANEL GARNISH CLIPS	5.00	40.00 L
13.	1	REAR TAILLAMP LOWER PANEL RETAINER		56.10 L
14.	1	REAR SIDE AIR DUCT/LHS		25.00 L
List Total S\$:				6,190.30
20.00% Discount S\$:				1,238.06
				4,952.24
SPECIAL NETT ITEMS:				
1.	1	REAR EMBLEM 'HYUNDAI'		30.20 L
2.	1	REAR EMBLEM 'H1'		26.30 L
3.	1	REAR EMBLEM 'H'		26.30 L

CONTINUE / ...

US \$5200
Low (78480) = 560

LIM YEW BOO SPRAY PAINT CO.

Blk 10, Sector C, #01-10, Sin Ming Ind. Est. Singapore 575645
 No. 176, Sin Ming Drive, #03-05, Sin Ming AutoCare, Singapore 575721
 Tel: 6453 4177 Fax: 6459 3724
 Email: limyewboo@singnet.com.sg
 Company Reg. No.: 200514/001

AXA INSURANCE SINGAPORE PTE LTD
 8 SHENTON WAY #27-01
 AXA TOWER SINGAPORE 068811

Attention: Motor Claim Department
 Contact: 63387288 Fax No.: 68804838

Estimate: TP19/022

Date: 30/04/2019
 Vehicle Num: GBC 3329T
 Make/Model: HYUNDAI H1 STAREX 2.5-2011
 Chassis/Eng#: KMPWBX7JMCU428218/D4C8893
 Accident Date: 05/04/2019
 Claim No.:
 Reference: LYB/GBC3329T/AXA/tp/sy
 Policy No.:

S/N	Quantity	Particular	Unit Price	Amount S\$
4	1	REAR '70 KMH' STICKER	12.00	12.00
5	2	REAR BUMPER CLIPS	5.00	10.00
6	1 set	REAR FENDER INNER SHIELD CLIPS	12.00	12.00
7	1 SET	REAR REVERSE SENSOR	250.00	250.00
Special Net Total S\$:				366.80
LABOUR				
TO APPLY RUST-PROOFING ON REPAIRED/ REPLACED PANELS				60.00
LABOUR TO REMOVE & REFIX REAR W/SCREEN				120.00
TO REMOVE & REFIX FUEL TANK IN ORDER TO FACILITATE REPAIR				80.00
TO CHECK & REPAIR AFFECTED RIM				120.00
TO REPLACE REVERSE SENSOR SET & CHECK WIRING FUNCTIONS				50.00
TO CHECK COMPUTERISED WHEEL ALIGNMENT				120.00
TO CHECK WATER SEEPAGE				20.00
TO REMOVE LH RR INNER TRIMING, GARNISH TO FACILITATE JOB				80.00
MOUNT VEHICLE ON JIG BENCH TO FACILITATE REPAIR JOB				350.00
TO CUT, WELD ON REAR FENDER, ALIGNMENT REAR AFFECTED AREA & LABOUR TO REPLACE ABOVE PARTS				1000.00
TO PUTTY, PRIMER & SPRAY PAINT ON RR TAILGATE, END PANEL, TAILLAMP LOWER PANEL, REAR FENDER USING 2K PAINT				800.00
Labour Total S\$:				3,980.00

E & O.E.

Total S\$: 9,299.04

for LIM YEW BOO SPRAY PAINT CO.

All cheques should be crossed and made payable to
 Lim Yew Boo Spray Paint Co.

Customer

E & O.E.

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Thursday, 25 April 2019 4:23 PM
To: Serene LIM
Cc: assignments; CS A Team; Admin A
Subject: RE: GBC3329T & SBU8313K AT 14A WILMONAR AVENUE ON 5/4/2019 *** LKK REF: CC4/ASM19006866/pa3

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Please note that all finalisation subject insurer's approval.

****Kindly arrange for survey.**

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Serene LIM <serene@autocare.com.sg>
Sent: Monday, 22 April 2019 4:35 PM
To: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Cc: assignments <assignments@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: Re: GBC3329T & SBU8313K AT 14A WILMONAR AVENUE ON 5/4/2019 *** LKK REF: CC4/ASM19006866/pa3

Hi Mei Kwan

Liability is obvious as AXA Insured driver stated she reversing.

Pls advise any update from AXA side, Thanks

Thank you & Regards

Serene LIM

Lim Yew Boo Spray Paint Co

Tel: +65 64545011 | Fax: +65 64593724 | Hp: +65 96852332

E-mail: serene@autocare.com.sg

From: Mei Kwan (LKKAUTO)

Sent: Wednesday, April 17, 2019 6:14 PM

To: Serene LIM

Cc: assignments ; CS A Team ; Admin A ; Hsiao Tong (LKKAUTO)

Subject: RE: GBC3329T & SBU8313K AT 14A WILMONAR AVENUE ON 5/4/2019 *** LKK REF: CC4/ASM19006866/pa3

'WITHOUT PREJUDICE'

SAVE AS TO COSTS


Dear Sir / Madam,

We refer to the above matter.

Please be informed that we are currently **pending verification for direct settlement.**

Fyi, OI has reported. Please refer to the below OI's sketch plan and statement.

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was going out as I knew the bend the normal route was blocked by the parking contractor.

I had to reverse. As I reversed I hit the parked vehicle - Damage to my rear right side of the car and his vehicle's rear left.

Please provide us the following and arrange for TP survey.

- evidence i.e. video/ scene photo
- estimated cost of repair

Please note that for liability, claim negotiation and settlement, please contact Hsiao Tong at 6742 3197.

Our respective case handler will look into the matter and revert to you in due course.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Serene LIM <serene@autocare.com.sg>

Sent: Tuesday, 16 April, 2019 4:45 PM

To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>

Subject: GBC3329T & SBU8313K AT 14A WILMONAR AVENUE ON 5/4/2019

To : Motor Claims Dept (Arrangement of Surveyor Unit)

RE: NOTICE TO THIRD PARTY INSURERS TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING
DAY PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIN-INJURY MOTOR ACCIDENT
CLAIMS (NIMA)
ACCIDENT INVOLVING GBC3329T & SBU8313K AT 14A WILMONAR AVENUE ON 5/4/2019

We are the repairer for M/S VLV PTE LTD the owner of vehicle no. GBC 3329T

Please be informed that the said vehicle can be inspected at the following venue:

Lim Yew Boo Spray Paint Co
Blk 10 Sin Ming Industrial Estate #01-10 Singapore 575645
Tel: 64534177 Fax: 64593724 Email: serene@autocare.com.sg

Contact Person: Serene Lim Hp : +65 96852332

Please also provide us a list of 10 surveyors as your nominated SJE (Single Joint Expert)

PLEASE ARRANGE OFFICER-IN-CHARGE TO LET US KNOW ASAP IF WE COULD DO DIRECT SETTLEMENT FOR THIS CASE

I/ We enclosed herewith a copy of our client **SAS Statement** for your reference. Looking forward to your kind assistance and co-operative in this matter.

Please note that if you fail to conduct the pre-repair inspection within the next 2 days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you

Regards
Serene LIM
Lim Yew Boo Spray Paint Co
Direct : +65 64545011
Mobile : +65 96852332



Re:<MANDATE IA> - [ACCIDENT INVOLVING SBU8313K (OI) & GBC3329T (TP) ON 05/4/2019]

Type

🔗 Question

Message

Hi, pls offer global sum at \$5500/- (all-in). TY.

Reply



林偉武噴漆公司

LIM YEW BOO SPRAY PAINT CO.

Blk 10 Sin Ming Industrial Estate Sector C #01-10 Singapore 575645
No. 176 Sin Ming Drive #03-05 Sin Ming AutoCare Singapore 575721
Tel: 6453 4177 Fax: 6459 3724
Email: limyewboo@singnet.com.sg Website: www.limyewboo.com
Co. Reg. No.: 200514/001

Our Ref: LYB/GBC3329T/AXA/tp/sl

Your Ref: SBU8313K (AXA)

21 June 2019

LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933 Attn : Motor Claims Dept

Dear Sirs

ACC INVLG GBC3329T & SBU8313K ALONG 14A WILMONAR AVENUE ON 5/42019

We are the repairers of vehicle nos. GBC 3329T and understand that you were the appointed surveyor by the insurer of vehicle nos. SBU 8313K involved in the aforesaid accident. Our investigations reveal that the accident was caused by the negligence of the vehicle insured by you. As such, we are looking to you for reimbursement calculated as follows;

1) Repair Costs	S\$5,200.00
2) Loss of use at \$80 per day X 8D	640.00
	<hr/>
TOTAL:	S\$5,840.00
	<hr/>

To substantiate our claim, we enclosed the following;

- 1) Final Repair bill
- 2) SAS Statement
- 3) Third Party Direct Settlement DV
- 4) Authorisation To Act
- 5) AXA DV

We look forward to your favorable reply in due course.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/ claimant.

Yours faithfully

Serene Lim
Claims Section

Encl.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

30 APRIL 2019

LIM THENG WAH
16 WILMONAR AVE
SINGAPORE 588048

Dear Sir/ Mdm

OUR REF : CC4/ASM19006866/pa3
YOUR REF : SBU 8313K
ACCIDENT INVOLVING SBU 8313K AND GBC 3329T ALONG/AT 15/16 WILMONAR AVE ON 05/04/2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from LIM YEW BOO SPRAY PAINT CO acting on behalf of the owner of GBC 3329T against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to chewht@lkkauto.com within 10 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6742 3197 or email us at chewht@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely


Chew Hsiao Tong
Case Handler
DID: 6742 3197
FAX: 6741 4108
EMAIL: chewht@lkkauto.com

Cc *AXA Insurance Pte Ltd*
 (Motor Claims Dept)

AUTHORISATION TO ACT

I/We, VLV PTE LTD (the third party claimant") of 1 BUKIT AYER MOLEK SINGAPORE 589695 (address), owner of GBC3329T (vehicle no.) hereby authorize LIM YEW BOO SPRAY PAINT CO ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. GBC3329T that was damaged pursuant to the accident which occurred on 5/4/2019 (date) along 14A WILMONAR AVENUE (location) involving vehicle no/s SBU8313K ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 14 (day) of June (month) 2019 (year)



Signed by "the third party claimant"
(with company stamp if applicable)



Signed by "the workshop"
(with company stamp)



AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	SBU 8313K	(Insd veh)	Model: HYUNDAI STAR X
	GBC 3329T	(TP veh)	
Date of Accident/ Time:	05/04/2019 / 10:00		

Repair Estimate	: \$	9,399.00	
Final Repair Cost	: \$	6,300.00	
Loss of Use	: \$	300.00	05 days at \$ 60.00 per day
Rental (if any)	: \$		days at \$ per day
LTA / GIA Search Fee	: \$		
Others:	: \$		
Final Settlement Sum	: \$	6,500.00	(global sum)
Payee Name: <u>LIM YEW BOO SPRAY PAINT CO.</u>			
Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)			
A)	For Non GIA Registered Workshop:	Agreed Liability	100 (%)
B)	For GIA Registered Workshop:	BOLA Applicable: Yes / No	BOLA Scenario No: _____
	BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks:			

NOTE:

- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are not received within 7 days of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a full and final settlement that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

Signature of workshop representative / Workshop stamp
Name of Representative: Kevin Lim
Date: 2/7/19

Signature of Witness / Workshop stamp (if applicable)
Name of Witness: Billy Yeo
Date: 2/7/19

Signature of AXA's surveyor/representative:
Name of AXA's surveyor / Representative:
Date: 5/7/2019



LIM YEW BOO SPRAY PAINT CO.

Blk 10, Sector C, #01-10, Sin Ming Ind. Est. Singapore 575645

No. 176, Sin Ming Drive, #03-05, Sin Ming AutoCare, Singapore 575721

Tel: 6453 4177 Fax: 6459 3724

Email: limyewboo@singnet.com.sg

Company Reg. No. : 200514/001.

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #27-01
AXA TOWER SINGAPORE 068811

Attention : Motor Claim Department

Contact : 63387288 Fax No. : 68804838

Final Repair Bill : TP19/022

Date : 01/07/2019

Vehicle Num. : GBC 3329T

Make/Model : HYUNDAI H1 STAREX 2.5-2011

Chassis/Eng# : KMFVBX7JMCU428218/D4C8B931487

Accident Date : 05/04/2019

Claim No. :

Reference : LYB/GBC3329T/AXA/tp/sy

Policy No. :

LUMP SUM

Amount S\$

5,200.00

E. & O.E.

Total S\$:

5,200.00



for LIM YEW BOO SPRAY PAINT CO.

All cheques should be crossed and made payable to
Lim Yew Boo Spray Paint Co.

Customer

E. & O.E.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM19006866/Kga3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:RICHARD ANG		Date : 15-07-2019		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SBU 8313K	Veh. Inspected	GBC 3329T	
Policy No.	GA022019	Coverage (\$)	0.00	
Claim No.	S9M01JQM	Excess (\$)	0.00	
Assign From		Assign Date	17/04/2019	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI STAREX (M)	c.c	2497	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	KMFWBX7JMCU428218	Colour	WHITE	
Odometer	116156	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/70 R16	NEXEN	8 mm	
L/H Front Tyre	215/70 R16	NEXEN	8 mm	
R/H Rear Tyre	215/70 R16	NEXEN	8 mm	
L/H Rear Tyre	215/70 R16	NEXEN	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/04/2019	Inspection Date	30/04/2019	
Survey held at	LIM YEW BOO SPRAY PAINT CO BLOCK 10, SECTOR C SIN MING ROAD INDUSTRIAL ESTATE, #01-10 SINGAPORE 575645.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 3329T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TAILGATE (CONSISTENT)	BENT	2,620.40	2,620.40
2	REAR TAILGATE ABSORBER @\$93.40 (CONSISTENT)	SERVICEABLE	186.80	-
1	REAR TAILGATE RUBBER (CONSISTENT)	SERVICEABLE	135.60	-
1	REAR TAILAMP (LH) (CONSISTENT)	CRACKED	384.90	384.90
1	REAR BUMPER (CONSISTENT)	BENT	435.00	435.00
1	REAR BUMPER RETAINER (CONSISTENT)	DISTORTED	22.00	22.00
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	SERVICEABLE	347.00	-
1	REAR BUMPER SPONGE (CONSISTENT)	NOT NECESSARY	218.00	-
1	REAR FENDER /LH (CONSISTENT)	BUCKLED	1,433.20	1,433.20
1	REAR FENDER INNER SHIELD /LH (CONSISTENT)	CRACKED	198.00	198.00
1	REAR TAILAMP LOWER PANEL GARNISH (CONSISTENT)	CRACKED	88.30	88.30
8	REAR TAILAMP LOWER PANEL GARNISH CLIPS @\$5.00 (CONSISTENT)	NECESSARY	40.00	40.00
1	REAR TAILAMP LOWER PANEL RETAINER	DISTORTED	56.10	56.10
1	REAR SIDE DUCT /LHS (CONSISTENT)	NOT NECESSARY	25.00	-
	LESS 20% DISCOUNT		-1,238.06	-1,055.58
			4,952.24	4,222.32
SPECIAL NETT ITEMS				
1	REAR EMBLEM 'HYUDAI' (SN) (CONSISTENT)	NECESSARY	30.20	30.20
1	REAR EMBLEM 'H1' (SN) (CONSISTENT)	NECESSARY	26.30	26.30
1	REAR EMBLEM 'H' (SN) (CONSISTENT)	NECESSARY	26.30	26.30
1	REAR '700KM/H' STICKER (SN) (CONSISTENT)	NECESSARY	12.00	12.00
2	REAR BUMPER CLIPS @\$5.00 (SN) (CONSISTENT)	NECESSARY	10.00	10.00
1	SET REAR FENDER INNER SHIELD CLIPS (SN) (CONSISTENT)	NECESSARY	12.00	12.00
1	SET REAR REVERSE SENSOR (SN) (CONSISTENT)	SERVICEABLE	250.00	-
			366.80	116.80
LABOUR				
	TO APPLY RUST-PROOFING ON REPAIRED /REPLACED PANELS.		120.00	60.00
	LABOUR TO REMOVE & REFIX REAR W/SCREEN.		150.00	120.00

Report Ref No. CC4/ASM19006866/Kga3q2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE & REFIX FUEL TANK IN ORDER TO FACILITATE REPAIR.		80.00	60.00
	TO CHECK & REPAIR AFFECTED RIM.	NOT NECESSARY	120.00	-
	TO REPLACE REVERSE SENSOR SET & CHECK WIRING FUNCTIONS.		60.00	50.00
	TO CHECK COMPUTERISED WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	TO CHECK WATER SEEPAGE.		60.00	20.00
	TO REMOVE LH RR INNER TRIMMING, GARNISH TO FACILITATE JOB.		120.00	80.00
	MOUNT VEHICLE ON JIG BENCH TO FACILITATE REPAIR JOB.	NOT NECESSARY	350.00	-
	TO CUT /WELD ON REAR FENDER, ALIGNMENT REAR AFFECTED AREA & LABOUR TO REPLACE ABOVE PARTS.		1,800.00	1,000.00
	TO PUTTY, PRIMER & SPRAY PAINT ON RR TAILGATE, END PANEL, TAILLAMP LOWER PANEL, REAR FENDER USING 2K PAINT.		1,000.00	800.00
			3,980.00	2,190.00
GRAND TOTAL			9,299.04	6,529.12
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,200.00















Report Ref No. CC4/ASM19006866/Kga3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

NAME	TYPE	SUB TYPE	AUTHOR	DATE UPLOADED
 LINK Inspection (3).pdf	Forms / Claim Documents	Others	LIK AUTO CONSULTANTS PTE LTD (TP)	17 July 2019
 LINK Adjustment La (3).pdf	Forms / Claim Documents	Others	LIK AUTO CONSULTANTS PTE LTD (TP)	17 July 2019
 PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LIK AUTO CONSULTANTS PTE LTD (TP)	17 July 2019
 AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LIK AUTO CONSULTANTS PTE LTD (TP)	17 July 2019
 WORKSHOP INVOICE.pdf	Invoice	Registrar	LIK AUTO CONSULTANTS PTE LTD (TP)	17 July 2019
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LIK AUTO CONSULTANTS PTE LTD (TP)	17 July 2019
 PART_CODE Rebate Enquiry.pdf	Forms / Claim Documents	Others	LIK AUTO CONSULTANTS PTE LTD (TP)	17 May 2019
 MANDATE LA dtd17052019.pdf	Forms / Claim Documents	Assessment	LIK AUTO CONSULTANTS PTE LTD (TP)	17 May 2019
 LINK SURVEY PHOTOS.pdf	Forms / Claim Documents	Assessment	LIK AUTO CONSULTANTS PTE LTD (TP)	17 May 2019
 TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LIK AUTO CONSULTANTS PTE LTD (TP)	13 May 2019
 LINK SURVEY PHOTO.pdf	Forms / Claim Documents	Assessment	LIK AUTO CONSULTANTS PTE LTD (TP)	8 May 2019
 LA.pdf	Forms / Claim Documents	Assessment	LIK AUTO CONSULTANTS PTE LTD (TP)	8 May 2019
 SURVEY LIST SEND TO WORKSHOP.mng	Letters and Correspondence	Workshop	KADRI Maitei	17 April 2019
 EMAIL FROM WORKSHOP (THIRD PARTY PRU).mng	Letters and Correspondence	Workshop	KADRI Maitei	17 April 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 GIA REPORT OF GBC3329T (TP).pdf	Reports & Statement	GIA Report	KADRI Mastein	17 April 2019
 EMAIL.msg	Letters and Correspondence	Others	KADRI Mastein	17 April 2019
 SBLJ0313K INSD GIA.pdf	Reports & Statement	GIA Report	NIKAM Santosh Pandurang	10 April 2019