

ASS. REC. BY:

REF: AXA/

68671/109

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Cheng Hoe

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 0.19k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 6/22 Person Contacted: _____ Vehicle: IN / OUT

Veh No: SGV 8074k Yr Regn: 06, 07

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: NIS Sunny EX c.c. 1597

Colour: M. Silver A/C: Insured / Std / NI / NA

Sp. Reading: 173859 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JNICFAN168 0109957

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NI / SRIm / STD / MIm or

Tyre Size: F: 195/55R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Five Stone

Front 7 mm Rear 6 mm

R/Bal. 7 mm R/Bal. 6 mm

L/Bal. 7 mm L/Bal. 6 mm

D.O.A. 15/4/19 D.O.I. 6/5/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

OLSKA & ALK

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to
8/5 ESR not ready

Date/Time, File Pass to?

: Prell. Report

Days Of Repair: _____

1)

: Final Report

Resurvey No. of Trlp: _____

Date/Time, File Return to?

2)

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee:

Transportation: _____ \$ + RS. SI

Fuel/OS

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

SGV 8074K

1 pc front bumper misc

_____ R/H side retaining disc

6 pc _____ clips misc

1 pc _____ moulding misc

1 pc R/H head lamp. - misc

1 pc for R/H fender - misc

_____ inner shield disc

1 pc for R/H shock absorber - ?

1 pc for R/H knuckle arm ?

1 pc for R/H wheel bearing ?

1 pc for R/H lower arm ?

1 pc for R/H sport rim ?

CHENG HOE MOTOR PTE LTD
Blk 1019, Yishun Ind. Park A
#01-374, Singapore 768761
Tel: 6755 6142 Fax: 6755 7719
Email: chmotor@singnet.com.sg

SGV 8074K

- ① To RAR for bumper assy, head lips, grille, for R/H fender, inner shield, KAR for R/H fender inner panel and realign the same \$580/4501
- ② Body & respray on the bumper, for R/H fender, bonnet, support panel and affected area \$700/6001
- ② RAR for R/H u/c and mech. steering \$230/?
- ④ Bumpers \$30/✓
- ⑤ To conduct computer wheel alignment \$60/✓

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4827G
Vehicle Details	
Vehicle No.:	SGV8074K
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Apr 2019
Vehicle Make:	NISSAN
Vehicle Model:	SUNNY 1.6EXA
Primary Colour:	Silver
Manufacturing Year:	2007
Engine No.:	QG16426536
Chassis No.:	JN1CFAN16Z0109957
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$11,737.00
Original Registration Date:	27 Jun 2007
First Registration Date:	27 Jun 2007
Transfer Count:	0
Actual ARF Paid:	\$11,502.00
OPC Cash Rebate Details	
OPC Cash Rebate Eligibility:	No
OPC Cash Rebate Eligibility Expiry Date:	-
OPC Cash Rebate Amount:	-
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	26 Jun 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$25,313.00
COE Rebate Amount:	\$16,172.00
Total Rebate Amount:	\$16,172.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 16 Apr 2019

OK

Enquire Vehicle & Owner Information (Vehicle No. XD7447T As At 15 Apr 2019 / 17:00:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: CHM-SGV8074

SGV8074K
TP/AXA

Current Owner Details

Owner ID Type: Company
Owner ID: 199804675H
Owner Name: VEOLIA ES SINGAPORE PTE. LTD.
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.: 17
Registered Street Name: TUAS AVENUE 12
Registered Unit No.: -
Registered Building Name: -
Registered Postal Code: 639037

Current Vehicle Details

Vehicle No.: XD7447T
Make Description/Model: VOLVO / FM370 64R DC
Insurance Company Name: AXA INSURANCE PTE LTD