

ASS. REC. BY:

REF: CS/SMD190068981 Atd39

Special Instruction:

Surveior: Adrian

ASSIGNMENT (Office)

From (Person): Ruth Chua

of SMD

Date/Time: 18.4.19 10.06a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GW2811J

Insured:

STW 2253J

at Workshop m/s Progressive Car

Tel:

67415336

of Blk 3022 A Ubi Road 1 #01-45

Policy No: D18m TPV 01015096

Claim No:

CMTD1901790

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

9.4.2019

22.4.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 18.4.19 10.20a.m

Person Contacted:

Pei Wen

Vehicle: IN / OUT

Date/Time

Action/Instruction (✓) Estimate

GW2811J - (C4/EQJ160192G2/GH73K2

D.O.A. 19/04/2019

24/4 @ 10:30am - Sent compo mail pending estimate to Ruth Chua

Confirmed finalised \$1,324.12. 3days.
(Red: \$70.32, 39%)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Apr 2019 Sendback Est	11 Apr 2019 16:29 S\$2,194.44	18 Apr 2019 10:06 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	SUARAIDI BIN RAHMAT, ID: S1232566E, Tel: +6591550438, Email: NOEMAIL		
Main Claimant:	QUEK SIOW CHEOK, ID: S0054053F		
Vehicle Reg. No.:	GW2811J	Date of Loss:	09/04/2019 19:00 - :59 [190 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / CMTD1901790	Policy/Cover Note No.:	D18MTPV01015096 (Comprehensive)
Vehicle Reg. No. (Insured):	SJW2253J	Policy No. (Claimant):	
		Excess:	
Repairer:	Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46, 408716 Ubi - Tel: 67415336		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Ruth Chua Gek Tiang - 6329 5153]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/04/2019]		
Driver/Custodian (Insured):	SUARAIDI BIN RAHMAT (61 / Male), NRIC: S1232566E, Tel: +6591550438 Email: NOEMAIL		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Sent Message

This mail is associated with :

**GW2811J (CMTD1901790)
[SJW2253J]**

TP
QUEK SIOW CHEOK
Apr 9 2019 7:00PM
[SUARAI DI BIN RAHMAT]
Progressive Car Care Pte Ltd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 24/04/2019 10:38 AM.

To ruth.chua@sompo.com.sg

Subject GW2811J (CMTD1901790) [SJW2253J]

Dear Sir/Madam,

Please be informed that we have inspected the vehicle GW 2811J on 22/04/2019
We are pending estimate from repairer.

Regards,
Denise
LKK Auto

DOCUMENTS SUMMARY

There are no documents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/04/2019 11:24
Date Of Accident	09/04/2019 19:15
Exact Location Of Accident	FARRER ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GW2811J
Insured/Policyholder	
Name Of Registered Owner	QUEK SIOW CHEOK TRADING
Co Reg No	53161314C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-96173223

Vehicle Particulars

Manufacturer	NISSAN
Model	URVAN-3.0 D (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	37265
Cover Note Number	

Driver

Name of Driver	QUEK SIOW CHEOK
NRIC No	S0054053F
Date Of Birth	23/01/1953
Occupation	INDOOR
Date Of Driving Pass	10/04/1974
Driving Experience	44 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96173223
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 4 QUEEN'S ROAD #07-103 SINGAPORE
Postcode	260004
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : LO SIU YIN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE CAR CARE PTE LTD TEL 6741 5336

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJW2253J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	SUARAI DI RAHMAT
NRIC/Passport Number	S1232566E
Contact Number	91550438
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) I acknowledge that my insurer and the Insurers' lawyers/law firms may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIC to their third party service providers or agents (including the lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) My Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (a) above may be shared / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, law or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: 
NIC/PIN No.:

Sketch Plan #2

SKETCH PLAN

	Vehicle A - 6ND811J B - 5JW253J
	Legend

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 9/4/2019, Around 2:15pm. I was driving along farrier Road. It was traffic heavy at the time. As I wish to change lane from lane 3 to lane 4, I check the filter traffic is clear and I slowly my van to lane 4. While my almost complete move in to lane 4. vehicle B hit my rear rear right portion. that was a witness saw the whole process of this accident happen. He said is driver of vehicle B is wrong.

DECLARATION

I/We declare the foregoing particulars are true in every respect.
 Please be advised that your insurer may have a fourteen (14) days clause whereby the claim against your policy must be made within the stipulated timeframe from the day of occurrence. Kindly check your policy for more details.

Policyholder's Signature	Driver's Signature	Reporting Centre Personnel's Signature
Date & Time:	(if driver is not the policyholder) Date & Time:	Name: NRIC/PPN No.: <i>penven</i>

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 11 Apr 2019)
 Parts: N/A NISSAN URVAN 3.0 D (M) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Progressive Car Care Pte Ltd/GW2811J/11/04/2019 16:29
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*TAIL LAMP ASSY - RH <i>rear</i>	0.00	0.00	*230.80F
2	1	NA	*REAR BUMPER WITH STEP PANEL <i>side</i>	0.00	0.00	*860.60F
3	1	NA	*REAR BUMPER SIDE HOLDER - LH <i>side</i>	0.00	0.00	*18.10F
4	1	NA	*REAR BUMPER SIDE HOLDER - RH <i>side</i>	0.00	0.00	*18.10F
5	10	NA	*REAR BUMPER CLIPS <i>side</i>	0.00	0.00	*42.00F
Sub Total (S\$)						971.00 <i>726.8</i>
- Add. Disc. on L/H Items 10.00% (S\$)						97.16
Total Parts (S\$)						874.44 <i>654.12</i>

Progressive Car Care Pte Ltd/GW2811J/11/04/2019 16:29. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

PAID. 654.12

LAB. 670.00

1324.12

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	REAR BUMPER SENSOR <i>see memo</i>	220.00 <i>40</i>
Sub Total (\$\$)			220.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	500.00 <i>40</i>
<u>Labour Items</u>			
2	TO KNOCK OUT DENTS; CUT/WELD; REMOVE; REPLACE ACCIDENT PARTS	New	250.00 <i>20</i>
3	TO CHECK WIRING	New	20.00 <i>✓</i>
4	TO REMOVE; REPLACE REAR BUMPER SENSOR	New	100.00 <i>50</i>
5	TO TUFF-KOTE	New	30.00 <i>✓</i>
Gross Labour Cost (\$\$)			1,100.00 <i>670</i>

Progressive Car Care Pte Ltd/GW2811J/11/04/2019 16:20, Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment includes the latest and reliable CAR-O-4 BEST MARK 2 repair bench, draw sifter and the support dolly system to provide accurate re-alignment and speedy repairs.

Adrian King
22/04/19
P/P 03 Days.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Apr 2019 Sendback Est	11 Apr 2019 16:29 \$2,194.44	18 Apr 2019 10:06 Edit Adj Rpt	\$1,324.12 Edit Estimates	\$1,324.12 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	SUARAI DI BIN RAHMAT, ID: S1232566E, Tel: +6591550438, Email: NOEMAIL								
Main Claimant:	QUEK SIOW CHEOK, ID: S0054053F								
Vehicle Reg. No.:	GW2811J	Date of Loss:	09/04/2019 19:00 - :59 [190 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CMTD1901790	Policy/Cover Note No.:	D18MTPV01015096 (Comprehensive)						
Vehicle Reg. No. (Insured):	SIW2253J	Policy No. (Claimant):							
		Excess:							
Repairer:	Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46, 408716 Ubi - Tel: 67415336								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Ruth Chua Gek Tiang - 6329 5153]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 30/04/2019]								
Driver/Custodian (Insured):	SUARAI DI BIN RAHMAT (61 / Male) , NRIC: S1232566E, Tel: +6591550438 Email: NOEMAIL								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

**GW2811J (CMTD1901790)
[SJW2253J]**

**TP
QUEK SIOW CHEOK
Apr 9 2019 7:00PM
[SUARAI BIN RAHMAT]
Progressive Car Care Pte Ltd**

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports					1 per page ☐
No	Finalized On			Thumbnail	Print
		Sompo Insurance Singapore Pte. Ltd. (HQ)			
1	18/04/19 10:07	Accident Statement		 Load HTM	
		Progressive Car Care Pte Ltd (HQ)			
1	11/04/19 16:29	Repairer Estimates		 Load HTM	
Photos/Images					3 per page ☐
No	Finalized On			Thumbnail	Print
		Progressive Car Care Pte Ltd (HQ)			
1	11/04/19 16:27	1		 Load JPG	☒
2	11/04/19 16:27	2		 Load JPG	☒
3	11/04/19 16:27	3		 Load JPG	☒
4	11/04/19 16:27	4		 Load JPG	☒
5	11/04/19 16:27	5		 Load JPG	☒
6	11/04/19 16:27	6		 Load JPG	☒
7	11/04/19 16:27	7		 Load JPG	☒
8	11/04/19 16:27	8		 Load JPG	☒
9	11/04/19 16:27	9		 Load JPG	☒
10	11/04/19 16:27	10		 Load JPG	☒
11	11/04/19 16:27	11		 Load JPG	☒
12	11/04/19 16:27	12		 Load JPG	☒
13	11/04/19 16:27	13		 Load JPG	☒
14	11/04/19 16:27	14		 Load JPG	☒
15	11/04/19 16:27	15		 Load JPG	☒
16	11/04/19 16:27	16		 Load JPG	☒
17	11/04/19 16:27	17		 Load JPG	☒
18	11/04/19 16:27	18		 Load JPG	☒
19	11/04/19 16:27	19		 Load JPG	☒
20	11/04/19 16:27	20		 Load JPG	☒
21	11/04/19 16:27	21		 Load JPG	☒
22	11/04/19 16:27	22		 Load JPG	☒
23	11/04/19 16:27	23		 Load JPG	☒
24	11/04/19 16:27	24		 Load JPG	☒
25	11/04/19 16:27	25		 Load JPG	☒
26	11/04/19 16:27	26		 Load JPG	☒
27	11/04/19 16:27	27		 Load JPG	☒
28	11/04/19 16:27	28		 Load JPG	☒
29	11/04/19 16:27	29		 Load JPG	☒
30	11/04/19 16:27	30		 Load JPG	☒
31	11/04/19 16:27	31		 Load JPG	☒
32	11/04/19 16:27	32		 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
				☒
33	11/04/19 16:27	33	Load JPG	☒
34	11/04/19 16:27	34	Load JPG	☒
35	11/04/19 16:27	35	Load JPG	☒
36	11/04/19 16:27	36	Load JPG	☒
37	11/04/19 16:27	37	Load JPG	☒
38	11/04/19 16:27	38	Load JPG	☒
39	11/04/19 16:27	39	Load JPG	☒
40	11/04/19 16:27	40	Load JPG	☒
41	11/04/19 16:27	41	Load JPG	☒
42	11/04/19 16:27	42	Load JPG	☒
43	11/04/19 16:27	43	Load JPG	☒
44	11/04/19 16:27	44	Load JPG	☒
45	11/04/19 16:27	45	Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/04/19 13:56	General View	Load JPG	☒
2	30/04/19 13:56	General View	Load JPG	☒
3	30/04/19 13:56	General View	Load JPG	☒
4	30/04/19 13:56	General View	Load JPG	☒
5	30/04/19 13:56	General View	Load JPG	☒
6	30/04/19 13:56	General View	Load JPG	☒
7	30/04/19 13:56	General View	Load JPG	☒
8	30/04/19 13:56	General View	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	11/04/19 09:34	TP - GW2811J (TP/EQ) Accident Report	Load PDF	
2	18/04/19 10:06	PRI - LKK	Load HTM	
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	11/04/19 16:23	E-filed GIA report	Load PDF	
2	11/04/19 16:23	Driver's NRIC & LICENSE	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19006898/ATD3Q2

Date: 06/05/2019

REFERENCE

Handling Insurer: Sampo Insurance Singapore Pte. Ltd. Policy No: D18MTPV01015096

Claimant Vehicle No : GW2811J **Insured Vehicle No :** SJW2253J

Date of Loss: 09/04/2019 **Nature of Claim:** TP **Claim No:** CMTD1901790

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GW2811J
Make & Model: NISSAN URVAN, 3.0 D (M) **Engine No:** ZD30028315
Reg. Date: 13/05/2003 (Man. Year: 2003) **Chassis No:** JN1MG4E25Z0701020
Colour: Gold **Odometer:** 445950 km
Engine Capacity: 2953 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 195R15C **Rear Tyre Size:** 195R15C
Front Left Side: KAPSEN 6 mm **Rear Left Side:** KAPSEN 6 mm
Front Right Side: KAPSEN 6 mm **Rear Right Side:** KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	874.44	654.12	220.32	25.20
Miscellaneous Items	220.00	0.00	220.00	100.00
Labour	600.00	270.00	330.00	55.00
Paintwork Labour	500.00	400.00	100.00	20.00
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	2,194.44	1,324.12	870.32	39.66
+ GST 7.00/7.00% (\$\$)	153.61	92.69	60.92	39.66
Nett Amount (\$\$)	2,348.05	1,416.81	931.24	39.66

INSPECTION

Date of Assignment: 18/04/2019 **Present Location:** Progressive Car Care Pte Ltd (HQ)
Date Inspected: 22/04/2019 **Inspected At:** Progressive Car Care Pte Ltd (HQ)
 Blk 3022A Ubi Road 1, #01-45/46
 Singapore 408716

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 06 May 2019)	
Parts:	N/A	NISSAN URVAN 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GW2811J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*TAIL LAMP ASSY - RH	Not Necessary	230.80 F	*- F
2	1	NA	*REAR BUMPER WITH STEP PANEL	Deformed	660.60 F	*660.60 F
3	1	NA	*REAR BUMPER SIDE HOLDER - LH	Necessary	18.10 F	*18.10 F
4	1	NA	*REAR BUMPER SIDE HOLDER - RH	Necessary	18.10 F	*18.10 F
5	10	NA	*REAR BUMPER CLIPS	Necessary	44.00 F	*30.00 F
					Sub Total (S\$)	971.60 726.80
					- Add. Disc. on L,N Items 10.00/10.00% (S\$)	97.16 72.68
					Total Parts (S\$)	874.44 654.12

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	REAR BUMPER SENSOR (NOT NECESSARY)	220.00	0.00
Sub Total (S\$)			220.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	500.00	400.00
<u>Labour Items</u>				
2	TO KNOCK OUT DENTS; CUT/WELD; REMOVE; REPLACE ACCIDENT PARTS	New	450.00	200.00
3	TO CHECK WIRING	New	20.00	20.00
4	TO REMOVE; REPLACE REAR BUMPER SENSOR	New	100.00	50.00
5	TO TUFF-KOTE	New	30.00	0.00
Gross Labour Cost (S\$)			1,100.00	670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >