

ASS. REC. BY:

REF: CS/SPF 190069001 Jv d301 Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Abdul Rahman

of

SPF

Date/Time:

18.4.19 8.35a.m

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLL 5229U

Insured:

QX FOIH

at Workshop m/s

Kah motor

Tel:

82886302

of

6 A mandai estate

Policy No:

Claim No:

AEMD / 105 / 009 / 2019 / 040

Sum Insured:

Excess:

Make of Veh:

D.O.A

3.4.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

"wp"

H.O.D. Endorsement:

Date/Time:

18.4.19 10.46a.m

Person Contacted:

Anikka

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLL 5229U -x

QX FOIH - x

17/19

@ 342pm Anikka said vehicle has not send in for repair

17/19

@ 557pm check with Hwee Jie range \$3K - \$4K

REF: Hwee Jie

REF: SPF

ASSIGNMENT

From: Date: 21/5/2019

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SLL 5229U

at Workshop m/s: Kah Motor

of: 6A Mendai estate

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

10.30am (waiting)

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS up

Date: Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

mv-\$78000

RECEIVED 03 JUL 2019

Do Not Finalise

Veh No: SLL 5229U Yt Regn: 22 Feb 2017

Type: M.Cn / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Civic GJ 1597

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 35381 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MRHFC5650GT00116

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD AirRim or

Tyre Size: F: 205/55 R16

R:

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A: 3/4/19 D.O.I: 21/5/19

Survey held at: Kah motor

Des. of Damages: Frt / Rea / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☒ : Preli. Report  
☐ : Final Report

Days Of Repair: 3

Resurvey No. of Trip:

Survey Fee:

1) Date/Time, File Return to?

2) 3/7 - typist

Add Fee: ☐ Site Insp (\$)  
☐ Interview (\$)  
☐ Tech. Invs (\$)  
☐ Weekend (\$)

Transportation: 5 + RS, SI  
Photos  
Others

Report Format: TP

Lump Sum / I.B.I: (\$)

TOTAL

220
220

## Veron Chen (LKKAUTO)

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Wednesday, 19 June 2019 10:18 AM  
**To:** Anikka Lai  
**Cc:** SUR  
**Subject:** RE: SLL 5229U-DOA: 3/4/2019

Dear Anikka,

Liability please check with SPF officer.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Anikka Lai <anikkalai@honda.com.sg>  
**Sent:** Tuesday, 18 June 2019 5:51 PM  
**To:** Veron Chen (LKKAUTO) <veronchen@lkkauto.com>  
**Subject:** RE: SLL 5229U-DOA: 3/4/2019

Dear Veron,

Yet to proceed repair as we have not received any email to confirm the liability. Pls advise if you can.

Thank you

Warmest Regards

Anikka Lai  
Kah Motor Co. Sdn Bhd  
6A Mandai Estate  
Singapore 729903  
DID : 6514 5248 HP : 8288 6302  
Email: [anikkalai@honda.com.sg](mailto:anikkalai@honda.com.sg)

---

**From:** Veron Chen (LKKAUTO) <veronchen@lkkauto.com>  
**Sent:** Tuesday, 18 June, 2019 4:30 PM  
**To:** Anikka Lai <anikkalai@honda.com.sg>  
**Subject:** SLL 5229U-DOA: 3/4/2019

Dear Anikka,

Kindly advise vehicle status.

Vehicle has been repaired ?

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

## Nivitha (LKK Auto)

---

**From:** Abdul Rahman MOHAMAD SALIM (SPF)  
<Abdul\_Rahman\_Mohamad\_Salim@spf.gov.sg>  
**Sent:** Thursday, 18 April 2019 8:35 AM  
**To:** Admin-D (LKKAuto)  
**Cc:** Rosalyn TAN (SPF); Frankie THAY (SPF); Hafizul Farhan RAHMAT (SPF)  
**Subject:** SLL5229U - TP CLAIMS AGAINST QX701H DOA: 03/04/2019

Your Ref : SLL5229U  
Our Ref : AEMD/105/009/2019/040

Dear Nivitha,

**RTA involving police veh QX701H and other veh SLL5229U on 3 Apr 2019**

Your preceding mail noted and refers wrt refer to the above matter.

Please assign a Pre-Repair Inspection for Vehicle **SLL5229U** at the following address:

**Kah Motor Co. Sdn Bhd**  
**6A Mandai Estate**  
**Singapore 729903**

For appointment, please contact DID : 6514 5248 HP : 8288 6302  
Email: [anikkalai@honda.com.sg](mailto:anikkalai@honda.com.sg)

Thanks.

Abdul Rahman (Mr)  
Accident Claims Officer  
Automotive Engineering & Management Division  
Police Logistics Department  
Singapore Police Force  
DID: (65) 6478 4840 | FAX: (65) 6478 4848



**HOME TEAM**  
TRANSFORMATION 2025  
One Home, One Team  
Building Our Future Together

**WARNING:** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

---

**From:** Admin-D (LKKAuto) <admin-d@lkkauto.com>  
**Sent:** Thursday, 11 April 2019 4:26 PM  
**To:** 'Anikka Lai' <anikkalai@honda.com.sg>; Frankie THAY (SPF) <Frankie\_THAY@spf.gov.sg>  
**Cc:** Abdul Rahman MOHAMAD SALIM (SPF) <Abdul\_Rahman\_Mohamad\_Salim@spf.gov.sg>; Hafizul Farhan RAHMAT (SPF) <Hafizul\_Farhan\_RAHMAT@spf.gov.sg>; Rosalyn TAN (SPF) <Rosalyn\_TAN@spf.gov.sg>  
**Subject:** FW: SLL5229U - TP CLAIMS AGAINST QX701H DOA: 03/04/2019  
**Importance:** High

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	8877C
<b>Vehicle Details</b>	
Vehicle No.:	SLL5229U
Vehicle to be Exported:	No
Intended Deregistration Date:	22 May 2019
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.6 VTI CVT
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	R16B21601420
Chassis No.:	MRHFC5650GT001116
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$20,818.00
Original Registration Date:	22 Feb 2017
First Registration Date:	22 Feb 2017
Transfer Count:	0
Actual ARF Paid:	\$21,146.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Feb 2027
PARF Rebate Amount:	\$15,859.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	21 Feb 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,889.00
COE Rebate Amount:	\$39,456.00
<b>Total Rebate Amount:</b>	<b>\$55,315.00</b>

The information contained herein is correct as at 22 May 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	04/04/2019 18:48
Date Of Accident	03/04/2019 10:30
Exact Location Of Accident	51 AMK AVE9 BASEMENT CARPARK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL5229U
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TOH GUO WEI
NRIC No	S8408877C
Email Address	JPS_SG@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-96168160
Alternative Phone No	OTHERS-96168160

### Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC 1.6 VTI CVT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2019-00002083
Cover Note Number	NA

### Driver

Name of Driver	TOH GUO WEI
NRIC No	S8408877C
Date Of Birth	24/03/1984
Occupation	INDOOR
Date Of Driving Pass	18/11/2005
Driving Experience	13 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96168160
Fax Number	
Contact Number	OTHERS-96168160
Email Address	JPS_SG@YAHOO.COM.SG

Address	NA
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	ANG MO KIO DIVISION HQ
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO POLICE REPORT NO F/20190403/2037 LOGDE AT ANG MO KIO DIVISION HQ ON 03 APRIL 2019 AT ABOUT 1021HRS, I WAS INFORMED THAT MY PRIVATE CAR REGISTRATION BEARING SLL5229U, A WHITE HONDA CIVIC, WHICH WAS PARKED AT THE BASEMENT CARPARK OF ANFG MO KIO POLICE DIVISION, HAD INVOLVED IN AN ACCIDENT ANOTHER 2 POLICE VEHICLES. THE 2 OTHER POLICE VEHICLES ARE: POLICE VAN GBC792H AND POLICE CAR QX701. I AM LODGING THE POLICE REPORT FOR REPAIR CLAIMS

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	QX701H
Vehicle Make/Model/Colour	HYUNDAI AVANTE 1.6 AT
Details Of Properties	NA
Vehicle Category	GOVERNMENT
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	UNKNOWN
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	



No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number	GBC792H
Vehicle Make/Model/Colour	NISSAN URVAN
Details Of Properties	NA
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	UNKNOWN
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

# Sketch Plan

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)  
I understand, acknowledge, agree and consent that:  
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:  
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;  
(ii) investigating the accident and/or my claims;  
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;  
(iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")  
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and  
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


VERIFIED BY AJAX MARS  
REPORTING OFFICER  
Hashim Kamari

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre  
Personnel

## Sketch Plan





# SINGAPORE POLICE FORCE



F/20190403/2037

1 of 2

**POLICE REPORT (NP299)**

Report No. F/20190403/2037

Police Station Of Origin  
Ang Mo Kio Division HQ  
51 Ang Mo Kio Avenue 9 SINGAPORE  
569784  
Tel No: 1800-2180000

Date/Time Report Made 03/04/2019 12:02	Vide Report No. F/20190403/0079	Station Diary No.	
Name Of Informant TOH GUO WEI	Address C/O 51 Ang Mo Kio Avenue 9 SINGAPORE 569784		
ID Type / ID No. NRIC NO / S8408877C	Contact No. Home/Office 68522999	Mobile 96168160	
Nationality SINGAPORE CITIZEN	Email Address TOH Guo Wei@spf.gov.sg		
Occupation Police officer	Sex Male	Age 35	Date of Birth 24/03/1984
Institution/School Name	Language English	Race Chinese	
Date/Time Of Incident 03/04/2019 10:00 - 03/04/2019 10:25	Location Of Incident 51 ANG MO KIO AVENUE 9 ANG MO KIO POLICE DIVISIONAL HQ* SINGAPORE 569784 Basement carpark		

**Brief details.**

On <sup>3</sup> April 2019 at about 1021hrs, I was informed that my private car registration bearing SLL5229U, a white Honda Civic, which was parked at the basement car park of Ang Mo Kio Police Division, had involved in an accident involving another 2 police vehicles. The 2 other police vehicles are; Police Van GBC792H and Police Car QX701H.

I am lodging the police report for repair claims.

Signature Of Officer Recording The Report: F / Insp TOH GUO WEI	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 03/04/2019 12:02
Officer In-Charge Of Case: F / Ang Mo Kio Police Divisional Investigation Branch / Insp WEE HUI LING, ANGELINA Contact No.:	Classification Of Case:

Authentication Stamp



**SINGAPORE  
POLICE FORCE**



F/20190403/2037

2 of 2

**POLICE REPORT (NP299)**

**CONTINUATION OF REPORT**

**Report No. F/20190403/2037**

Signature Of Officer Recording The Report:

F / Insp TOH GUO WEI

Signature Of Interpreter:  
Not applicable

Officer In-Charge Of Case:  
F / Ang Mo Kio Police Divisional Investigation Branch /  
Insp WEE HUI LING, ANGELINA  
Contact No.:

Authentication Stamp

Signature Of Informant:

Date/Time:  
03/04/2019 12:02

Classification Of Case:

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Fax: 64784848

Attn: Mr Frankie

From: Anikka (Kah Motor)

**QUOTATION**

Mobile: 82886302

GST Reg No.: M200050223

Fax: 63625015

Company Ref. No.: S60FC1380G

21/5 - 10:30am Survey

Customer : SINGAPORE POLICE  
TANGLIN POST OFFICE  
PO BOX 60  
SINGAPORE 912402

Registration No : SLL5229U

Chassis No : MRHFC5650GT001116

Model : CIVIC 1.6 VTI YM2016

Owner's Name : TOH GUO WEI

Ins Policy No. :

Date of Accident : 3/4/2019

Document No. : SQT19001524 Page 1

Date : 4. Apr 2019

Customer No. : SP0000001

Svc Advisor : ANIKKA LAI SWEE KAM

Engine No : R16B21601420

Date | Time : 4. Apr 2019 4:46:01 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: )						
	OWNER: TOH GUO WEI						
	OWNER INSURER : FWD						
	ACC DATE: 03/04/2019						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: SPF						
	TP VEH: QX701H						
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER 00 ✓	1	617.20	25	462.90	32.40	495.30
71593-TEA-T01	SPACERR.RR.BUMPER SIDE nec ✓	1	11.50	25	8.62	0.60	9.22
71598-TEA-T01	SPACERL.RR.BUMPER SIDE nec ✓	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIP,BUMPER nec ✓	1	2.30	25	1.72	0.12	1.84
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER SCR ✓	1	36.40	25	27.30	1.91	29.21
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER ?	1	164.70	25	123.52	8.65	132.17
	Sum Item				632.68	44.28	676.96
BKBU02R	REMOVE & RENEW RR BUMPER INCLUDING FITTINGS ON	1	1000.00	560	1000.00	70.00	1070.00
BP01R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (1P)	1	800.00	450	800.00	56.00	856.00
BOSUN	SUNDRIES install	1	100.00	20	100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	120.00	80	120.00	8.40	128.40
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	100.00		100.00	7.00	107.00
	Sum Labor				2120.00	148.40	2,268.40

Survey By: Huan Jit - Lkk

Date & Time: 21/5/19

Excess: -

Total Amount: 2,752.68 192.68 2,945.36

Total (Inclusive of GST): 2,945.36

Printed on 4/4/2019 5:42:30 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn Bhd, it will be refunded.



# KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

## QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G


Customer : SINGAPORE POLICE  
TANGLIN POST OFFICE  
PO BOX 60  
SINGAPORE 912402  
Registration No : SLL5229U  
Chassis No : MRHFC5650GT001116  
Model : CIVIC 1.6 VTI YM2016  
Owner's Name : TOH GUO WEI  
Ins Policy No. :  
Date of Accident : 3/4/2019

Document No. : SQT19001524 Page 2  
Date : 4. Apr 2019  
Customer No. : SP0000001  
Svc Advisor : ANIKKA LAI SWEE KAM  
Engine No : R16B21601420  
Date | Time : 4. Apr 2019 4:46:01 PM  
Surveyor Name :  
Survey Date :  
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Status	P/P						
Signature							

Hwee Jia-LKK

3days



64784840

Printed on 4/4/2019 5:42:30 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF19006900/Jvd3e2		
ACCIDENT CLAIM SECTION (SPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333		Date : 19-07-2019		
ATTN : ABDUL RAHMAN		Code : SPF		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	QX 701H	Veh. Inspected	SLL 5229U	
Policy No.		Coverage (\$)	0.00	
Claim No.	AEMD/105/009/2019/040	Excess (\$)	0.00	
Assign From	ABDUL RAHMAN	Assign Date	18/04/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA CIVIC	c.c	1597	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	MRHFC5650GT001116	Colour	WHITE	
Odometer	35381	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm	
L/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm	
R/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm	
L/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	03/04/2019	Inspection Date	21/05/2019	
Survey held at	KAH MOTOR.CO.SDN.BHD 6A MANDAI ESTATE SINGAPORE 729903			
<b>5a. Remarks</b>				
A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 5229U**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FACE ASSY, RR.BUMPER (SN)	DENTED	462.90	462.90
1	SPACERR.RR.BUMPER SIDE (SN)	NECESSARY	8.62	8.62
1	SPACERL.RR.BUMPER SIDE (SN)	NECESSARY	8.62	8.62
1	CLIP, BUMPER (SN)	NECESSARY	1.72	1.72
1	GARNISH, RR.BUMPER LOWER (SN)	SCRATCHED	27.30	27.30
1	BEAM COMPRR.BUMPER (SN)	* CHECK	123.52	-
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
			732.68	529.16
<b>LABOUR</b>				
	REMOVE & RENEW RR BUMPER INCLUDING FITTINGS ON.		1,000.00	560.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (1P)		800.00	450.00
	REMOVE & INSTALL REVERSE SENSORS - 4PCS (N).		120.00	80.00
	APPLY BODY UNDERSIDE COATING (N).	NOT NECESSARY	100.00	-
			2,020.00	1,090.00
<b>GRAND TOTAL</b>			<b>2,752.68</b>	<b>1,619.16</b>
<b>RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$123.52 NETT)</b>				<b>1,619.16</b>

Report Ref No. CS/SPF19006900/Jvd3e2

**ONG HWEE JIE**

Automotive Assessor

**ADRIAN LING WAI PING**

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.