

CC3/MSG19006923/Uq,d3N2

108/11/231 wef

ASS. REC. BY: Marcus

REF:

MS161

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SGN8976A
 at Workshop m/s SP.
 of _____
 Insured: 53478033
 Policy No. MSD/VPCP/18-000867
 Claims No. MSC/V/19-000468
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs: 12 days Res: Yes or NoLum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Date / Time Action / Instruction

21/4/19 14:05 29-11-2021
spare tyre missing ref 8849

22/4 @ 1:43pm - sent police report via email to MS16.

16/5/19 conf. and 1/5 @ 8800 with Alin. (Ref 29407.70, 76%)

RECEIVED 16 MAY 2019

Date/Time, File Pass to?

☐

: Prelim. Report

11/14/5 11/15/5

☐

: Final Report

Date/Time, File Return to?

2)

Report Format:

MER-TP

Lump Sum / I.B.I. (\$

8800

Days Of Repair: 12Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) Photos

) Others

TOTAL

250
10

260

Veh No: SGN8976A Yr Regn: 11/06Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Toyota wish cc 1794Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 370706 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: 2NE100325270Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55-R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm R/Bal: 6 mmL/Bal: 6 mm L/Bal: 6 mmD.O.A. 17/4/19 D.O.I. 18/4/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & Lf.
 The U/C / Chassis frame / Body Structure affected due to collision.



ANNOUNCING Think One Automobile & Trading
as sgCarMart Premium Dealer for the 8th Consecutive Year

**Think One**

Automobile & Trading Pte Ltd
Trading Pte Ltd
Finance Pte Ltd
Leasing Pte Ltd
Automotive Pte Ltd

Toyota Wish

Price Range

Depreciation

> 10 year

Vehicle Type

Submit

Advanced Search

Home > Used Cars > Mr Benz Traders > Toyota Wish 1.8A X Sunroof (COE till 11/2021)

Toyota Wish 1.8A X Sunroof (COE till 11/2021)

- Overview
- Financial
- Insurance
- Accessories
- Similar
- Research
- Photos
- Map
- PREMIUM AD

Price	\$28,600		
Depreciation	\$11,150 /yr	Reg Date	10-Nov-2006 (2yrs 6mths 22days COE left)
Mileage	N.A.	Manufactured	2006
Road Tax	\$1,264 /yr	Transmission	Auto
Dereg Value	\$14,374 as of today (change)	OMV	\$18,872
COE	\$28,027	ARF	\$20,760
Engine Cap	1,794 cc	Power	97.0 kW (130 bhp)
Curb Weight	1,320 kg	No. of Owners	1
Type of Vehicle	MPV		

Features

Powerful And Reliable 16 Valves VVT-i DOHC Engine, Smooth 4 Speed Steptronic Gearbox, Digital Climate Control Aircon, Airbags, ABS, 7 Seaters.

Accessories

Sports Rims, DVD Player, Reverse Sensors, Leather Upholstery, Knockdown Rear Seats.

Description

1 Owner! Rare Wish 1.8A With Sunroof/Rear Aircon Excellent Condition, 100% Accident Free, Powerfull Engine, Well Maintained Gearbox, Smooth Driving, Call Now For Viewing.

Category

COE Car, Premium Ad Car

Status

Available

Resources



Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free
Find out the market value of your existing car for free. Get started



- Shortlist
- Compare
- Add note
- Report Error
- More Actions

Seller Information

Company	Mr Benz Traders	
	» dealer's pricelist	
	» 69 vehs sold 69 vehs available	
Address	210 Turf Club Road Lot A6	
	Search cars nearby this location	
Location	Car Mall @ The Grandstand	
Office No	63461282	
Contact Person(s)	Stanley Loo	90012123
	Ansel	98607949
	Bernard	96609891
	Chester	90676766

Posted on: 13-Apr-2019 | Last Updated on: 14-Apr-2019

Upfront Payment [» more Financial info](#)

Transfer Fee \$25

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Business
Owner ID:	1353B

Vehicle Details

Vehicle No.:	SGN8976A
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 A
Primary Colour:	Grey
Manufacturing Year:	2006
Engine No.:	1ZZ2691721
Chassis No.:	ZNE100325270
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$18,561.00
Original Registration Date:	30 Nov 2006
First Registration Date:	30 Nov 2006
Transfer Count:	1
Actual ARF Paid:	\$20,418.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	29 Nov 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$28,027.00
COE Rebate Amount:	\$14,651.00
Total Rebate Amount:	\$14,651.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 18 Apr 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/04/2019 15:31
Date Of Accident	17/04/2019 15:30
Exact Location Of Accident	ALONG ECP TWDS CHANGI
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGN8976A
Insured/Policyholder	
Name Of Registered Owner	TRUE DRIVE
Co Reg No	-
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-91099266

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	18-MJ000977-R00
Cover Note Number	-

Driver

Name of Driver	CHARLES LEE BOON KENG(CHARLES LI WENQING)
NRIC No	S7233504Z
Date Of Birth	11/09/1972
Occupation	OUTDOOR
Date Of Driving Pass	16/03/1993
Driving Experience	26 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91099266
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 141 SERANGOON NORTH AVE 2 #10-02
Postcode	550141
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	6
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : MARIANA GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	SERANGOON NORTH NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 108 SERANGOON NORTH AVENUE 1 #01-709 , POSTCODE: 550108 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2849999 - FAX NO: 63431742
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO POLICE REPORT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJX7803J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SMJ311X
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SHB5553H
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category TAXI
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number SJV6411Z
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 5

Vehicle Registration Number SLP8144P
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver

NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name CHARLES LEE BOON KENG(CHARLES LI WENQING)
Approximate Age
Injuries Sustain BODY
Injured person in which vehicle? SGN8976A
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

DETAILS OF INJURED PERSON 2

Name MARIANA
Approximate Age
Injuries Sustain BODY
Injured person in which vehicle? SGN8976A
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

Date of Accident : 17/4/19 Accident Time: 15:30 (24-HR-Format)
Accident Place : Along ECP towards Changi Airport
Vehicle No. (Car Plate No.) : SGW 876A Make/Model: _____
Insurance Company : TM Policy No: MT000977
Owner or Company Name /IC No. : True Drive / 53341363B
Owner or Company Contact No. : _____ Owner's Hp _____ Company Tel _____
DRIVER'S Name / IC No. : Charles Lee Boon Keng / 57233504Z
DRIVER'S Date Of Birth : 11/9/1972 DRIVER'S License Pass Date 16/3/1993
Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: _____
DRIVER'S Address : 11/141 Serangoon North Ave 2 #10-02
DRIVER'S Contact No./ Alt No. : 1) _____ 2) 5550141
DRIVER'S Occupation : INDOOR \ OUTDOOR (e.g. working inside or outside office)
Email Address : _____
Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET
Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance
Number of Passengers (Including Driver): 2 person
Was there any video Captured by car camera: YES \ NO
Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose
Any Injury (If YES, Pls state): yes

Other Party Driver's Particular (if any)

Vehicle No: SJX 7803J (W316)	Vehicle No: SMJ 311X
Vehicle Make/Model: _____	Vehicle Make/Model: _____
Name Driver: _____	Name Driver: _____
IC No. Driver/Contact: _____	IC No. Driver/Contact: _____

* NEW - Passenger's name & gender:

Mariana (F)

Vehicle D SHB 5553H
Vehicle E SJV 6411Z
Vehicle F SLP 8144P

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

					A - SGN 8976A
					B - SJX 7803J
					C - SMJ 311X
					D - SHB 5553H
					E - SJV 6411Z
					F - SLP 8144P

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to the police report T/20190417/2203

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20190417/2203

Police Station Of Origin:
Serangoon North NPP
108 Serangoon North Ave 1 #01-709
SINGAPORE 550108
Tel No: 1800-2849999

1 of 5

Report No. T/20190417/2203

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 17/04/2019 21:33	Vide Report No.:	Station Diary No.: 24
--	------------------	--------------------------

Informant's Particulars

Name of Informant: CHARLES LEE BOON KENG			Address: APT BLK 141 SERANGOON NORTH AVENUE 2 #10-02 SINGAPORE 550141		
ID Type / ID No.: NRIC NO / S7233504Z			Contact No.: Home/Office: Mobile: 91099266		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 46	Date of Birth: 11/09/1972	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: PRIVATE HIRE			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 17/04/2019 15:30	Type of Location: Expressway
Location: Along Road 1 EAST COAST PARKWAY Along ECP under Marine Parade Flyover towards Changi Airport				
Weather: Sunny		Road Surface: Dry	Road Speed Limit: 90 Km/h	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Chain Collision			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGN8976A	Car				Seriously Damaged	1
SHB5553H	Car				Slightly Damaged	0
SJV6411Z	Car				Seriously Damaged	0
SJX7803J	Car				Seriously Damaged	0
SLP8144P	Car				Slightly Damaged	0



SINGAPORE POLICE FORCE



T/20190417/2203

Police Station Of Origin:
Serangoon North NPP
108 Serangoon North Ave 1 #01-709
SINGAPORE 550108
Tel No: 1800-2849999

2 of 5

Report No. T/20190417/2203

CONTINUATION OF REPORT

Details of Vehicle Involved						
Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
SMJ311X	Car				Seriously Damaged	0

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	CHARLES LEE BOON KENG	ID No.	S7233504Z
Related Vehicle	SGN8976A (Car)	Contact No.	91099266
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	05	Degree of Injury	Slight

Driver		Degree of Injury		Slight	
Name	Swee Hin Kwang			ID No.	S1418503H
Related Vehicle	SHB5553H (Car)			Contact No.	90900998
Hospital/Clinic	NIL			Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL			Date Discharge	NIL
No. of Days granted Medical Leave	NIL			Degree of Injury	NIL

Driver		Degree of Injury		Slight	
Name	Nuzrul Hakiem Bin Abbas			ID No.	S7401451H
Related Vehicle	SJV6411Z (Car)			Contact No.	96756393
Hospital/Clinic	NIL			Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL			Date Discharge	NIL
No. of Days granted Medical Leave	NIL			Degree of Injury	NIL



Police Station Of Origin:
Serangoon North NPP
108 Serangoon North Ave 1 #01-709
SINGAPORE 550108
Tel No: 1800-2849999

CONTINUATION OF REPORT

Driver			
Name	Guo Jintao	ID No.	S8873814D
Related Vehicle	SJX7803J (Car)	Contact No.	81198254
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	Koh Sien Ming Michael	ID No.	S6926088H
Related Vehicle	SLP8144P (Car)	Contact No.	96251296
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	Andrew Ann Huan Chen	ID No.	S9109958F
Related Vehicle	SMJ311X (Car)	Contact No.	97323880
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 17/04/2019 at about 1530hours along ECP under Marine Parade Flyover towards Changi Airport, I was driving my vehicle bearing car plate number SGN 8976A on the first lane, extreme right. There was a car in front of me bearing car plate number SLP8144P suddenly slow down, came to a stop and to avoid any collision, I applied my e-brake and came to a full stop. There was a distance between me and the first car and I didn't knock until the first car.

After which I felt an impact and there was a car behind me bearing car plate number SJX7809J hit against the rear of my car. The first impact resulted my car to shift forward and bump into the car in front of me. Subsequently I felt that another impact as there was another car also involved in this chain collision.

I then get down the vehicle and there were a total of 6 vehicles involved in this chain collision.



**SINGAPORE
POLICE FORCE**



T/20190417/2203

Police Station Of Origin:
Serangoon North NPP
108 Serangoon North Ave 1 #01-709
SINGAPORE 550108
Tel No: 1800-2849999

4 of 5

Report No. T/20190417/2203

CONTINUATION OF REPORT

The following vehicles are in sequence for the chain collision:

- 1)SLP8144P
- 2)SGN8976A
- 3)SJX7803J
- 4)SMJ311X
- 5)SHB5553H
- 6)SJV6411Z

Traffic Police came down, took photos and all of our particulars. Ambulance came down to made a check on one of the driver and no one was conveyed to hospital. No one was injured during this accident. I wish to state that I was carrying a passenger during the point of time as I am private hire driver. I also wish to state that I am driving 90km/hour. I do have an in-car camera but only able to capture the front view of my car. The driver in front of me also verified with me that I didn't knock until his car.

That's all.



**SINGAPORE
POLICE FORCE**



T/20190417/2203

Police Station Of Origin:
Serangoon North NPP
108 Serangoon North Ave 1 #01-709
SINGAPORE 550108
Tel No: 1800-2849999

5 of 5

Report No. T/20190417/2203

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

F /

Sgt 2 ALVIN OH WEI JIE

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Staff Sgt SUFIYAN BIN KHAIRI

Contact No.: 65476390

Signature Of Informant:

Date/Time:

17/04/2019 21:33

Classification Of Case:

SN 151

Authentication Stamp

NP168



Signature:

Singapore Police Force

FASTECH AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

VEHICLE NO:SGN 8976A

QTY	PARTICULAR
1 PCS	REAR WINDSCREEN
1 PCS	REAR WINDSCREEN MOULDING
1 PCS	TAILGATE 1245.10
1 PCS	TAILGATE INNER LOCK
1 PCS	TAILGATE REAR LOGO
1 PCS	TAILGATE 'WISH' EMBLEM
1 PCS	TAILGATE INNER TRIM BOARD 488.10
1 SET	TAILGATE INNER TRIM BOARD CLIPS
1 PCS	TAILGATE WEATHERSTRIP
1 PCS	TAILGATE OUTER CHROME MOULDING
2 PCS	TAILGATE DAMPERS @\$350.00
1 PCS	TAILGATE INNER HOLDER GARNISH
1 PCS	REAR BUMPER 481.10
2 PCS	REAR BUMPER REFLECTORS @\$105.00
2 PCS	REAR BUMPER SIDE HOLDERS @\$68.50
1 SET	REAR BUMPER CLIPS
2 PCS	REAR BUMPER DAMPERS @\$55.60
1 PCS	REAR END PANEL 581.10
1 PCS	REAR END PANEL LOWER MEMEBR
1 PCS	REAR END PANEL TOP GARNISH
2 PCS	TAILLAMPS @\$458.10
2 PCS	TAILLAMP HOUSING PANELS @\$455.10 408.10
1 PCS	REAR FLOOR PANEL
1 PCS	REAR FLOOR PANEL TOP BOARD
2 PCS	REAR FENDERS @\$977.10
2 PCS	REAR FENDER INNER TRIM BOARDS @\$605.10
1 SET	REAR FENDER INNER TRIM BOARD CLIPS
1 PCS	REAR EXHAUST
2 PCS	REAR EXHAUST MOUNTINGS @\$65.00
1 PCS	REAR EXHAUST HEAT SHIELD 166.50
1 PCS	REAR SPARE TYRE BRACKET & CARRIAGE 399.90
1 PCS	REAR AIR VENT
1 PCS	BONNET
1 PCS	BONNET INSULATOR
1 SET	BONNET INSULATOR CLIPS
1 PCS	BONNET LOCK
1 PCS	BONNET OUTER CHROME MOULDING
2 PCS	HEADLAMPS @\$689.10
1 PCS	FRONT BUMPER 481.10
1 PCS	FRONT BUMPER REINFORCEMENT
1 PCS	FRONT BUMPER SPONGE
2 PCS	FRONT BUMPER SIDE HOLDERS @\$65.50
1 SET	FRONT BUMPER CLIPS
2 PCS	FRONT BUMPER FOG LAMP COVERS @\$68.00
1 PCS	FRONT BUMPER CENTRE GRILLE
1 PCS	FRONT GRILLE

not Authorised
N/A
12/4/19
4/5 = 8800/
1247.

11	\$1,288.50	X
11	\$128.70	/
Body ID	\$1,866.10	/
11/11	\$388.80	/
11	\$68.10	/
11	\$60.50	X
11/11	\$645.10	/
11	\$50.00	/
11	\$299.50	/
11/11	\$388.20	/
11	\$700.00	X
11	\$45.00	X
11	\$665.30	/
11	\$210.00	X
11	\$137.00	/
11	\$50.00	/
11/11	\$111.20	/
11/11	\$699.10	/
11/11	\$211.50	/
11	\$288.60	/
11	\$916.20	/
11/11	\$910.20	100
11	\$1,120.10	X
11	\$588.20	X
11	\$1,954.20	X
11/11	\$1,210.20	/
11	\$50.00	X
11	\$788.50	X
11	\$130.00	X
11	\$211.10	/
11	\$450.50	/
11	\$121.00	/
11	\$678.10	X
11	\$211.50	X
11	\$50.00	X
11	\$145.50	/
11	\$155.30	X
11	\$1,378.20	/
11	\$830.00	/
11	\$266.20	/
11	\$166.50	/
11	\$131.00	X
11	\$50.00	/
11	\$136.00	X
11	\$188.20	X
11	\$166.60	/

1 PCS	FRONT BRACE PANEL
1 PCS	FRONT SUPPORT PANEL
1 PCS	AIR CON CONDENSER
1 PCS	AIR CON SUCTION HOSE
1 PCS	AIR CON DISCHARGE HOSE
1 PCS	RADIATOR
1 PCS	RADIATOR FAN MOTOR
1 PCS	RADIATOR FAN BLADE
1 PCS	RADIATOR FAN COWLING
2 PCS	HORN UNITS @\$105.00
2 PCS	FRONT FENDERS @\$650.10
2 PCS	FRONT FENDER INNERSHIELDS @\$195.10

7-1	\$121.50	✓
2	\$688.10	✓
5-1	\$1,213.10	X
17	\$395.50	X
17	\$388.10	X
17	\$1,866.50	X
17	\$450.50	X
17	\$150.40	X
17	\$209.10	X
17	\$210.00	X
17	\$1,300.20	X
17	\$390.20	X
	\$28,687.70	

1 PCS	S.NETT
1 PCS	REAR BUMPER REVERSE SENSOR
1 PCS	REAR END PANEL SEALANT
1 PCS	REAR FLOOR PANEL INSULATOR
1 PCS	REAR WINDSCREEN SEALANT
1 SET	REAR LICENCE PLATE W/HOLDER
1 SET	FRONT LICENCE PLATE W/HOLDER
1 BOL	RADIATOR COOLANT

shuttl	\$280.00	200
re	\$50.00	✓
re	\$200.00	100
re	\$50.00	40
17	\$50.00	X
one	\$50.00	40
17	\$50.00	X

LABOUR CHARGES:

TO CHECK WIRING
TO DISMANTLE & REPLACING REAR REVERSE SENSOR
TO DISMANTLE & REFIX REAR WINDSCREEN
TO TRANSFER TAILGATE MECHANISM
TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTREY
TO DISMANTLE & REFIX REAR EXHAUST
TO DISMANTLE & REFIX PETROL TANK
TO MOUNT VEHICLE ON CAR O-LINER
TO REFILL AIRCON GAS
TO SPRAY RUST PROOFING
LABOUR FOR PANEL BEATING & REPLACING PARTS
TO PUTTY & SPRAY PAINTING

\$80.00	30
\$80.00	50
\$150.00	120
\$100.00	60
\$150.00	80
\$100.00	60
17	\$100.00 X
17	\$380.00 X
	\$150.00 100
	\$200.00 80
	\$2,800.00 1500
	\$2,500.00 1800

TOTAL \$36,207.70

1-109145
\$185.87



LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG19006923/UQD3N2

Date: 17/05/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VPCP/18-000867
Claimant Vehicle No :	SGN8976A	Insured Vehicle No :	SJX7803J
Date of Loss:	17/04/2019	Nature of Claim:	TP
		Claim No:	MSC/V/19-000468

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGN8976A	Engine No:	1ZZ2691721
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	ZNE100325270
Reg. Date:	30/11/2006 (Man. Year: 2006)	Odometer:	310706 km
Colour:	Grey		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R17	Rear Tyre Size:	205/55R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	29,417.70	8,615.87	20,801.83	70.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,790.00	3,880.00	2,910.00	42.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	36,207.70	12,495.87	23,711.83	65.49
Approved Total (Overridden) (S\$)		8,800.00		
(S\$)	36,207.70	8,800.00	27,407.70	75.70
+ GST 7.00/7.00% (S\$)	2,534.54	616.00	1,918.54	75.70
Nett Amount (S\$)	38,742.24	9,416.00	29,326.24	75.70

INSPECTION

Date of Assignment:	24/04/2019	
Date Inspected:	18/04/2019 Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	12.0 days	

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 May 2019)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGN8976A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR WINDSCREEN	Not Necessary	1,288.50 F	*- FL
2	1	*REAR WINDSCREEN MOULDING	Necessary	128.70 F	*128.70 FL
3	1	*TAILGATE	Badly Dented	1,866.10 F	*1,245.10 FL
4	1	*TAILGATE INNER LOCK	Dented/Jammed	388.80 F	*388.80 FL
5	1	*TAILGATE REAR LOGO	Necessary	68.10 F	*68.10 FL
6	1	*TAILGATE WISH EMBLEM	Not fitted	60.50 F	*- FL
7	1	*TAILGATE INNER TRIM BOARD	Deformed/Torn	645.10 F	*488.10 FL
8	1	*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 F	*50.00 FL
9	1	*TAILGATE WEATHERSTRIP	Torn	299.50 F	*299.50 FL
10	1	*TAILGATE OUTER CHROME MOULDING	Bent/Cracked	388.20 F	*388.20 FL
11	2	*TAILGATE DAMPERS	Not Necessary	700.00 F	*- FL
12	1	*TAILGATE INNER HOLDER GARNISH	Not Necessary	45.00 F	*- FL
13	1	*REAR BUMPER	Distorted	665.30 F	*481.10 FL
14	2	*REAR BUMPER REFLECTORS	Not Necessary	210.00 F	*- FL
15	2	*REAR BUMPER SIDE HOLDERS	Bent	137.00 F	*137.00 FL
16	1	*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
17	2	*REAR BUMPER DAMPERS	Bent/Dented	111.20 F	*111.20 FL
18	1	*REAR END PANEL	Badly Dented	699.10 F	*581.10 FL
19	1	*REAR END PANEL LOWER MEMBER	Badly Dented	211.50 F	*211.50 FL
20	1	*REAR END PANEL TOP GARNISH	Twisted	288.60 F	*288.60 FL
21	2	*TAILLAMPS	Cracked	916.20 F	*916.20 FL
22	1	*TAILLAMP HOUSING PANELS	O/s Dented	910.20 F	*408.10 FL
23	1	*REAR FLOOR PANEL	Repair	1,120.10 F	*- FL
24	1	*REAR FLOOR PANEL TOP BOARD	Serviceable	588.20 F	*- FL
25	2	*REAR FENDERS	Repair	1,954.20 F	*- FL
26	2	*REAR FENDER INNER TRIM BOARDS	Deformed/Torn	1,210.20 F	*1,210.20 FL
27	1	*SET REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	50.00 F	*- FL
28	1	*REAR EXHAUST	Repair	788.50 F	*- FL
29	2	*REAR EXHAUST MOUNTINGS	Not Necessary	130.00 F	*- FL
30	1	*REAR EXHAUST HEAT SHIELD	Bent	211.10 F	*166.50 FL
31	1	*REAR SPARE TYRE BRACKET & CARRIAGE	Cracked	450.50 F	*399.90 FL
32	1	*REAR AIR VENT	Distorted	121.00 F	*121.00 FL
33	1	*BONNET	Repair	678.10 F	*- FL
34	1	*BONNET INSULATOR	Not Necessary	211.50 F	*- FL
35	1	*SET BONNET INSULATOR CLIPS	Not Necessary	50.00 F	*- FL
36	1	*BONNET LOCK	Twisted	145.50 F	*145.50 FL
37	1	*BONNET OUTER CHROME MOULDING	Not Necessary	155.30 F	*- FL
38	2	*HEADLAMPS	Cracked	1,378.20 F	*1,378.20 FL
39	1	*FRONT BUMPER	Torn	830.00 F	*481.10 FL
40	1	*FRONT BUMPER REINFORCEMENT	Dented	266.20 F	*266.20 FL
41	1	*FRONT BUMPER SPONGE	Torn	166.50 F	*166.50 FL
42	2	*FRONT BUMPER SIDE HOLDERS	Not Necessary	131.00 F	*- FL
43	1	*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
44	2	*FRONT BUMPER FOG LAMP COVERS	Not Necessary	136.00 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
45	1	*FRONT BUMPER CENTRE GRILLE	Not Necessary	188.20 F	*- FL
46	1	*FRONT GRILLE	Twisted	166.60 F	*166.60 FL
47	1	*FRONT BRACE PANEL	Twisted	121.50 F	*121.50 FL
48	1	*FRONT SUPPORT PANEL	Repair	688.10 F	*- FL
49	1	*AIR CON CONDENSER	Serviceable	1,213.10 F	*- FL
50	1	*AIR CON SUCTION HOSE	Not Necessary	395.50 F	*- FL
51	1	*AIR CON DISCHARGE HOSE	Not Necessary	388.10 F	*- FL
52	1	*RADIATOR	Not Necessary	1,866.50 F	*- FL
53	1	*RADIATOR FAN MOTOR	Not Necessary	450.50 F	*- FL
54	1	*RADIATOR FAN BLADE	Not Necessary	150.40 F	*- FL
55	1	*RADIATOR FAN COWLING	Not Necessary	209.10 F	*- FL
56	2	*HORN UNITS	Not Necessary	210.00 F	*- FL
57	2	*FRONT FENDERS	Not Necessary	1,300.20 F	*- FL
58	2	*FRONT FENDER INNERSHIELDS	Not Necessary	390.20 F	*- FL
59	1	*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
60	1	*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
61	1	*REAR FLOOR PANEL INSULATOR	Necessary	200.00 FS	*100.00 FS
62	1	*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
63	1	*SET REAR LICENCE PLATE W/HOLDER	Not Necessary	50.00 FS	*- FS
64	1	*SET FRONT LICENCE PLATE W/HOLDER	Cracked	50.00 FS	*40.00 FS
65	1	*BOT RADIATOR COOLANT	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$)	29,417.70	11,344.50
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	2,728.63
Total Parts (\$\$)	29,417.70	8,615.87

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING REAR REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
5	TO DISMANTLE & REFIX SEAT,CUSHION & UPHOLSTERY	New	150.00	80.00
6	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	60.00
7	TO DISMANTLE & REFIX PETROL TANK	New	100.00	0.00
8	TO MOUNT VEHICLE ON CAR O-LINER	New	380.00	0.00
9	TO REFILL AIRCON GAS	New	150.00	100.00
10	TO SPRAY RUST PROOFING	New	200.00	80.00
11	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	2,800.00	1,500.00
12	TO PUTTY & SPRAY PAINTING	New	2,500.00	1,800.00
Gross Labour Cost (S\$)			6,790.00	3,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >