

108/11/13) wef

ASS. REC. BY: Marcus

REF:

cc3/MSG19000424 / 46 d3

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SLA 47237  
 at Workshop m/s LP.  
 of SMD 8988  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SLA 47237 Yr Regn: 3.16  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or CA /  
 Make: Toyota Corolla Altis cc 1598  
 Colour: white A/C: Insured / Std / NI / NA  
 Sp. Reading: 11189 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: MR053REH104548522  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 205/65R16  
 R: \_\_\_\_\_

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 666.  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 4 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS LTA 42997  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 7 mm R/Bal. 7 mm  
 L/Bal. \_\_\_\_\_ mm L/Bal. \_\_\_\_\_ mm  
 D.O.A. 17/4/19 D.O.I. 18/4/19  
 Survey held at \_\_\_\_\_  
 Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or  
Rear  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
22/4 @ 1:49pm - sent police report to msh via email  
30/4/19 4/5 @ 4200 confirmed with Alin.  
( \$ 13,391.70 Rd - 76% )

RECEIVED 07 MAY 2019

Date/Time, File Pass to? 02/05/19  
 1) Type 4  
 Date/Time, File Return to? \_\_\_\_\_  
 2) \_\_\_\_\_  
☐ : Preli. Report  
☒ : Final Report  
 Days Of Repair: 4  
 Resurvey No. of Trip: 1  
 Survey Fee: 300  
 Transportation: \_\_\_\_\_  
 Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_ )  
☐ : Interview (\$ \_\_\_\_\_ )  
☐ : Tech. Invs (\$ \_\_\_\_\_ )  
☐ : Weekend (\$ \_\_\_\_\_ )  
 Report Format :  
 Lump Sum / I.B.I. (\$ 4,200/- 45 )  
 TOTAL

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 07 May 2019

## Preliminary Advice

Insured Vehicle No	: SMD8988Y	Accident Date	: 17/04/2019
TP Vehicle No	: SLA4723Z	Assignment Date	: 07/05/2019
Make	: TOYOTA COROLLA ALTIS	Est. Duration of Repair	: 4 days
Date of Inspection	: 18/04/2019		
Inspection At	: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,591.70
Revised Amount	:S\$	5,285.37
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,285.37
Lump Sum Repair	:S\$	4,200.00

### Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### Remarks

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	18/04/2019 13:55
Date Of Accident	17/04/2019 12:10
Exact Location Of Accident	ALONG COMMONWEALTH AVENUE TOWARDS CLEMENTI
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLA4723Z
Insured/Policyholder	
Name Of Registered Owner	REI TOGASHI
NRIC No	S7183222H
Email Address	SEAN.YQX@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97770600
Alternative Phone No	OFFICE-NOPHONE

### Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00459690/01
Cover Note Number	

### Driver

Name of Driver	REI TOGASHI
NRIC No	S7183222H
Date Of Birth	10/01/1971
Occupation	INDOOR
Date Of Driving Pass	08/07/2002
Driving Experience	16 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97770600
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	SEAN.YQX@GMAIL.COM

Address	965 BUKIT TIMAH ROAD #10-05
Postcode	589662
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT TIMAH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 1 DUKE ROAD , POSTCODE: 268914 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4629999 - FAX NO: 64628933
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN AND POLICE REPORT (REPORT NO.: T/20190417/2164)

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMD8988Y
Vehicle Make/Model/Colour	TOYOTA HARRIER
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TEO KE HUEY
NRIC/Passport Number	
Contact Number	9005 7968
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name REI TOGASHI

Approximate Age

Injuries Sustain

Injured person in which vehicle? SLA4723Z

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan Pg. 1

**SKETCH PLAN**

**IMPORTANT NOTICE**

VEHICLE NO: SLA 4723 I  
ACCIDENT DATE: 17/04/2019 @ 12:00pm

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

**NOTE: DO NOTE THAT YOU MAY HAVE A 14-DAYS TIMEFRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE REFER TO YOUR POLICY FOR MORE INFORMATION.**

Policyholder's Signature

Date & Time: 17 Apr 2019  
4:40pm

Driver's Signature

(If driver is not the policyholder)  
Date & Time:


CHARN'S CUSTOMCRAFT

Reporting Centre Personnel Signature

Name:  
NRIC/FIN No.:

# Sketch Plan #2 Pg. 1

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


At approximately 12.10 PM, along Commonwealth Ave towards Clementi, I stopped as the traffic light is red.

Car (B) on lane one made a sharp left while changing lane failing to have proper lookout and knocked into Car (A) which is stationary. This hard knock caused severe pain to the neck and head.

OWN DAMAGE ( )    3RD PARTY CLAIM ☒    REPORTING ONLY ☒    OWN WORKSHOP ( )

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature  
 Date & Time: 17 Apr 2019  
 4:40 PM

\_\_\_\_\_  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

CHARN'S CUSTOM CRAFT  
 Reporting Center  
 Name: \_\_\_\_\_  
 NRIC/PIN No.: \_\_\_\_\_





# SINGAPORE POLICE FORCE



T/20190417/2164

Police Station Of Origin:  
Bukit Timah N.P.C  
1 Duke's Road SINGAPORE 268914  
Tel No: 1800-4629999

1 of 3

Report No. T/20190417/2164

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 17/04/2019 18:28		Vide Report No.:		Station Diary No.: 87	
<b>Informant's Particulars</b>					
Name of Informant: REI TOGASHI			Address: 965 BUKIT TIMAH ROAD #10-05 SINGAPORE 589662		
ID Type / ID No.: NRIC NO / S7183222H			Contact No.: Home/Office: Mobile: 97770600		
Nationality: JAPANESE			Email:		
Sex: Female	Age: 48	Date of Birth: 10/01/1971	Type of Informant: Driver		
Race: Japanese			Language:		Institution / School Name:
Occupation: Housewife			Driving Licence Information: Class: 3 Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 17/04/2019 12:10	Type of Location: X-Junction
Location: Along Road 1 COMMONWEALTH AVENUE  Commonwealth Avenue towards Clementi				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume: Moderate
Type of Collision: Moving Vehicle Against - Others				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLA4723Z	Car	TOYOTA	COROLLA ALTIS CLASSIC 1.6 CVT	White	Slightly Damaged	0
SMD8988Y	Car					0

**Details of Vehicle Insurance**

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------





Police Station Of Origin:  
Bukit Timah N.P.C  
1 Duke's Road SINGAPORE 268914  
Tel No: 1800-4629999

Report No. T/20190417/2164

**CONTINUATION OF REPORT**

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLA4723Z	DIRECT ASIA INSURANCE (SINGAPORE) PTE. LTD.	MT/00459690/01	01/03/2018	29/02/2020

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	REI TOGASHI	ID No.	S7183222H
Related Vehicle	SLA4723Z (Car)	Contact No.	97770600
Hospital/Clinic	ONE DOCTORS FAMILY CLINIC	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	17/04/2019	Date Discharge	17/04/2019
No. of Days granted Medical Leave	03	Degree of Injury	Slight

**Brief Details.**

On 17/04/2019 at about 1210hrs, I was driving my vehicle (SLA4723Z) along Commonwealth Avenue towards Clementi Road. I stopped in the middle lane along the junction as the traffic light was red. While I was stationery, another car (SMD8988Y) on the right lane made a sharp left while changing lane, the driver failed to have proper lookout and knocked into my car. My car's rear boot was dented and had some cracks. Due to the hard impact I suffered severe pain on the neck and head. However I did not require any immediate medical attention. After the incident I went to see a doctor and was given 3 days of medical leave. Both of us exchanged particulars at scene.

I have a car camera which had recorded the footage of the incident.



SINGAPORE  
POLICE FORCE



T/20190417/2164

Police Station Of Origin:  
Bukit Timah N.P.C  
1 Duke's Road SINGAPORE 268914  
Tel No: 1800-4629999


3 of 3

Report No. T/20190417/2164

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan



IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

E /

Sgt 3 YUVARANI D/O MAHENDRAN

Signature Of Interpreter:

Not applicable

Signature Of Informant:

Date/Time:

17/04/2019 18:28

Officer In Charge Of Case:

TP / AEIT /

Staff Sgt WONG SIEU LUI

Contact No.: 65476151



SINGAPORE  
POLICE FORCE

Classification Of Case:

SN 170

Authentication Stamp

NP168

SIGNATURE

# FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Not Authorized  
HKK  
18/4/19 H/s = 4200  
4200

SLA 47232

Qty Particular

Amount S\$

List Item:

1PCS BOOTLID

Box/Box \$963.10 ✓

1PCS BOOTLID REAR LOGO

see \$58.90 ✓

1PCS BOOTLID 'COROLLA' EMBLEM

see \$39.30 ✓

1PCS BOOTLID 'ALTIS' EMBLEM

see \$43.60 ✓

1PCS BOOTLID INNER LOCK

see \$382.70 X

1PCS BOOTLID LOCK STRIKER

11 \$34.60 X

1PCS BOOTLID WEATHERSTRIP

twl \$168.20 ✓

2PCS BOOTLID REFLECTORS @\$339.50

11 \$679.00 X

1PCS BOOTLID OUTER CHROME MOULDING

11 \$233.70 X

1PCS BOOTLID INNER TRIM COVER

11 \$349.30 X

1SET BOOTLID INNER TRIM COVER CLIPS

12 \$45.00 X

2PCS BOOTLID HINGES @\$67.40

11 \$134.80 X

1PCS REAR END PANEL

Box/Box \$587.20 ✓

1PCS REAR END PANEL TOP GARNISH

twl \$232.00 ✓

1PCS REAR END PANEL LOCK SENSOR

11 \$159.30 X

1PCS REAR BUMPER

Box/Box \$486.50 ✓

2PCS REAR BUMPER SIDE RETAINERS @\$104.40

11 \$208.80 X

2PCS REAR BUMPER SIDE HOLDERS @\$57.60

11 \$115.20 X

2PCS REAR BUMPER SPLASH SHIELDS @\$52.80

11 \$105.60 X

2PCS REAR BUMPER REFLECTORS @\$57.30

11 \$114.60 X

2PCS REAR BUMPER PARKING SENSORS @\$282.00 25x2=430

shub \$564.00 ✓

1PCS REAR BUMPER PARKING SENSOR WIRE HARNESS

11 \$247.80 X

1PCS REAR BUMPER REINFORCEMENT

Box \$362.70 ✓

257

# FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Qty	Particular	Amount S\$
-----	------------	------------

## List Item:

2PCS	TAILLAMPS @\$364.50	2729.00 ✓
2PCS	TAILLAMP HOUSING PANELS @\$106.20	212.40 X
2PCS	REAR FENDERS @\$986.80	1973.60 X
2PCS	REAR FENDER INNER TRIMS @\$355.90	711.80 X
1PCS	REAR FLOOR PANEL	786.90 X
1PCS	REAR FLOOR PANEL TOP BOARD	256.40 X
1PCS	REAR EXHAUST	931.90 X
2PCS	REAR EXHAUST MOUNTINGS @\$40.70	81.40 X
1PCS	REAR WINDSCREEN MOULDING	86.10 X
1PCS	REAR EXHAUST HEAT SHIELD	66.30 X
List Item Total:		\$12,151.70

4100.50  
25%  
3075.37

## Special Nett Item:

1PCS	REAR END PANEL SEALANT	80.00 50
1SET	REAR FLOOR PANEL INSULATOR	300.00 X
1PCS	REAR WINDSCREEN SEALANT	80.00 X
Special Nett Total:		\$460.00

## Labour Charge:

TO CHECK WIRING.	\$80.00 30
TO DISMANTLE & REPLACING PARKING SENSOR.	\$80.00 50
TO DISMANTLE & REFIX BOOTLID MECHANISM.	\$100.00 60
TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY.	\$150.00 80

# FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Qty      Particular

## Labour Charge:

TO SPRAY RUST PROOFING.

\$120.00 60

TO DISMANTLE & REPLACING REAR EXHAUST.

11 \$100.00 X

TO DISMANTLE & REFIX REAR WINDSCREEN.

11 \$150.00 X

LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN

& REPLACING PARTS.

\$2200.00 800

TO PUTTY & SPRAY PAINTING.

\$2000.00 1080

Labour Charge Total:

\$4980.00

5288.37

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$17,591.70



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Apr 2019		07 May 2019 15:21 <a href="#">Edit Adj Rpt</a>	<b>S\$4,200.00</b> <a href="#">Edit Estimates</a>	<b>S\$4,200.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by Insurer]</span>									
Insured:	<b>GUAN YIPENG</b> , ID: S83806241, Tel: +6591766947								
Main Claimant:	<b>REI TOGASHI</b> , ID: S7183222H								
Vehicle Reg. No.:	<b>SLA4723Z</b>	Date of Loss:	17/04/2019 12:00 - :59 [37 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 591046</b>	Policy/Cover Note No.:	29093126 (Comprehensive) Coverage: 23/08/2018 - 22/08/2019						
Vehicle Reg. No. (Insured):	<b>SMD8988Y</b>	Policy No. (Claimant):							
		Excess:	S\$700.00						
Repairer:	<b>Fastech Auto Pte Ltd (HQ)</b> 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Monica Chung Pei Zhen</b> - 6594 2552]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... <b>[Final Rpt due 06/06/2019]</b>								
Driver/Custodian (Insured):	TEO KE HUEY ( ), NRIC: S8579323C, Tel: +6590057968 Email:								
Adj Asg. Remarks:	DIRECT SUREVY DONE BY LKK ON 18.04.2019								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



















































## Claim Documents

\*SLA4723Z (591046)  
[SMD8988Y]

TP  
REI TOGASHI  
Apr 17 2019 12:00PM  
[GUAN YIPENG]  
Fastech Auto Pte Ltd

Upload Documents   Upload Photos   Compose New Letter			View View in Browser		
<b>Assessment Reports</b>			1 per page		<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	23/04/19 14:08	<b>Accident Statement</b> From: SC - Reg. No: SMD8988Y, Claimant: GUAN YIPENG	1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/05/19 16:24	<b>Adjuster Immediate Advice</b>	1	Load HTM	
<b>Photos/Images</b>			3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/05/19 16:29	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
2	07/05/19 16:29	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
3	07/05/19 16:29	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
4	07/05/19 16:29	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
5	07/05/19 16:29	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
6	07/05/19 16:29	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
7	07/05/19 16:29	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
8	07/05/19 16:29	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
9	07/05/19 16:29	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
10	07/05/19 16:29	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
11	07/05/19 16:29	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
12	07/05/19 16:29	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
13	07/05/19 16:29	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
14	07/05/19 16:29	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
15	07/05/19 16:29	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
16	07/05/19 16:29	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
17	07/05/19 16:29	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
18	07/05/19 16:29	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
19	07/05/19 16:29	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
20	07/05/19 16:29	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
21	07/05/19 16:29	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
22	07/05/19 16:29	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
23	07/05/19 16:29	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
24	07/05/19 16:29	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
25	07/05/19 16:29	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
26	07/05/19 16:29	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
27	07/05/19 16:29	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
28	07/05/19 16:29	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
29	07/05/19 16:29	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
30	07/05/19 16:29	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
31	07/05/19 16:29	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
32	07/05/19 16:29	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>



Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
33	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
34	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
35	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
36	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
37	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
38	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
39	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
40	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
41	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
42	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
43	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
44	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
45	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
46	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
47	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
48	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
49	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
50	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
51	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
52	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
53	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
54	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
55	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
56	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
57	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
58	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
59	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
60	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
61	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
62	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
63	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
64	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
65	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
66	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
67	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
68	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
69	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
70	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
71	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
72	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
73	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
74	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
75	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
76	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
77	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
78	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
79	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
80	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
81	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
82	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
83	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
84	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
85	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
86	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
87	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
88	07/05/19 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
89	07/05/19 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	07/05/19 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	07/05/19 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	07/05/19 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	07/05/19 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	07/05/19 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/04/19 14:08	SLA4723Z E-file & Police report From: SC - Reg. No: SMD8988Y, Claimant: GUAN YIPENG	 Load PDF	
2	07/05/19 15:22	DIRECT SURVEY BY LKK ON 18.04.2019	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG19006924/USD3Q2

Date: 08/05/2019

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29093126

Claimant Vehicle No: SLA4723Z

Insured Vehicle No: SMD8988Y

Date of Loss: 17/04/2019

Nature of Claim: TP

Claim No: 591046

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLA4723Z

Make &amp; Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Engine No: 1ZRY272936

Reg. Date: 01/03/2016 (Man. Year: 2016)

Chassis No: MR053REH104548522

Colour: White

Odometer: 51189 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/65 R16

Rear Tyre Size:

205/65 R16

Front Left Side: Yokohama 7 mm

Rear Left Side:

Yokohama 7 mm

Front Right Side: Yokohama 7 mm

Rear Right Side:

Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,611.70	3,125.37	9,486.33	75.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,980.00	2,160.00	2,820.00	56.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>17,591.70</b>	<b>5,285.37</b>	<b>12,306.33</b>	<b>69.96</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,200.00</b>		
(S\$)	17,591.70	4,200.00	13,391.70	76.13
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,231.42</b>	<b>294.00</b>	<b>937.42</b>	<b>76.13</b>
<b>Nett Amount (S\$)</b>	<b>18,823.12</b>	<b>4,494.00</b>	<b>14,329.12</b>	<b>76.13</b>

### INSPECTION

Date of Assignment: 07/05/2019

Date Inspected: 18/04/2019 Inspected At:

Fastech Auto Pte Ltd (HQ)

1 Kaki Bukit Ave 6, #01-46/48/50 Autobay

Singapore 417883

Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 08 May 2019)
<b>Parts:</b> 143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLA4723Z)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent / Buckled	963.10 F	*963.10 FL
2	1		*BOOTLID REAR LOGO	Necessary	58.90 F	*58.90 FL
3	1		*BOOTLID COROLLA EMBLEM	Necessary	39.30 F	*39.30 FL
4	1		*BOOTLID ALTIS EMBLEM	Necessary	43.60 F	*43.60 FL
5	1		*BOOTLID INNER LOCK	Serviceable	382.70 F	*- FL
6	1		*BOOTLID LOCK STRIKER	Not Necessary	34.60 F	*- FL
7	1		*BOOTLID WEATHERSTRIP	Twisted	168.20 F	*168.20 FL
8	2		*BOOTLID REFLECTORS	Not Necessary	679.00 F	*- FL
9	1		*BOOTLID OUTER CHROME MOULDING	Not Necessary	233.70 F	*- FL
10	1		*BOOTLID INNER TRIM COVER	Not Necessary	349.30 F	*- FL
11	1		*SET BOOTLID INNER TRIM COVER CLIPS	Not Necessary	45.00 F	*- FL
12	2		*BOOTLID HINGES	Not Necessary	134.80 F	*- FL
13	1		*REAR END PANEL	Dented / Bent	587.20 F	*587.20 FL
14	1		*REAR END PANEL TOP GARNISH	Twisted	232.00 F	*232.00 FL
15	1		*REAR END PANEL LOCK SENSOR	Not Necessary	159.30 F	*- FL
16	1		*REAR BUMPER	Dented / Deformed	486.50 F	*486.50 FL
17	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	208.80 F	*- FL
18	2		*REAR BUMPER SIDE HOLDERS	Not Necessary	115.20 F	*- FL
19	2		*REAR BUMPER SPLASH SHIELDS	Not Necessary	105.60 F	*- FL
20	2		*REAR BUMPER REFLECTORS	Not Necessary	114.60 F	*- FL
21	2		*REAR BUMPER PARKING SENSORS	Shorted	564.00 F	*430.00 FL
22	1		*REAR BUMPER PARKING SENSOR WIRE HARNESS	Not Necessary	247.80 F	*- FL
23	1		*REAR BUMPER REINFORCEMENT	Dented	362.70 F	*362.70 FL
24	2		*TAILLAMPS	Cracked	729.00 F	*729.00 FL
25	2		*TAILLAMP HOUSING PANELS	Repair	212.40 F	*- FL
26	2		*REAR FENDERS	Not Necessary	1,973.60 F	*- FL
27	2		*REAR FENDER INNER TRIMS	Not Necessary	711.80 F	*- FL
28	1		*REAR FLOOR PANEL	Not Necessary	786.90 F	*- FL
29	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	256.40 F	*- FL
30	1		*REAR EXHAUST	Not Necessary	931.90 F	*- FL
31	2		*REAR EXHAUST MOUNTINGS	Not Necessary	81.40 F	*- FL
32	1		*REAR WINDSCREEN MOULDING	Not Necessary	86.10 F	*- FL
33	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	66.30 F	*- FL
34	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*50.00 FS
35	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	300.00 FS	*- FS
36	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **12,611.70**    **4,150.50**  
 - List Item Discount on L Items 0.00/25.00% (\$\$)    0.00    1,025.13

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					12,611.70	3,125.37

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING PARKING SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX BOOTLID MECHANISM	New	100.00	60.00
4	TO DISMANTLE & REFIX SEAT ,CUSHION UPHOLSTERY	New	150.00	80.00
5	TO SPRAY RUST PROOFING	New	120.00	60.00
6	TO DISMANTLE & REPLACING REAR EXHAUST	New	100.00	0.00
7	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
8	LABOUR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS	New	2,200.00	800.00
9	TO PUTTY & SPRAY PAINTING	New	2,000.00	1,080.00
Gross Labour Cost (S\$)			4,980.00	2,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >