







## SMRT Accident Vehicle Repair Estimates

Vic

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 06/05/2019

User ID : CatherineLee

### Section A - Accident Details

Registration Number	5MB5077G
Case Reference Number	BUS/03/19/5066
Registration Date	3/8/2015
Company Type	SMRT Buses Ltd
Make	ALEXANDER DENNIS
Model	ENVIRO 500
Name of Driver	Mohd Khairunizam Bin Hj Ismail
Type of Accident	Side Swipe
Accident Date and Time	29/3/2019 3:45 PM
Accident Reported Date and Time	29/3/2019 5:45 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	24101201
Special instruction to ARC, if any	5MB5077G - RIGHT CENTRE PORTION 5KM9570M (TP) - INSURED WITH AIG
Prepared Date and Time	8/4/2019 8:13 PM
Chassis Number	SFD78CLR5EMTL3976
Mileage	
Work Shop	
Repair Completion Date and Time	

L/s \$2250/- 3days.

### Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,590.00	\$1,080.00
Total Spray Cost	\$708.00	\$538.00
Total Spare Part Cost	\$639.74	\$639.74
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$2,937.74	\$2,237.74
Lump Sum Total	\$2,950.00	\$2,250.00
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	Jeong Choon Hwee	Hwee Jie
ARC / Surveyor Sign Off Date	17/04/2019 1:29 PM	17/04/2019 1:35 PM
Signature		
Remarks		U/S REPAIR. AFTER REPAIR PHOTO.

### Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
00 Woodlands Industrial Park EA, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662633
Accident Reporting Number : 68662672

Date Generated : 06/05/2019

User ID : CatherineLee

### Section D - Details of Repair Estimates

#### Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & REPLACE RH SIDE SWIPE BODY TO REAR RH PORTION.	\$1,590.00	\$1,060.00
<b>Total Labour</b>	<b>\$1,590.00</b>	<b>\$1,060.00</b>

#### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PUTTY & RESPRAY	\$708.00	\$538.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$708.00</b>	<b>\$538.00</b>

#### Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
<b>Total Other Costs</b>		

#### Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6011242	BODY RH	30106514	PANEL EXTERIOR RH, F OR ADL DD BUS	1.00	\$464.09	10.00	\$417.68	Replace	Replace BUC
4006314	CONSUMABLE	SikaSeal-265	ADHESIVE DIRECT GLAZING	6.00	\$37.00	0.00	\$222.00	Replace	Replace
4006313	CONSUMABLE	SIKA® Primer-206 G+P	PRIMER (SIKA 206 G+P)	1.00	\$80.00	0.00	\$80.00	Replace	Replace
4006315	CONSUMABLE		ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace	Replace
<b>Total</b>					<b>\$681.09</b>		<b>\$799.68</b>		

#### Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									



## Case Details

Case Reference Number : BUS03185066  
 Type of Repair : Accident Repair  
 Vehicle Registration Number : S4M5507G

Company Type : SMRT Buses Ltd  
 Estimation ID : EST-6405-ID  
 Assigned By : Eileen Bay Yee Ling

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd  
 Accident Date and Time : 23/03/2019 07:45 AM  
 Vehicle Age(In Months) : -

## Documents / Photographs

View Documents / Photographs

Total Documents : 1

## Estimation Details

### Spare Part's Cost Detail

SMRT Recommendation												Surveyor Approval			
BOV Type	Coating Type	Partion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks	
Standard	Main	BODY RH	6011345	PANEL EXTERIOR RH FOR ADL DD BUS	1	484.00	484.00	10.00	417.60	Replace	1	417.60	Replace	+	
Standard	Main	CONSUMABLE	4006314	ADHESIVE DIRECT GLAZING	6	37.00	222.00	0.00	222.00	Replace	6	222.00	Replace	+	
Standard	Main	CONSUMABLE	4006313	PRIMER (SIKA 206 G-P)	1	80.00	80.00	0.00	80.00	Replace	1	80.00	Replace	+	
Standard	Main	CONSUMABLE	4006315	ACTNATOR	1	80.00	80.00	0.00	80.00	Replace	1	80.00	Replace	+	
Total Spare Part Cost :												799.60	Surveyor Total	799.60	
Lump Sum Discount (%) :												20.00	Lump Sum Dis (%)	20	
Final Spare Part Cost :												639.74	Final Sur Total	639.74	

### Labour's Cost Detail

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REMOVE & REPLACE RH SIDE SWIPE BODY TO REAR RH PORTION	1,000.00	1,000	
Total:			1,000.00	1,000.00	

### Spray Cost Detail

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO PUTTY & RESPRAY	708.00	576	
Total:			708.00	576.00	

### Other Cost Detail

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			0.00	0.00	

## Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Cost	639.74	639.74
Total Labour Cost	1,000.00	1,000.00
Total Spray Painting	708.00	576.00
Other	0.00	0.00
Overall Total	2,350.74	2,237.74
Lump Sum Repair Option	-	-
Lump Sum Total	2,350.00	2,250.00
Surveyor Approved Amount:		2,250.00

No of Repair Days	Estimator Assessment(E)	Surveyor Assessment(S)
Remarks	4	3
Surveyor Name		L/D REPAIR AFTER REPAIR PHOTO
Signature		Handwritten signature
Survey Date	170542019	Save Clear

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



AIG ASIA PACIFIC INSURANCE Pte Ltd  
C/O LKK Auto Consultants Pte Ltd  
51 Ubi Avenue 1  
#02-25 Paya Ubi Industrial Park  
Singapore 408933

### Without Prejudice

SMRT AUTOMOTIVE SERVICES PTE LTD  
6 Ang Mo Kio Street 62  
Singapore 569140  
Tel : 65 6866 2650  
Fax : 65 6368 7421  
www.smrt.com.sg

Your Ref.: CC3/AIG19006937/jhb3

Our Ref.: BUS/03/19/5066/PT

Date : 01.07.2019

Dear Sirs,

### ACCIDENT INVOLVING SMB5077G AND SKM9570M ON 29.03.2019

#### CLAIMS RESPONSE

- ☐ We refer to your letter dated \_\_\_\_\_ and our letter dated \_\_\_\_\_
- ☐ We claim on behalf of \_\_\_\_\_
- ☐ We acknowledge the receipt of your letter/claims dated \_\_\_\_\_
- ☐ We have forward your claim to our Insurer. They will liaise directly with you.
- ☒ We enclose our documents marked "E" in the list below;
- ☐ Please give us your documents marked "R" in the list below:
- |  |  |   |
|--|--|---|
| <input type="checkbox"/> Police/SAS report of _____  | <input type="checkbox"/> Discharge Voucher | <input type="checkbox"/> Others : _____ |
| <input type="checkbox"/> Investigation Results       | <input type="checkbox"/> Repair Invoice    | _____                                   |
| <input type="checkbox"/> Photographs                 | <input type="checkbox"/> Letter of Claims  | _____                                   |
| <input type="checkbox"/> Confirmation of Taxi Rental | <input type="checkbox"/> Survey Report     | _____                                   |
- ☐ We are looking into this matter and will revert to you.
- ☐ We disclaim our liabilities. The accident was caused by your driver.
- ☐ Without admission of liability, we offer you S\$ \_\_\_\_\_ all in to settle the case amicably.
- ☐ Please quantify your claims
- ☐ We wish to survey / re-survey your vehicle. Please arrange and let us know the date & time.
- ☐ We have no other alternatives but have to take legal action against you.
- ☐ Your offer of S\$ \_\_\_\_\_ is accepted. Please let us have your Discharge Voucher.
- ☐ Your offer of S\$ \_\_\_\_\_ is rejected. Please increase your offer to S\$ \_\_\_\_\_
- ☒ Please let us have your cheque payable to **SMRT BUSES LTD**
- ☐ Others \_\_\_\_\_

  
Patrick Tan  
for Manager, Claims  
Claims Department

Thank you.

Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

**From:** Eileen Bay Yee Ling (Auto Svcs/Claims & IA/Claims & IA/Buses) [<mailto:eileenbay@smrt.com.sg>]

**Sent:** Friday, 17 May, 2019 11:23 AM

**To:** CS A Team; Admin A

**Cc:** Karen Chan Siau Chin (Auto Svcs/Claims & IA/Claims & IA/Buses)

**Subject:** LOD - ACCIDENT INVOLVING SMB5077G AND SKM9670M ON 29/03/2019 ALONG BT TIMAH RD

Our Ref: **BUS/03/19/5066/EB**

Dear Sir / Madam,

We claim on behalf of **SMRT BUSES LTD**, owner of the vehicle Reg. No.: **SMB5077G**.

Your driver's negligent driving has caused the above accident. As a result, my client has suffered the following losses:-

Cost of Repair	\$2,250.00
Loss of Use	\$1,050.00 ( 3 days x \$350.00 )
LTA Search Fee	\$7.00
<b>Total</b>	<b>\$3,307.00</b>

We enclose the following documents:

- 1) Repair Invoice
- 2) LTA Search
- 3) SAS report

We look forward to your confirmation to settle our claims within 15 days from the date of this email.

Kindly issue payment in favour to **SMRT BUSES LTD**.

Thanks and regards,

*Eileen Bay*

Claims and Insurance Agency

DID: +65 6556 3549 | E: [eileenbay@smrt.com.sg](mailto:eileenbay@smrt.com.sg)

6 Ang Mo Kio Street 62

Singapore 569140





## Jia Le (LKK Auto)

---

**From:** Vic (LKKAUTO)  
**Sent:** Monday, 17 June 2019 3:36 PM  
**To:** Jia Le (LKK Auto)  
**Subject:** FW: LOD - ACCIDENT INVOLVING SMB5077G AND SKM9670M ON 29/03/2019 ALONG BT TIMAH RD LKK ERF CC3/AIG19006937/Jhb3  
**Attachments:** 20190405\_BUS03195066\_SAS2579627.pdf; img-517111633-0001.pdf; INV.PDF; STATEMENT.PDF

---

**From:** Eileen Bay Yee Ling (Auto Svcs/Claims & IA/Claims & IA/Buses) [mailto:eileenbay@smrt.com.sg]  
**Sent:** Friday, 17 May, 2019 5:44 PM  
**To:** Vic (LKKAUTO)  
**Cc:** Karen Chan Siau Chin (Auto Svcs/Claims & IA/Claims & IA/Buses); Admin A; Jia Le (LKK Auto)  
**Subject:** RE: LOD - ACCIDENT INVOLVING SMB5077G AND SKM9670M ON 29/03/2019 ALONG BT TIMAH RD LKK ERF CC3/AIG19006937/Jhb3

### WITHOUT PREJUDICE

Dear Vic,

There is no CCTV for this case.

Thanks and regards,

*Eileen Bay*

Claims and Insurance Agency  
DID: +65 6556 3549 | E: [eileenbay@smrt.com.sg](mailto:eileenbay@smrt.com.sg)  
6 Ang Mo Kio Street 62  
Singapore 569140



---

**From:** Vic (LKKAUTO) [mailto:vicalpeh@lkkauto.com]  
**Sent:** Friday, 17 May 2019 3:25 PM  
**To:** Eileen Bay Yee Ling (Auto Svcs/Claims & IA/Claims & IA/Buses)  
**Cc:** Karen Chan Siau Chin (Auto Svcs/Claims & IA/Claims & IA/Buses); Admin A; Vic (LKKAUTO); Jia Le (LKK Auto)  
**Subject:** RE: LOD - ACCIDENT INVOLVING SMB5077G AND SKM9670M ON 29/03/2019 ALONG BT TIMAH RD LKK ERF CC3/AIG19006937/Jhb3

Without Prejudice

Dear Eileen,

We refer to your below email and the contents were noted.

Both drivers reported that the other vehicle cut lane (please refer to the attached Insured statement). As such, we would like to request for any evidence from your side for our further action.



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG19006937/Jhb3

30 MAY 2019

**LOW LI YEAN**  
39 GILSTEAD RD  
#01-01  
SINGAPORE 309083

Dear Sir/Madam,

**ACCIDENT INVOLVING SKM 9570M & SMB 5077G ALONG/AT NEWTON CIRCUS  
ON 29/03/2019**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SMB 5077G against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

CHAN JIA LE  
Case Handler  
DID: 6749 5792  
FAX: 6741 4108  
Email: [JiaLe@lkkauto.com](mailto:JiaLe@lkkauto.com)

c.c. *AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)*



**AUTHORIZATION TO ACT**  
**(AIG Asia Pacific - Express Third Party Claim)**


I, SMRT BUSES LTD (the third party claimant") of 6 ANG MO KIO STREET 62 (S)569140 (address), owner of SMB 5077G (vehicle no.) hereby authorize SMRT AUTOMOTIVE SERVICES PTE LTD ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no SMB 5077G that was damaged pursuant to the accident which occurred on 29/03/2019 (date) along BUKIT TIMAH ROAD AFTER BS: 40031 (NEWTON FC) (location) involving vehicle no/s SKM 9570M ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the ~~workshop~~: (SMRT BUSES LTD)

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 28 (day) of June (month) 2019 (year)

   
Signed by "the third party claimant"  
(with chop if applicable)

   
Signed by "the workshop"  
(with chop)

or his property damage and will not affect his personal injuries claim and/or uninsured losses claim in a later claim.  
Further, the settlement terms herein should not be used as evidence to prejudice to the claimant's personal injuries claim and/or other uninsured losses claim arising of the subject matter in this action.

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, **SMRT AUTOMOTIVE SERVICES PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$1,125.00** (Repair Cost), **S\$525.00** (Loss of Use/Rental), **S\$7.00** (Disbursement) for vehicle no. **SMB 5077G** that was damaged pursuant to the accident which occurred on **29/03/2019** (date) along **BUKIT TIMAH ROAD AFTER BS: 40031 (NEWTON FC)** (location) involving vehicle no/s **SKM 9570M**. This is pursuant to the inspection conducted on **17/04/2019** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **SMRT BUSES LTD** ("the third party claimant") of vehicle no. **SMB 5077G** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SMB 5077G** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 28 (day) of June (month) 2019 (year)



045

Signed by appointed surveyor



Signed by "the workshop" (with chop)



SMRT Automotive Services Pte Ltd  
251 North Bridge Road Singapore 179102  
Tel: 65 63311000 Fax: 65 63340247



### Tax Invoice

GST Reg No. : MR-8500001-7  
CRN : 199004280Z  
Invoice No. : IV190500235  
Date : 14.05.2019  
Vehicle No. : SMB5077G  
Your Ref No. : BUS/03/19/5066  
Our Ref No. : 24101201  
Terms : 30 Days

Customer Code: 3000066

SMRT BUSES LTD


Block Unit  
STREET 62  
6 ANG MO KIO  
SINGAPORE 569140

Description	Qty	Unit Cost	Add / (Discount) \$ Amount	Amount
LUMP SUM AMOUNT FOR REPAIR AS PER SURVEYOR'S RECOMMENDATION	1.00		\$	2,250.00
GRAND TOTAL				\$ 2,250.00

Remark :

Make/Model : ENVIRO 500  
Accident Date : 29.03.2019

N.B. Payment by cheque should be crossed and  
made payable to 'SMRT Automotive Services Pte Ltd'.  
No receipt will be issued unless requested.

  
Authorized Signature  
for SMRT Automotive Services Pte Ltd

## Enquire Transaction History

### Transaction History Details

Log Date/Time:	04 Apr 2019 / 15:00:49	Transaction Amount:	\$7.49
Asset Type:	Vehicle		
Asset ID:	SKM9570M		
Transaction Type:	18.32 Insurance Enquiry (GIRO Payment)	Channel:	External Agency
User ID:	ESASBAH0 - BALQISH BINTE ABDUL HALIL	Business Transaction Reference No.:	20190404150049803974

Search Date / Time: 29 Mar 2019 15:45:00  
Insurance Company: AIG ASIA PACIFIC INSURANCE PTE. LTD.  
Information displayed is correct as at the log date and time.

[Enquire Related Logs](#)

[Back to List](#)

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Apr 2019 <a href="#">Edit Reg</a>		17 Apr 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$2,250.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,250.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	LOW LI YEAN, ID: 57287750J								
Main Claimant:	SMRT BUSES LTD, Co. Reg. No.: 198202292D								
Vehicle Reg. No.:	SMB5077G	Date of Loss:	29/03/2019 00:00 - :59 [43 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 5707163625SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SKM9570M	Policy No. (Claimant):	D-18090224MFBP						
		Excess:							
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68562628								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 30/04/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (22/04/2019): Request To Upload TP GIA Report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*SMB5077G (5707163625SG)**  
**[SKM9570M]**  
**TP**  
**SMRT BUSES LTD**  
**Mar 29 2019 12:00AM**  
**[LOW LI YEAN]**  
**SMRT Automotive Services Pte Ltd**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a> <a href="#">Upload Video</a> <a href="#">Upload Audio</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Letters/Correspondences</b>			1 per page <input type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown		<a href="#">Edit</a>
<b>Photos/Images</b>			3 per page <input type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/04/19 10:20	General View		<a href="#">Load JPG</a>
2	23/04/19 10:20	General View		<a href="#">Load JPG</a>
3	23/04/19 10:20	General View		<a href="#">Load JPG</a>
4	23/04/19 10:20	General View		<a href="#">Load JPG</a>
5	23/04/19 10:20	General View		<a href="#">Load JPG</a>
6	23/04/19 10:20	General View		<a href="#">Load JPG</a>
7	23/04/19 10:20	General View		<a href="#">Load JPG</a>
8	23/04/19 10:20	General View		<a href="#">Load JPG</a>
9	23/04/19 10:20	General View		<a href="#">Load JPG</a>
10	23/04/19 10:20	General View		<a href="#">Load JPG</a>
11	23/04/19 10:20	General View		<a href="#">Load JPG</a>
12	23/04/19 10:20	General View		<a href="#">Load JPG</a>
13	23/04/19 10:20	General View		<a href="#">Load JPG</a>
14	10/05/19 10:13	Photo After Spray		<a href="#">Load JPG</a>
15	10/05/19 10:13	Photo After Spray		<a href="#">Load JPG</a>
16	10/05/19 10:13	Photo After Spray		<a href="#">Load JPG</a>
<b>Documentation</b>			1 per page <input type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/04/19 18:13	TP ESTIMATE- MARKED		<a href="#">Load PDF</a>
2	22/04/19 18:13	TP GIA REPORT		<a href="#">Load PDF</a>
3	09/07/19 09:31	WORKSHOP INVOICE		<a href="#">Load PDF</a>
4	09/07/19 09:31	AUTHORISATION TO ACT FORM		<a href="#">Load PDF</a>
5	09/07/19 09:31	Release Voucher		<a href="#">Load PDF</a>
6	09/07/19 09:31	LTA SEARCH		<a href="#">Load PDF</a>
7	09/07/19 09:31	LETTER TO OI		<a href="#">Load PDF</a>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	22/04/19 09:44	OI GI Report		<a href="#">Load PDF</a>

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>			<a href="#">Reset</a> <a href="#">Save</a> <a href="#">Print</a>
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKM9570M (Insd veh)	Model:	ALEXANDER DENNIS
	SMB5077G (TP veh)		ENVIRO500 8.8 D (A)
Date of Accident:	29/03/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	3,144.09
Final Repair Cost	:	\$	1,125.00
Loss of Use	:	\$	525.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	7.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	1,657.00

3.00 days at \$350.00 per day  
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability \_\_\_\_\_ 50 \_\_\_\_\_ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_\_

BOLA Liability: \_\_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	SMRT Buses Ltd	:	\$ 1,657.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

09 Jul

2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

# LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19006937/JDB3Q2

Date: 09/07/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SMB5077G

**Insured Vehicle No :** SKM9570M

Date of Loss: 29/03/2019

Nature of Claim: TP

Claim No: 5707163625SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMB5077G**

Make &amp; Model: ALEXANDER DENNIS ENVIRO500, 8.8 D (A)

Engine No: 22145513

Reg. Date: 03/08/2015 (Man. Year: 2014)

Chassis No: SFD76CLR5EMTL3976

Colour: Multi-colour

Odometer: 229773 km

Engine Capacity: 8849 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	305/70 R22.5	Rear Tyre Size:	305/70 R22.5 (D)
Front Left Side:	Firenza 7 mm	Rear Left Side:	Firenza 7/7 mm
Front Right Side:	Firenza 7 mm	Rear Right Side:	Firenza 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	846.09	799.68	46.41	5.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,298.00	1,598.00	700.00	30.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,144.09</b>	<b>2,397.68</b>	<b>746.41</b>	<b>23.74</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,250.00</b>		
<b>Nett Amount (S\$)</b>	<b>3,144.09</b>	<b>2,250.00</b>	<b>894.09</b>	<b>28.44</b>
<b>+ Loss of Use (3.0 x S\$350.00/day) (S\$)</b>		1,050.00		
		<b>(S\$) 3,300.00</b>		
<b>Liab Amount (50.00%) (S\$)</b>		<b>1,650.00</b>		
<b>+ Doc/Search Fee (S\$)</b>		7.00		
<b>Nett Liability (S\$)</b>		<b>1,657.00</b>		

### INSPECTION

Date of Assignment: 17/04/2019

Date Inspected: 17/04/2019 Inspected At:

SMRT Automotive Services Pte Ltd  
(Woodlands)

60 Woodlands Industrial Park E4  
Singapore 757705

Estimated Period of Repair: 3.0 days

---

**Adjuster:** ONG HWEE JIE

**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL,EXTERIOR:R/H,FOR ADL DD BUS	Buckled	464.09 F	*464.09 FL
2	6		*ADHESIVE :DIRECT GLAZING	Necessary	222.00 FS	*222.00 FS
3	1		*PRIMER (SIKA 206 G+P)	Necessary	80.00 FS	*80.00 FS
4	1		*ACTIVATOR	Necessary	80.00 FS	*80.00 FS
					<b>Sub Total (\$\$)</b>	<b>846.09 846.09</b>
					<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	<b>0.00 46.41</b>
					<b>Total Parts (\$\$)</b>	<b>846.09 799.68</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REPLACE RH SIDE SWIPE BODY TO REAR RH PORTION	New	1,590.00	1,060.00
2	TO PUTTY & RESPRAY	New	708.00	538.00
Gross Labour Cost (\$\$)			2,298.00	1,598.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >