

22/03/2002

ASS. REC. BY:

REF: CS/FCI19006949/Js d307 Special Instruction:

(CWS) Surveyor: Hwa Jie ASSIGNMENT (Office)
 From (Person): Eilon Lee of FCI Date/Time: 18.4.19 3.32p.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMJ 4137 G Insured: SHC 8668K
 at Workshop m/s Kah moto Tel: 82886302
 of 6 A Mandai Estate Body Repair & Paint Centre

Policy No: _____ Claim No: D19002613 MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 17.4.2019
 (Client's Record)

CA / REV / REP. / REV 24 HRS "wp" H.O.D. Endorsement: _____

Date/Time: 18.4.19 4.00 p.m Person Contacted: Ani Kkg Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SMJ 4137 G - x</u>
	<u>SHC 8668K - CS/FCI19002834/ Dvd3</u> <u>D.O.A - 06/02/2019</u>
<u>26/04/19</u>	<u>@ 17:34 pm revised PA to May via email.</u>

Surveillance Unit

REF: FCI

ASSIGNMENT

From: _____ Date: 25/4/19

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMJ 4137G

at Workshop m/s Kah Motor

of 6A Mondai Estate

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: After 10am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{hup}

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMJ 4137G Yr Regn: 1 mar 2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Jazz C.C 1498

Colour Red A/C: Insured / Std / NI / NA

Sp. Reading 3203 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMGK585OKS202476

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 17/4/19 D.O.I. 25/4/19

Survey held at Kah Motor

Des. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Confirmed P/P \$8813.13/ 6 days of repair.
(\$ 5,233.51 red - 37%)

RECEIVED 9 JUL 2019

Date/Time, File Pass to?

03/07/19

1) Typist

Date/Time, File Return to?

2) _____

☐ : Preli. Report

☒ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

_____ S + RS _____ SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ 8,813.13 P/P)

4x19 = 60

170 + 60

90

50

68

308

MOTOR SURVEY ASSIGNMENT

Date	18-04-2019	Our Ref No. D19002613MFSH
Accident Date	17-04-2019	Claim Type. Third Party
Insured Vehicle	SHC8668K	Third Party Vehicle. SMJ4137G
Survey Location	6A MANDAI ESTATE BODY REPAIR & PAINT CENTRE	
Contact Person.	ANIKKA LAI	
Contact No.	65145248/ 82886302	Fax No. 0
Survey Type	DIRECT SETTLEMENT: V. OUT E. ✓	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	KAH MOTOR CO. SDN. BHD.	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1123B
Vehicle Details	
Vehicle No.:	SMJ4137G
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Apr 2019
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.5 CVT
Primary Colour:	Red
Manufacturing Year:	2019
Engine No.:	L15B34100149
Chassis No.:	JHMGK5850KS202476
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$17,200.00
Original Registration Date:	01 Mar 2019
First Registration Date:	01 Mar 2019
Transfer Count:	0
Actual ARF Paid:	\$17,200.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Feb 2029
PARF Rebate Amount:	\$12,900.00
Intended COE Rebate Details	
COE Expiry Date:	28 Feb 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$25,920.00
COE Rebate Amount:	\$25,503.00
Total Rebate Amount:	\$38,403.00

The information contained herein is correct as at 26 Apr 2019

OK

Shirley Hiew (LKK Auto)

From: Hwee Jie (LKK Auto) <hweejie@lkkauto.com>
Sent: Monday, 1 July 2019 4:08 PM
To: Anikka Lai
Cc: Shirley Hiew (LKK Auto)
Subject: RE: SMJ4137G - FINALIZATION

Hi,

Finalized P/P \$8,813.13/- 6days of repair.

Best Regards,
Hwee Jie | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 9180 3151 | Email: Hweejie@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Anikka Lai [mailto:anikkalai@honda.com.sg]
Sent: Thursday, 23 May, 2019 7:12 PM
To: Hwee Jie (LKK Auto)
Cc: SUR
Subject: SMJ4137G - FINALIZATION

Dear Hwee Jie,

We enclosed the total final repair costs for,

Vehicle No.	SMJ4137G
Final Repair Costs (exclude GST)	\$8813.13
Repair Period* (Days)	6 days

****Note: Repair period does include Sunday and Public Holiday.***

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.


In addition, I have attached photos of before paint, '?' items and supplementary parts (if any) for your records.

Thank you

Warmest Regards

Anikka Lai
Kah Motor Co. Sdn Bhd
6A Mandai Estate
Singapore 729903
DID : 6514 5248 HP : 8288 6302
Email: anikkalai@honda.com.sg

From: Printer Service <printservice@honda.com.sg>
Sent: Thursday, 23 May, 2019 7:07 PM
To: Anikka Lai <anikkalai@honda.com.sg>
Subject: Attached Image



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 26 April 2019 5:34 PM
To: 'Eileen Lee'; 'CWS Motor Claims'
Cc: assignments; SUR
Subject: RE: SURVEY ASSESSMENT - D19002613MFSH/1
Attachments: SMJ 4137G - Preli Advise .pdf

Dear May,

Enclosed preliminary revised of vehicle SMJ 4137G.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 18 April, 2019 3:32 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19002613MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19002613MFSH

Date: 26 April 2019

Our Ref: CS/FCI19006949/Jsd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SMJ 4137G .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 25/04/2019 at the premises of M/s Kah Motor Co. Sdn. Bhd. and have the following to report:-

Workshop Estimate Amount	: S\$ <u>13,997.89</u> .
Revised Estimate Amount	: S\$ <u>11,502.83</u> .
"Check" Items Amount	: S\$ <u>1,441.82</u> .
Market Value	: S\$ _____ .
LTA Reimbursement Value	: S\$ _____ .
Nett Value	: S\$ _____ .

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 5 Days

Yours faithfully,
Ong Hwee Jie
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/04/2019 18:59
Date Of Accident	17/04/2019 07:40
Exact Location Of Accident	SEMBAWANG RD OPP CHONG PANG CAMP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMJ4137G
Insured/Policyholder	
Name Of Registered Owner	ZYRE RAPHAELA LOH RUI MIEN
NRIC No	S8241123B
Email Address	ZYRE_82@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-91182852
Alternative Phone No	OFFICE-91182852

Vehicle Particulars

Manufacturer	HONDA
Model	JAZZ-1.5 VTIR (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	JIANG TIANXIANG
Passport No/FIN	G6976699X
Date Of Birth	18/11/1985
Occupation	INDOOR
Date Of Driving Pass	01/07/2016
Driving Experience	2 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97774635
Fax Number	
Contact Number	
EEmail Address	ZYRE_82@HOTMAIL.COM

Address	-
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	WOODLANDS NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 1 WOODLANDS DRIVE 63 , POSTCODE: 738070 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-7679999 - FAX NO: 67673652
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS ANNEX D&E POLICE REPORT NO. L/20190417/7022

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC8668K
Vehicle Make/Model/Colour	HYUNDAI I40 / BLUE
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	MOHAMED ISHAK JAHABAR ALI
NRIC/Passport Number	S6980123D
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	JIANG TIANXIANG
Approximate Age	34
Injuries Sustain	BACKACHE
Injured person in which vehicle?	SMJ4137G
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	


Vehicle Number: SMJ 4137G


SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)** I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "**Purposes**")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:



 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Sketch Plan Pg. 2

Vehicle Number: SMJ 4137G

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 17/4/2019 @ about 07:40hrs. as my vehicle (*) was travelling along Sembawang Road towards Thomson. the front vehicle ~~to~~ slowed down and stopped, as my vehicle, followed suit. A few second later, Veh B hit onto my vehicle rear portion with a great impact, caused the damages to my vehicle.

I was alone and no injury at the point of accident. However, I felt backache while heading to the reporting center; I will consult doctor after reporting the case.

*Statement recorded in _____ language by driver.

*Own Damage (OD) Claim submission must be proceeded within 14 Days from Date of Accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



L/20190417/7022

1 of 2

POLICE REPORT (NP299)

Report No. L/20190417/7022

Police Station Of Origin
Woodlands Division HQ
1 Woodlands Street 12 SINGAPORE 738622
Tel No:1800-4660000

Date/Time Report Made 17/04/2019 17:05	Vide Report No.	Station Diary No.
Name Of Informant JIANG TIANXIANG	Address APT BLK 17 MARSILING LANE #10-253 SINGAPORE 730017	
ID Type / ID No. FIN NO / G6976699X	Contact No. Home/Office:	Mobile: 97774635
Nationality CHINESE	Email Address tianxiang2046@gmail.com	
Occupation Management executive	Sex Male	Age 33
Institution/School Name	Date of Birth 18/11/1985	Race Chinese
Date/Time Of Incident 17/04/2019 07:40 - 17/04/2019 07:45	Location Of Incident SEBBAWANG ROAD	

Brief details.

I was driving to work on 17th April, 0740am and driving along sembawang rd towards thomson (near Chong Pang). There was a Traffic Light that turned red and I was the 4th or 5th car from the stop light. I stopped normally but the rear vehicle failed to stop and crashed into me. I am now suffering from pain in several parts of my body and doctor have certified me unfit for work for 7 days.

Subjects Involved	
Suspect	
Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 17/04/2019 17:05
Officer In-Charge Of Case:	Classification Of Case:

Authentication Stamp



**SINGAPORE
POLICE FORCE**



L/20190417/7022

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. L/20190417/7022

Person Name	Unknown		
Gender	Male	Age	35-55
Race	Indian	Language	English
Occupation	Taxi driver	Complexion	Very dark
Build	Medium	Height About	165cm
Attire Last Worn	Dark blue shirt with collar	Hair Colour	Black
Hair Style	Bald		
Victim			
Person Name	JIANG TIANXIANG		
ID Type	FIN NO	ID No	G6976699X
Gender	Male	Age	33
Race	Chinese	Language	English
Occupation	Management executive	Address Type	
Address	APT BLK 17 MARSILING LANE #10-253 SINGAPORE 730017		Mobile No 97774635
Is Informant A Victim?	Yes		
Person Name	JIANG TIANXIANG (Informant)		

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 17/04/2019 17:05
Officer In-Charge Of Case:	Classification Of Case:

Authentication Stamp

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

Registration No : SMJ4137G

Chassis No : JHMGK5850KS202476

Model : JAZZ 1.5VTIR CVT 19YM (EURO 6)

Owner's Name : ZYRE RAPHAELA LOH RUI MIEN

Ins Policy No. :

Date of Accident : 17/4/2019

Document No. : SQT19001741

Date : 17. Apr 2019

Customer No. : WZF002

Svc Advisor : ANIKKA LAI SWEE KAM

Engine No : L15B34100149

Date | Time : 17. Apr 2019 7:02:26 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: ZYRE RAPHEALA LOH RUI MIEN OWNER INSURER: TOKIO MARINE ACC DATE: 17/04/2019 SURVEYED BY: DATE: REF NO: TP INSURER: MS FCL TP VEH: SHC8668K						
04715-T5B-J50ZZ	FACE,RR.BUMPER DEF ✓	1	502.50	25	376.87	26.38	403.25
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE rec ✓	1	16.90	25	12.67	0.89	13.56
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE rec ✓	1	16.90	25	12.67	0.89	13.56
91505-TM8-003	CLIP,BUMPER rec ✓	9	2.30	25	15.52	1.09	16.61
71502-T5A-J60	COVER,R.RR.BUMPER nn x	1	20.70	25	15.52 x	1.09	16.61
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR shorted ✓	1	320.00		320.00	22.40	342.40
71507-T5A-J60	COVER,L.RR.BUMPER nn x	1	20.70	25	15.52 x	1.09	16.61
71510-T5B-J50ZA	DIFFUSER ASSY,RR.PR DEF ✓	1	206.80	25	155.10	10.86	165.96
68100-T5B-Z50ZZ	TAILGATE COMP Buc ✓	1	730.60	25	547.95	38.36	586.31
74440-T5A-003	WEATHERSTRIPTAILGATE DEF	1	92.30	25	69.22	4.85	74.07
74800-T5S-K61	LOCK ASSY,TAILGATE Suc x	1	78.90	25	59.17 x	4.14	63.31
75722-T5L-T01	EMBLEMRR. rec ✓	1	10.90	25	8.17	0.57	8.74
75701-T5A-000	EMBLEMH rec ✓	1	10.70	25	8.02	0.56	8.58
90301-SP0-003	NUTPAINT CUTTING nn x nn	2	2.50	25	3.75	0.26	4.01
74890-T5B-911	GARNISH ASSYRR.LICENSE nn x	1	200.60	25	150.45 x	10.53	160.98
33500-T5A-J02	TAILLIGHT ASSY,R. nn x	1	223.90	25	167.92 x	11.75	179.67
33550-T5A-J02	TAILLIGHT ASSYL. scr ✓	1	223.90	25	167.92	11.75	179.67
34150-T5A-J01	LIGHT ASSYR.LID nn x	1	81.70	25	61.27 x	4.29	65.56
34155-T5A-J01	LIGHT ASSYL.LID nn x	1	81.70	25	61.27 x	4.29	65.56

Printed on 17/4/2019 8:16:32 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd. it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

Registration No : SMJ4137G

Chassis No : JHMGK5850KS202476

Model : JAZZ 1.5VTIR CVT 19YM (EURO 6)

Owner's Name : ZYRE RAPHAELA LOH RUI MIEN

Ins Policy No. :

Date of Accident : 17/4/2019

Document No. : SQT19001741

Date : 17. Apr 2019

Customer No. : WZF002

Svc Advisor : ANIKKA LAI SWEE KAM

Engine No : L15B34100149

Date | Time : 17. Apr 2019 7:02:26 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
18307-T5B-903	SILENCER COMPEXHAUST <i>nnx</i>	1	430.10	25	322.57	22.58	345.15
66100-TAR-T10ZZ	PANEL COMPRR. <i>9 00 ✓</i>	1	320.40	25	240.30	16.82	257.12
04655-TAS-300ZZ	PANEL SET,RR.FLOOR <i>? nux</i>	1	683.30	25	512.47	35.87	548.34
65540-T5A-N00ZZ	STIFFENER COMP,R.RR. <i>? nux</i>	1	86.90	25	65.17	4.56	69.73
65590-T5A-N00ZZ	STIFFENER COMP,L.RR.SIDE <i>? nux</i>	1	86.90	25	65.17	4.56	69.73
84521-T5A-901ZA	LID ASSYSAPARE TIRE <i>? nux</i>	1	189.80	25	142.35	9.96	152.31
84550-TAS-U00	BOX ASSY,CARGO FLOOR <i>? nux</i>	1	110.60	25	82.95	5.81	88.76
84440-T5A-J02ZA	LINING ASSYTAILGATE LOWER <i>nnx</i>	1	53.70	25	40.27	2.82	43.09
38387-TF0-003	ANTENNA ASSYL.F. <i>a nux</i>	1	61.80	25	46.35	3.24	49.59
74940-TR0-003	BUZZER ASSYSMART <i>? CRA</i>	1	60.10 <i>60.40</i>	25	45.07 <i>45.30</i>	3.15	48.22
72841-SH3-315	OILSHEET <i>? nux</i>	3	40.70	25	91.57	6.41	97.98
73127-TY0-000	RUBBER CWINDSHIELD DAMPER <i>nel ✓</i>	1	11.40	25	8.55	0.60	9.15
73214-T5A-013	RUBBERWINDSHIELD DAMPER <i>nel ✓</i>	2	6.50	25	9.75	0.68	10.43
73226-SZW-000	DAMPERSTD 5X5 <i>nel ✓</i>	1	8.50	25	6.37	0.45	6.82
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>nel ✓</i>	1	60.00		60.00	4.20	64.20
Sum Item					3967.89	277.75	4,245.64

BOSUN	SUNDRIES	1	100.00		20 100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	120.00		100 120.00	8.40	128.40
BC012R	RESET VEHICLE SMART ENTRY SYSTEM (N)	1	200.00		200.00 ✓	14.00	214.00
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA (N)	1	280.00		280.00 ✓	19.60	299.60
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	800.00		350 800.00	56.00	856.00
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	800.00		350 800.00	56.00	856.00
BOJSE	BODY JOINT SEALANT. <i>End Panel</i>	1	100.00		80 80 100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT.	1	100.00		80 100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	120.00		100 120.00	8.40	128.40
BG02R	REPLACE RR. WINDSCREEN.(N)	1	560.00		560.00 ✓	39.20	599.20
BMU30R	REMOVE & REPLACE EXHAUST SYSTEM.(N)	1	350.00		350.00 X	24.50	374.50

Printed on 17/4/2019 8:16:32 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

Registration No : SMJ4137G

Chassis No : JHMGK5850KS202476

Model : JAZZ 1.5VTIR CVT 19YM (EURO 6)

Owner's Name : ZYRE RAPHAELA LOH RUI MIEN

Ins Policy No. :

Date of Accident : 17/4/2019

Document No. : SQT19001741

Date : 17. Apr 2019

Customer No. : WZF002

Svc Advisor : ANIKKA LAI SWEE KAM

Engine No : L15B34100149

Date | Time : 17. Apr 2019 7:02:26 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 3

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BKRP02M	CUT OFF & RENEW RR PANEL & DAMAGE PARTS.	1	3500.00	19.80	3500.00	245.00	3745.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. 6P	1	3000.00	27.80	3000.00	210.00	3210.00
Sum Labor					10030.00	702.10	10,732.10

Survey By: Hue Jie - Lkk

Date & Time: 25/4/19

Excess: -

Status: PIP Sdaga.

Signature: [Signature]

Total Amount 13,997.89 979.85 14,977.74

Total (Inclusive of GST) 14046.64 14,977.74

14046.87

[Signature]
29/4/19

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 17/4/2019 8:16:32 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd. it will be refunded.



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZF002 / MS FIRST CAPITAL
Chassis No: JHMGK5850KS202476
License No: SMJ4137G
Mileage: 3203
Engine No: L15B34100149

Document No: SVO19026115
Printed By: ANIKKALAI
Order Date: 25. April 2019
Order Time: 11:02:33 AM
Service Advisor: ANIKKA LAI SWEE KAM

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: ZYRE RAPHEALA LOH RUI MIEN OWNER INSURER: TOKIO MARINE ACC DATE: 17/04/2019 SURVEYED BY: HWEE JIE / LKK DATE: 25/04/2019 REF NO: TP INSURER: MS FCL TP VEH: SHC8668K						
04715-T5B-J50ZZ	FACE,RR.BUMPER DEF	1	502.50	25	376.87	26.38	403.25
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE nec	1	16.90	25	12.67	0.89	13.56
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE nec	1	16.90	25	12.67	0.89	13.56
91505-TM8-003	CLIP,BUMPER nec	9	2.30	25	15.52	1.09	16.61
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR shanded	1	320.00		320.00	22.40	342.40
71510-T5B-J50ZA	DIFFUSER ASSY,RR.PR DER	1	206.80	25	155.10	10.86	165.96
68100-T5B-Z50ZZ	TAILGATE COMP BUC	1	730.60	25	547.95	38.36	586.31
74440-T5A-003	WEATHERSTRIPTAILGATE DEF	1	92.30	25	69.22	4.85	74.07
75722-T5L-T01	EMBLEMRR. nec	1	10.90	25	8.17	0.57	8.74
75701-T5A-000	EMBLEMH nec	1	10.70	25	8.02	0.56	8.58
90301-ST0-003	NUTPUSH 3MM nec A	2	2.10	25	3.15	0.22	3.37
33550-T5A-J02	TAILLIGHT ASSYL. SCR	1	223.90	25	167.92	11.75	179.67
66100-TAR-T10ZZ	PANEL COMPRR. DD	1	320.40	25	240.30	16.82	257.12
74940-TZ5-A01	BUZZER ASSYSMART CRA	1	60.40	25	45.30	3.17	48.47
73127-TY0-000	RUBBER CWINDSHIELD DAMPER nec	1	11.40	25	8.55	0.60	9.15
73214-T5A-013	RUBBERWINDSHIELD DAMPER nec	2	6.50	25	9.75	0.68	10.43
73226-SZW-000	DAMPERSTD 5X5 nec	1	8.50	25	6.37	0.45	6.82
BO-WS-SEALANT	WINDSCREEN SEALANT (N) nec	1	60.00		60.00	4.20	64.20
84640-T5A-003ZA	LINING ASSYRR.PANEL DEF A	1	60.80	25	45.60	3.19	48.79
	SUM PARTS:				2,113.13	147.93	2,261.06
BOSUN		1	20.00		20.00	1.40	21.40
	SUNDRIES						
BA02R	1610	1	100.00		100.00	7.00	107.00
	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)						
BC012R		1	200.00		200.00	14.00	214.00
	RESET VEHICLE SMART ENTRY SYSTEM (N)						
BC011R	0671	1	280.00		280.00	19.60	299.60
	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA (N)						
BKTG02R	0671	1	350.00		350.00	24.50	374.50
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)						
BMI03D	1757	1	350.00		350.00	24.50	374.50
	REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)						
BOJSE	1610	1	80.00		80.00	5.60	85.60
	BODY JOINT SEALANT END PANEL						



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZF002 / MS FIRST CAPITAL
Chassis No: JHMGK5850KS202476
License No: SMJ4137G
Mileage: 3203
Engine No: L15B34100149

Document No: SVO19026115
Printed By: ANIKKALAI
Order Date: 25. April 2019
Order Time: 11:02:33 AM
Service Advisor: ANIKKA LAI SWEE KAM

BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	100.00	100.00	7.00	107.00
BG02R	1757 REPLACE RR. WINDSCREEN.(N)	1	560.00	560.00	39.20	599.20
BKRP02M	0671 CUT OFF & RENEW RR PANEL & DAMAGE PARTS. FLOOR PANEL INCLUDING FITTINGS ON ATTACHMENT ITEM	1	1,960.00	1,960.00	137.20	2,097.20
BP05R	1610 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P)	1	2,700.00	2,700.00	189.00	2,889.00
			SUM LABOUR:	6,700.00	469.00	7,169.00
			TOTAL SGD	8,813.13	616.93	9,430.06
Total Payable (SGD)						9,430.06

GST Amount is calculated from individual line(s)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI19006949/Jsd3e2

36 ROBINSON ROAD

#16-01 CITY HOUSESINGAPORE 068877

Date : 22-07-2019



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 8668K	Veh. Inspected	SMJ 4137G
Policy No.		Coverage (\$)	0.00
Claim No.	D19002613MFSH	Excess (\$)	0.00
Assign From	EILEEN LEE	Assign Date	18/04/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA JAZZ	c.c	1498
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JHMGK5850KS202476	Colour	RED
Odometer	3203	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/55 R16	DUNLOP	6 mm
L/H Front Tyre	185/55 R16	DUNLOP	6 mm
R/H Rear Tyre	185/55 R16	DUNLOP	6 mm
L/H Rear Tyre	185/55 R16	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	17/04/2019	Inspection Date	25/04/2019
Survey held at	KAH MOTOR.CO.SDN.BHD 6A MANDAI ESTATE SINGAPORE 729903		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMJ 4137G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FACE,RR.BUMPER (SN)	DEFORMED	376.87	376.87
1	SPACER,R.RR.BUMPER SIDE (SN)	NECESSARY	12.67	12.67
1	SPACER,L.RR.BUMPER SIDE (SN)	NECESSARY	12.67	12.67
9	CLIP, BUMPER (SN)	NECESSARY	15.52	15.52
1	COVER,R.RR.BUMPER (SN)	NOT NECESSARY	15.52	-
4	ACT RR.SENSOR (SN)	SHORTED	320.00	320.00
1	COVER,L.RR.BUMPER (SN)	NOT NECESSARY	15.52	-
1	DIFFUSER ASSY.RR.PR (SN)	DEFORMED	155.10	155.10
1	TAILGATE COMP (SN)	BUCKLED	547.95	547.95
1	WEATHERSTRIPTAILGATE (SN)	DEFORMED	69.22	69.22
1	LOCK ASSY, TAILGATE (SN)	SERVICEABLE	59.17	-
1	EMBLEMRR. (SN)	NECESSARY	8.17	8.17
1	EMBLEMH (SN)	NECESSARY	8.02	8.02
2	NUTPAINT CUTTING (SN)	NOT NECESSARY	3.75	-
1	GARNISH ASSYRR.LICENSE (SN)	NOT NECESSARY	150.45	-
1	TAILLIGHT ASSY, R (SN)	NOT NECESSARY	167.92	-
1	TAILLIGHT ASSYL. (SN)	SCRATCHED	167.92	167.92
1	LIGHT ASSYR.LID (SN)	NOT NECESSARY	61.27	-
1	LIGHT ASSYL.LID (SN)	NOT NECESSARY	61.27	-
1	SILENCER COMPEXHAUST (SN)	NOT NECESSARY	322.57	-
1	PANEL COMPRR. (SN)	DENTED	240.30	240.30
1	PANEL SET, RR.FLOOR (SN)	NOT NECESSARY	512.47	-
1	STIFFENER COMP,R.RR (SN)	NOT NECESSARY	65.17	-
1	STIFFENER COMP,L.RR.SIDE (SN)	NOT NECESSARY	65.17	-
1	LID ASSYSPARE TIRE (SN)	NOT NECESSARY	142.35	-
1	BOX ASSY, CARGO FLOOR (SN)	NOT NECESSARY	82.95	-
1	LINING ASSYTAILGATE LOWER (SN)	NOT NECESSARY	40.27	-
1	ANTENNA ASSYL.F. (SN)	NOT NECESSARY	46.35	-
1	BUZZER ASSYSMART (SN)	CRACKED	45.30	45.30
3	OILSHEET (SN)	NOT NECESSARY	91.57	-
1	RUBBER CWINDSHIELD DAMPER (SN)	NECESSARY	8.55	8.55

Report Ref No. CS/FCI19006949/Jsd3e2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	RUBBERWINDSHIELD DAMPER (SN)	NECESSARY	9.75	9.75
1	DAMPERSTD 5X5 (SN)	NECESSARY	6.37	6.37
1	WINDSCREEN SEALANT (SN)	NECESSARY	60.00	60.00
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
2	NUTPUSH 3MM (SN) (ADDITIONAL)	NECESSARY	3.15	3.15
1	LINING ASSYRR.PANEL (SN) (ADDITIONAL)	DEFORMED	45.60	45.60
			4,116.87	2,133.13
	LABOUR			
	REMOVE & RENEW REVERSE SENSORS - 4PCS.		120.00	100.00
	RESET VEHICLE SMART ENTRY SYSTEM.		200.00	200.00
	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA.		280.00	280.00
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &.		800.00	350.00
	REMOVE & INSTALL REAR COMPARTMENT LININGS.		800.00	350.00
	BODY JOINT SEALANT.		100.00	80.00
	BODY JOINT SEALANT.	NOT NECESSARY	100.00	-
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER.		120.00	100.00
	REPLACE RR.WINDSCREEN.		560.00	560.00
	REMOVE & REPLACE EXHAUST SYSTEM.	NOT NECESSARY	350.00	-
	CUT OFF & RENEW RR PANEL & DAMAGE PARTS.		3,500.00	1,960.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (6P).		3,000.00	2,700.00
			9,930.00	6,680.00
GRAND TOTAL			14,046.87	8,813.13
RECOMMENDED COST OF REPAIRS				8,813.13

Report Ref No. CS/FCI19006949/Jsd3e2

ONG HWEЕ JIE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.