

ASS. REC. BY:

REF: CS/SMO19006967/KSD362

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Ruth Chua

of SMO

Date/Time: 18.4.2019 16:59 pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SLV 6957 S

Insured:

at Workshop m/s Lai Huat (nung kee)

Tel: 64538110

of 160 Sin ming Drive #04-01

Policy No: D19MTPV01000361

Claim No: CMTD 1901950

Sum Insured:

Excess: \$400/-

Make of Veh:

D.O.A. 18.4.2019

(Client's Record)

22.4.2019

CA REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 22.4.19 5.47 pm

Person Contacted:

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLV 6957 S
22/04/19	@ 14:37 p.m. revised IA to Ruth Chua via merimer
22/04/19	@ 14:38 p.m. mandate renewed authorize repair to Ruth Chua via merimer.
22/04/19	@ 14:42 p.m. mandate approved by Ruth Chua via merimer
22/04/19	@ 17:52 p.m. revert authorize repair to Jerry Goparaj via email

Director

REF:

CS/SMD 19006967/KSD3

SMD

ASSIGNMENT

From: Date: 22/4/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLV6957S
at Workshop m/s Lai Huet Meng Kee.
of 160 Sin Ming Drive # 04-01

Insured:

Policy No.

Claims No.

Sum Insured: Excess: \$400 / TBA

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$138k

IDAC Accident Rpt: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 1.B.1% 3 Val.: Yes or No

CA / (REV) / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLV6957S Yr Regn: 01, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Kia A) Soranto Wagon C.C. 2199

Colour: M. Black A/C: Insured / Std / NI / NA

Sp. Reading: 18001 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KNAP1481BMT5411488

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: R: 235/60R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. mm

R/Bal. mm

L/Bal. mm

L/Bal. mm

D.O.A. 18/4/19

D.O.I. 22/4/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

13/5 82345-20 Confirmed
(\$133.00 Red - 5%)

Date/Time, File Pass to?

24/05/19

1) Typ. 4

Date/Time, File Return to?

2)

☐: Preli. Report☒: Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐: Site Insp (\$)☐: Interview (\$)☐: Tech. Invs (\$)☐: Weekend (\$)

Survey Fee:

Transportation: \$ + RS, \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ 2,345-20 p/p)

N

261

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Apr 2019 Sendback Est	18 Apr 2019 16:24 S\$2,378.20	18 Apr 2019 16:59 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	NG XUNXI (HUANG XUNXI), ID: S7829676C, Tel: +6596923015, Email: NGXUNXI@GMAIL.COM		
Vehicle Reg. No.:	SLV6957S	Date of Loss:	18/04/2019 14:00 - :59 [15 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / CMTD1901950	Policy/Cover Note No.:	D19MTPV01000361 (Comprehensive)
		Excess:	
Repairer:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Ruth Chua Gek Tiang - 6329 5153]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/04/2019]		
Driver/Custodian:	NG XUNXI (HUANG XUNXI) (40 / Male), NRIC: S7829676C, Tel: +6596923015 Email: NGXUNXI@GMAIL.COM		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

MV - \$138K

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9676C
Vehicle Details	
Vehicle No.:	SLV6957S
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Apr 2019
Vehicle Make:	KIA
Vehicle Model:	SORENTO 2.2(8AT) CRDI 2WD S/R
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	D4HBHH347421
Chassis No.:	KNAPH81BMJ5411488
Maximum Power Output:	147.0 kW (197 bhp)
Open Market Value:	\$30,411.00
Original Registration Date:	11 Jan 2018
First Registration Date:	11 Jan 2018
Transfer Count:	0
Actual ARF Paid:	\$34,576.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Jan 2028
PARF Rebate Amount:	\$25,932.00
Intended COE Rebate Details	
COE Expiry Date:	10 Jan 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,002.00
COE Rebate Amount:	\$40,975.00
Total Rebate Amount:	\$66,907.00

The information contained herein is correct as at 22 Apr 2019

OK

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 24 May 2019 5:03 PM
To: 'Jenny Lim'
Cc: SUR
Subject: RE: Finalisation - SLV 6957S / Kia Sorento
Attachments: SLV 6957S - SUPPLEMENTARY MARKED.pdf

Dear Jenny,

Supplementary approved by insurance.

Confirmed final fig of \$ 2,345.20 (part by part) @ 4 days of repairs before excess \$400/- & GST.

Final invoice and all supporting documents sent over to Sompo Insurance Singapore Pte. Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jenny Lim [mailto:jenny.lim@laihuat.com.sg]
Sent: Friday, 10 May 2019 4:27 PM
To: Kenneth Kong <KennethKong@lkkauto.com>
Subject: Finalisation - SLV 6957S / Kia Sorento

Dear Sir

For your confirmation, please:

- Parts: \$1,282.00
- 10%: \$ 128.20
- SN: \$ 35.00
- L&P: \$ 900.00 (include supplementary)

Sub-total: \$2,345.20 / Excess cost: \$400.00

Supporting documents and photographs are enclosed for your reference.

Thank you.

Kind regards.

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596267

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 22 April 2019 5:52 PM
To: jenny.lim@laihuat.com.sg
Cc: SUR
Subject: SLV 6957S OD 18/04/2019

Dear Jenny,

As instructed by our client, please proceed to repair the insured vehicle **SLV 6957S (Excess \$ 400/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

SLV6957S (CMTD1901950)

OD

Apr 18 2019 2:00PM

[NG XUNXI (HUANG XUNXI)]

Lai Huat (Meng Kee) Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From Sompo Insurance Singapore Pte. Ltd. (SOMPO_SG), sent on 23/05/2019 14:54 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$2345.20) - SLV6957S - Claim Handler: Ruth Chua Gek Tiang

Approved:2345.20.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

SLV6957S (CMTD1901950)

OD

Apr 18 2019 2:00PM

[NG XUNXI (HUANG XUNXI)]

Lai Huat (Meng Kee) Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From Sampo Insurance Singapore Pte. Ltd. (SOMPO_SG), sent on 22/04/2019 14:42 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$2178.20) - SLV6957S - Claim Handler: Ruth Chua Gek Tiang

Approved:2178.20.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ruth Chua Gek Tiang

Date: 23 May 2019

Preliminary Advice

Vehicle No	: SLV6957S	Accident Date	: 18/04/2019
Make	: KIA SORENTO	Policy No.	: D19MTPV01000361
Assignment Date	: 18/04/2019	Excess	: S\$400.00
Date of Inspection	: 22/04/2019	Est. Duration of Repair	: 4 days
Inspection At	: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity Singapore 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,478.20 (inclusive supplementary)
Revised Amount	:S\$	2,345.20 (inclusive supplementary)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,345.20
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	138,000.00
COE / PARF Rebate	:S\$	66,907.00
Salvage Value	:S\$	
Margin for Repair	:S\$	71,093.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have received supplementary from repairer. Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair. Supplementary amount is \$ 100.00

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ruth Chua Gek Tiang

Date: 22 Apr 2019

Preliminary Advice

Vehicle No	: SLV6957S	Accident Date	: 18/04/2019
Make	: KIA SORENTO	Policy No.	: D19MTPV01000361
Assignment Date	: 18/04/2019	Excess	: S\$400.00
Date of Inspection	: 22/04/2019	Est. Duration of Repair	: 4 days
Inspection At	: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity Singapore 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,378.20
Revised Amount	:S\$	2,117.70
Check Items (Estimated)	:S\$	60.50
Total	:S\$	2,178.20
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	138,000.00
COE / PARF Rebate	:S\$	66,907.00
Salvage Value	:S\$	
Margin for Repair	:S\$	71,093.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/04/2019 14:50
Date Of Accident	18/04/2019 14:00
Exact Location Of Accident	SLIP ROAD OF BISHAN ROAD TO ANG MO KIO AVE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLV6957S
Insured/Policyholder	
Name Of Registered Owner	NG XUNXI (HUANG XUNXI)
NRIC No	S7829676C
Email Address	NGXUNXI@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96923015
Alternative Phone No	OTHERS-96923015

Vehicle Particulars

Manufacturer	KIA
Model	SORENTO 2.2L DIESEL
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D19MTPV01000361
Cover Note Number	

Driver

Name of Driver	NG XUNXI (HUANG XUNXI)
NRIC No	S7829676C
Date Of Birth	05/10/1978
Occupation	INDOOR
Date Of Driving Pass	28/12/1999
Driving Experience	19 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96923015
Fax Number	
Contact Number	OTHERS-96923015
Email Address	NGXUNXI@GMAIL.COM

Address	BLK 33 BISHAN STREET 11 #09-12
Postcode	579820
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO WITH OWNER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJM4864K
Vehicle Make/Model/Colour	NISSON LATIO
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



 Policyholder's Signature
 Date & Time: 18 APR 2019

 DRIVER SketchPlan Form_V3

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Person's Signature
 Name: Poh Kwee Choo
 NRIC/FIN No.: S6840583A

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At junction between Bishan Road and Ang Mo Kio Ave 1, on 18 Apr 2019 2pm. My car (SLV 6957 S) was waiting to turn left behind a peach-colour Nissan Latio (SJM 4864 K). My car knocked into this car from behind.




DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:
18 Apr 2019
2.45 pm

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Poh Kwee Choo
NRIC/FIN No.: S6840583A



**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623
Tel: 6461 6555 | Fax: 6221 3302 | Website: www.sompo.com.sg
Co. Reg. No.: 198905490E | GST Reg. No.: M200903196

Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Cert No./Policy No. : D19MTPV01000361
Insured : NG XUN XI
Motor Car (Registration No.) : SLV6957S
Cover : Comprehensive - ExcelDrive FOCUS
Policy Commencement Date : 11 JANUARY 2019 00:00
Policy Expiry Date : 10 JANUARY 2020 23:59
Maximum Liability (Section I) : Market value at time of loss
Excess* : \$800 - Section I
(Waived up to 50% or maximum S\$600 whichever is lower if accident repair is done at ExcelDrive Workshops for the first claim per policy year)
Voluntary Excess* : N.A.
Windscreen Excess* : S\$100.00 - Waived if Repair at ExcelDrive Workshop
Loss of Use : N.A.
* Subject to GST wherever applicable

Persons or Classes of Persons entitled to drive*

1. The Insured.
2. Any other person who is driving on the Insured's order or with his permission.
3. In the event of the death of the insured,
 - a. any member of the insured's family, or a paid driver who has been driving the Motor Car during the life of the insured and permission to drive had not been withdrawn prior to the death of the insured; and
 - b. any other person who has been given permission to drive the Motor Car prior to the death and such permission had not been withdrawn by the Insured.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Car or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Car. And provided further that the Motor Car is registered under the Road Traffic Act (Chapter 276) and its registration under the Road Traffic Act (Chapter 276) has not been cancelled at the time of the accident, loss or damage.

Limitations As To Use

Use only for social, domestic and pleasure purpose and for the Insured's business. The Policy does not cover use for hire or reward, racing, pace-making, speed testing, reliability trial, the carriage of goods other than samples in connection with any trade or business or use for any purposes in connection with the Motor Trade.

ExcelDrive Workshops and Accident Reporting

It is a condition precedent to liability that the Insured shall call at the Company's Accident Reporting Center with the Motor Car within 24 hours of the accident or by the next working day thereof.

All accident repairs to the Motor Car must be carried out at ExcelDrive Workshops, otherwise the claim is not payable under the Policy. For ExcelDrive Prestige Plan, accident repairs to the Motor Car can be carried out at any workshop other than ExcelDrive Workshops.

For the list of Accident Reporting Centres and ExcelDrive Workshops, please visit our website at www.sompo.com.sg or call our Emergency Hotline: (65) 6226 3323.

I/We HEREBY CERTIFY that the policy to which this Certificate relates is issued in accordance with (1) the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia); and (2) the Policy terms, conditions and exceptions of the Private Car Policy ref MTP.27

Sompo Insurance Singapore Pte. Ltd.

Authorised Signatory

Date/Time of Issue : 14 DECEMBER 2018 11:16

IMPORTANT NOTICE

- o Keep the Certificate in your Motor Car.
- o Under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189), it shall be unlawful for any person to use or cause to permit any other person to use a motor vehicle without a valid policy of insurance under the Act.
- o On the sale of the Motor Car or if for any reason the Insurance is terminated during its currency, the Insured must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a statutory declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).
- o This Policy will cease to be valid once the Motor Car has been sold to another person. The Policy is not transferable to the new owner of the Motor Car.

Intermediary Code & Name : 11G05800 & GREAT EASTERN FINANCIAL ADVISERS PTE LTD CI Code: 22A R6DZZ04PIJDDMAAJ

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 9676C

Vehicle Details

Vehicle No.: SLV6957S
Vehicle to be Exported: Yes
Intended Deregistration Date: 18 Apr 2019
Vehicle Make: KIA
Vehicle Model: SORENTO 2.2(8AT) CRDI 2WD S/R
Primary Colour: Black
Manufacturing Year: 2017
Engine No.: D4HBHH347421
Chassis No.: KNAPH81BMJ5411488
Maximum Power Output: 147.0 kW (197 bhp)
Open Market Value: \$30,411.00
Original Registration Date: 11 Jan 2018
First Registration Date: 11 Jan 2018
Transfer Count: 0
Actual ARF Paid: \$34,576.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 10 Jan 2028
PARF Rebate Amount: \$25,932.00

Intended COE Rebate Details

COE Expiry Date: 10 Jan 2028
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$47,002.00
COE Rebate Amount: \$37,601.00
Total Rebate Amount: \$63,533.00

The information contained herein is correct as at 18 Apr 2019

OK

來發(明記)摩多有限公司

LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity

160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722

Tel: 64538110 Fax: 64596267 Email: info@laihuat.com.sg

UEN: 199407592C

INSURER: Sompoo Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	70430
Policy No:	D19MTPV01000361	Date of Loss:	18/04/2019
Vehicle Reg. No.:	SLV6957S	Driveable?	
Driver Age/Info:	40 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	NG XUNXI (HUANG XUNXI)	Contact No:	+6596923015
Driver:	NG XUNXI (HUANG XUNXI)		

Make/Model:	KIA SORENTO, 2.2 D CRDI 2WD S/R (A)	Vehicle Reg. Date:	11/01/2018
Vehicle Colour:	Black		
Engine No:	D4HBHH347421	Chassis No:	KNAPH81BMJ5411486
Odometer:	17888 KM		

Paint Type:
 Total Loss? NO
 Est. Duration of Repair (day) 8 & 4 day



Not with the
 Resurvey B & paint
 1. B.1
 Fax: 62564315

Description of Accident/Loss PLEASE REFER TO SKETCH PLAN.
 Present Location: LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING)

COST OF CLAIMS

	Amount
Parts	1,478.20
Miscellaneous Items	0.00
Labour	300.00
Paintwork Labour	600.00
Towing	0.00

Calculated Gross Total (S\$)	2,378.20
- Excess (S\$)	400.00
(S\$)	1,978.20
+ GST 7.00% (S\$)	138.47
Nett Amount (S\$)	2,116.67

This claim is handled by: JENNY LIM LAI FOONG

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Apr 2019)

Parts: M1-SUV KIA SORENTO 2.2 D CRDI 2WD S/R (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Lai Huat (Meng Kee) Motor Pte Ltd/SLV6957S/18/04/2019 16:24

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*Front number plate base	0.00	0.00	Ref *18.00 F	✓
2	1		*Front bumper	0.00	0.00	Bu *230.00 F	✓
3	1		*Front bumper lower centre grille	0.00	0.00	DIT *85.00 F	2
4	1		*Front radiator grille	0.00	0.00	CM *280.00 F	✓
5	1		*Bonnet	0.00	0.00	Ry *550.00 F	✓
6	4		*Front bumper clips	0.00	0.00	Mc *6.00 F	✓
7	1		*Radiator top cover	0.00	0.00	CM *58.00 F	✓
8	1		*Front bumper sponge	0.00	0.00	*55.00 F	7
9	1		*Front bumper lower garnish	0.00	0.00	Bu *30.00 F	✓
10	1		*Front number plate	0	0.00	Bu *35.00 FS	✓

F=Franchise part. S=SpcNatl.

Sub Total (\$\$) 1,347.00
+ Margin on L,N Items 10.00% (\$\$) 131.20

Total Parts (\$\$) 1,478.20

Lai Huat (Meng Kee) Motor Pte Ltd/SLV6957S/18/04/2019 16:24. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected,

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	To spray paint	New	600.00
<u>Labour Items</u>			
2	To dismantle and renew above parts	New	300.00
Gross Labour Cost (S\$)			900.00

Lai Huat (Meng Kee) Motor Pte Ltd/SLV6957S/18/04/2019 16:24. Not valid without Reference section.
Generated using Merlmen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

來發(明記)摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity
160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722
Tel: 64538110 Fax: 64596267 Email: info@laihuat.com.sg
UEN: 199407592C

INSURER: Sompoo Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	70430
Policy No:	D19MTPV01000361	Date of Loss:	18/04/2019
Vehicle Reg. No.:	SLV6957S	Driveable?	
Driver Age/Info:	40 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	NG XUNXI (HUANG XUNXI)	Contact No:	+6596923015
Driver:	NG XUNXI (HUANG XUNXI)		

Make/Model:	KIA SORENTO, 2.2 D CRDI 2WD S/R (A)	Vehicle Reg. Date:	11/01/2018
Vehicle Colour:	Black		
Engine No:	D4HBHH347421	Chassis No:	KNAPH81BMJ5411488
Odometer:	17888 KM		

Paint Type: *1B1*

Total Loss? **NO**

Est. Duration of Repair (day) *5 & 4 day*

Not with a resurvey B4 paint

fax: 62564315

Description of Accident/Loss PLEASE REFER TO SKETCH PLAN.

Present Location: LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING)

COST OF CLAIMS

	Amount
Parts	1,478.20
Miscellaneous Items	0.00
Labour	300.00
Paintwork Labour	600.00
Towing	0.00
Calculated Gross Total (S\$)	2,378.20
- Excess (S\$)	400.00
(S\$)	1,978.20
+ GST 7.00% (S\$)	138.47
Nett Amount (S\$)	2,116.67

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Calculated Gross Total (S\$)

- Excess (S\$)

(S\$)

+ GST 7.00% (S\$)

Nett Amount (S\$)

This claim is handled by: JENNY LIM LAI FOONG

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Apr 2019)

Parts: M1-SUV KIA SORENTO 2.2 D CRDI 2WD S/R (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Lai Huat (Meng Kee) Motor Pte Ltd/SLV6957S/18/04/2019 16:24

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*Front number plate base	0.00	0.00	<i>Red</i> *18.00 F	✓
2	1		*Front bumper	0.00	0.00	<i>Bu</i> *230.00 F	✓
3	1		*Front bumper lower centre grille	0.00	0.00	<i>Di</i> *85.00 F	2
4	1		*Front radiator grille	0.00	0.00	<i>CM</i> *280.00 F	✓
5	1		*Bonnet	0.00	0.00	<i>Bz</i> *550.00 F	✓
6	4		*Front bumper clips	0.00	0.00	<i>nu</i> *6.00 F	✓
7	1		*Radiator top cover	0.00	0.00	<i>CM</i> *58.00 F	✓
8	1		*Front bumper sponge	0.00	0.00	<i>CM</i> *55.00 F	2
9	1		*Front bumper lower garnish	<i>Sm</i> 0.00	0.00	<i>Bu</i> *30.00 F	4X
10	1		*Front number plate	0	0.00	<i>Bz</i> *35.00 FS	✓

F=Franchise part. S=SpcNett.

Sub Total (S\$) 1,347.00

+ Margin on L,N Items 10.00% (S\$) 131.20

Total Parts (S\$) 1,478.20

Lai Huat (Meng Kee) Motor Pte Ltd/SLV6957S/18/04/2019 16:24. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	To spray paint	New	600.00
<u>Labour Items</u>			
2	To dismantle and renew above parts	New	300.00
Gross Labour Cost (S\$)			900.00

Lai Huat (Meng Kee) Motor Pte Ltd/SLV6957S/18/04/2019 16:24. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

SUPPLEMENTARY

No	Particulars	Lab.Type	Amount
Labour Items			
1	To repair front headlamp LH	New	100.00
Gross Labour Cost (S\$)			100.00

Lai Huat (Meng Kee) Motor Pte Ltd/SLV6957S/10/05/2019 14:22. Not valid without Reference section.
Generated using Merlmen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Apr 2019 Sendback Est	18 Apr 2019 16:24 S\$2,378.20	18 Apr 2019 16:59 Edit Adj Rpt	S\$2,345.20 Edit Estimates	S\$2,345.20 View Rpt		Pending for Survey Report Cancel Case
Supp #1	10 May 2019 14:21	10 May 2019 14:22 S\$100.00	10 May 2019 14:22			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	NG XUNXI (HUANG XUNXI), ID: S7829676C, Tel: +6596923015, Email: NGXUNXI@GMAIL.COM		
Vehicle Reg. No.:	SLV6957S	Date of Loss:	18/04/2019 14:00 - :59 [15 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / CMTD1901950	Policy/Cover Note No.:	D19MTPV01000361 (Comprehensive)
		Excess:	S\$400.00
Repairer:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Ruth Chua Gek Tiang - 6329 5153]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 30/04/2019]		
Driver/Custodian:	NG XUNXI (HUANG XUNXI) (40 / Male), NRIC: S7829676C, Tel: +6596923015 Email: NGXUNXI@GMAIL.COM		

ASSOCIATED MAIL RECEIVED

View All Compose Case Mail

- SOMPO_SG (23/05/2019): Alert - Adj Mandate Approved (S\$2345.20) - SLV6957S - Claim Handler: Ruth Chua G...
- SOMPO_SG (22/04/2019): Alert - Adj Mandate Approved (S\$2178.20) - SLV6957S - Claim Handler: Ruth Chua G...

ALL ASSOCIATED TASKS

View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLV6957S (CMTD1901950)
OD
Apr 18 2019 2:00PM
[NG XUNXI (HUANG XUNXI)]
Lai Huat (Meng Kee) Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Assessment Reports									1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)								Thumbnail	Print	
1	18/04/19 16:24	Repairer Estimates								Load HTM		
2	10/05/19 14:22	Repairer Estimates Suppl. #1								Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	22/04/19 14:37	Adjuster Immediate Advice								Load HTM		
2	23/05/19 11:44	Adjuster Immediate Advice								Load HTM		
Photos/Images									3 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)								Thumbnail	Print	
1	18/04/19 16:22	Front View								Load JPG	<input checked="" type="checkbox"/>	
2	18/04/19 16:22	Front View Left								Load JPG	<input checked="" type="checkbox"/>	
3	18/04/19 16:22	Front View Left								Load JPG	<input checked="" type="checkbox"/>	
4	18/04/19 16:22	Front View Left								Load JPG	<input checked="" type="checkbox"/>	
5	18/04/19 16:22	Front View Left								Load JPG	<input checked="" type="checkbox"/>	
6	18/04/19 16:22	Front View Left								Load JPG	<input checked="" type="checkbox"/>	
7	18/04/19 16:22	Front View Left								Load JPG	<input checked="" type="checkbox"/>	
8	18/04/19 16:22	Front View Left								Load JPG	<input checked="" type="checkbox"/>	
9	18/04/19 16:22	Front View Left								Load JPG	<input checked="" type="checkbox"/>	
10	18/04/19 16:22	Chassis Number								Load JPG	<input checked="" type="checkbox"/>	
11	18/04/19 16:22	Tyre - Yokohama								Load JPG	<input checked="" type="checkbox"/>	
12	18/04/19 16:22	Tyre size								Load JPG	<input checked="" type="checkbox"/>	
13	18/04/19 16:22	Front View								Load JPG	<input checked="" type="checkbox"/>	
14	18/04/19 16:22	Front View								Load JPG	<input checked="" type="checkbox"/>	
15	18/04/19 16:22	Odometer Reading								Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	23/05/19 11:52	General View								Load JPG	<input checked="" type="checkbox"/>	
2	23/05/19 11:52	General View								Load JPG	<input checked="" type="checkbox"/>	
3	23/05/19 11:52	General View								Load JPG	<input checked="" type="checkbox"/>	
4	23/05/19 11:52	General View								Load JPG	<input checked="" type="checkbox"/>	
5	23/05/19 11:52	General View								Load JPG	<input checked="" type="checkbox"/>	
6	23/05/19 11:52	General View								Load JPG	<input checked="" type="checkbox"/>	
7	23/05/19 11:52	General View								Load JPG	<input checked="" type="checkbox"/>	
8	23/05/19 11:52	General View								Load JPG	<input checked="" type="checkbox"/>	
9	23/05/19 11:52	General View								Load JPG	<input checked="" type="checkbox"/>	
10	23/05/19 11:52	General View								Load JPG	<input checked="" type="checkbox"/>	
11	23/05/19 11:52	General View								Load JPG	<input checked="" type="checkbox"/>	
12	23/05/19 11:52	General View								Load JPG	<input checked="" type="checkbox"/>	
13	23/05/19 11:52	General View								Load JPG	<input checked="" type="checkbox"/>	
14	23/05/19 11:52	General View								Load JPG	<input checked="" type="checkbox"/>	
15	23/05/19 11:52	General View								Load JPG	<input checked="" type="checkbox"/>	
16	23/05/19 11:52	General View								Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
17	23/05/19 11:53	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
18	23/05/19 11:53	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
19	23/05/19 11:53	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
20	23/05/19 11:53	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
21	23/05/19 11:53	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	18/04/19 16:24	E-filed GIA report		Load PDF	
2	18/04/19 16:24	Driver's NRIC & Driving Licence		Load PDF	
3	18/04/19 16:24	Certificate of Insurance		Load PDF	
4	18/04/19 16:24	Enquire PARF / COE Rebate for Registered Vehicle		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	22/04/19 14:37	ESTIMATE.pdf		Load PDF	
2	23/05/19 11:50	ESTIMATE & SUPP MARKED.pdf		Load PDF	

Linked Accident Report Documents

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	18/04/19 16:15	Accident Statement		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	18/04/19 15:08	SCENE PHOTO		Load JPG	<input checked="" type="checkbox"/>
2	18/04/19 15:08	SCENE PHOTO		Load JPG	<input checked="" type="checkbox"/>
3	18/04/19 15:08	SCENE PHOTO		Load JPG	<input checked="" type="checkbox"/>
4	18/04/19 16:14	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	18/04/19 16:14	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	18/04/19 16:14	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	18/04/19 16:14	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	18/04/19 15:50	Sketch Plan		Load TIF	
2	18/04/19 15:51	CERTIFICATE OF INSURANCE		Load TIF	
3	18/04/19 15:51	DRIVER'S NRIC + DRIVING LICENCE		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST Reset Save Print
There are no document checklists configured.
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place, #05-01/06, Singapore Land Tower
Singapore 048623

Our File No: CS/SMO19006967/KSD3E2

Date: 12/06/2019

REFERENCE

Insured/Claimant: NG XUNXI (HUANG XUNXI) Policy No: D19MTPV01000361
Date of Loss: 18/04/2019 Nature of Claim: OD Claim No: CMTD1901950

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLV6957S**
Make & Model: KIA SORENTO, 2.2 D CRDI 2WD S/R (A) Engine No: D4HBHH347421
Reg. Date: 11/01/2018 (Man. Year: 2017) Chassis No: KNAPH81BMJ5411488
Colour: Metallic Black Odometer: 18001 km
Engine Capacity: 2199 cc
Market Value/New Car Price: S\$138,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/60 R18 Rear Tyre Size: 235/60 R18
Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm
Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,478.20	1,445.20	33.00	2.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	400.00	400.00	0.00	0.00
Paintwork Labour	600.00	500.00	100.00	16.67
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,478.20	2,345.20	133.00	5.37
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	2,078.20	1,945.20	133.00	6.40
+ GST 7.00/7.00% (S\$)	145.47	136.16	9.31	6.40
Nett Amount (S\$)	2,223.67	2,081.36	142.31	6.40

INSPECTION

Date of Assignment: 18/04/2019 Present Location: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
Date Inspected: 22/04/2019 Inspected At: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
160 Sin Ming Drive #04-01, Sin Ming
AutoCity
Singapore 575722
Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Jun 2019)
Parts:	M1-SUV	KIA SORENTO 2.2 D CRDI 2WD S/R (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV6957S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front number plate base (WCP)	Dented	18.00 F	*18.00 F
2	1		*Front bumper (WCP)	Buckled	230.00 F	*230.00 F
3	1		*Front bumper lower centre grille (WCP)	Distorted	85.00 F	*85.00 F
4	1		*Front radiator grille (WCP)	Cracked	280.00 F	*280.00 F
5	1		*Bonnet (WCP)	Bent	550.00 F	*550.00 F
6	4		*Front bumper clips (WCP)	Necessary	6.00 F	*6.00 F
7	1		*Radiator top cover (WCP)	Cracked	58.00 F	*58.00 F
8	1		*Front bumper sponge (WCP)	Cracked	55.00 F	*55.00 F
9	1		*Front bumper lower garnish (WCP)	Serviceable	30.00 F	*- F
10	1		*Front number plate	Bent	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	1,347.00	1,317.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	131.20	128.20
Total Parts (\$\$)	1,478.20	1,445.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	To spray paint	New	600.00	500.00
<u>Labour Items</u>				
2	To dismantle and renew above parts	New	300.00	300.00
<u>Supplementary #1</u>				
<u>Labour Items</u>				
3	To repair front headlamp LH	New	100.00	100.00
Gross Labour Cost (\$\$)			1,000.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >